

Invoice

ASS. REC BY:

REP: CS/FCI18000603/ Ugd3nz

Special Services

By: Marcus

ASSIGNMENT (Office)

From (Person): Teo Swee Keong

FCI

Date/Time: 09/01/18 @ 7:09pm

Estimated Cost:

Bill to:

OD (H) / WS / TP RES / OD RES / EVA / TV / MV / CS

To Inspect Vehicle No: SJP 8412P

Insured: SHA 1239Y

at Workshop n/o: Hock Wah Motor

Tel: 6441 5655

of Blk 3011, Bedok North Ave 4 #01-2008

Policy No:

Claim No:

SHA 1239Y

Sum Insured:

Excess:

Make of Veh:

D.O.A 05/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

HOD Endorsement

Date/Time: 9:48am @ 10/01/18

Person Contacted:

Malvise

Vehic IN OUT

Date/Time

Action/Instruction (✓ Estimate)

SJP 8412P - NA / TMI 11013424 / S2

D.O.A = 09/07/2011

SHA 1239Y - CC3 / AXA 10023661 / Fg 1-2k2

D.O.A = 17/11/2010

12/1/18 @ 4:34pm revised to Swee Keong by email.

Surveillance mercantile

REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SJP 8412P  
 at Workshop m/s Kochuch  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 24  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJP 8412P Yr Regn: 4 09  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CA

Make: Toyota picnic C.C. 1998  
 Colour: Silver A/C Insured / Std / NI / NA  
 Sp. Reading: 139191 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 C/No: ITEGH 2313200026465  
 Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_ R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>5/1/18</u>	D.O.I. <u>11/1/18</u>

Survey held at \_\_\_\_\_

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
11/1/18 Confined L/S #1150 with marks  
(Red & 1727-BF, 61%)

RECEIVED 29 JAN 2018

Date/Time File Pass to? ☐ : Preli. Report

1) 29/1/18 turnist ☐ : Final Report

Date/Time File Return to?

2) \_\_\_\_\_

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation

\_\_\_\_\_ \$ + RS \_\_\_\_\_ \$

Phone

Client

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format: TP

Lump Sum / B.I.: (\$ 1150)

TOTAL

110  
50  
50  
26

236

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18000603/Uqd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 10-01-2018



Code : FCI2

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SHA 1239Y	Veh. Inspected	SJP 8412P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	TEO SWEE KEONG	Assign Date	10/01/2018

**2. Vehicle Particulars & Condition**

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

**4. Description of Damages**

--

**5. General Information**

Accident Date	05/01/2018	Inspection Date	
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SHA 1239Y

Date: 12 January 2018

Our Ref: CS/FCI18000603/Uqd3

The Motor Claims Department  
First Capital Insurance Ltd


Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SJP 8412P .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/01/2018 at the premises of M/s HOCK WAH MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,927.37</u> .
Revised Estimate Amount	: S\$ <u>1,452.60</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:  
The vehicle sustained damages  
at the n/s rear portion.



Yours faithfully

CHUA KANG SENG  
Licensed Appraiser

Reference No.: C9/KC1/8002603/16943  
Policy Type: OD / (TP) / TP RES / TL / EVA

SJP 8412P

Typist

Admin ( Nirpha ): Case handler to make sure all information created by the assignment team are ACCURATE.

<u>Y-Date</u>	<u>N-Date</u>
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	

- |   |                                       |
|---|---------------------------------------|
| C | Reference No.                         |
| C | Customer Code                         |
| N | Assign From                           |
| C | Assign Date                           |
| C | Veh No (Inspected)                    |
| C | Veh No (Insured)                      |
| C | D.O.A                                 |
| C | Policy No                             |
| C | Claim No                              |
| C | Insurance Authorisation (CA /REV/REP) |
| C | Report Type                           |
| C | Weekend Charges                       |
| N | Survey held at/Repairer               |
| C | Excess                                |

Surveyor ( Maria ): Case handler to make sure the surveyor completed all required information.

C	Vehicle No
C	Regn Month/Year
N	Vehicle Type
N	Make & Model
C	Engine Capacity. (C.C)
N	Colour
C	Odometer. (Sp.Reading)
C	Chassis No
N	General Condition
N	Steering
N	Brake
N	Modification (Modi)
C	Tyre Size
N	Tyre Make
C	Tyre Balance
C	Date of Inspection
N	Survey held
N	Des.of Damages

1	
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	

C Damaged Vehicle Photographs Uploaded

	
--	---

N	ALL Parts condition
C	Market Value for OD cases
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C	Days of repair
C	Finalised Amount
C	Re-Inspection Cases to Finalize within 5 Days

✓	
✓	
✓	


C Resurvey photo Uploaded

1	

Check By:

Case Handler

Date \_\_\_\_\_

\*C: Critical \*N: Non-Critical

21/05/2014

**Nivitha (LKK Auto)**

---

**From:** Teo Swee Keong <TeoSweeKeong@first-insurance.com.sg>  
**Sent:** Tuesday, 9 January 2018 7:09 PM  
**To:** 'assignments@lkkauto.com'  
**Cc:** Serene Ler, Hock Wah Motor Pte Ltd <motor@hockwah.com.sg>  
(motor@hockwah.com.sg)  
**Subject:** NEW SURVEY ASSIGNMENT - OUR REF: SHA1239Y DOA:05/01/2018  
**Attachments:** FW: TP CLAIM\_SJP8412P & SHA1239Y\_DOA:05/01/2018 (224 KB); MOTOR SURVEY ASSIGNMENT.pdf

Dear Sirs

New survey request for your handling.

Thanks and Regards,

**SK Teo**  
**Motor Claims Dept**

36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 | Company Regn. No. 195000106C  
email: [MotorClaims@first-insurance.com.sg](mailto:MotorClaims@first-insurance.com.sg)

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to [www.first-insurance.com.sg](http://www.first-insurance.com.sg) for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

---

**From:** Hock Wah Motor Pte Ltd [mailto:[motor@hockwah.com.sg](mailto:motor@hockwah.com.sg)]  
**Sent:** Tuesday, January 09, 2018 9:36 AM  
**To:** Teo Swee Keong <TeoSweeKeong@first-insurance.com.sg>  
**Subject:** RE: YR REF: SJP8412P OUR REF: SHA1239Y DOA:05/01/2018

Dear Sir/Madam

We would like to choose LKK Auto Consultants Pte Ltd as surveyor company.

Thank you.

Best Regards

Mavis Er

Customer Service Executive

**Hock Wah Motor Workshop Pte Ltd**

Blk 3011 Bedok North Avenue 4 | #01-2008/2010/2012/2014 | Singapore 489977

Tel: 6441 5655 | Fax: 6243 8121 | Website: [www.hockwah.com.sg](http://www.hockwah.com.sg)

---

**From:** Teo Swee Keong [mailto:[TeoSweeKeong@first-insurance.com.sg](mailto:TeoSweeKeong@first-insurance.com.sg)]  
**Sent:** Monday, 8 January, 2018 2:53 PM  
**To:** Hock Wah Motor Pte Ltd <[motor@hockwah.com.sg](mailto:motor@hockwah.com.sg)>

Cc: Serene Ler <Serener@first-insurance.com.sg>

Subject: YR REF: SJP8412P OUR REF: SHA1239Y DOA:05/01/2018

Dear Sirs,

We refer to your survey request dated 08/01/2018.

Please find below our list of surveyors for your reference. Kindly select from our list below and inform us of your choice within the next 2 days.

1. LKK Auto Consultants Pte Ltd
2. Vicom Ltd

Once you inform us of your choice, the surveyor will be appointed within 2 working days of your email.

If you do not agree to any of the surveyors above, you may proceed to appoint your own surveyor. In this instance, we will also appoint a surveyor from our list above to conduct the PRI. Upon completion of repairs, please contact our appointed surveyor to conduct a physical re-inspection of the vehicle.

Thank you.

Thanks and Regards,

SK Teo  
Motor Claims Dept

36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 | Company Regn. No. 195000106C  
email: [MotorClaims@first-insurance.com.sg](mailto:MotorClaims@first-insurance.com.sg)

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to [www.first-insurance.com.sg](http://www.first-insurance.com.sg) for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

---

From: Caroline Cabrera

Sent: Monday, January 08, 2018 2:11 PM

To: Teo Swee Keong <[TeoSweeKeong@first-insurance.com.sg](mailto:TeoSweeKeong@first-insurance.com.sg)>

Subject: FW: TP CLAIM\_SJP8412P & SHA1239Y\_DOA:05/01/2018

Dear SK,

For survey

Thanks & Regards

*Caroline Cabrera*

Motor Claims Department

First Capital Insurance Ltd

A member of **MS&AD** INSURANCE GROUP

36 Robinson Road #16-01 City House| Singapore 068877 | Reg. No. 195000106C  
D: 6507 3848 | F: 6507 3849

email: [www.first-insurance.com.sg](http://www.first-insurance.com.sg)

*Personal Data Protection Act 2012 ("PDPA"):*

*Under the PDPA, there are various requirements that regulate the processing of your personal data.  
Please refer to [www.first-insurance.com.sg](http://www.first-insurance.com.sg) for details of PDPA Personal Data Collection Statement.*

*Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.*

*If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.  
If you have received this message in error, please delete the message and all copies from your system  
and notify the sender immediately by return e-mail.*

---

**From:** Hock Wah Motor Pte Ltd [<mailto:motor@hockwah.com.sg>]

**Sent:** Monday, January 8, 2018 1:39 PM

**To:** Motor\_Claims <[Motor\\_Claims@first-insurance.com.sg](mailto:Motor_Claims@first-insurance.com.sg)>

**Subject:** TP CLAIM\_SJP8412P & SHA1239Y\_DOA:05/01/2018

Dear Sir/Madam

Attached herewith our client's GIA report that claim against your insured SHA1239Y.

The above mention vehicle not in Bedok workshop, please assist to make necessary arrangement

Please revert the liability of the above case.

Thank you..

Best Regards

Mavis Er

Customer Service Executive

**Hock Wah Motor Workshop Pte Ltd**

Blk 3011 Bedok North Avenue 4 | #01-2008/2010/2012/2014 | Singapore 489977

Tel: 6441 5655 | Fax: 6243 8121 | Website: [www.hockwah.com.sg](http://www.hockwah.com.sg)



MOTOR SURVEY ASSIGNMENT

Date 9/1/18  
Accident Date 5/1/18  
Insured Vehicle SHA1239Y  
Survey Location Hock Wah Motor Workshop Pte Ltd  
Blk 3011 Bedok North Ave 4  
#01-2008/2010/2012/2014  
Contact No. Singapore 489911  
Tel: 6441 5655  
Our Ref No. SHA1239Y  
Claim Type 3rd Party  
Third Party Vehicle SJP8412P  
Contact Person Mavis Er  
Fax No. 6243 8121

Survey Type Without Prejudice (No est. provided) Liability clear but quantum to be agreed.

Appointed Surveyor LKK  
Contact Person  
Contact Number 6256 3561  
Fax No. 6841 6315

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. Accident Reports & est

Cc : Workshop Hock Wah Motor Workshop Pte Ltd Attention Mavis Er  
Officer in charge Serene Ler

IMPORTANT NOTE

Kindly submit the survey report by email only to [surveyor@first-insurance.com.sg](mailto:surveyor@first-insurance.com.sg) within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 12 January, 2018 4:34 PM  
**To:** 'Teo Swee Keong'; assignments  
**Cc:** 'Serene Ler'; SUR  
**Subject:** RE: NEW SURVEY ASSIGNMENT - OUR REF: SHA1239Y DOA:05/01/2018  
**Attachments:** CSFCI18000603Uqd3.pdf

Dear Sir/Madam,

Enclosed herewith preliminary advice of SJP 8412P.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 10 January, 2018 9:50 AM  
**To:** 'Teo Swee Keong' <[TeoSweeKeong@first-insurance.com.sg](mailto:TeoSweeKeong@first-insurance.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Serene Ler' <[Sereneler@first-insurance.com.sg](mailto:Sereneler@first-insurance.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: NEW SURVEY ASSIGNMENT - OUR REF: SHA1239Y DOA:05/01/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Teo Swee Keong [<mailto:TeoSweeKeong@first-insurance.com.sg>]  
**Sent:** Tuesday, 9 January 2018 7:09 PM  
**To:** 'assignments@lkkauto.com' <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** Serene Ler <[Sereneler@first-insurance.com.sg](mailto:Sereneler@first-insurance.com.sg)>; Hock Wah Motor Pte Ltd <[motor@hockwah.com.sg](mailto:motor@hockwah.com.sg)>  
([motor@hockwah.com.sg](mailto:motor@hockwah.com.sg)) <[motor@hockwah.com.sg](mailto:motor@hockwah.com.sg)>  
**Subject:** NEW SURVEY ASSIGNMENT - OUR REF: SHA1239Y DOA:05/01/2018

Dear Sirs

New survey request for your handling.

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5353F
Vehicle Details	
Vehicle No.:	SJP8412P
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PICNIC AUTO W/O ROOF RACK
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	1AZH328899
Chassis No.:	JTEGH23B200026465
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$23,511.00
Original Registration Date:	14 Apr 2009
First Registration Date:	14 Apr 2009
Transfer Count:	1
Actual ARF Paid:	\$23,511.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Apr 2019
PARF Rebate Amount:	\$12,931.00
Intended COE Rebate Details	
COE Expiry Date:	13 Apr 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$4,889.00
COE Rebate Amount:	\$613.00
<b>Total Rebate Amount:</b>	<b>\$13,544.00</b>

The information contained herein is correct as at 11 Jan 2018

OK

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4.  
#01-2008/10/12 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1715353F  
KINTAN BTE SAID  
BLK 494C TAMPINES STREET 43  
#03-342  
SINGAPORE 522494  
TEL : 83224268 FAX :  
PH :  
ATTN :

## ESTIMATE BILL

Number : EB00004713  
Date : 9/1/2018  
Case No : AD00009495  
Vehicle No : SJP8412P  
Chassis : JTEGH23B200026465  
Year of Mfr : 2009  
Policy No : 5087276092-01  
Model : TOYOTA PICNIC 2.0  
(A)

### Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR BUMPER <i>Deep cut 7</i>	1.0	576.80	25	432.60
2	REAR BUMPER TOWING COVER <i>11</i>	1.0	42.70	25	32.03
3	REAR REFLECTOR LH <i>11</i>	1.0	69.69	25	52.27
4	REAR TAIL LAMP LH <i>11</i>	1.0	69.69	25	52.27
5	REAR SHOCK ABSORBER LH <i>11</i>	1.0	157.60	25	118.20
List Price - Parts Sub Total					687.37
6	REAR REVERSE SENSOR <i>Shut...</i>	1.0	280.00	0	280.00
7	REAR REVERSE SENSOR <i>reput</i>	1.0	280.00	0	280.00
8	REAR TYRE LH <i>Ex X</i>	1.0	380.00	0	380.00
9	REAR RIM LH - REPAIR <i>11 X</i>	1.0			
10	REAR FENDER LH - REPAIR <i>11 X</i>	1.0			
Special Nett Price - Parts Sub Total					940.00
Parts Total					1,627.37
11	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	600.00	0	600.00
12	SPRAY PAINT ON THE AFFECTED AREAS	1.0	600.00	0	600.00
13	ANTI-RUST COATING	1.0	100.00	0	100.00
Labour Sub Total					1,300.00
SINGAPORE DOLLARS : THREE THOUSAND ONE HUNDRED THIRTY-TWO AND CENTS TWENTY-NINE ONLY					3,132.29
Less Excess					0.00
SUBTOTAL					2,927.37
GST 7.00%					204.92
TOTAL					3,132.29

Date of accident : 05/01/2018 09:00 PM Place : ALONG ECP TOWARDS CITY

E. & O. E.

- the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

CUSTOMER SIGNATURE

Acknowledged by Repairer

Signature:

Page 1 of 1

HOCK WAH MOTOR WORKSHOP PTE LTD



AUTHORISED SIGNATURE

\* N = Item not subjected to GST

Issued by : MAVIS




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18000603/Uqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 30-01-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 1239Y	Veh. Inspected	SJP 8412P	
Policy No.		Coverage (\$)	0.00	
Claim No.	SHA 1239Y	Excess (\$)	0.00	
Assign From	TEO SWEE KEONG	Assign Date	09/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PICNIC (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTEGH23B200026465	Colour	SILVER	
Odometer	139191	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	05/01/2018	Inspection Date	11/01/2018	
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 8412P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DEEP CUT	576.80	576.80
1	REAR BUMPER TOWING COVER	NOT NECESSARY	42.70	-
1	REAR REFLECTOR LH	NOT NECESSARY	69.69	-
1	REAR TAIL LAMP LH	NOT NECESSARY	69.69	-
1	REAR SHOCK ABSORBER LH	NOT NECESSARY	157.60	-
	LESS 25% DISCOUNT		-229.11	-144.20
			687.37	432.60
<b>SPECIAL NETT ITEMS</b>				
1	REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR REVERSE SENSOR (SN)	REPEATED	280.00	-
1	REAR TYRE LH (SN)	SERVICEABLE	380.00	-
1	REAR RIM LH (NPA)(SN)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER LH (NPA)(SN)	TO REPAIR SEE LABOUR	-	-
			940.00	200.00
<b>LABOUR</b>				
	LABOUR TO REMOVE & REFIT NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF REAR RIM LH AND REAR FENDER LH.		600.00	400.00
	SPRAY PAINT ON THE AFFECTED AREAS.		600.00	420.00
	ANTI-RUST COATING.	NOT NECESSARY	100.00	-
			1,300.00	820.00
<b>GRAND TOTAL</b>			<b>2,927.37</b>	<b>1,452.60</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,150.00</b>

Report Ref No. CS/FCI18000603/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.