

INS. CASE OWNER:

JALYN

CC 3/AIG1800

0612

72 6632

LKK:

IDAC:

Surveyor:

Tan Jiah

DOI:

10/1/18

Date / Time:

10/1/18

Registered in Merimen:

10/1/18

re-assign / CCU / FTE



Insured Vehicle No.:

SJB 7874E

Name of Insured:

LIAM YUEN PATI

Insured Tel No.:

HP: 9780967

Excess Sec II :S\$

D.O.A: 02/01/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LIAM CHUNG MING

Driver Tel No.:

(V/L: YES/ NO)

Claim No.:

767687895839

Policy No.:

700161746

Make / Model:

PROTON

Place of Accident:

DIT WAS SHIP RD INTO

UTF SITE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time		STAGE	DATE / PIC
10/1/18	SJB 7874E - X	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI: 25/01/18 - vic	
		After call ltr to OI: 19/01/18 - vic ok	
15/01/18	SJB 7874E - X	Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☒
		LTA / GIA:	☒
		Medical Bill:	☒
		PIR:	☒
		Mandate/Reject Instruction:	☒
		LOD	☒
		Payment Breakdown Form:	☒
		Post-Repair Photos:	☒
		Others:	☒

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

S\$

18,074.85

(10 days)

Reduction:

27

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

(w/ass)

S\$

19,289.80

Loss of Rental (LOR):

S\$

—

(days)

Loss of Use (LOU):

S\$

720.00

x 12 days)

Loss of Income (LOI):

S\$

—

(\$ x days)

LOR only ☐ LOU only ☒

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

290.00

Disbursement:

S\$

—

(e.g. Tow/ Independent)

Legal Cost

S\$

—

Total:

S\$

20,301.80

Global Sum S\$:

—

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

19,291.80

Name 1:

PERFORMANCE MOTORS LTD

Payee 2: (Strike if N.A.)

S\$

1,010.00

Name 2:

CHER CHING FERN

Payee 3: (Strike if N.A.)

S\$

—

Name 3:

uk)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4320.00

COPY SENT

h

— — — — —

	
N/S	O/S
	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18000612/T1hb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 10-01-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJS 7874E	Veh. Inspected	SLH 9529Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	07/01/2018	Inspection Date	10/01/2018.
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190538 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

09 JAN 2018

Estimate No. : b1 45439
Date Estimated : 09/01/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Cher Ching Fern
62 Flora Road
#03-04 The Gale

Singapore 509746

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH9529Z	V791421	24/11/2016	216d CAT	0

DESCRIPTION

To replace rear bumper, tailgate, tail panel and attachments including knock out dent area cause by accident.

apinting rear bumper, tailgate, tail panel and trunk floor.

To replace rear exhaust silencer including alignment system and conduct checks for leak.

To remove and install rear windscreen glass

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

To check electrical wiring systems and lightings at the rear section for proper function.

To carry out body cavity preservation.
(Per panel).

To carry out body cavity preservation.
(For cut panel).

Sundries.

Repair - 2550 ✓
Replace - 4250 ✓
VALUE 5,950.00

Repair - 2399 ✓
Replace - 2877 ✓
3,197.00

451 531.00

✓ 649.00

451 531.00

✓ 150 177.00

✓ 100 118.00

nn X 451? 531.00

✓ 150.00

Total Labour 1: 11,834.00

DESCRIPTION

RUBBER MOUNTING
REAR SILENCER
TAILPIPE TRIM CHROME
HOLDER EXHAUST SYSTEM
TRUNK LID
TAIL PANEL

QTY	PRIC	VALUE
24	17.05	34.10
1	1,167.45	b1 ✓ 1,167.45
1	95.15	nn ✓ 95.15
24	55.80	24.20 nn ✓ 55.80
1	1,146.30	b7 ✓ 1,146.30
1	355.20	nn ✓ 355.20

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190121 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45439
Date Estimated : 09/01/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH9529Z	V791421	24/11/2016	216d CAT	0

DESCRIPTION

REAR BUMPER PANEL PRIMED (PDC)
RR BUMPER LH SIDE GUIDE
RR BUMPER RH SIDE GUIDE
REAR BUMPER CARRIER
SUPPORT
RR BUMPER LH INNER SIDE GUIDE
RR BUMPER RH INNER SIDE GUIDE
SET MOUNTS PDC SENSOR REAR
GROMMET
BADGE (BMW)
STRIKER BOOT LID
LOCK TRUNK LID
REAR FLAP TOWING EYE PRIMED
REAR BUMPER HEAT INSULATOR
SENSOR WIRE FOR SMART OPENER TOP
SENSOR WIRE FOR SMART OPENER BOTTOM
ULTRASONIC SENSOR BLACK
DECOUPING RING PDC TORQUE CONVERTER
BLIND RIVET AVIBVLB
SCREW (SF PLUS M5X15)
(DG/SL) BODY ADHESIVE K5B (195ML)
(DG) CLEANER R1 (100ML)
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)
PUNCH RIVET N4

QTY	PRIC	VALUE
1	966.25	966.25
1	46.65	46.65
1	46.65	46.65
1	413.45	413.45
1	36.40	36.40
1	57.15	57.15
1	57.15	57.15
1	62.50	62.50
2	0.75	1.50
1	69.50	69.50
1	54.40	54.40
1	189.10	189.10
1	30.30	30.30
1	57.70	57.70
1	42.10	42.10
1	40.50	40.50
4	248.70	994.80
4	5.05	20.20
19	0.55	10.45
5	0.55	2.75
1	281.55	281.55
1	23.85	23.85
2	131.55	263.10
19	0.55	10.45

Total Parts : 6,615.40

10/1/19 14.45

Taufik

97495749

Delivery to

taufik@hikauto.com

My World Days Recommend

7-10 days

18522.25

Labour 1	:	11,834.00
Parts	:	6,615.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,291.46
Grand Total	:	19,740.86

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

21,760.85

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45439
Date Estimated : 09/01/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -

Cher Ching Fern
62 Flora Road
#03-04 The Gale

Singapore 509746

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLH9529Z	V791421	24/11/2016	216d CAT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.60	4.00		10.40 nec ✓
# CLAMPING BUSH *	54.30	1.00		54.30 de ✓
# RUBBER MOUNTING * <i>REPORT</i>	17.05	1.00		17.05 de ✓
# RUBBER MOUNTING *	17.05	1.00		17.05 de ✓
# V BAND CLAMP *	41.80	1.00		41.80 bt ✓
# GASKET *	8.25	1.00		8.25 nec ✓
# EXCHANGE EXHAUST PIPE CATALYST *	1,849.15	1.00		1,849.15 bt ✓
# MUFFLER CLAMP D=63.2MM *	41.80	1.00		41.80 bt ✓
# EXCH DIESEL PARTICULATE FILTER EU5 *	3,550.20	1.00		3,550.20 bt ✓
# HOLDER EXHAUST SYSTEM * <i>REPORT</i>	27.20	1.00		27.20 bt ✓
# HOLDER EXHAUST SYSTEM	27.20	1.00		27.20 bt ✓
# STEERING BOX HEAT RESISTANT PLATE *	58.30	1.00		58.30 bt ✓
# BOOT LID/TAILGATE PUSH BOTTON ICAM *	46.05	1.00		46.05 de ✓
# HOOK AND LOOP FASTENER *	2.80	8.00		22.40 nec ✓
# SMART OPENER CONTROL UNIT *	457.45	1.00		457.45 dig ✓

Total Labour :	
Total Parts :	6,228.60
Total Labour & Parts :	6,228.60

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45439
Date Estimated : 09/01/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Cher Ching Fern
62 Flora Road
#03-04 The Gale

Singapore 509746

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLH9529Z	V791421	24/11/2016	216d CAT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.60	4.00		10.40 net ✓
# CLAMPING BUSH *	54.30	1.00		54.30 de ✓
# RUBBER MOUNTING * <i>Repeated</i>	17.05	1.00		17.05 de ✓
# RUBBER MOUNTING *	17.05	1.00		17.05 de ✓
# V BAND CLAMP *	41.80	1.00		41.80 bt ✓
# GASKET *	8.25	1.00		8.25 net ✓
# EXCHANGE EXHAUST PIPE CATALYST *	1,849.15	1.00		1,849.15 bt ✓
# MUFFLER CLAMP D=63.2MM *	41.80	1.00		41.80 bt ✓
# EXCH DIESEL PARTICULATE FILTER EU5 *	3,550.20	1.00		3,550.20 bt ✓
# HOLDER EXHAUST SYSTEM * <i>repeat</i>	27.20	1.00		27.20 bt ✓
# HOLDER EXHAUST SYSTEM *	27.20	1.00		27.20 bt ✓
# STEERING BOX HEAT RESISTANT PLATE *	58.30	1.00		58.30 bt ✓
# BOOT LID/TAILGATE PUSH BOTTON ICAM *	46.05	1.00		46.05 de ✓
# HOOK AND LOOP FASTENER *	2.80	8.00		22.40 net ✓
# SMART OPENER CONTROL UNIT *	457.45	1.00		457.45 dis ✓

Total Labour :
Total Parts : 6,228.60
Total Labour & Parts : 6,228.60

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45439
Date Estimated : 09/01/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -

Cher Ching Fern
62 Flora Road
#03-04 The Gale

Singapore 509746

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	
SLH9529Z	V791421	24/11/2016	216d CAT	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
To replace rear bumper and attachments, tailgate include making good the tail end panel and knocking out dents caused by the accident	2550.00		2,550.00	✓	
To spray paint rear bumper, tailgate and tail end panel	2399.00		2,399.00	✓	
To replace rear exhaust silencer and attachments include alignment and conducting checks for leak	451.00		451.00	✓	
To remove and install rear windscreen glass include conducting checks for leak	649.00		649.00	✓	
To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00	✓	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	✓	
To carry out body cavity preservation. (Per panel).	100.00		100.00	✓	
Sundries	150.00		150.00	✓	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.60	4.00		10.40
# CLAMPING BUSH *	54.30	1.00		54.30
# RUBBER MOUNTING * > repeat	17.05	1.00		17.05
# RUBBER MOUNTING *	17.05	1.00		17.05
# V BAND CLAMP *	41.80	1.00		41.80
# GASKET *	8.25	1.00		8.25
# EXCHANGE EXHAUST PIPE CATALYST *	1,849.15	1.00		1,849.15
REAR SILENCER	1,167.45	1.00		1,167.45
# MUFFLER CLAMP D=63.2MM *	41.80	1.00		41.80
# EXCH DIESEL PARTICULATE FILTER EU5 *	3,550.20	1.00		3,550.20
# HOLDER EXHAUST SYSTEM * - repeat	27.20	1.00		27.20

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

# HOLDER EXHAUST SYSTEM <i>-repeat</i>	27.20	1.00	27.20
# STEERING BOX HEAT RESISTANT PLATE *	58.30	1.00	58.30
TRUNK LID	1,146.30	1.00	1,146.30 ✓
REAR BUMPER PANEL PRIMED (PDC)	966.25	1.00	966.25 ✓
REAR BUMPER CARRIER	413.45	1.00	413.45 ✓
SUPPORT	36.40	1.00	36.40 ✓
RR BUMPER LH INNER SIDE GUIDE	57.15	1.00	57.15 ✓
RR BUMPER RH INNER SIDE GUIDE	57.15	1.00	57.15 ✓
GROMMET	0.75	2.00	1.50 ✓
BADGE (BMW)	69.50	1.00	69.50 ✓
# BOOT LID/TAILGATE PUSH BOTTON ICAM *	46.05	1.00	46.05
# HOOK AND LOOP FASTENER *	2.80	8.00	22.40
SENSOR WIRE FOR SMART OPENER TOP	42.10	1.00	42.10 ✓
SENSOR WIRE FOR SMART OPENER BOTTOM	40.50	1.00	40.50 ✓
# SMART OPENER CONTROL UNIT *	457.45	1.00	457.45 ✓
ULTRASONIC SENSOR BLACK	248.70	3.00	746.10 ✓
(DG) CLEANER R1 (100ML)	23.85	1.00	23.85 ✓
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	1.00	131.55 ✓

SUPPLEMENTARY ITEMS

Total Labour :	6,900.00
Total Parts :	11,127.85
Total Labour & Parts :	18,027.85
Deduction for Excess :	0.00
Total Repair Costs less Excess:	18,027.85
GST @7%:	1,261.95
Grand Total :	19,289.80

Vic (LKKAUTO)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Thursday, 31 May, 2018 6:12 PM
To: Taufikh (LKKAUTO); Vic (LKKAUTO)
Subject: Re: FINAL REPORT / SLH9529Z

Urgent reminder

From: PBSP
Sent: Saturday, 7 April 2018 11:29:44 AM
To: taufikh@lkkauto.com; vicalpeh@lkkauto.com
Subject: FINAL REPORT / SLH9529Z

Dear Taufikh and Vic

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 6,900.00
Total Parts : 11,127.85
Total Labour & Parts : 18,027.85

Repair days: 10

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

Print Received Message

This mail is associated with :

***SLH9529Z (6341332866SG)**
[SJS7874E]

TP

CHER CHING FERN

Jan 7 2018 1:00AM

[Chan Yuen Fatt]

Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 21/06/2019 00:31 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$20301.80) - SLH9529Z - Claim Handler: Foo, Chit Yan

Approved:20301.80:Subject to Final Repair Bill, GIA Search Bill, Medical Bills & LOA from respective claimant of their medical expenses

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SLH 95292	Model:	
Date of Accident:	7-1-2018		

Global Sum Settlement	: [] Yes	[] No	
Repair Estimate	: \$	19740.86	
Final Repair Cost	: \$	19289.80	
Loss of Use	: \$	720.00	12 days at \$ 60 per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$	2.00	
Others: Medical fee	: \$	290.00	
	: \$		
Final Settlement Sum	: \$	20301.80	

Is Third Party Workshop GIA Registered? ☐ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No
BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown

1)	Performance Motors Ltd	\$	19289.80
2)	Performance Motors Ltd	\$	2.00
3)	Cher Ching Fern	\$	720.00
	Cher Ching Fern		290.00

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jan 2018 Edit Reg		10 Jan 2018 00:00 Edit Adj Rpt	S\$18,027.85 Edit Estimates	S\$18,027.85 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by adjuster\]](#)

Insured:	Chan Yuen Fatt, ID: S2568117G, Tel: +6597805363		
Main Claimant:	CHER CHING FERN, ID: S7806201J		
Vehicle Reg. No.:	SLH9529Z	Date of Loss:	07/01/2018 01:00 - :59 [14 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6341332866SG	Policy/Cover Note No.:	2100161756 (Comprehensive)
Vehicle Reg. No. (Insured):	SJS7874E	Policy No. (Claimant):	C0064561
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 19/01/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (21/06/2019): Alert - Adj Mandate Approved (S\$20301.80) - SLH9529Z - Claim Handler: Foo, Chit ...
- AIG_SG_EXPRESS (28/11/2018): Alert - Adj Mandate Maintained - SLH9529Z - Claim Handler: Kesaval, Jaclyn-M

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SLH9529Z (6341332866SG)
[SJS7874E]**

TP

CHER CHING FERN

Jan 7 2018 1:00AM

[Chan Yuen Fatt]

Performance Motors Limited

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Letters/Correspondences				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1 per page ▼	☒
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Thumbnail	Print
			1 Edit	
Assessment Reports				
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	1 per page ▼	☒
1	11/01/18 09:45	Accident Statement From: OD - Reg. No: SJS7874E, Claimant: CHAN YUEN FATT	Thumbnail	Print
			1 Load HTM	
Photos/Images				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	☒
1	25/09/18 13:17	Odometer Reading	Thumbnail	Print
			1 Load JPG	☒
2	25/09/18 13:17	Chassis Number	1 Load JPG	☒
3	25/09/18 13:18	General View	1 Load JPG	☒
4	25/09/18 13:18	General View	1 Load JPG	☒
5	25/09/18 13:18	General View	1 Load JPG	☒
6	25/09/18 13:18	General View	1 Load JPG	☒
7	25/09/18 13:18	General View	1 Load JPG	☒
8	25/09/18 13:18	General View	1 Load JPG	☒
9	25/09/18 13:18	General View	1 Load JPG	☒
10	25/09/18 13:18	General View	1 Load JPG	☒
11	25/09/18 13:18	General View	1 Load JPG	☒
12	25/09/18 13:18	General View	1 Load JPG	☒
13	25/09/18 13:18	General View	1 Load JPG	☒
14	25/09/18 13:18	General View	1 Load JPG	☒
15	25/09/18 13:18	General View	1 Load JPG	☒
16	25/09/18 13:18	General View	1 Load JPG	☒
17	25/09/18 13:18	General View	1 Load JPG	☒
18	25/09/18 13:18	General View	1 Load JPG	☒
19	25/09/18 13:18	General View	1 Load JPG	☒
20	25/09/18 13:18	General View	1 Load JPG	☒
21	25/09/18 13:18	General View	1 Load JPG	☒
22	25/09/18 13:18	General View	1 Load JPG	☒
23	25/09/18 13:18	General View	1 Load JPG	☒
24	25/09/18 13:18	General View	1 Load JPG	☒
25	25/09/18 13:18	General View	1 Load JPG	☒
26	25/09/18 13:18	General View	1 Load JPG	☒
27	25/09/18 13:18	General View	1 Load JPG	☒
28	25/09/18 13:18	General View	1 Load JPG	☒

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
29	25/09/18 13:18	General View	 Load JPG	☒
30	25/09/18 13:18	General View	 Load JPG	☒
31	25/09/18 13:18	General View	 Load JPG	☒
32	25/09/18 13:18	General View	 Load JPG	☒
33	25/09/18 13:18	General View	 Load JPG	☒
34	25/09/18 13:18	General View	 Load JPG	☒
35	25/09/18 13:18	General View	 Load JPG	☒
36	25/09/18 13:18	General View	 Load JPG	☒
37	25/09/18 13:18	General View	 Load JPG	☒
38	25/09/18 13:18	General View	 Load JPG	☒
39	25/09/18 13:18	General View	 Load JPG	☒
40	25/09/18 13:18	General View	 Load JPG	☒
41	25/09/18 13:18	General View	 Load JPG	☒
42	25/09/18 13:18	General View	 Load JPG	☒
43	25/09/18 13:18	General View	 Load JPG	☒
44	25/09/18 13:18	General View	 Load JPG	☒
45	25/09/18 13:18	General View	 Load JPG	☒
46	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
47	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
48	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
49	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
50	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
51	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
52	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
53	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
54	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
55	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
56	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
57	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
58	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
59	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
60	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
61	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
62	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
63	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
64	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
65	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
66	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
67	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
68	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
69	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
70	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
71	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
72	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
73	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
74	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
75	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
76	25/09/18 13:19	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
77	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
78	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
79	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
80	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
81	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
82	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
83	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
84	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
85	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
86	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
87	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
88	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
89	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
90	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
91	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
92	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
93	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
94	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
95	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
96	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
97	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
98	25/09/18 13:19	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/01/18 15:53	TP ESTIMATE	 Load TIF	
2	10/01/18 15:53	TP GIA REPORT	 Load PDF	
3	11/01/18 17:17	TP ESTIMATE- MARKED	 Load PDF	
4	25/09/18 13:15	TP SUPPLEMENTARY - MARKED	 Load PDF	
5	25/09/18 13:17	LETTER TO OI	 Load PDF	
6	24/10/18 17:54	GIA SEARCH	 Load PDF	
7	24/10/18 17:54	MEDICAL FEE	 Load PDF	
8	05/04/19 16:45	TP LETTER OF AUTHORIZATION FOR MEDICAL BILLS	 Load PDF	
9	09/07/19 14:11	AUTHORISATION TO ACT	 Load PDF	
10	09/07/19 14:11	RELEASE VOUCHER	 Load PDF	
11	09/07/19 14:11	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	10/05/19 11:02	Clear Report	 Load DOCX	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJS7874E (Insd veh)	Model:	BMW 216D 1.5 D ACTIVE
	SLH9529Z (TP veh)		TOURER (F45) (A)
Date of Accident:	07/01/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	26,483.41
Final Repair Cost	:	\$	19,289.80
Loss of Use	:	\$	720.00
Rental (if any)	:	\$	12.00 days at \$60.00 per day
LTA / GIA Search Fee	:	\$	2.00
Medical Fee:	:	\$	290.00
	:	\$	
Final Settlement Sum	:	\$	20,301.80
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 19,291.80
2)	CHER CHING FERN	:	\$ 1,010.00
3)		:	\$
4)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

09 Jul
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18000612/T1HB3S2

Date: 09/07/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100161756
Claimant Vehicle No :	SLH9529Z	Insured Vehicle No :	SJS7874E
Date of Loss:	07/01/2018	Nature of Claim:	TP
		Claim No:	6341332866SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH9529Z	Engine No:	34369660B37C15A
Make & Model:	BMW 216D, 1.5 D Active Tourer (F45) (A)	Chassis No:	WBA2B32070V791421
Reg. Date:	01/11/2016 (Man. Year: 2016)	Odometer:	14573 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45R18	Rear Tyre Size:	225/45R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,066.85	11,277.85	1,789.00	13.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,684.00	6,750.00	4,934.00	42.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,750.85	18,027.85	6,723.00	27.16
+ GST 7.00/7.00% (S\$)	1,732.56	1,261.95	470.61	27.16
Nett Amount (S\$)	26,483.41	19,289.80	7,193.61	27.16
+ Loss of Use (12.0 x S\$60.00/day) (S\$)		720.00		
+ Medical Costs (S\$)		290.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		20,301.80		

INSPECTION

Date of Assignment:	10/01/2018	
Date Inspected:	10/01/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	10.0 days	

7/9/2019

Adjuster Report

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*RUBBER MOUNTING	Deformed	34.10 FS	*34.10 FS
2	1		*REAR SILENCER	Bent	1,167.45 FS	*1,167.45 FS
3	1		*TAILPIPE TRIM CHROME	Not Necessary	95.15 FS	*- FS
4	2		*HOLDER EXHAUST SYSTEM	Necessary	111.60 FS	*54.40 FS
5	1		*TRUNK LID	Bent	1,146.30 FS	*1,146.30 FS
6	1		*TAIL PANEL	Not Necessary	355.20 FS	*- FS
7	1		*REAR BUMPER PANEL PRIMED (PDC)	Deformed	966.25 FS	*966.25 FS
8	1		*RR BUMPER LH SIDE GUIDE	Not Necessary	46.65 FS	*- FS
9	1		*RR BUMPER RH SIDE GUIDE	Not Necessary	46.65 FS	*- FS
10	1		*REAR BUMPER CARRIER	Bent	413.45 FS	*413.45 FS
11	1		*SUPPORT	Deformed	36.40 FS	*36.40 FS
12	1		*RR BUMPER LH INNER SIDE GUIDE	Deformed	57.15 FS	*57.15 FS
13	1		*RR BUMPER RH INNER SIDE GUIDE	Deformed	57.15 FS	*57.15 FS
14	1		*SET MOUNTS PDC SENSOR REAR	Not Necessary	62.50 FS	*- FS
15	2		*GROMMET	Necessary	1.50 FS	*1.50 FS
16	1		*BADGE (BMW)	Necessary	69.50 FS	*69.50 FS
17	1		*STRIKER BOOT LID	Not Necessary	54.40 FS	*- FS
18	1		*LOCK TRUNK LID	Not Necessary	189.10 FS	*- FS
19	1		*REAR FLAP TOWING EYE PRIMED	Not Necessary	30.30 FS	*- FS
20	1		*REAR BUMPER HEAT INSULATOR	Not Necessary	57.70 FS	*- FS
21	1		*SENSOR WIRE FOR SMART OPENER TOP	Deformed	42.10 FS	*42.10 FS
22	1		*SENSOR WIRE FOR SMART OPENER BOTTOM	Distorted	40.50 FS	*40.50 FS
23	1		*ULTRASONIC SENSOR BLACK	Not Working 3pcs Only	994.80 FS	*746.10 FS
		4pcs				
24	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.20 FS	*- FS
25	19		*BLIND RIVET AVIBVLB	Not Necessary	10.45 FS	*- FS
26	1		*SCREW (SF PLUS M5X5)	Not Necessary	2.75 FS	*- FS
27	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Not Necessary	281.55 FS	*- FS
28	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
29	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary 1pc Only	263.10 FS	*131.55 FS
		2pcs				
30	19		*PUNCH RIVET N4	Not Necessary	10.45 FS	*- FS
31	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
32	4		*BLIND RIVET NUT M6	Necessary	10.40 FS	*10.40 FS
33	1		*CLAMPING BUSH	Deformed	54.30 FS	*54.30 FS
34	1		*RUBBER MOUNTING	Repeated	17.05 FS	*- FS
35	1		*RUBBER MOUNTING	Repeated	17.05 FS	*- FS
36	1		*V BAND CLAMP	Bent	41.80 FS	*41.80 FS
37	1		*GASKET	Necessary	8.25 FS	*8.25 FS
38	1		*EXCHANGE EXHAUST PIPE CATALYST	Bent	1,849.15 FS	*1,849.15 FS
39	1		*MUFFLER CLAMP D=63.2MM	Bent	41.80 FS	*41.80 FS
40	1		*EXCH DIESEL PARTICULATE FILTER EU5	Bent	3,550.20 FS	*3,550.20 FS
41	1		*HOLDER EXHAUST SYSTEM	Repeated	27.20 FS	*- FS
42	1		*HOLDER EXHAUST SYSTEM	Repeated	27.20 FS	*- FS
43	1		*STEERING BOX HEAT RESISTANT PLATE	Bent	58.30 FS	*58.30 FS
44	1		*BOOT LID / TAILGATE PUSH BOTTOM ICAM	Deformed	46.05 FS	*46.05 FS
45	8		*HOOK AND LOOP FASTENER	Necessary	22.40 FS	*22.40 FS
46	1		*SMART OPENER CONTROL UNIT	Distorted	457.45 FS	*457.45 FS

F=Franchise part, S=SpcNett.

Total Parts (S\$) 13,066.85 11,277.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER, TAILGATE, TAIL PANEL AND ATTACHMENTS INCLUDING KNOCK OUT DENT AREA CAUSE BY ACCIDENT.	New	5,950.00	2,550.00
2	PAINTING REAR BUMPER, TAILGATE, TAIL PANEL AND TRUNK FLOOR.	New	3,197.00	2,399.00
3	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK.	New	531.00	451.00
4	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS.	New	649.00	649.00
5	TO TRANSFER LOCK MECHANISM FORM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION.	New	531.00	451.00
6	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.	New	177.00	150.00
7	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)	New	118.00	100.00
8	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)	New	531.00	0.00
Gross Labour Cost (S\$)			11,684.00	6,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >