

22/03/2012

ASS. REC. BY:

REF:

CS/CT118000615/Gvb⁷²

Special Instructions:

Surveyor:

Maiman

ASSIGNMENT (Office)

From (Person): Joel Goh

of

CTL

Date/Time: 10012018 339pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 8718M

Insured:

SJB 8245D

at Workshop m/s

Premium

Tel:

6768 9911

of

95 Ubi Rd 1

Policy No:

DM PCSN3077101700

Claim No:

SNM18 000092002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 03/01/2018

CA / REV / REP. / REV 24 HRS 'wpi'

12.01.2018 @ 10:30am

H.O.D. Endorsement:

Date/Time:

10012018 3:58pm

Person Contacted:

Kee Siang

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT 8718M - X
	SJB 8245D - X
12/2/18	Final fig \$ 4754.60 confirmed by email (Ref 2263.40, 33/7)

2017
SIRV/0001

XPR.

REF: C11

ASSIGNMENT

From: _____ Date: 12.01.2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLT 8718M

at Workshop m/s Premium

of 55 Ubi Rd 1

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

10:30am



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR. Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLT 8718M Vn Regn. 14 Nov 2017

Type: M/Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 C.C. 1395

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 3243 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZF40JA023458

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40 ZR18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A.

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I.

12-01-18 11Am

Survey held at w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 12 FEB 2018

Date/Time, File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 12/2 typist

Report Format : meriman

Lump Sum / I.B.I: (\$ 4754.60)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation

) \$ - RS - LS

) Photos

) Other

TOTAL

220

Survey Department Check List (Case Handler)

Reference No.: CS | CTI 800 615 | 615
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages				

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON | 12/12/18
 Case Handler | Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18000615/Gvb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 10-01-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJB 8245D	Veh. Inspected	SLT 8718M
Policy No.	DMPCSN3077101700	Coverage (\$)	0.00
Claim No.	SNM18D00092C02	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	10/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	03/01/2018	Inspection Date	12/01/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2018		10 Jan 2018 15:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LENG HOCK HENG DANNY, ID: S8219076G		
Main Claimant:	PAULINE WONG LAI FONG, ID: S2562708C		
Vehicle Reg. No.:	SLT8718M	Date of Loss:	03/01/2018 14:00 - :59
Claim Type:	TP / SNM18D00092C02	Policy/Cover Note No.:	DMPCSN3077101700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJB8245D	Policy No. (Claimant):	1700076321
		Excess:	S\$0.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/01/2018]		
Driver/Custodian (Insured):	LENG HOCK HENG DANNY (35 / Male), NRIC: S8219076G		
Adj Asg. Remarks:	ESTIMATE \$7,118.00, ASSIGN TO XING GUO QIANG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 12 February 2018 9:09 AM
To: Mei Kwan (LKKAUTO); Boo seng yak; Guo Qiang (LKKAUTO)
Cc: CS A Team; Admin A; Carrine Leong; Nora Khai; SUR
Subject: RE: FINAL REVISION SLT8718 - TP CHINA - SUSRVEYED 12 JAN 18 *** LKK REF: CS/CTI18000615/Gvb

Dear Mr Boo,

Confirm repair cost of \$4754.60 before GST @ 3 days of repairs.

Final invoice and all supporting documents sent to China Taiping

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO)
Sent: Monday, 12 February 2018 8:49 AM
To: Boo seng yak <boojohnny@gmail.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: FINAL REVISION SLT8718 - TP CHINA - SUSRVEYED 12 JAN 18 *** LKK REF: CS/CTI18000615/Gvb

Dear Johnny,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/CTI18000615/Gvb	Veron

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [<mailto:boojohnny@gmail.com>]
Sent: Saturday, 10 February, 2018 4:27 PM

To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>
Subject: FINAL REVISION SLT8718 - TP CHINA - SUSRVEYED 12 JAN 18

Hi Guo Qiang and all,

Revised estimate is attached.

Please confirm repair cost of \$4754.60 @ 3 days of repairs.

B4 paint and checked items photos attached.

Your early closure is well appreciated.

best regards - jb

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2708C
Vehicle Details	
Vehicle No.:	SLT8718M
Vehicle to be Exported:	No
Intended De-registration Date:	15 Jan 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	CVN045415
Chassis No.:	WAUZZZF40JA023458
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,727.00
Original Registration Date:	14 Nov 2017
First Registration Date:	14 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$27,818.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Nov 2027
PARF Rebate Amount:	\$20,863.00
Intended COE Rebate Details	
COE Expiry Date:	13 Nov 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,414.00
COE Rebate Amount:	\$56,432.00
Total Rebate Amount:	\$77,295.00

The information contained herein is correct as at 15 Jan 2018

OK



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : PAULINE WONG LAI FONG
Period of Insurance : 14 Nov 2017 To 13 Nov 2018
Engine No. : CVN045415
Chassis No. : WAUZZZF40JA023458

Vehicle No. : SLT8718M
Policy No. : 1700076321
Endorsement No. :
Issued Date : 20 Nov 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAIF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

PAULINE WONG LAI FONG

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website: www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125220

PREMIUM LEASING - MH
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Chang Qian Yee

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number **S1543368Z**

Name

TAY ENG HUAT

Birth Date: **21 Sep 1962**

Issue Date: **04 Dec 2003**



REPUBLIC OF SINGAPORE IDENTITY CARD NO. S1543368Z



Name

TAY ENG HUAT



鄭榮發

Race

CHINESE

Date of Birth

21-09-1962

Country of Birth

SINGAPORE

Sex

M

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number **S2562708C**

Name

PAULINE WONG LAI FONG

Birth Date: **29 Jun 1967**

Issue Date: **11 Jul 2003**



REPUBLIC OF SINGAPORE IDENTITY CARD NO. S2562708C



Name

PAULINE WONG LAI FONG



黃麗風

Race

CHINESE

Date of birth

29-06-1967

Country of birth

MALAYSIA

Sex

F

S2562708C

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

30 Apr 1982



NP 428A



0992154

NRIC No: **S1543368Z**



Blood Group: **O+** Date of issue: **30-05-1993**

**80 DIDO STREET
SINGAPORE 459502**

NRIC No: **S1543368Z**

Date: **14-01-2002** No: **4180128**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

10 Aug 1985



NP 428A



4169445

NRIC No: **S2562708C**



Date of issue: **01-02-2008**

**80 DIDO STREET
SINGAPORE 459502**

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0017/2018/GW
Date : 5-Jan-18

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no : **SJB8245D**

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Ms Pauline Wong Lai Fong
Address : 80 DIDO STREET

Singapore 459502

Telephone : (HP) 96498135
Type of Claim : Third Party Claim
Policy No. : 1700076321
Vehicle No : **SLT 8178 M**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : Nov-17
Engine No : CVN045415
Chassis No : WAUZZZF40JA023458
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Jan-18
Place of Accident : TRAFFIC LIGHT ALONG MACPERSON RD TOWARD PAYA LEBAR

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 8178 M.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor assy.	S/N	\$ 360.00	✓ ✓
2	To dismantle and renew rear bumper assy. Re- organise rear crash management components. Reinstall all parts removed.		\$ 900.00	600 ✓
3	To respray rear bumper.		\$ 800.00	600 ✓
4	To carry out diagnostic check.	S/N	\$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		:	\$ 2,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 8718 M.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER / RL	\$ 1,844.00	✓
2	REAR BUMPER SECURING STRIP	\$ 182.00	181.50
3	REAR BUMPER SPOILER	\$ 203.00	203
4	REAR LIGHT REFLECTOR -LH/RH	\$ 66.00	X
5	REAR BOOT LID	\$ 349.00	X
6	TAILGATE OPENING FOR SENSOR LINE	\$ 179.00	X
7	REAR BUMPER SENSOR	4 \$ 830.00	X
8	REAR BUMPER SENSOR SEAL RING	\$ 15.00	X
9	REAR BUMPER CARRIER	\$ 756.00	755.50
10	REAR BUMPER GASKET	2 \$ 22.00	X
11	REAR BUMPER GUIDE SECTION LH/RH	2 \$ 73.00	X
12	REAR BUMPER LOWER GUIDE SECTION LH/RH	2 \$ 36.00	X
13	LOWER GUIDE PIN	2 \$ 11.00	X
14	SUNDRIES	\$ 300.00	15.60
TOTAL SPARE PARTS		: \$ 4,866.00	
TOTAL LABOUR CHARGES		: \$ 2,252.00	
GRAND TOTAL		: \$ 7,118.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

3 Days.

Guo Qian - 82880282

before paint photos.

12/1/18.


15/1/18

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKH Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0017/2018/GW
Date	:	5-Jan-18

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no : SJB8245D

China Taiping Insurance (SG) Pte Ltd
105 Cecil Street
#19-00 The Octagon
Singapore 069534

Hi Guo Qiang
3 days - ok - jb 10 Feb 18

Attn: Ms Angie - Motor Claims Dept/Windscreen
Tel: 6389 6541 - Fax: 6224 7175

Owner's Name	:	Ms Pauline Wong Lai Fong
Address	:	80 DIDO STREET

	:	Singapore 459502
Telephone	:	(HP) 96498135
Type of Claim	:	Third Party Claim
Policy No.	:	1700076321
Vehicle No	:	SLT 8178 M
Model Code	:	Audi A4 SEDAN 1.4 TFSI
Model / Year	:	Nov-17
Engine No	:	CVN045415
Chassis No	:	WAUZZZF40JA023458
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	3-Jan-18
Place of Accident	:	TRAFFIC LIGHT ALONG MACPERSON RD TOWARD PAYA LEBAR

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 8178 M.

<u>S/N</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer rear parking aid and rear lid kick sensor assy.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew rear bumper assy. Re-organise rear crash management components. Reinstall all parts removed.		\$ 900.00	\$ 600.00
3	To respray rear bumper.		\$ 800.00	\$ 600.00
4	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 2,252.00</u>	<u>\$ 1,752.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 8718 M.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,844.00	\$ 1,844.00
2	REAR BUMPER SECURING STRIP	\$ 182.00	\$ 181.50
3	REAR BUMPER SPOILER	\$ 203.00	\$ 203.00
4	REAR LIGHT REFLECTOR -LH/RH	\$ 66.00	
5	REAR BOOT LID	\$ 349.00	
6	TAILGATE OPENING FOR SENSOR LINE	\$ 179.00	
7	REAR BUMPER SENSOR	4 \$ 830.00	
8	REAR BUMPER SENSOR SEAL RING	\$ 15.00	
9	REAR BUMPER CARRIER	\$ 756.00	\$ 755.50
10	REAR BUMPER GASKET	2 \$ 22.00	
11	REAR BUMPER GUIDE SECTION LH/RH	2 \$ 73.00	
12	REAR BUMPER LOWER GUIDE SECTION LH/RH	2 \$ 36.00	
13	LOWER GUIDE PIN	2 \$ 11.00	
14	SUNDRIES	\$ 300.00	\$ 18.60
	TOTAL SPARE PARTS	\$ 4,866.00	\$ 3,002.60
	TOTAL LABOUR CHARGES	\$ 2,252.00	\$ 1,752.00
	GRAND TOTAL	\$ 7,118.00	\$ 4,754.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118000615/GVBN2

Date: 12/02/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3077101700
Claimant Vehicle No :	SLT8718M	Insured Vehicle No :	SJB8245D
Date of Loss:	03/01/2018	Nature of Claim:	TP
		Claim No:	SNM18D00092C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT8718M	Engine No:	CVN045415
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF40JA023458
Reg. Date:	14/11/2017 (Man. Year: 2017)	Odometer:	3243 km
Colour:	Blue		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40ZR18	Rear Tyre Size:	245/40ZR18
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,866.00	3,002.60	1,863.40	38.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,252.00	1,752.00	500.00	22.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,118.00	4,754.60	2,363.40	33.20
+ GST 7.00/7.00% (S\$)	498.26	332.82	165.44	33.20
Nett Amount (S\$)	7,616.26	5,087.42	2,528.84	33.20

INSPECTION

Date of Assignment:	10/01/2018	
Date Inspected:	12/01/2018	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Feb 2018)
Parts:	143	AUDI A4 1.4 TFSI S TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT8718M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	1,844.00 FS	*1,844.00 FS
2	1	*REAR BUMPER SECURING STRIP	Necessary	182.00 FS	*181.50 FS
3	1	*REAR BUMPER SPOILER	Scratched	203.00 FS	*203.00 FS
4	2	*REAR LIGHT REFLECTOR-LH/RH	Not Necessary	66.00 FS	*- FS
5	1	*REAR BOOT LID	Not Necessary	349.00 FS	*- FS
6	1	*TAILGATE OPENING FOR SENSOR LINE	Not Necessary	179.00 FS	*- FS
7	4	*REAR BUMPER SENSOR	Not Necessary	830.00 FS	*- FS
8	1	*REAR BUMPER SENSOR SEAL RING	Not Necessary	15.00 FS	*- FS
9	1	*REAR BUMPER CARRIER	Bent	756.00 FS	*755.50 FS
10	2	*REAR BUMPER GASKET	Not Necessary	22.00 FS	*- FS
11	2	*REAR BUMPER GUIDE SECTION LH/RH	Not Necessary	73.00 FS	*- FS
12	2	*REAR BUMPER LOWER GUIDE SECTION LH/RH	Not Necessary	36.00 FS	*- FS
13	2	*LOWER GUIDE PIN	Not Necessary	11.00 FS	*- FS
14	1	*SUNDRIES	Necessary	300.00 FS	*18.60 FS
Total Parts (S\$)				4,866.00	3,002.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER ASSY.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	900.00	600.00
3	TO RESPRAY REAR BUMPER	New	800.00	600.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,252.00	1,752.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >