



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

12/1/18
@11am

AXA/AIG(SLK6894C)
DOA: 03/01/2018@1630

AIG ASIA PACIFIC INSURANCE PTE LTD

10/01/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SGB 1889 C - TOYOTA COROLLA 1.6
CHASSIS NO: MR053ZEC107107703 (2005)

1 pc	Front fender LH	\$ 184.80 R
	LESS 25%	\$ 46.20
		<u>\$ 138.60</u>

Remove and replace the above.	\$ 120.00 ✓
-------------------------------	-------------

Putty and respray front fender LH	\$ 280.00 240
	<u>\$ 538.60</u>

ADD 7% GST	\$ 37.70
	<u>\$ 576.30</u>

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....

Rasul
Hp 90014068
2 days
P/P
12/01/18 @ 1100hr

Resy after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: