

# 新合利服務公司

## Sin Hup Lee Service Co.

Block 1005 Bukit Merah Lane2 #01-20

Singapore 159761

Tel: 6278 2482 Fax: 6271 9802

Email: sinhuplee@gmail.com

Reg. No. 083995/00E

7 January 2018

Attn: Motor Claim Department  
ERGO Insurance Pte. Ltd  
5 Temasek Boulevard,  
#04-01 Suntec Tower Five,  
Singapore 038985.

TIRTA SARI PTE LTD  
c/o Sin Hup Lee Service Co.  
Block 1005 Bukit Merah Lane 2 #01-20  
Singapore 159761

Dear Sir/Ms,

**RE: Road Traffic Accident on 02 January 2018 along Scotts Road involving vehicle  
YP3000A/GY5165K.**

### **Quotation for Repair Vehicle No: GY5165K, Volkswagen (Third Party Claim)**

Quantity	List Item		Price
1	Rear Gate LH	\$	2,461.20
1	Rear Gate RH	\$	2,461.20
1	Rear Gate Logo	\$	97.75
1	Rear Gate Emblem "CADDY"	\$	82.30
2	Rear Gate Window Inner Seal	\$	97.20
2	Rear Gate Window Sealant	\$	160.00
1	Rear Gate Third Brake Light	\$	206.55
1	Rear Gate Wiper Blade	\$	62.90
1	Rear Gate Wiper Arm	\$	182.75
1	Rear Gate Motor	\$	498.50
1	Rear Gate Lower Lock	\$	181.20
1	Rear Gate Upper Lock	\$	181.20
1	Rear Gate Rubber	\$	179.55
1	Rear Gate Licence Lamp	\$	75.40
1	Rear Gate Garnish	\$	283.20
1	Rear Bumper	\$	786.10
1	Rear Bumper Reinforcement	\$	680.55
2	Rear Bumper Bracket	\$	71.50

10	Rear Bumper Clip	\$	35.00
		\$	8,784.05
		Less 10%	\$ 878.41
			\$ 7,905.65

**S Nett**

1	Rear Gate Sticker "70KM"	\$	20.00
1	Rear Gate Sticker "6 PAX"	\$	20.00
1set	Rear Bumper Sensor	\$	180.00
		\$	220.00

**Labour**

1	To repair Rear Panel, Rear Inner Member, remove and re-fix damaged parts, straighten and realign affected areas	\$	840.00
2	To spray paint on affected areas	\$	700.00
3	To remove and refix Rear Gate Window Glass LH and RH side	\$	200.00
4	To remove and refix Rear Gate Mechanism, check and test Wiper Motor & Centre Locking System	\$	180.00
85	To rust proof affected area	\$	100.00
<b>Total Amount</b>		\$	10,145.65

Kindly arrange your surveyor to survey my vehicle.

We look forward to hear from you soon.

Thank you.

**Yours Faithfully**

**Mr Wong**