

CARTIMES

autolution

Vehicle No. SFA509Z

Car Model : Audi Q5

Chassis No. WAUZZZ8R89A055367

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYORS ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Front bumper	Damaged	1078.00	
1	Front LHS headlamp	Damaged	2634.50	1 avic
1	Fender LHS	Damaged	887.70	-dt.
1	Fender inner sheild	Damaged	236.50	Y CVC
1	LHS passanger door	Damaged	2273.70	× R.
1	LHS door handle	Damaged	132.00	- aux.
1	LHS rear door	Damaged		XTZ.
1	LHS rim	Damaged	2192.30	- cus.
1	Bonnet	Damaged	3742.20	文た
1	Front lower arm LH	Damaged	1182.50	× SW
1	Knuckle arm	Damaged	1210.00	LONG
1	Linkage	Damaged	181.50	× avc
1	Control arm	Damaged	634.70	X CNC
2	Upper arm	Damaged	1269.40	× anc
1	Wheel bearing	Damaged	734.80	?
1	Shock absorber	Damaged	1842.50	Xano
			22506.00	
			5% 1125.30	
			21380.70	

Vehicle No. SFA509Z

s/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYORS ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1600.00	801 .
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	700.
3	To remove and replace front door	80.00	×
4	Remove and replace,Front lower arm LH,Knuckle arm, Linkage,Control arm,Upper arm,Wheel bearing and Shock absorber	250.00	120?
5	Perfrom wheel alignment	130.00	80.
	Labour Total :	3060.00	
	TOTAL (PARTS & LABOUR):	24440.70	

Mes Drahon)

Mes Drahon Photo

Hab Ando MAD.

16/1/2018.

Cowday S.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: