

CP MOTORS PTE LTD

160 Sin Ming Drive #05-05 Sin Ming Auto City
Singapore 575722

Tel No. : 64571357 Fax No. : 64595357

Tax Reg. No. : 201535864N Buss. Reg. No. : 201535864N

C/O CP Motors Pte Ltd
160 Sin Ming Drive #05-05
Sin Ming Auto City S 575722

Attention : Motor Claim Department

Contact : 82018103

Not Authorized
1-B1
Resurvey B & paint
4 days

Estimate : ES000081

Date : 08/01/2018
Vehicle Num. : SJU9188D
Make/Model : BMW 730Li-2009
Chassis/Eng# : WBAKB22050CN74312
Accident Date : 08/01/2018
Claim No. :
Reference : T/P Claim Against AXA
Policy No. : GA079232/1

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :			
1.	1 pc	Right Headlamp	2,971.40 ✓
2.	1 pc	Front Bumper	1,938.15 ✓
3.	1 pc	Front Bumper Sensor	352.90 ✓
4.	1 pc	Right Front Bumper Nozzle Cover	75.90 ✓
5.	1 pc	Right Front Bumper Nozzle Pump	254.90 ?
6.	1 pc	Right Front Bumper Side Retainer	83.75 ✓
7.	1 pc	Front Bumper Chrome Moulding	47.35 ✓
8.	1 pc	HID Bulb	392.20 ?
9.	1 pc	Right Front Fender	1,471.85 x
List TotalS\$:			7,588.40
10.00% Discount S\$:			758.84
			6,829.56
LABOUR :			
Focus Headlamp			40.00 201
To Install Parking Sensor To New Bumper			140.00 601
Resetting			250.00 ?
To straighten front bumper reinforcement, front support panel, right front fender inner panel include replacement of parts.			800.00 4001
Spray paint on right front fender, front bumper, front support panel.			900.00 5001
Labour Total S\$:			2,130.00

E. & O.E.

Total S\$: 8,959.56


for CP MOTORS PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: