



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKB5288M

Mdm Goh Siok Kuan

69 Jalan Binchang
Singapore 578554

Mobile: 96171708

Vehicle & Document Information

WIP No **20353**
Reg No/Reg Date **SKB5288M / 18/05/2017**
Date In/Mileage **/ 0**
Chassis No **WDD2221622A291506**
Engine No **27682430461698**
Make/Model **MB/MB S 320 L SEDAN (V222)**
Colour/Trim **027 799 Diamond Whi/ 048 801 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	10/01/2018/ 10:49	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 1700018019 // 09.01.18 DRIVE IN/EXCESS : 10.01.18 // TP CAR NO.: FBC8024P=AXA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				✓ 480.00
A BPILAB DISASSEMBLE AND REPLACE LEFT REAR DOOR, LEFT REAR FENDER, LEFT RUNNING BOARD				1920 2400.00
A BPIRES RESPRAY ON LEFT REAR DOOR, LEFT REAR FENDER, LEFT RUNNING BOARD				✓ 1800.00
M LEFT REAR DOOR MOULDING	1.00	151.91	00.00	net ✓ 151.91
M LEFT RUNNING BOARD	1.00	833.07	00.00	Rx 833.07

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

Tanjik 97495749
wp 29/1/18 @ 1245
sur@lkkant.com
4 days.

Nett 5,664.98
7% GST on 5664.98 396.55
Total Payable 6,061.53

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg