



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SKB5288M

Mdm Goh Siok Kuan

69 Jalan Binchang  
Singapore 578554

Mobile: 96171708

### Vehicle & Document Information

WIP No **20353**  
Reg No/Reg Date **SKB5288M / 18/05/2017**  
Date In/Mileage **/ 0**  
Chassis No **WDD2221622A291506**  
Engine No **27682430461698**  
Make/Model **MB/MB S 320 L SEDAN (V222)**  
Colour/Trim **027 799 Diamond Whi/ 048 801 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	10/01/2018/ 10:49	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M BPNSUN

POLICY NO/ACC DATE : 1700018019 // 09.01.18  
DRIVE IN/EXCESS : 10.01.18 // TP CAR NO.: FBC8024P=AXA  
DATE IN/DATE SURVEY:  
BY/AUTHORIZED ON :

A BPILAB

USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO  
IDENTIFICATION STANDARD. NETT

A BPILAB

DISASSEMBLE AND REPLACE LEFT REAR DOOR, LEFT REAR FENDER,  
LEFT RUNNING BOARD

A BPIRES

RESPRAY ON LEFT REAR DOOR, LEFT REAR FENDER, LEFT RUNNING  
BOARD

M LEFT REAR DOOR MOULDING

M LEFT RUNNING BOARD

Qty	Unit Price	Disc%	Amount
1.00	151.91	00.00	151.91
1.00	833.07	00.00	833.07

Confirmed & accepted by

Authorized signatory and company stamp

	Nett	
7% GST on	5664.98	396.55
<b>Total Payable</b>	<b>6,061.53</b>	

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg