



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN. : MOTOR CLAIMS FAX :		NAME : Ms Susan Lam Yoke Peng ADDRESS : 26A St. Michael's Road #08-02 Riverside Melodies Singapore 327995 TEL : 91853350CLEMENT		WIP : 55647 EXCESS : DATE: 9-Jan-18	
VEH NO :	SKV5376L	DATE IN :		CONTACT PERSON :	VION 6395 7877
CHASSIS NO :	JM6KE1072G0333621	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA CX5 2.0L	DATE REG.:	22-Sep-15	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO		QTY		REVISED	PRICES
1	RHS FRONT DOOR <i>X repair.</i>	1	MKDY3-58-02XK		\$ 1,155.60
2	HINGE UPPER(RHS), FRONT DOOR <i>X</i>	1	MKD53-58-210		\$ 42.00
3	HINGE LOWER(RHS), FRONT DOOR <i>X</i>	1	MD461-59-210A		\$ 39.70
4	CHROME(RHS), FRONT DOOR <i>mis</i>	1	MKD53-50-640D		\$ 55.00
5	FASTENER, FRONT DOOR <i>X</i>	1	MGD7A-50-EA1		\$ 3.00
6	CLIP, FRONT DOOR <i>X</i>	1	MG51D-58-315A		\$ 2.20
7	GROMMET, FRONT DOOR <i>X</i>	2	MB499-62-868		\$ 6.40
8	GROMMET, FRONT DOOR <i>X</i>	1	M9991-00-503		\$ 3.60
9	GROMMET, FRONT DOOR <i>X</i>	9	MGJ6A-58-975		\$ 25.20
10	RHS REAR DOOR <i>mis</i>	1	MKDY3-72-02XC		\$ 1,605.70
11	HINGE LOWER(RHS), REAR DOOR <i>X</i>	1	MKD53-72-240		\$ 42.60
12	HINGE UPPER(RHS), REAR DOOR <i>X</i>	1	MKD53-72-210		\$ 46.00
13	CHROME(RHS), REAR DOOR <i>mis</i>	1	MKD53-50-660B		\$ 43.15
14	FASTENER, REAR DOOR <i>mis</i>	1	MKD53-72-762A		\$ 11.70
15	FASTENER, REAR DOOR <i>mis</i>	1	MGD7A-50-EA1		\$ 3.00
16	CLIP, REAR DOOR <i>mis</i>	1	MG51D-58-315A		\$ 2.20
17	GROMMET, REAR DOOR <i>mis</i>	1	MBF67-51-261		\$ 2.20
18	GROMMET, REAR DOOR <i>mis</i>	1	M9991-00-503		\$ 3.60
19	GROMMET, REAR DOOR <i>mis</i>	7	MGJ6A-58-975		\$ 19.60
20	CLIP, DOOR GARNISH <i>mis</i>	6	MKD53-50-M38		\$ 70.20
21	CLIP, DOOR GARNISH <i>mis</i>	3	MC273-50-714		\$ 35.10
22	GROMMET, DOOR SPEAKER <i>mis</i>	7	MGJ6A-58-975		\$ 19.60
23	GARNISH LOWER(RHS), FRONT DOOR <i>mis</i>	1	MKD53-51-RA0C		\$ 213.30
24	GARNISH UPPER(RHS), FRONT DOOR <i>mis</i>	1	MKD53-51-RC0B		\$ 129.30
25	GARNISH(RHS), REAR FENDER <i>scr</i>	1	MKD53-51-W50C		\$ 209.60
26	RHS FRONT FENDER <i>X repair</i>	1	MKD53-52-111A		\$ 487.90
27	GARNISH(RHS), FRONT FENDER <i>X NN</i>	1	MKD53-51-W20C		\$ 177.80
TOTAL PARTS					\$ 4,455.25
LESS 10%					\$ 445.53

TOTAL PARTS COST				\$ 4,009.73
<u>Labour Description</u>				
1		TO REPLACE RHS FRONT FENDER, RHS FRONT DOOR AND RHS REAR DOOR. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1575	\$ 2,520.00
2		TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR AND RHS REAR DOOR.	1800	\$ 2,400.00
3	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	315	\$ 1,260.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
6	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	2	NETT / \$ 120.00
7	MZ-BR-SUNDRI	SUNDRIES.	20	NETT \$ 100.00

6 Days.
 before paint photos.
 Eric Qiang - 8288 0282
 11/1/18

TOTAL LABOUR	\$ -	\$ 7,000.00
TOTAL PARTS	\$ -	\$ 4,009.73
TOTAL	\$ -	\$ 11,009.73
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:
 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

 Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: