



			<b>TOTAL PARTS COST</b>	<b>\$ 4,009.73</b>
<b>Labour Description</b>				
1		TO REPLACE RHS FRONT FENDER, RHS FRONT DOOR AND RHS REAR DOOR. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		\$ 2,520.00
2		TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR AND RHS REAR DOOR.		\$ 2,400.00
3	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.		\$ 1,260.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 350.00
6	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	NETT	\$ 120.00
7	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 100.00
			TOTAL LABOUR	\$ - \$ 7,000.00
			TOTAL PARTS	\$ - \$ 4,009.73
			TOTAL	\$ - \$ 11,009.73
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			<b>GRAND TOTAL</b>	<b>\$ - \$ -</b>

REMARKS:  
 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

**TRANS EUROKARS PTE LTD**

\_\_\_\_\_  
 Authorised Signature