LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Lonpac Insurance Bhd From: LKK Auto Consultants Pte Ltd

300 Beach Road #17-04/07 The Concourse

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 199555 Singapore 408933

Attn: Gerald Poh Date: 12 Jan 2018

Preliminary Advice

Vehicle No : SJK7768X Accident Date : 08/01/2018 : Z17VP05015678 Make : BMW 118I Policy No. Assignment Date : 10/01/2018 **Excess** : S\$500.00

Date of Inspection : 11/01/2018 Est. Duration of Repair : 15.00

Inspection At : WAH HONG MOTORS & CREDIT PTE LTD (HQ)

38 TOH GUAN ROAD EAST, #01-57, ENTERPRISE HUB

SINGAPORE 608581

Point of Impact / General Description of Damages

The vehicle recovered from flood. Many electrical & mechanism parts found damaged and contaminated by flood water at the time of inspection.

Repairer's Estimate (Gross)	:S\$	22,150.00
Revised Amount	:S\$	7,000.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair (ESTIMATED)	:S\$	7,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	25,000.00
COE / PARF Rebate	:S\$	16,975.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,025.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :