

WIDOM

ASS. REC. BY

REF: CS/MSG18000644/T1rd3n2

Field Instruction

ASSIGNMENT (Office)

Meimen

Taufich

From (Person)

Lionel Tan

of

MSIG

Date/Time: 10/01/2018 @ 4:06pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / DV / MV / CS

To Inspect Vehicle No

XE787C

Insured

XD13014

at Workshop no

Accord Auto

Tel

9274 0999

or B1K1009, Bkt Merah Lane 3 # 01-80

Policy No

28718557MKF

Claim No

545086

Sum Insured

Excess

Make of Veh

D.O.A. 09/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp

R.O.D. Return

Date/Time

4.48pm @ 10/1/18

Person Contacted

celia

Vehicle DL OUT

Date/Time

Action Instruction

✓

53 Pioneer Road (Heng Soon Paint Works) - Grace 6269 8719

XE787C-X

XD 787C - NJA/V1080 27111/41

D.O.A : 03/10/2008

Confirm \$9590.40 @ 7 days (Red: \$9906.40, 51%.)

ASSIGNMENT

From: Maximen Date: 11-01-2018 Veh No: XE 787C Yr Regn: 2015 June

Estimated Cost: OD / P / WS / TP RES / OD RES / EVA / INV / MV Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

To Inspect Vehicle No: XE 787C Make: UD Trucks GKBSELDHNT 10837

at Workshop m/s: Accord Auto Colour: Purple A/C: Insured / Std / NI / NA

of 53 Pioneer Rd (Liang Soon) Sp. Reading: 210437 T/Radio: Insured / Std / NI / NA

Insured: Grace - 6269 8719 Eng/No: GKB5E00567

Policy No: Good / Fair / Poor / Burnt Gen. Cond: Good / Fair / Poor / Burnt

Claims No: Steering: In order / Jammed / Leaked / Burnt or

Sum Insured: Brake: In order / Jammed / Leaked / Burnt or

(Client's Record) Mod: (Nil) / S/Rim / STD A/Rim or

Make of Veh: Tyre Size: F: 295/80R22.5

(Policy Condition) R: n - (17)

Remark: The veh had commenced its BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

repair at the time of inspection. TOYO / YOKO or Falken

Bal. or Market Value:

N/S	O/S

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle IN / OUT

Survey held at: Accord Auto.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Price checked 7/5/18

Date/Time: File Pass to? ☐ : Preli. Report

1) typist ☒ : Final Report

Date/Time: File Return to?

2)

Report Format: 7P

Lump Sum / I.B.I: 9540.40

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp \$

☐ Interview \$

☐ Tech Invs \$

☐ Weekend \$

Survey Fee

Transportation

Photos

Others

TOTAL

300

10

310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18000644/T1rd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 11-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 1301U	Veh. Inspected	XE 787C
Policy No.	28718557MKC	Coverage (\$)	0.00
Claim No.	545086	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	11/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/01/2018	Inspection Date	11/01/2018
Survey held at	53 PIONEER ROAD (LIANG SOON PAINT WORKS)		
Repairer	ACCORD AUTO SERVICES PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jan 2018		10 Jan 2018 16:06 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	CWT INTEGRATED PTE.LTD., Co. Reg. No.: 197701671C		
Main Claimant:	PO SAN TRANSPORTATION PTE LTD, Co. Reg. No.: 200822834N		
Vehicle Reg. No.:	XE787C	Date of Loss:	09/01/2018 10:00 - :59
Claim Type:	TP / 545086	Policy/Cover Note No.:	28718557MKF (Third Party Only) Coverage: 01/04/2017 - 31/03/2018
Vehicle Reg. No. (Insured):	XD1301U	Policy No. (Claimant):	
		Excess:	
Repairer:	Accord Auto Services Pte Ltd (Bukit Merah) BLK 1009 BUKIT MERAH LANE 3, #01-80, 159723 Bukit Merah - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/01/2018]		
Adj Asg. Remarks:	Please contact Cella Lai @ 6271 7433 or 9274 0999 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/01/2018 16:18
Date Of Accident	09/01/2018 10:50
Exact Location Of Accident	42C PENJURU ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE787C
-----------------------------	--------

Insured/Policyholder

Name Of Registered Owner	PO SAN TRANSPORTATION PTE LTD
Co Reg No	200822834N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-88214559

Vehicle Particulars

Manufacturer	UD TRUCKS
Model	GKB5ELDHNT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	BVF2SB0002641701
Cover Note Number	N.A

Driver

Name of Driver	HO KWOK KEONG
NRIC No	S7230879D
Date Of Birth	28/08/1972
Occupation	OUTDOOR
Date Of Driving Pass	25/01/1994
Driving Experience	23 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88214559
Fax Number	
Contact Number	
EMail Address	AINSLY@POSAN.COM.SG

Address	HDB BOON LAY MEADOW, 181A BOON LAY DRIVE #04-604
Postcode	641181
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - U-TURN
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I (XE787C) WAS STATIONARY IN THE DRIVEWAY INSIDE 42C PENJURU ROAD ON THE LEFT SIDE WHEN A VEHICLE (XD1301U) ON MY RIGHT SIDE MAKE A SUDDEN U-TURN TO HIS LEFT AND HIT ME. THE LEFT SIDE OF THE CONTAINER MAKE CONTACT WITH THE FRONT LEFT SIDE OF MY VEHICLE. NO INJURIES INVOLVED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD1301U
Vehicle Make/Model/Colour	NISSAN GKB45CLBHNB / WHITE
Details Of Properties	NIL
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN WENG MIN
NRIC/Passport Number	F7421087L
Contact Number	85066880
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail packages); and/or
(v) complying with applicable law as administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHAMMAD SULHANDI BIN
MOHD AFFANDI


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan

DRIVEWAY OF 42K PENJURAN ROAD



Common Statement

ACCIDENT STATEMENT (2000 characters)

I (XE0787C) WAS STATIONARY IN THE DRIVEWAY INSIDE 42C PENJURU ROAD ON THE LEFT SIDE WHEN A VEHICLE (XD1301U) ON MY RIGHT SIDE MAKE A SUDDEN UTURN TO HIS LEFT AND HIT ME. THE LEFT SIDE OF THE CONTAINER MAKE CONTACT WITH THE FRONT LEFT SIDE OF MY VEHICLE. NO INJURIES INVOLVED.


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMMAD SULHANDI BIN MOH AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

9 January 2018 at 1:13 PM

Date/Time:

9 January 2018 at 1:13 PM

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL: 62715133 / 62717433 FAX: 62745715

ESTIMATE REPAIR

Pg1

MSIG Insurance (Singapore) Pte Ltd

Date: 16.1.2018

Owner's Name : Po San Transportation Pte Ltd

Vehicle No : XE787C

Claim Type: Third Party Claim

Vehicle Make & Model : UD Trucks

Chassis No: GKB5E00567

Registration Date : 22 Jun 2015 (YOM 2015) COE Expiry Date 21 Jun 2025

DOA: 9.1.2018

No	Description	Unit	List (\$)
1	FRONT BUMPER LH ASSY	1	\$ bt✓ 650.00
2	FRONT BUMPER BRACKET LH	1	\$ X ny 80.00
3	FRONT HEADLAMP LH	1	\$ X ny 780.00
4	FRONT SIGNAL LAMP LH	1	\$ ana✓ 43.00
5	FRONT SIDE LAMP LH	1	\$ X ny 43.00
6	FRONT BUMPER SIDE GARNISH LH (END CAP BUMPER)	1	\$ cut✓ 128.00
7	FRONT FENDER LH	1	\$ ana✓ 382.00
8	FRONT DOOR PILLAR OUTER LH	1	\$ RX 860.00
9	FRONT DOOR ASSY LH	1	\$ bt✓ 5,244.00
10	FRONT DOOR CHECKER LH	1	\$ dis✓ 150.00
11	FRONT DOOR HINGE LH (UPPER)	1	\$ bt✓ 195.00
12	FRONT DOOR HINGE LH (LOWER)	1	\$ bt✓ 195.00
13	FRONT DOOR GLASS OUTER MOULDING LH	1	\$ de✓ 88.00
14	FRONT DOOR GLASS REGULATOR MOTOR LH	1	\$ X ny 80.00
15	FRONT DOOR GLASS CHANNEL LH	1	\$ nny 118.00
16	FRONT DOOR GLASS CHANNEL BEADING	1	\$ X ny 82.00
17	FRONT DOOR WEATHERSTRIPE	1	\$ ana✓ 280.00
18	FRONT DOOR SIDE RUBBER LH	1	\$ X ny 95.00
19	FRONT DOOR EMBLEM "UD7420"	1	\$ ny✓ 105.00
20	FRONT DOOR INNER LOCK	1	\$ X ny 368.00
21	FRONT DOOR LOCK STRIKER LH	1	\$ X ny 35.00
22	FRONT DOOR INNER TRIM BOARD LH	1	\$ X ny 514.00
23	FRONT DOOR SIGNAL LAMP LH	1	\$ ana✓ 40.00
24	FRONT STEP BOARD (TOP)	1	\$ X ny 320.00
25	FRONT STEP BOARD GARNISH (TOP)	1	\$ de✓ 456.00
26	FRONT STEP BOARD MOUTING BRACKET (TOP)	1	\$ X ny 148.00
27	FRONT STEP BOARD GARNISH LAMP COVER LH	1	\$ X ny 264.00
Total (A):			\$ 7956 11,743.00
Less 10%			\$ 7160.40 1,174.30
Total:			\$ 10,568.70

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL: 62715133 / 62717433 FAX: 62745715

ESTIMATE REPAIR

Pg2

MSIG Insurance (Singapore) Pte Ltd

Date: 16.1.2018

Owner's Name : Po San Transportation Pte Ltd

Vehicle No : XE787C

Claim Type: Own Damage Claim

Vehicle Make & Model : UD Trucks

Chassis No: GKB5E00567

Registration Date : 22 Jun 2015 (YOM 2015) COE Expiry Date 21 Jun 2025

DOA: 9.1.2018

[illegible]

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL:62715133/62717433 FAX:62745715

Pg 3

DOA: 9.1.2018

[illegible]

Lumpsum 10% - ~~45,860~~ 9590.40
 7 days.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000644/T1RD3N2

Date: 13/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28718557MKF
Claimant Vehicle No :	XE787C	Insured Vehicle No :	XD1301U
Date of Loss:	09/01/2018	Nature of Claim:	TP
		Claim No:	545086

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE787C	Engine No:	GH11728325
Make & Model:	UD TRUCKS QUON GK, 10.8 D GKB5ELDHT (M)	Chassis No:	GKB5E00567
Reg. Date:	22/06/2015 (Man. Year: 2015)	Odometer:	210437 km
Colour:	Purple		
Engine Capacity:	10837 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80R22.5	Rear Tyre Size:	295/80R22.5 (D)
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8/8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,826.80	7,490.40	6,336.40	45.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,670.00	2,100.00	3,570.00	62.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,496.80	9,590.40	9,906.40	50.81
+ GST 7.00/7.00% (S\$)	1,364.78	671.33	693.45	50.81
Nett Amount (S\$)	20,861.58	10,261.73	10,599.85	50.81

INSPECTION

Date of Assignment:	10/01/2018	
Date Inspected:	11/01/2018 Inspected At:	Accord Auto Services Pte Ltd (Bukit Merah) BLK 1009 BUKIT MERAH LANE 3, #01-80 Singapore 159723
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Aug 2018)	
Parts:	N/A	UD TRUCKS QUON GK 10.8 D GKB5ELDHNT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE787C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER LH ASSY	Bent	650.00 FL	*650.00 FL
2	1		*FRONT BUMPER BRACKET LH	Not Necessary	80.00 FL	*- FL
3	1		*FRONT HEADLAMP LH	Not Necessary	780.00 FL	*- FL
4	1		*FRONT SIGNAL LAMP LH	Cracked	43.00 FL	*43.00 FL
5	1		*FRONT SIDE LAMP LH	Not Necessary	43.00 FL	*- FL
6	1		*FRONT BUMPER SIDE GARNISH LH (END CAP BUMPER)	Cut	128.00 FL	*128.00 FL
7	1		*FRONT FENDER LH	Cracked	382.00 FL	*382.00 FL
8	1		*FRONT DOOR PILLAR OUTER LH	Repair	860.00 FL	*- FL
9	1		*FRONT DOOR ASSY LH	Bent	5,244.00 FL	*5,244.00 FL
10	1		*FRONT DOOR CHECKER LH	Distorted	150.00 FL	*150.00 FL
11	1		*FRONT DOOR HINGE LH (UPPER)	Bent	195.00 FL	*195.00 FL
12	1		*FRONT DOOR HINGE LH (LOWER)	Bent	195.00 FL	*195.00 FL
13	1		*FRONT DOOR GLASS OUTER MOULDING LH	Deformed	88.00 FL	*88.00 FL
14	1		*FRONT DOOR GLASS OUTER MOTOR LH	Not Necessary	80.00 FL	*- FL
15	1		*FRONT DOOR GLASS CHANNEL LH	Not Necessary	118.00 FL	*- FL
16	1		*FRONT DOOR GLASS CHANNEL BEADING	Not Necessary	82.00 FL	*- FL
17	1		*FRONT DOOR WEATHERSTRIPE	Cut	280.00 FL	*280.00 FL
18	1		*FRONT DOOR SIDE RUBBER LH	Not Necessary	95.00 FL	*- FL
19	1		*FRONT DOOR EMBLEM (UD7420)	Necessary	105.00 FL	*105.00 FL
20	1		*FRONT DOOR INNER LOCK	Not Necessary	368.00 FL	*- FL
21	1		*FRONT DOOR LOCK STRIKER LH	Not Necessary	35.00 FL	*- FL
22	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	514.00 FL	*- FL
23	1		*FRONT DOOR SIGNAL LAMP LH	Cracked	40.00 FL	*40.00 FL
24	1		*FRONT STEP BOARD (TOP)	Not Necessary	320.00 FL	*- FL
25	1		*FRONT STEP BOARD GARNISH (TOP)	Deformed	456.00 FL	*456.00 FL
26	1		*FRONT STEP BOARD MOUNTING BRACKET (TOP)	Not Necessary	148.00 FL	*- FL
27	1		*FRONT STEP BOARD GARNISH LAMP COVER LH	Not Necessary	264.00 FL	*- FL
28	1		*FRONT STEP BOARD LH (LOWER)	Not Necessary	320.00 FL	*- FL
29	1		*FRONT STEP BOARD GARNISH LH (LOWER)	Not Necessary	320.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
30	1		*FRONT STEP BOARD YELLOW REFLECTOR (LOWER)	Not Necessary	40.00 FL	*-FL
31	1		*FRONT STEP ARCH PANEL LH (TOP)	Not Necessary	680.00 FL	*-FL
32	1		*FRONT STEP BRACKET LH (LOWER)	Not Necessary	483.00 FL	*-FL
33	1		*FRONT MIRROR STAY ASSY LH	Not Necessary	741.00 FL	*-FL
34	1		*FRONT MIRROR ROUND LH	Not Necessary	155.00 FL	*-FL
35	1		*FRONT MIRROR SQUARE SMALL LH	Not Necessary	150.00 FL	*-FL
36	1		*FRONT MIRROR SQUARE BIG LH (LOWER)	Not Necessary	170.00 FL	*-FL
37	1		*SET CORNER GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
38	1		*SET BUMPER SCREW/CLIPS	Necessary	60.00 FS	*30.00 FS
39	1		*SET DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
40	1		*SET FRONT DOOR COMPANY LETTER & LOGO STICKER	Necessary	260.00 FS	*200.00 FS
41	1		*SET FRONT CORNER PANEL COMPANY LETTER STICKER	Necessary	85.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,307.00	8,286.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,480.20	795.60
Total Parts (\$\$)	13,826.80	7,490.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON DAMAGE AFFECTED PORTION OF CAR	New	1,500.00	900.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	2,500.00	900.00
3	CHECK WIRING SYSTEM & LIGHT	New	180.00	30.00
4	ANTI RUST TREATMENT	New	180.00	30.00
5	TO CHECK & ADJUST WHEEL ALIGNMENT	New	350.00	-
6	TO REMOVE/REPLACE FRONT WINDSCREEN TO FACILITATE REPAIR	New	300.00	-
7	TO REMOVE/REFIX FRONT DOOR LH INNER ATTACHMENT	New	200.00	80.00
8	TO REMOVE/REPACE DOOR PILLAR	New	280.00	100.00
9	TO REMOVE/REFIX FRONT DOOR GLASS TO FACILITATE REPAIR	New	180.00	60.00
Gross Labour Cost (\$\$)			5,670.00	2,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >