

ASS. SEC. BY:

REF: CS/FCI18000646/4tb

Special Instructions

Marcus

ASSIGNMENT (Office)

From (Person): Teo Swee Keong

FCI

Date/Time: 11/01/2018 @ 8:43pm

Estimated Cost

Est. #

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBG 2860K

Search: SHA 2388T

to Workshop no: ~~Tan Lim Motor~~ CBC

Tel: 6858 5151

at: 51 Defu Lane 10

Folio No

Claim No: D18000436 MF&H.

Sum Insured

Event

Make of Veh

DOA: 10/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

ESC Estimated

Date/Time: 8:55am @ 10/1/18

Person Contacted: Sharon

Page: 1 OCT

Date/Time

Action/Instructions

Remarks

All - Revert preli via email.

Change workshop to Cycle & Carriage.

mercari

REF:

201/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: G2G 2860K
 at Workshop m/s: Tan Loo
 of _____
 Insured: SKIA23887
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: G2G 2860K Yr Regn: 7 17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or (M)
 Make: MAXUS cc: 1850
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 18477 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: LSKH46L12HA05873P
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Insider / Jammed / Leaked / Burnt or
 Brake: Insider / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/70R16
 R: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection
 Bal. or Market Value: 68 / ~~68~~
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 22 days Res: Yes or No
 Lum Sum: 10 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS 7003
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hookook
 Front Rear
 R/Bal: 7 mm R/Bal: 7 mm
 L/Bal: 7 mm L/Bal: 7 mm
 D.O.A: 10/1/18 B.O.I: 11/1/18
 Survey held at: C&C ubi 17/1/18
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rt.
 The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction L7A38201 nett 28799 30/1/18 C&C prepare Estimation
new car 70k.
change workshop to C&C ubi,
6/4/18 confirmed Repair sum \$26,000 with Chris
limited Repair (Red: 9446.44, 26%)

RECEIVED 10 APR 2018

Date/Time: File Pass to? : Prell. Report
 : Final Report
 // 1014 Typset
 Date/Time: File Return to?

Days Of Repair: 22
 Resurvey No. of Trip: 2

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Insp (\$)
 Weekend (\$)

Survey Fee: 170 1575
 Transportation: 50
 S+R: 50450
195
940

Report Format: TP
 Lump Sum / I.B.I: (\$ 26000/-)

580
DSP
12/4/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18000646/Utb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-01-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 2388T	Veh. Inspected	GBG 2860K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/01/2018	Inspection Date	11/01/2018
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	16-01-2018	Our Ref No. D18000436MFSH
Accident Date	10-01-2018	Claim Type. Third Party
Insured Vehicle	SHA2388T	Third Party Vehicle. GBG2860K
Survey Location	330 UBI ROAD 3	
Contact Person.	MARS LER	
Contact No.	65949163/ 91792566	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE - FULCO MOTOR DEALER PTE LTD - (SERVICE)	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

MOTOR SURVEY ASSIGNMENT

Date	11/1/18	Our Ref No.	SHA 2388T
Accident Date	10/1/18	Claim Type	3rd Party
Insured Vehicle	SHA 2388T	Third Party Vehicle	4BG2860K

Survey Location	Tan Lim Motor Pte Ltd 51 Debu Lane 10 Spore 539216	Contact Person	Lam Wei Shong William
-----------------	--	----------------	--------------------------

Contact No.	6858 5151	Fax No.	6858 0877
-------------	-----------	---------	-----------

Survey Type DIRECT SETTLEMENT WITH QUANTUM TO BE AGREED.

Appointed Surveyor	Lhh	Fax No.	68416315
Contact Person			
Contact Number	6256 3561		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. Accident Reports & est

Cc : Workshop	Tan Lim Motor Pte Ltd	Attention	Wei Shong
Officer In charge	Eileen Lee		

IMPORTANT NOTE

Kindly submit the survey report by email only to surveyor@first-insurance.com.sg within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Nivitha (LKK Auto)

From: Teo Swee Keong <TeoSweeKeong@first-insurance.com.sg>
Sent: Thursday, 11 January 2018 8:43 PM
To: 'assignments@lkkauto.com'
Cc: Eileen Lee; wei.shong@tlimotor.com.sg; caymen@tlimotor.com.sg
Subject: NEW SURVEY ASSIGNMENT - OUR REF: SHA2388T DOA: 10.01.2018
Attachments: FW: Arrange survey - Accident Involving GBG2860K and SHA2388T on 10.01.2018 (736 KB); MOTOR SURVEY ASSIGNMENT.pdf

Dear Sirs

New survey request for your handling.

Thanks and Regards,

SK Teo
Motor Claims Dept

36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 | Company Regn. No. 195000106C
email: MotorClaims@first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Wei Shong [mailto:wei.shong@tlimotor.com.sg]
Sent: Thursday, January 11, 2018 10:42 AM
To: Teo Swee Keong <TeoSweeKeong@first-insurance.com.sg>
Cc: Eileen Lee <EileenLee@first-insurance.com.sg>; caymen@tlimotor.com.sg
Subject: RE: YR REF: GBG2860K OUR REF: SHA2388T DOA: 10.01.2018

Dear Swee Keong,

We select LKK to survey our client vehicle.

Thank you.

Regards,



Lam Wei Shong
William
wei.shong@tlimotor.com.sg

O: +65 6858 5151
F: +65 6858 0877

Tan Lim Motor Pte
51 Defu Lane 10
Singapore 539218
<http://www.tlimotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place security programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Teo Swee Keong [<mailto:TeoSweeKeong@first-insurance.com.sg>]
Sent: Thursday, January 11, 2018 10:18 AM
To: wei.shong@tlmotor.com.sg
Cc: Eileen Lee <EileenLee@first-insurance.com.sg>; caymen@tlmotor.com.sg
Subject: YR REF: GBG2860K OUR REF: SHA2388T DOA: 10.01.2018

Dear Sirs,

We refer to your survey request dated 11/01/2018.

Please find below our list of surveyors for your reference. Kindly select from our list below and inform us of your choice within the next 2 days.

1. LKK Auto Consultants Pte Ltd
2. Vicom Ltd

Once you inform us of your choice, the surveyor will be appointed within 2 working days of your email.

If you do not agree to any of the surveyors above, you may proceed to appoint your own surveyor. In this instance, we will also appoint a surveyor from our list above to conduct the PRI. Upon completion of repairs, please contact our appointed surveyor to conduct a physical re-inspection of the vehicle.

Thank you.

Thanks and Regards,

SK Teo
Motor Claims Dept

36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 | Company Regn. No. 195000106C
email: MotorClaims@first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Harminder Kaur
Sent: Thursday, January 11, 2018 9:06 AM
To: Teo Swee Keong <TeoSweeKeong@first-insurance.com.sg>
Subject: FW: Arrange survey - Accident Involving GBG2860K and SHA2388T on 10.01.2018

Survey

Best Regards,
Harminder Kaur
Motor Claims

First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | TEL : 6507 3848 | Fax No. : 6507 3849 | Company Regn. No. 195000106C

A member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Wei Shong [mailto:wei_shong@tlmotor.com.sg]

Sent: Wednesday, January 10, 2018 8:36 PM

To: Motor Claims <MotorClaims@first-insurance.com.sg>

Cc: caymen@tlmotor.com.sg

Subject: Arrange survey - Accident Involving GBG2860K and SHA2388T on 10.01.2018

Your insured: - SHA2388T

Our client:- GBG2860K

Without prejudice

Dear Executive,

We enclose the following documents for your attention:-

- a. Copy of our client's GIA report;
- b. Copy of the estimated cost of repair.

Pursuant to paragraph 6.2 of Pre-Action Protocol for NIMA Cases, please let us know within **2 working days** whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

Vehicle in our premises.

We await for your favourable reply.

Thank you.

Regards,



Lam Wei Shong
William
wei_shong@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte I
51 Defu Lane 10
Singapore 539216
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 17 January 2018 1:14 PM
To: 'Teo Swee Keong'; assignments
Cc: 'Eileen Lee'; SUR
Subject: FW: NEW SURVEY ASSIGNMENT - OUR REF: SHA2388T DOA: 10.01.2018
Attachments: PRELI ADVISED GBG 2860K.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **GBG 2860K**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 12 January 2018 8:55 AM
To: 'Teo Swee Keong' <TeoSweeKeong@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@first-insurance.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: NEW SURVEY ASSIGNMENT - OUR REF: SHA2388T DOA: 10.01.2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo Swee Keong [<mailto:TeoSweeKeong@first-insurance.com.sg>]
Sent: Thursday, 11 January 2018 8:43 PM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Eileen Lee <EileenLee@first-insurance.com.sg>; wei.shong@tlmotor.com.sg; caymen@tlmotor.com.sg
Subject: NEW SURVEY ASSIGNMENT - OUR REF: SHA2388T DOA: 10.01.2018

Dear Sirs

New survey request for your handling.

Thanks and Regards,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SHA 2388T

Date: 17/1/2018

Our Ref: CS/FCI18000646/Utb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBG 2860K

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/1/2018 at the premises of M/s TAN LIM MOTOR, and have the following to report: -

Workshop Estimate Amount	: S\$ <u>11,000.00 (LABOUR ONLY)</u>
Revised Estimate Amount	: S\$ <u>4,010.00 (LABOUR ONLY)</u>
"Check" Items Amount	: S\$ <u>1,200.00</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the front body.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Marcus

Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7800B
Vehicle Details	
Vehicle No.:	GBG2860K
Vehicle to be Exported:	Yes
Intended De-registration Date:	10 Jan 2018
Vehicle Make:	MAXUS
Vehicle Model:	G10 VAN 6MT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	19D4N1PYH316K004
Chassis No.:	LSKG4GL12HA058739
Maximum Power Output:	-
Open Market Value:	\$19,254.00
Original Registration Date:	12 Jul 2017
First Registration Date:	12 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$963.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jul 2027
COE Category:	C - Goods Vehicle & Bus



Maxus Min Price to No Max Depreciation Vehicle Type Category Submit Advanced Search

Home > New Cars > New Car Brands > Maxus > Maxus G10

Tools & Tips

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle

Vehicle Inspection

STA Professional & Hassle-free vehicle inspection

Related Articles

AFOND SPA - Experience relaxation

Go to articles

Maxus G10

Overview Pricing Photos Research Reviews Specs Features Similar Accessories Promo



Details


Distributor Cycle & Carriage Commercial Vehicle Centre (Maxus)
Hotline 67455000
Built in China
Pricelist 11-Sep Pricelist Select Another Date
Promotion No current promotions. Alert me when new promotions are inserted

USER RATINGS: No review posted. Be the first to Rate it!

Submodel	Price	Depreciation ?	Fuel Economy	Power	Transmission	Detailed Info
1.9 Panel Van (Euro 5) (M)	\$75,988	-	13.2km/L	143hp	6-speed (M)	Specs Features

Price updated 08-Jan-2018

Maxus G10 Photos



Similar New Cars Similar Used Cars

	Citroen Dispatch From : \$77,988		Maxus V80 From : \$75,988		Nissan NV200 (P1) From : \$64,000
	Opel Combo From : \$79,888		Renault Kangoo From : \$79,600		

Authorized Distributor Maxus cars are Maxus V80, Maxus V80 Comuter.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable. But no assurance can be given that this information is accurate, complete or correct. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7800B
Vehicle Details	
Vehicle No.:	GBG2860K
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jan 2018
Vehicle Make:	MAXUS
Vehicle Model:	G10 VAN 6MT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	19D4N1PYH316K004
Chassis No.:	LSKG4GL12HA058739
Maximum Power Output:	-
Open Market Value:	\$19,254.00
Original Registration Date:	12 Jul 2017
First Registration Date:	12 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$963.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$40,212.00
COE Rebate Amount:	\$38,201.00
Total Rebate Amount:	\$38,201.00

The information contained herein is correct as at 11 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/01/2018 19:06
Date Of Accident	10/01/2018 06:50
Exact Location Of Accident	JUNCTION OF CECIL STREET AND CROSS STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG2860K
Insured/Policyholder	
Name Of Registered Owner	KAI HUAT ROASTED AND FOODSTUFF SUPPLY
Co Reg No	42967800B
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67442894

Vehicle Particulars

Manufacturer	MAXUS
Model	G10-1.9 (A)
Exact Purpose for which vehicle was being used at time of accident	DELIVERY USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M492655
Cover Note Number	12.07.2017 TO 11.07.2018

Driver

Name of Driver	LEE MEW CHUE
NRIC No	S1263421H
Date Of Birth	24/09/1957
Occupation	OUTDOOR
Date Of Driving Pass	28/11/2013
Driving Experience	4 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-98481239
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	164 TAI KENG GARDENS
Postcode	535436
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 10.01.2018 at about 0650hrs, I was driving my vehicle (A: GBG2860K) along the 3rd lane of Cecil Street. When the traffic light was green, I continued to move forward. Suddenly, a taxi (B: SHA2388T) drove out from Cross Street even when the traffic light showed "Red". Thus, resulting in a collision. Vehicle A (GBG2860K): No passenger on board. Vehicle B (SHA2388T): 1 passenger on board.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA2388T
Vehicle Make/Model/Colour	
Details Of Properties	COMFORT TAXI
Vehicle Category	TAXI
Name of Driver	CHOI LAY SIONG
NRIC/Passport Number	S1692274I
Contact Number	
Address	
Postcode	
Insurance Company Name	FIRST CAPITAL INSURANCE LTD
Nature Of Damage	FRONT PORTION
No. Of Passenger (Including Driver)	2

DETAILS OF INJURED PERSON 1

Name	LEE MEW CHUE
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GBG2860K
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	164 TAI KENG GARDENS
Postcode	535436

SKETCH PLAN


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


開發燒臘食品供應商
KAI HUAT ROASTED AND FOODSTUFF SUPPLY




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: 
NRIC/PIN No.:



CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE



CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

MAXUS

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
KAI HUAT ROASTED & FOODSTUFF SUPPLY Blk 3020 Ubi Ave 2 #03-125 Ubi Industrial Park Singapore 408896 Contact No Mobile: 96322894	Cust No/Name	/Kai Huat Roasted & Foodstuff Su
	Reg No/Reg Date	GBG2860K / 12/07/2017
	Date In/Mileage	17/01/2018/ 0
	Chassis No	LSKG4GL12HA058739
	Engine No	19D4N1PYH316K004
	Make/Model	MAXCV/G10D19TMT
	Colour/Trim	GRY / BK Black

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	04/04/2018/ 09:22	DS	323 / ChrisBulaclac	50804

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 TO REPLACE FRONT NUMBER PLATE WITH CASING				50.00 ✓
S MIPNT88088 TO REMOVE & REPLACE RADIATOR ASSY & A/C CONDENSER TOP UP FREON GAS & COOLANT				280.00 ✓
S MIPNT88088 TO REMOVE & RE-INSTALL ENGINE ASSY TO GIVE WAY ACCESS FOR REPAIR				1200 1800.00
S MIPNT88088 TO SET UP TOOLS FOR CELLENT BENCH TO ALIGN FRT CHASSIS				500 1000.00
S MIPNT88088 TO CHECK LIGHTING & WIRING SYSTEM ON FRONT ACCIDENT AREAS				100 200.00
S MIPNT88088 TO PERFORM COMPUTERIZED WHEEL ALIGNMENT				180.00 ✓
S MIPNT88088 TO REPLACE FRT BUMPER, TOP SUPPORT PANEL, BOTH FRONT FENDER ETC STRAIGHTEN, REFORM, ALIGN FRONT ACCIDENT AREAS				8400.00
S MIPNT88088 TOWING FEE				200.00
S MIPNT98088 SPRAY PAINTING ON FRONT ACCIDENT AREAS				2940.00
S MIPNT88088 TO APPLY SEALANT ON FRONT ACCIDENT AREAS				100.00 ✓
S MIPNT88088 TO PERFORM COMPUTER SCANNING, PROGRAMMING & RESETTING.				250.00 ✓
S MIPNT88088 TO REPLACE DASHBOARD ASSY, STEERING AIRBAG, PASSENGER AIRBAG & SENSORS				1800.00
S MIPNT88088				70.00 ✓

not authorized
17/1/18
take photo before repair.
22/1/18

Estimate

Repair sum
\$26,000


6000
120
2700
900

Confirm & accepted by

12450

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



MAXUS

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
KAI HUAT ROASTED & FOODSTUFF SUPPLY Blk 3020 Ubi Ave 2 #03-125 Ubi Industrial Park Singapore 408896 Contact No Mobile: 96322894	Cust No/Name	/Kai Huat Roasted & Foodstuff Su
	Reg No/Reg Date	GBG2860K / 12/07/2017
	Date In/Mileage	17/01/2018/ 0
	Chassis No	LSKG4GL12HA058739
	Engine No	19D4N1PYH316K004
	Make/Model	MAXCV/G10D19TMT
	Colour/Trim	GRY / BK Black

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	04/04/2018/ 09:22	DS	323 / ChrisBulacIac	50804
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	NC00037012	HOSE ARM-FRT SOLV	1.00	8.00 10.00	NA 7.20
M	NC00027778	HOSE ARM-FRT SOLV	1.00	8.00 10.00	NA 7.20
M	NC00027310	PUMP-HDLP WPR	1.00	36.00 10.00	NA 32.40
M	NC00027314	TUBE-FRT WPR FTG	1.00	2.00 10.00	NA 1.80
M	NC00027313	WASHER TANK CAP	1.00	3.00 10.00	NA 2.70
M	NC00025067-4100	HOOD	1.00	1062.00 10.00	Buc 955.80
M	NC00022557	LH HINGE	1.00	21.00 10.00	Buc 18.90
M	NC00020576	RH HINGE	1.00	21.00 10.00	Buc 18.90
M	NC00027304	WIPER TANK	1.00	180.00 10.00	Repair 162.00
M	NC00027305	WIPER TANK CAP	1.00	3.00 10.00	Repair 2.70
M	NC00027306	WIPER WASHER MOTOR	1.00	15.00 10.00	Repair 13.50
M	NC00079506	WIPER TANK HOSE	1.00	14.00 10.00	NA 12.60
M	NC00070693-4100	FENDER-FRT RH	1.00	376.00 10.00	Buc/Buc 338.40
M	NC00070692-4100	FENDER-FRT LH	1.00	376.00 10.00	Buc/Buc 338.40
M	NC00064214	PANEL-FDR INSULATOR	1.00	8.00 10.00	Buc 7.20
M	NC00064213	PANEL-FDR INSULATOR	1.00	8.00 10.00	Buc 7.20
M	NC00073482	RH LINER-FRT W/H	1.00	70.00 10.00	Buc 63.00
M	NC00073481	LH LINER-FRT W/H	1.00	70.00 10.00	Buc 63.00
M	NC00008711	CLIP-FRT LINER	20.00	1.00 10.00	Buc 18.00
M	NC00056663	HEADLAMP LH	1.00	1652.00 10.00	Che 1486.80
M	NC00056664	HEADLAMP RH	1.00	1652.00 10.00	Che 1486.80
M	NC00036427	LAMP-FRT FOG LH	1.00	69.00 10.00	NA 62.10
M	NC00036428	LAMP-FRT FOG RH	1.00	69.00 10.00	Buc 62.10
M	NC00040306	RADIATOR ASM	1.00	315.00 10.00	Buc/Buc 283.50
M	NC00016652	MOUNTING RAD RUB UPR	1.00	3.00 10.00	NA 2.70
M	NC00016653	LWR RAD MTNG RUB	2.00	3.00 10.00	NA 5.40
M	NC00063177	CONDENSER ASM	1.00	421.00 10.00	Buc/Buc 378.90
M	NC00095030	BLOWER-LH	1.00	254.00 10.00	Che/Buc 228.60
M	NC00042394	RH BLOWER	1.00	266.00 10.00	Che/Buc 239.40
M	NC00055035	RAD SHROUD COWL	1.00	86.00 10.00	Che 77.40
M	NC00042587	INTERCOOLER ASM	1.00	437.00 10.00	Buc/Buc 393.30
M	NC00053796-4100	CROSSMEMBER ASM-RAD	1.00	650.00 10.00	Buc 585.00
M	NC00047707-4100	BRACKET-RAD UPR C/MB	1.00	96.00 10.00	Buc 86.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE



CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

MAXUS

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
KAI HUAT ROASTED & FOODSTUFF SUPPLY Blk 3020 Ubi Ave 2 #03-125 Ubi Industrial Park Singapore 408896 Contact No Mobile: 96322894	Cust No/Name	/Kai Huat Roasted & Foodstuff Su
	Reg No/Reg Date	GBG2860K / 12/07/2017
	Date In/Mileage	17/01/2018/ 0
	Chassis No	LSKG4GL12HA058739
	Engine No	19D4N1PYH316K004
	Make/Model	MAXCV/G10D19TMT
	Colour/Trim	GRY / BK Black

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	04/04/2018/ 09:22	DS	323 / ChrisBulaclac	50804

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M NC00042325	SIDE DEFLECTOR RH	1.00	6.00 10.00	Torn 5.40
M NC00045314	RH DEFLECTOR	1.00	3.00 10.00	11 2.70
M NC00051816	UPR RAD INSULATOR	1.00	5.00 10.00	11 4.50
M NC00059699	INSULATOR RADIATOR	2.00	5.00 10.00	11 9.00
M NC00053614	LH DEFLECTOR CONDENS	1.00	26.00 10.00	D.S 23.40
M NC00053615	RH DEFLECTOR CONDENS	1.00	26.00 10.00	D.S 23.40
P NC00008711	CLIP-RAD GRL	10.00	1.00 10.00	see 9.00
M NC00033625	SENSOR TEMP	1.00	7.00 10.00	11 6.30
M NC00048761	SENSOR INL TEMP	1.00	45.00 10.00	11 40.50
M NC00039667	HOUSING FILTER ASM-	1.00	100.00 10.00	11 90.00
M NC00030763	AIR INTAKE SENSOR	1.00	176.00 10.00	11 158.40
M NC00036179	PIPE AIR INTAKE	1.00	97.00 10.00	Cre 87.30
M NC00046742	DASHBOARD ASSY	1.00	1131.00 10.00	Torn 1017.90
M NC00021840	AIRBAG ASM-DRIVER S1	1.00	1600.00 10.00	11 1440.00
M NC00021841	AIRBAG ASM-FRT PASS	1.00	1800.00 10.00	11 1620.00
M NC00016929	SPRING ASM-CLOCK	1.00	64.00 10.00	11 57.60
M NC00024331	MODULE ASM-AIR	1.00	1776.00 10.00	11 1598.40
M NC00016880	HORN ASM-LOW TONE	1.00	43.00 10.00	11 38.70
M JJMZ313950	COOLANT	4.00	26.00 10.00	see 93.60
M WV2800807-500ML	DPS BRAKE FLUID DOT	2.00	6.50 10.00	see 11.70
M JJMZ320215	AT FLUID 1L	2.00	15.50 10.00	see 27.90
M NC10048140	THROTTLE BODY	1.00	1900.00 10.00	D/K 1710.00

Z NOTES
 ACCIDENT ON 10/01/2018 ALONG JUNCTION OF CECIL STREET AND CROSS STREET
 OWNER CLAIMING THIRD PARTY
 REQUIRED REPLACEMENT VAN
 TP : SHA2388T TP INS : FIRST CAPITAL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____

Authorized signatory and company stamp

Parts	17,096.44
Labour	0.00
Standard Menu	0.00
Specialist Job	17,270.00
Others (Lub, etc)	0.00
Sundry	1,080.00
Total (w/o GST)	35,446.44

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



陳林際喙私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

First Capital Insured's Veh No : SHA2388T

Date of Accident : 10 January 2018

*not repair
nu
take the whole
party.
11/1/18
Jay.*

Messrs Kai Huat Roasted And Foodstuff Supply

Date : 10 January 2018

Estimate To Repair GBG2860K - Maxus G10 VAN 6MT

Chassis No : LSKG4GL12HA058739

*lkk - Marcus
11/01/18 1045h*

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	bonnet <i>Bac</i>	\$ 0.00
02	2 ps	bonnet hinges @ \$.00 <i>Self</i>	\$ 0.00
03	1 pc	bonnet insulation padding <i>De</i>	\$ 0.00
04	6 ps	bonnet insulation padding clips @ \$.00 <i>nu</i>	\$ 0.00
05	1 pc	bonnet support rod <i>17X</i>	\$ 0.00
06	1 pc	bonnet support clip-holder <i>nu</i>	\$ 0.00
07	1 pc	bonnet lock <i>Two</i>	\$ 0.00
08	1 pc	bonnet lock cable <i>?</i>	\$ 0.00
09	1 pc	bonnet lock centre brace panel <i>Two</i>	\$ 0.00
10	2 ps	bonnet rubber stopper big @ \$.00 <i>nu</i>	\$ 0.00
11	2 ps	bonnet rubber stopper small @ \$.00 <i>nu</i>	\$ 0.00
12	1 pc	wiper grille <i>BRD</i>	\$ 0.00
13	8 ps	wiper grille clips @ \$.00 <i>nu</i>	\$ 0.00
14	1 pc	wiper grille weatherstrip with foam <i>nu</i>	\$ 0.00
15	2 ps	wiper grille side rubber cover @ \$.00 <i>17X</i>	\$ 0.00
16	1 pc	o/s wiper arm <i>17X</i>	\$ 0.00
17	1 pc	o/s wiper arm bolt cover <i>17X</i>	\$ 0.00
18	1 pc	o/s wiper nozzle <i>17X</i>	\$ 0.00
19	1 pc	wiper tank <i>DIS</i>	\$ 0.00
20	1 pc	wiper tank motor <i>?</i>	\$ 0.00
21	1 pc	wiper tank filler neck <i>?</i>	\$ 0.00
22	1 pc	front support panel <i>Self/Two</i>	\$ 0.00
23	2 ps	front support panel air duct @ \$.00 <i>To.2</i>	\$ 0.00
24	2 ps	headlamps @ \$.00 <i>Mkura o/s BRD</i>	\$ 0.00
25	2 ps	headlamp panels @ \$.00 <i>o/s Self 12c</i>	\$ 0.00
26	2 ps	front fenders @ \$.00 <i>Self/Two</i>	\$ 0.00
27	2 ps	front fender inner liners @ \$.00 <i>To.2</i>	\$ 0.00
28	12 ps	front fender inner liner clips @ \$.00 <i>nu</i>	\$ 0.00
29	2 ps	front fender air baffle rear @ \$.00 <i>?</i>	\$ 0.00
30	6 ps	front fender air baffle clips @ \$.00 <i>?</i>	\$ 0.00
31	1 pc	n/s front fender 1/4 glass with weatherstrip <i>17X</i>	\$ 0.00
32	1 pc	o/s front fender wheel house panel <i>?</i>	\$ 0.00
33	1 pc	horn <i>One</i>	\$ 0.00
34	1 pc	horn stay <i>?</i>	\$ 0.00
35	1 pc	front bumper <i>DIS</i>	\$ 0.00
36	2 ps	front bumper air guide @ \$.00 <i>To.2</i>	\$ 0.00
37	4 ps	front bumper air guide clips @ \$.00 <i>nu</i>	\$ 0.00
38	1 pc	front bumper reinforcement <i>DIS</i>	\$ 0.00
39	2 ps	front bumper side retainers @ \$.00 <i>Self</i>	\$ 0.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

First Capital Insured's Veh No : SHA2388T
Date of Accident : 10 January 2018

Messrs Kai Huat Roasted And Foodstuff Supply

Date : 10 January 2018

Estimate To Repair GBG2860K - Maxus G10 VAN 6MT
Chassis No : LSKG4GL12HA058739

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
40	2 ps	front bumper fog lamps @ \$.00 <i>o/s one 1pc</i>	\$ 0.00
41	2 ps	front bumper fog lamp garnish @ \$.00 <i>o/s mis 1pc</i>	\$ 0.00
42	1 pc	front bumper lower centre air grille ?	\$ 0.00
43	1 pc	front bumper tow cover ?	\$ 0.00
44	1 pc	front bumper absorber foam <i>to...</i>	\$ 0.00
45	2 ps	front bumper headlamp washer nozzle @ \$.00 ?	\$ 0.00
46	2 ps	front bumper headlamp washer nozzle cover @ \$.00 ?	\$ 0.00
47	2 ps	front bumper headlamp washer nozzle pump @ \$.00 ?	\$ 0.00
48	1 set	front bumper headlamp washer hose ?	\$ 0.00
49	2 ps	front bumper headlamp washer hose T-joint @ \$.00 ?	\$ 0.00
50	1 pc	front bumper lower under cover/splashield ?	\$ 0.00
51	6 ps	front bumper lower under cover/splashield clips @ \$.00 ?	\$ 0.00
52	1 pc	outdoor temperature sensor ?	\$ 0.00
53	1 pc	cylinder head-top cover <i>BRW</i>	\$ 0.00
54	1 pc	radiator assy ?	\$ 0.00
55	1 pc	radiator top hose ?	\$ 0.00
56	1 pc	radiator bottom hose ?	\$ 0.00
57	1 pc	radiator expansion tank ?	\$ 0.00
58	1 pc	radiator expansion tank by pass hose ?	\$ 0.00
59	1 pc	radiator and aircon fan assy ?	\$ 0.00
60	1 pc	radiator bypass pipe ?	\$ 0.00
61	2 ps	radiator top mounts @ \$.00 ?	\$ 0.00
62	2 ps	radiator bottom mounts @ \$.00 ?	\$ 0.00
63	1 pc	radiator bottom garnish - cover ?	\$ 0.00
64	1 pc	radiator grille complete with moulding ?	\$ 0.00
65	1 pc	radiator grille upper weatherstrip ?	\$ 0.00
66	1 pc	turbo inlet cooler ?	\$ 0.00
67	1 pc	turbo inlet cooler hose intake ?	\$ 0.00
68	1 pc	turbo inlet cooler hose outlet ?	\$ 0.00
69	1 pc	air-cleaner tank assy ?	\$ 0.00
70	1 pc	air-cleaner tank intake hose ?	\$ 0.00
71	1 pc	air-resonator tank ?	\$ 0.00
72	1 pc	air-cleaner tank air flow sensor ?	\$ 0.00
73	1 pc	brake master pimp <i>21 X</i>	\$ 0.00
74	1 pc	aircon condenser <i>3rd/2nd</i>	\$ 0.00
75	2 ps	aircon condenser top mounts @ \$.00 <i>o/s 7th 1pc</i>	\$ 0.00
76	1 pc	aircon hose - condenser to compressor ?	\$ 0.00
77	1 pc	aircon pipe - compressor to evaporator ?	\$ 0.00
78	1 pc	aircon compressor ?	\$ 0.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

First Capital Insured's Veh No : SHA2388T
Date of Accident : 10 January 2018

Messrs Kai Huat Roasted And Foodstuff Supply

Date : 10 January 2018

Estimate To Repair GBG2860K - Maxus G10 VAN 6MT
Chassis No : LSKG4GL12HA058739

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
79	1 pc	aircon belt ?	\$ 0.00
80	1 pc	power steering belt ?	\$ 0.00
81	1 pc	power steering hose - pump to steering rack ?	\$ 0.00
82	1 pc	power steering fluid ?	\$ 0.00
83	1 pc	power steering reservoir tank ?	\$ 0.00
84	1 pc	water pump 11X	\$ 0.00
85	1 pc	water pump pulley 11X	\$ 0.00
86	1 pc	o/s engine mount ?	\$ 0.00
87	1 pc	n/s engine mount ?	\$ 0.00
88	1 pc	gearbox mount ?	\$ 0.00
89	1 pc	engine mount rear ?	\$ 0.00
90	1 pc	o/s front wheel rim 2 X	\$ 0.00
91	1 pc	o/s front shock absorber 11X	\$ 0.00
92	1 pc	o/s front lower arm 11X	\$ 0.00
93	1 pc	o/s front wheel knuckle 11X	\$ 0.00
94	1 pc	o/s front wheel bearing with hub 11X	\$ 0.00
95	1 pc	ABS module 11X	\$ 0.00
96	1 pc	ABS relay 11X	\$ 0.00
97	2 ps	ABS brake pipe front @ \$.00 11X	\$ 0.00
98	2 ps	ABS brake pipe rear @ \$.00 11X	\$ 0.00
99	1 pc	ABS brake pipe feed 11X	\$ 0.00
100	2 ps	SRS airbag sensor @ \$.00 11X	\$ 0.00
101	1 pc	SRS airbag control module 11X	\$ 0.00
102	1 pc	SRS airbag steering 11X	\$ 0.00
103	1 pc	SRS airbag - spiral sensor steering 11X	\$ 0.00
104	1 pc	SRS airbag front passenger 11X	\$ 0.00
105	1 pc	instrument dashboard assy 11X	\$ 0.00
106	1 pc	driver's seat belt 11X	\$ 0.00
107	1 pc	front passenger's seat belt 11X	\$ 0.00
		Less 10 %	\$ 0.00
<u>SPECIAL NETT ITEMS</u>			
108	1 set	sundries & bulbs 11X	\$ 280.00
109	1 pc	front fender 1/4 glass sealant 11X	\$ 60.00
110	1 pc	front licence plate 54 40	\$ 80.00
111	1 pc	radiator coolant 11X	\$ 20.00
112	1 tin	brake fluid 11X	\$ 0.00

First Capital Insured's Veh No : SHA2388T

Date of Accident : 10 January 2018

TAN

51 D
Tel : 68585

GST

2,180.00
0.00
280.00
60.00
80.00
20.00
=

Messrs Kai Huat Roasted And Foodstuff Supply

0.00

Estimate To Repair GBG2860K - Maxus G10 VAN 6MT
Chassis No : LSKG4GL12HA058739

60.00
30.00
170.00
370.00
60.00

S/No	Quantity	Description
		SPECIAL NETT ITEMS
113	1 pc	o/s front wheel tyre <i>suca</i>
		LABOUR & MISC. CHARGES
01		Towing charges.
02		To check electrical lighting concerned.
03		To dismantle air-con assy, remove and renewal of parts, vac and charge-in gas.
04		To remove and renew SRS airbag sensor, control module, in sensor and spiral sensor.
05		To check steering geometry and computer wheel alignment.
06		To drop o/s front suspension undercarriage parts, remove an renewal of the necessary parts, to perform final checking and testing.
07		To dismantle and refit instrument dashboard, check electrical lightings and re-run, re-route wire harness.
08		To lift-up engine with gearbox and refit the same.
09		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.
10		To remove and renew engine and gearbox mountings.
11		To remove and refit n/s front fender 1/4 glass
12		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.
13		To rust-proofing of the affected areas.
14		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.
15		Putty and spray painting of the affected portion.
		Total

200.00
120.00
1,500.00
1,200.00
=

3,570.00

3,570.00

640.00

=

4,010.00

0.00

650.00

650.00

=

1,270.00

\$ 11	800.00	<i>α</i>
\$	550.00	<i>?</i>
\$ 11	80.00	<i>X</i>
\$ 11	280.00	<i>X</i>
\$	120.00	<i>✓</i>
\$	3,200.00	<i>500</i>
\$	2,200.00	<i>1200</i>
\$	10,260.00	
\$	11,000.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display (damaged part) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18000646/Utbq2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-04-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 2388T	Veh. Inspected	GBG 2860K
Policy No.		Coverage (\$)	0.00
Claim No.	D18000436MFSH	Excess (\$)	0.00
Assign From	TEO SWEE KEONG	Assign Date	11/01/2018
2. Vehicle Particulars & Condition			
Make & Model	MAXUS (M)	c.c	1850
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	LSKG4GL12HA058739	Colour	GREY
Odometer	18477	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/70 R16	HANKOOK	7 mm
L/H Front Tyre	215/70 R16	HANKOOK	7 mm
R/H Rear Tyre	215/70 R16	HANKOOK	7 mm
L/H Rear Tyre	215/70 R16	HANKOOK	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/01/2018	Inspection Date	17/01/2018
Survey held at	TAN LIM MOTOR PTE LTD		
Repairer	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		22 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 2860K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT NUMBER PLATE WITH CASING (SN)	BENT	50.00	50.00
1	DOOR COMPANY STICKER DETAILS (SN)	NECESSARY	70.00	70.00
1	FRT RH SEATBELT ASSY (SN)	ACTIVATED	540.00	540.00
1	FRT LH SEATBELT ASSY (SN)	ACTIVATED	540.00	540.00
1	FASCIA -FRT BPR (W/LP) (SN)	DISTORTED	728.14	728.14
1	LH PLUG-HDLP WASHING (SN)	NECESSARY	5.40	5.40
1	RH PLUG-HDLP WASHING (SN)	NECESSARY	5.40	5.40
1	GRILLE -FRT BPR LWR (SN)	DISTORTED	129.60	129.60
1	LH PANEL -FRT FOGLEIGH (SN)	NOT NECESSARY	9.00	-
1	RH PANEL -FRT FOGLEIGH (SN)	CRACKED	9.00	9.00
1	LH BRKT -HDLP WASHING (SN)	BENT	9.90	9.90
1	RH BRKT -HDLP WASHING (SN)	BENT	9.90	9.90
1	ABSORBER -FRT BPR ENG (SN)	TORN	37.80	37.80
1	LH SUPPORT -BUMPER FR (SN)	BENT	5.40	5.40
1	RH SUPPORT -BUMPER FR (SN)	BENT	5.40	5.40
1	DEFLECTOR UPR GRILLE (SN)	DISTORTED	17.10	17.10
1	RH SIDE DEFLECTOR (SN)	DISTORTED	5.40	5.40
1	GRILLE ASM-RAD (SN)	CRACKED	153.90	153.90
1	FRT LOGO (SN)	NECESSARY	20.70	20.70
4	CLIP -RAD GRL (SN)	NECESSARY	3.60	3.60
1	PANEL ASM-FRT W/S (SN)	TO REPAIR SEE LABOUR	148.50	-
3	CLIP -RAD GRL (SN)	NECESSARY	2.70	2.70
2	NOZZLE -HDLP WA (SN)	NOT NECESSARY	135.00	-
1	HOSE ASM -HDLP WA (SN)	TWISTED	37.80	37.80
1	WIPER WASHER TANK (SN)	DISTORTED	30.60	30.60
1	WASHER MOTOR (SN)	NOT NECESSARY	24.30	-
1	WASHER LVR SENSOR (SN)	NOT NECESSARY	36.90	-
1	HOSE ARM-FRT SOLV (SN)	NOT NECESSARY	7.20	-
1	HOSE ARM-FRT SOLV (SN)	NOT NECESSARY	7.20	-
1	PUMP -HDLP WPR (SN)	NOT NECESSARY	32.40	-

Report Ref No. CS/FCI18000646/Utbq2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TUBE -FRT WPR FTG (SN)	NOT NECESSARY	1.80	-
1	WASHER TANK CAP (SN)	NOT NECESSARY	2.70	-
1	HOOD (SN)	BUCKLED	955.80	955.80
1	LH HINGE (SN)	BENT	18.90	18.90
1	RH HINGE (SN)	BENT	18.90	18.90
1	WIPER TANK (SN)	REPEATED	162.00	-
1	WIPER TANK CAP (SN)	REPEATED	2.70	-
1	WIPER WASHER MOTOR (SN)	REPEATED	13.50	-
1	WIPER TANK HOSE (SN)	NOT NECESSARY	12.60	-
1	FENDER -FRT RH (SN)	BENT / BUCKLED	338.40	338.40
1	FENDER -FRT LH (SN)	BENT / BUCKLED	338.40	338.40
1	PANEL-FDR INSULATOR (SN)	TORN	7.20	7.20
1	PANEL-FDR INSULATOR (SN)	TORN	7.20	7.20
1	RH LINER -FRT W/H (SN)	TORN	63.00	63.00
1	LH LINER -FRT W/H (SN)	TORN	63.00	63.00
20	CLIP -FRT LINER (SN)	NECESSARY	18.00	18.00
1	HEADLAMP LH (SN)	CRACKED	1,486.80	1,486.80
1	HEADLAMP RH (SN)	CRACKED	1,486.80	1,486.80
1	LAMP -FRT FOG LH (SN)	NOT NECESSARY	62.10	-
1	LAMP -FRT FOG RH (SN)	BROKEN	62.10	62.10
1	RADIATOR ASM (SN)	BENT / PUNCTURE	283.50	283.50
1	MOUNTING RAD RUB UPR (SN)	NECESSARY	2.70	2.70
2	LWR RAD MTNG RUB (SN)	NECESSARY	5.40	5.40
1	CONDENSER ASM (SN)	BENT / PUNCTURE	378.90	378.90
1	BLOWER -LH (SN)	CRACKED / JAMMED	228.60	228.60
1	RH BLOWER (SN)	CRACKED / JAMMED	239.40	239.40
1	RAD SHROUD COWL (SN)	CRACKED	77.40	77.40
1	INTERCOOLER ASM (SN)	DENTED / PUNCTURE	393.30	393.30
1	CROSSMEMBER ASM -RAD (SN)	DISTORTED	585.00	585.00
1	BRACKET -RAD UPR C/MB (SN)	TORN	86.40	86.40
1	SIDE DEFLECTOR RH (SN)	TORN	5.40	5.40

Report Ref No. CS/FCI18000646/Utbq2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RH DEFLECTOR (SN)	NOT NECESSARY	2.70	-
1	UPR RAD INSULATOR (SN)	NOT NECESSARY	4.50	-
2	INSULATOR RADIATOR (SN)	NOT NECESSARY	9.00	-
1	LH DEFLECTOR CONDENS (SN)	DISTORTED	23.40	23.40
1	RH DEFLECTOR CONDENS (SN)	DISTORTED	23.40	23.40
10	CLIP -RAD GRL (SN)	NECESSARY	9.00	9.00
1	SENSOR TEMP (SN)	NOT NECESSARY	6.30	-
1	SENSOR INL TEMP (SN)	NOT NECESSARY	40.50	-
1	HOUSING FILTER ASM (SN)	NOT NECESSARY	90.00	-
1	AIR INTAKE SENSOR (SN)	NOT NECESSARY	158.40	-
1	PIPE AIR INTAKE (SN)	CRACKED	87.30	87.30
1	DASHBOARD ASSY (SN)	TORN	1,017.90	1,017.90
1	AIRBAG ASM-DRIVER SI (SN)	ACTIVATED	1,440.00	1,440.00
1	AIRBAR ASM-FRT PASS (SN)	ACTIVATED	1,620.00	1,620.00
1	SPRING ASM -CLOCK (SN)	ACTIVATED	57.60	57.60
1	MODULE ASM-AIR LH (SN)	ACTIVATED	1,598.40	1,598.40
1	HORN ASM -LOW TONE (SN)	NOT NECESSARY	38.70	-
4	COOLANT (SN)	NECESSARY	93.60	93.60
2	DPS BRAKE FLUID DOT (SN)	NECESSARY	11.70	11.70
2	AT FLUID 1L (SN)	NECESSARY	27.90	27.90
1	THROTTLE BODY (SN)	DENTED / CRACKED	1,710.00	1,710.00
			18,296.44	17,288.44
LABOUR				
TO REMOVE & REPLACE RADIATOR ASSY & A/C CONDENSER TOP UP FREON GAS & COOLANT.			280.00	280.00
TO REMOVE & RE-INSTALL ENGINE ASSY TO GIVE WAY ACCESS FOR REPAIR.			1,800.00	1,200.00
TO SET UP TOOLS FOR CELLENT BENCH TO ALIGN FRT CHASSIS.			1,000.00	500.00
TO CHECK LIGHTING & WIRING SYSTEM ON FRONT ACCIDENT AREAS.			200.00	100.00
TO PERFORM COMPUTERIZED WHEEL ALIGNMENT.			180.00	180.00

Report Ref No. CS/FCI18000646/Utbq2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE FRT BUMPER ,TOP SUPPORT PANEL,BOTH FRONT FENDER ETC STRAIGHTEN ,REFORM ,ALIGN FRONT ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF PANEL ASM-FRT W/S.		8,400.00	6,000.00
	TOWING FEE.		200.00	120.00
	SPRAY PAINTING ON FRONT ACCIDENT AREAS.		2,940.00	2,700.00
	TO APPLY SEALANT ON FRONT ACCIDENT AREAS.		100.00	100.00
	TO PERFORM COMPUTER SCANNING ,PROGRAMMING & RESETTING.		250.00	250.00
	TO REPLACE DASHBOARD ASSY ,STEERING AIRBAG,PASSENGER AIRBAG & SENSORS .		1,800.00	900.00
			17,150.00	12,330.00
	GRAND TOTAL		35,446.44	29,618.44
RECOMMENDED COST OF REPAIR SUM				26,000.00

Report Ref No. CS/FCI18000646/Utbq2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.