

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 227M

MAKE :

MODEL : HYUNDAI i40

DATE 10/1/2018 10:05

DOA: 09.01.18

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X Repair</i>			\$ 1,052.20
	Front Bumper Bracket (LH) ?			\$ 24.60
	Front Fender (LH) <i>X Repair</i>			\$ 619.00
	Frt Wheel Hub Cap			\$ 150.70
	SUB TOTAL			\$ 1,846.50
	LESS 20%			\$ 369.30
	DISCOUNTED TOTAL			\$ 1,477.20
	Labour Charge			
	Panel Beating			\$ 560.00 <i>300</i>
	Spray Painting Charge			\$ 400.00 <i>260</i>
	Tuff Kote			\$ 50.00 <i>X</i>
	TOTAL LABOUR			\$ 1,010.00
	ESTIMATE TOTAL			\$ 2,487.20
	<i>Kalvin LKK</i> <i>10/1/18 1440 hrs.</i> <i>3 days.</i> <i>PIP</i> <i>After Repair photo</i>			
	<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modifications is allowed • Supplementary items must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairs Signature: Date:</p> </div>			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Larry Ng