

ASS. CASE OWNER:

CC 4 / AXA1800

LKK:
IDAC:

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II : \$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: NO FOR PERM DON

Driver Tel No.:

(V/L YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

22

If NO or B 28, Ass. Lia:

Repair Cost:

\$

Loss of Rental (LOR):

\$

(

days)

Loss of Use (LOU):

\$

(\$

x

days)

Loss of Income (LOI):

\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$

Medical:

\$

Disbursement:

\$

(e.g. Tow/ Independent)

Legal Cost

\$

Total:

\$

Global Sum \$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

Name 1:

Payee 2: (Strike if N.A.)

\$

Name 2:

Payee 3: (Strike if N.A.)


\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:



COPY SENT

REF: ASM (AXA)

ASSIGNMENT

From: _____ Date: 15.01.2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBB 4239T

at Workshop m/s

Sunc

of

Kaki Bukit

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

16k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GA / PR See _____ Consistent? : Yes or No

Est. Repairs: 12 days Res: Yes or No

Lum Sum: 26 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBB 4239T Yr Regn: 18/2 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: Mif 200 Double 2477

Colour: white A.O: Insured / Std / NI / NA

Sp. Reading: 212266 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MMCTNKB 409D 003623

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal: 7 mm R/Bal: 7 mm

L/Bal: 7 mm L/Bal: 7 mm

D.O.A: 07/1/18 D.O.I: 15/1/18

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: 274567

\$10 k.

(ren 17066 | 63.03%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee

Transportation

3-4-5-6-7-8-9-10

Photos

Others

Add Fee: ☐ : Site Insp. \$☐ : Interview \$☐ : Tech. Insp. \$☐ : Weekend \$

Report Format: _____

Lump Sum / I.B.I: \$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18000653/Uyb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 11-01-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 9451H	Veh. Inspected	GBB 4239T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	10/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/01/2018	Inspection Date	15/01/2018	
Survey held at	SMC AUTO ENGRG WORKS 1 KAKI BUKIT AVE 6 #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

528.00	
2,455.00	
170.00	
655.00	
450.00	
210.00	
230.00	
170.00	
315.00	
246.00	
387.00	
<u>5,816.00</u>	
90%	
5,234.40	CHECK
= 15,427.10 TOTAL	

2,150.00		
1,070.00		
330.00		
185.00		
760.00		
223.00		40.00
1,895.00		30.00
195.00		50.00
460.00		1,800.00
135.00		1,100.00
<u>7,403.00</u>	10.00	200.00
90%	200.00	100.00
6,662.70	210.00	3,320.00
= 10,192.70 REVISED		



SMC AUTO ENGINEERING WORKS

1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

Tel: 6741 1731 Fax: 6744-5746 Email: smc_eplow@ynhoo.com.sg

ROC No:

52889066B

Estimate

Customer

Name: AXA Insurance Singapore Pte Ltd

Address: Motor Claims Department

8 Shenton Way #27-01

AXA Tower

Singapore 068811

Invoice/Ref No:

GBB4239T180110

Date:

11-01-18

Vehicle No:

GBB4239T

Model/Make:

Mitsubishi L200

Double Cab 2.5L Turbo 5M/T Diesel

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Fender 02 pcs (@ \$2,150.00) <i>n/s R o/s Buc</i>	\$ 4,300.00	170 1850
2	Fender Inner Panel 02 pcs (@ \$1,070.00) <i>o/s Buc</i>	\$ 2,140.00	170 1020
3	Canopy Front Structure Panel (Inner Front Panel) <i>n</i>	\$ 2,195.00	X
4	Tail Lamps 02 pcs (@ \$330.00) <i>o/s cre</i>	\$ 660.00	170 315
5	Tail Lamp Side Clips 02 pcs (@ \$15.00) <i>n</i>	\$ 30.00	X
6	Tail Lamp Panel 02 pcs (@ \$264.00) <i>n</i>	\$ 528.00	X
7	Reflector 02 pcs (@ \$185.00) <i>o/s cre</i>	\$ 370.00	X
8	Floor Panel <i>Bodyside/crumpled</i>	\$ 2,455.00	2450
9	Floor Lower Inner Panel <i>n/s</i>	\$ 410.00	N X
10	End Panel <i>Roby</i>	\$ 760.00	N N
11	Lower Lamp <i>o/s cre</i>	\$ 223.00	N N
12	Number Plate Lamps 02 pcs (@ \$85.00) <i>n</i>	\$ 170.00	X
13	Tailgate Lower Member (Support Bar) <i>n</i>	\$ 655.00	X
14	Exhaust Silencer <i>n</i>	\$ 875.00	X
15	Exhaust Mounting 02 pcs (@ \$45.00) <i>n</i>	\$ 90.00	X
16	Tailgate <i>3000</i>	\$ 1,895.00	1415
17	Tailgate Lock 02 pcs (@ \$225.00) <i>o/s Jm</i>	\$ 450.00	700
18	Tailgate Lock Striker 02 pcs (@ \$105.00) <i>n</i>	\$ 210.00	X
19	Tailgate Hinges 02 pcs (@ \$115.00) <i>n</i>	\$ 230.00	X
20	Tailgate Stopper 02 pcs (@ \$85.00) <i>n</i>	\$ 170.00	X
21	Tailgate Inner Cover <i>Bodyside</i>	\$ 315.00	X
22	Tailgate Outer Handle <i>twi/cre</i>	\$ 246.00	X
23	Tailgate Handle Outer Garnish <i>cre</i>	\$ 387.00	X
25	Tailgate Third Brake Light <i>cre</i>	\$ 195.00	X
24	Tailgate "70 KM/H" sticker <i>n</i>	\$ 15.00	105.00
26	Reverse Sensor 1 set <i>cre</i>	\$ 220.00	2025.00
27	Rear Rh Fender Cowling <i>Diy 282</i>	\$ 460.00	N
28	Fender Side Garnish <i>n/s</i>	\$ 347.00	N
29	Fender Mudflap <i>De</i>	\$ 135.00	N
	Remove and refix rear tailgate components	\$ 80.00	40
	To check all wiring & electrical component for proper function	\$ 100.00	30
	Remove and refix rear reverse sensor	\$ 100.00	50
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 2,800.00	2000
	To putty & spray painting & including touch up paint on accident affected areas	\$ 1,800.00	1100
	Remove and refix rear canopy to facilitate repair	\$ 800.00	200
	Remove and replace rear exhaust pipe system to facilitate repairs <i>n</i>	\$ 150.00	X
	To apply Rust Proofing, resal tuff-coating treatment on accident area	\$ 100.00	✓

Total Parts & Labour of estimate for damaged vehicle

\$ 27,066.00

Total amount in Lump Sum Basis for repaired vehicle

\$

SDLS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Affected
slat

n/s #10,000

15/1/18

John, John, John



M/s SMC Auto Engineering Works

15 day.

2-9958

102

89622

126922



SMC AUTO ENGINEERING WORKS

13 Kallang Road, A/C Unit 6 #01-01, A/C Unit Bay @ Kallang Road, Singapore 3417807

Tel: 6741 1731 Fax: 6744 5745 Email: smc_eplo@ yahoo.com.sg

ROC No:

528890668

Estimate

Customer	Invoice/Ref No:	GBB4239T180110
Name: AXA Insurance Singapore Pte Ltd	Date:	11-01-18
Address: Motor Claims Department	Vehicle No:	GBB4239T
8 Shenton Way #27-01	Model/Make:	Mitsubishi L200
AXA Tower		Double Cab 2.5L Turbo 5M/T Diesel
Singapore 068811		

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Fender 02 pcs (@ \$52,150.00) <i>N/S R o/s Buc</i>	\$ 4,300.00	170
2	Fender Inner Panel 02 pcs (@ \$1,070.00) <i>o/s Buc</i>	\$ 2,140.00	170
3	Canopy Front Structure Panel (Inner Front Panel) <i>N</i>	\$ 2,195.00	X
4	Tail Lamps 02 pcs (@ \$330.00) <i>o/s ene</i>	\$ 660.00	170
5	Tail Lamp Side Clips 02 pcs (@ \$15.00) <i>N 1</i>	\$ 30.00	X
6	Tail Lamp Panel 02 pcs (@ \$264.00)	\$ 528.00	7
7	Reflector 02 pcs (@ \$185.00) <i>o/s ene</i>	\$ 370.00	7
8	Floor Panel	\$ 2,455.00	7
9	Floor Lower Inner Panel <i>N S</i>	\$ 410.00	N X
10	End Panel <i>so b/w</i>	\$ 760.00	N N
11	Lower Lamp o/s <i>ene</i>	\$ 223.00	N N
12	Number Plate Lamps 02 pcs (@ \$85.00)	\$ 170.00	7
13	Tailgate Lower Member (Support Bar)	\$ 655.00	7
14	Exhaust Silencers <i>N 1</i>	\$ 875.00	X
15	Exhaust Mounting 02 pcs (@ \$45.00) <i>N 1</i>	\$ 90.00	X
16	Tailgate <i>so b/w</i>	\$ 1,895.00	7
17	Tailgate Lock 02 pcs (@ \$225.00)	\$ 450.00	7
18	Tailgate Lock Striker 02 pcs (@ \$105.00)	\$ 210.00	7
19	Tailgate Hinges 02 pcs (@ \$115.00)	\$ 230.00	7
20	Tailgate Stopper 02 pcs (@ \$85.00)	\$ 170.00	7
21	Tailgate Inner Cover	\$ 315.00	7
22	Tailgate Outer Handle	\$ 246.00	7
23	Tailgate Handle Outer Garnish	\$ 387.00	7
25	Tailgate Third Brake Light <i>ene</i>	\$ 195.00	7
24	Tailgate "70 KM/H" sticker <i>N</i>	\$ 15.00	SN 105-W
26	Reverse Sensor 1 set <i>ene</i>	\$ 220.00	SN 2025-W
27	Rear Rh Fender Cowling <i>D/S</i>	\$ 460.00	N
28	Fender Side Garnish <i>N S</i>	\$ 347.00	N
29	Fender Mudflap <i>De</i>	\$ 135.00	X
	Remove and refix rear tailgate components	\$ 80.00	40
	To check all wiring & electrical component for proper function	\$ 100.00	30
	Remove and refix rear reverse sensor	\$ 100.00	50
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 2,800.00	1800
	To putty & spray painting & including touch up paint on accident affected areas	\$ 1,800.00	1100
	Remove and refix rear canopy to facilitate repair	\$ 800.00	200
	Remove and replace rear exhaust pipe system to facilitate repairs <i>N 1</i>	\$ 150.00	X
	To apply Rust Proofing, reseat tuff coating treatment on accident area	\$ 100.00	✓

Total Parts & Labour of estimate for damaged vehicle

\$ 27,066.00

Total amount in Lump Sum Basis for repaired vehicle

\$

SDLS:

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Affected
late

1/5

15/1/18

John, Mr. After repair



M/s SMC Auto Engineering Works

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3585C

Vehicle Details

Vehicle No.:	GBB4239T
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jan 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	L200 DOUBLE CAB 2.5L TURBO 5M/T DIESEL
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	4D56UCBL2603
Chassis No.:	MMCJNKB409D003623
Maximum Power Output:	-
Open Market Value:	\$24,354.00
Original Registration Date:	18 Feb 2009
First Registration Date:	18 Feb 2009
Transfer Count:	0
Actual ARF Paid:	\$24,354.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3585C
Vehicle Details	
Vehicle No.:	GBB4239T
Vehicle to be Exported:	No
Intended De-registration Date:	15 Jan 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	L200 DOUBLE CAB 2.5L TURBO 5M/T DIESEL
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	4D56UCBL2603
Chassis No.:	MMCJNKB409D003623
Maximum Power Output:	-
Open Market Value:	\$24,354.00
Original Registration Date:	18 Feb 2009
First Registration Date:	18 Feb 2009
Transfer Count:	0
Actual ARF Paid:	\$24,354.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Feb 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$5,212.00
COE Rebate Amount:	\$567.00
Total Rebate Amount:	\$567.00

The information contained herein is correct as at 15 Jan 2018

OK



SELL YOUR CAR BY BIDDING
HIGHEST SELLING PRICE GUARANTEED!
OR GET \$100 CASH!



Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Year Coe Renewal Honda Stream 1.8A



\$2800 Downpayment Monthly
 From \$688 Onwards. Lowest
 3.68%P.A@GV Cars Financing
 GV Credit Pte Ltd StarAd

Browse by Category Sort by Date Posted 20 results/page

14 vehicles

L200

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	L200		Any	Any	Any	Any	Any	Any	Available



Mitsubishi Triton L200 2.5M
Double-Cab (COE till 01/2023)

Fuel Type: Diesel

ABWIN (1994) Pte Ltd

Posted: 15-Jan-2018 Tags: 2008 Mitsubishi Triton, Mitsubishi Triton, Mitsubishi, Triton, Used Mitsubishi

\$50,800

\$10,220 /yr

04-Jan-2008

2,477 cc

Truck

Available



Mitsubishi L200 Single-Cab
(COE till 10/2022)

Fuel Type: Diesel

The Mitsubishi L200, One Of The Most Highly Sought After Pickup In The Market. Renowned For It's Power And Reliability.

Car (S) Pte Ltd

Posted: 15-Jan-2018 Tags: 2007 Mitsubishi L200, Mitsubishi L200, Mitsubishi, L200, Used Mitsubishi

\$34,800

\$7,330 /yr

15-Oct-2007

2,477 cc

Truck

Available

**Mitsubishi L200 Double-Cab**

\$43,800

\$15,550 /yr

09-Nov-2010

2,477 cc

Truck

Available

Fuel Type: Diesel

5 Seater Double Cab 4x4 Turbo Diesel! Rare 1 Owner Only. Low Mileage. Comes With Full Bodykit Worth \$2000. Ideal For Future To Renew COE, Can Be Used For Both Family And Business Use. Can Be Register ...

Posted: 15-Jan-2018 Tags: 2010 Mitsubishi L200, Mitsubishi L200, Mitsubishi, L200, Used Mitsubishi



Mitsubishi L200 Single-Cab
(COE till 10/2022)

Fuel Type: Diesel

Looking For A Unique City And Rural Compatible Drive? Why Not Take A Look At This Beauty Here? Mint And Accident-Free Rare L200. Renowned For Its Power And Reliability. Most Wear And Tear Has Already...

Car (S) Pte Ltd

Posted: 15-Jan-2018 Tags: 2007 Mitsubishi L200, Mitsubishi L200, Mitsubishi, L200, Used Mitsubishi

\$34,800

\$7,330 /yr

15-Oct-2007

2,477 cc

Truck

Available

Car Buying

Car Selling

Car Aftermarket

Buying a pre-owned car, but
 Unsure of its Condition?
 Get, STA Car Evaluation

Car Ownership

On The Move

Lifestyle

**Mitsubishi L200 Single-Cab**

\$29,800

\$11,670 /yr

05-Aug-2010

2,477 cc

158,000 km

Truck

Available

Fuel Type: Diesel

Rare Single Cab Pick Up In The Market! 1 Owner Only. Call Us For Viewing. Doorstep Viewing Available!

Car (S) Pte Ltd

Posted: 14-Jan-2018 Tags: 2010 Mitsubishi L200, Mitsubishi L200, Mitsubishi, L200, Used Mitsubishi



Mitsubishi L200 Single-Cab
(COE till 07/2022)

Fuel Type: Diesel

Mitsubishi L200 Single Cab 4x4 Diesel Turbo Engine! 4 Wheel Drive, New Paintwork, Free Road Tax, Full Checked Plate! Engine/Gear Box Condition Tip Top! High Loan/High Trade-in Available! See To Believ...

Compare

\$33,800

\$7,500 /yr

19-Jul-2007

2,477 cc

Truck

Available



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M006Z7
Our ref: CC4/ASM18000653/Uyb3

Date: 17.01.2018

The Motor Claims Department
M/s AXA INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBB4239T


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15.01.2018 at the premises of M/s Smc Auto Engineering Works and have the following to report:-

Workshop Estimate Amount	: S\$	27,066.00
Revised Estimate Amount	: S\$	10,192.70
"Check" Items Amount	: S\$	5,234.40
Total (Including Check Items)	: S\$	15,427.10
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: TBA days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser



Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time : 11 Jan 2018 / 18:17:06

Receipt Date/Time : 11 Jan 2018 / 18:17:06

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180111-001760

Previous Receipt No. :

**S/N Item Description/
Business Transaction Reference
No.**

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - GBB4239T

As at 10 Jan 2018/10:30:00

Insurance Co: FIRST CAPITAL INS LTD

1 Insurance Enquiry - GBB4239T

Enquiry Fee

20180111181549981333

7.00	0.49	7.49
------	------	------

Sub-Total

7.00	0.49	7.49
------	------	------

Total Before Rounding

7.00	0.49	7.49
------	------	------

Rounding Difference

0.04

Total Amount Payable

7.45

Paid By

xxxxxxxxxxxx4559 Credit Card:
Visa/MasterCard

7.45

Total

7.45

Cash Change

0.00

Tendered Amount

7.45

Excess Refundable Amount

0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

30 APRIL 2018

**SANTA FRESH VEGETABLE SUPPLIER
506 JELAPANG ROAD
SINGAPORE 670506**

Dear Sir/Madam,

**OUR REF : CC4/ASM18000653/Umb3
YOUR REF : GBC 9451H
ACCIDENT INVOLVING GBC 9451H AND GBB 4239T ALONG SLE TOWARD CITY
ON 10.01.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s SMC AUTO ENGRG WORKS, acting on behalf of the owner of GBB 4239T against your motor insurance policy.

Based on the accident report, accident scenario, it was reported that your vehicle had rear-ended the Third Party vehicle GBB 4239T. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to bevanlim@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at bevanlim@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Bevan Lim
Case Handler
DID: 6749 4274
FAX: 6741 4108
Email: bevanlim@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

Our Ref: GBB4239T180110

Date: 03/02/2018

Your Ref:

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

Attn: Motor Claims Department

Dear Sir / Madam

**TRAFFIC ACCIDENT ALONG SLE (BKE WOODLAND AVENUE 2) NEAR 12 KILOMETRES SIGNAGE
INVOLVING GBB4239T AND GBC9451H ON 10/01/2018**

We/I, **Messers STVE PTE LTD** (Nric / ROC No **198703585C**), the registered owners of m/vehicle – **GBB4239T** at all material times of the above accident. Our/my vehicle was surveyed by "AXA" authorized appraiser and we/I based our/my claims on his recommendation for **S\$10,000-00** being the repair for **15 Days** (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle **GBC9451H** when the same was involved in the aforesaid accident with our/my m/vehicle – **GBB4239T**

We/I whereby you are the insurers of m/vehicle **GBC9451H** and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle – **GBB4239T** has suffered loss and damage as follows:

(a) Cost of repairs	S\$ 10,000-00
(b) Pre-Inspection for 02days @S\$120-00	240-00
(c) Lost Of Use for 15 days @S\$120-00	1,800-00
(d) Towing fee	64-20

Total Amount

S\$ 12,104-20

We/I enclose herewith copies of the supporting documents for vehicle no **GBB4239T** as follows:-


- (i) Motor Accident Report;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s SMC Auto Engineering Works**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,


The owner of m/vehicle **GBB4239T**
Messers STVE PTE LTD
cc. SMC Auto Engrg Works



ISLAND RECOVERY SERVICES

BU 1026, Ubi Road 1 #04-146 Singapore 401 9
Telephone: 6747 7400 Email: islandrecovery@gmail.com
Facsimile: 6844 7233 Web: www.islandrecovery.com.sg
GST Reg.No. M90370499P Co. Reg. 53120055L



HOTLINE: 9182 8211

M/S:

LIU'S BROTHER

Cash Sales/ Work Order

NO. 1169241

Date: 10/11/2018

Vehicle No: GBB 4239 T Model: MITSUBISHI L200

Time Start: 1030hr

Time End: 1205hr

From: Woodlands Ave 1, 11/11 Reserved Car

To: 1 Batu Bukit Ave 6, Auto Reg #01-01

Remarks: Rub-rub pick-up

- ☐ Change Tyres / Jump Start
- ☐ Basement / Multi Carpark
- ☐ Using King Dolley

☒ Accident

- ☐ Crane Up / Winch Out
- ☐ Dismantle Shaft / Brake

☐ Use Car Carrier

☐ Open Door

☐ Loaded

AMOUNT S\$ 60/-

GST S\$ 4.20

TOTAL S\$ 64.20

biSAFE³

Chau CK Oh 14413E

Important Note:

Island Recovery Services

Received By

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdeemeanour to your vehicle whilst being transported.



SMC AUTO ENGINEERING WORKS

1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

Tel: 6741 1731 Fax: 6744-5746 Email: smc_eplow@yahoo.com.sg

ROC No: 52889066B

Final Bill

Customer

Name: AXA Insurance Singapore Pte Ltd
Address: Motor Claims Department
8 Shenton Way #27-01
AXA Tower Singapore 068811

Invoice/Ref No: GBB4239T180110

Date: 03-02-18

Vehicle No: GBB4239T

Model/Make: Mitsubishi L200

Double Cab 2.5L Turbo 5M/T Diesel

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Fender 02 pcs (@ \$2,150.00)	\$ 4,300.00	\$ -
2	Fender Inner Panel 02 pcs (@ \$1,070.00)	\$ 2,140.00	\$ -
3	Canopy Front Structure Panel (Inner Front Panel)	\$ 2,195.00	\$ -
4	Tail Lamps 02 pcs (@ \$330.00)	\$ 660.00	\$ -
5	Tail Lamp Side Clips 02 pcs (@ \$15.00)	\$ 30.00	\$ -
6	Tail Lamp Panel 02 pcs (@ \$264.00)	\$ 528.00	\$ -
7	Reflector 02 pcs (@ \$185.00)	\$ 370.00	\$ -
8	Floor Panel	\$ 2,455.00	\$ -
9	Floor Lower Inner Panel	\$ 410.00	\$ -
10	End Panel	\$ 760.00	\$ -
11	Lower Lamp	\$ 223.00	\$ -
12	Number Plate Lamps 02 pcs (@ \$85.00)	\$ 170.00	\$ -
13	Tailgate Lower Member (Support Bar)	\$ 655.00	\$ -
14	Exhaust Silences	\$ 875.00	\$ -
15	Exhaust Mounting 02 pcs (@ \$45.00)	\$ 90.00	\$ -
16	Tailgate	\$ 1,895.00	\$ -
17	Tailgate Lock 02 pcs (@ \$225.00)	\$ 450.00	\$ -
18	Tailgate Lock Striker 02 pcs (@ \$105.00)	\$ 210.00	\$ -
19	Tailgate Hinges 02 pcs (@ \$115.00)	\$ 230.00	\$ -
20	Tailgate Stopper 02 pcs (@ \$85.00)	\$ 170.00	\$ -
21	Tailgate Inner Cover	\$ 315.00	\$ -
22	Tailgate Outer Handle	\$ 246.00	\$ -
23	Tailgate Handle Outer Garnish	\$ 387.00	\$ -
25	Tailgate Third Brake Light	\$ 195.00	\$ -
24	Tailgate "70 KM/H" sticker	\$ 15.00	\$ -
26	Reverse Sensor 1 set	\$ 220.00	\$ -
27	Rear Rh Fender Cowling	\$ 460.00	\$ -
28	Fender Side Garnish	\$ 347.00	\$ -
29	Fender Mudflap	\$ 135.00	\$ -
	Remove and refix rear tailgate components	\$ 80.00	\$ -
	To check all wiring & electrical component for proper function	\$ 100.00	\$ -
	Remove and refix rear reverse sensor	\$ 100.00	\$ -
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 2,800.00	\$ -
	To putty & spray painting & including touch up paint on accident affected areas	\$ 1,800.00	\$ -
	Remove and refix rear canopy to facilitate repair	\$ 800.00	\$ -
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 150.00	\$ -
	To apply Rust Proofing, reseal tuff coating treatment on accident area	\$ 100.00	\$ -


Total Parts & Labour of estimate for damaged vehicle

\$ 27,066.00

Total amount in Lump Sum Basis for repaired vehicle

\$ 10,000.00

SDLS: Ten Thousand Only



M/s SMC Auto Engineering Works

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3585C

Vehicle Details

Vehicle No.: GBB4239T

Vehicle to be Exported: No

Intended De-registration Date: 11 Jan 2018

Vehicle Make: MITSUBISHI

Vehicle Model: L200 DOUBLE CAB 2.5L TURBO 5M/T DIESEL

Primary Colour: Silver

Manufacturing Year: 2008

Engine No.: 4D56UCBL2603

Chassis No.: MMCJNKB409D003623

Maximum Power Output: -

Open Market Value: \$24,354.00

Original Registration Date: 18 Feb 2009

First Registration Date: 18 Feb 2009

Transfer Count: 0

Actual ARF Paid: \$24,354.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

TEO Kitty

From: TEO Kitty
Sent: Wednesday, November 27, 2019 12:50 AM
To: smc_eplow@yahoo.com.sg
Subject: AXA REF - S8M006Z7 - ACCIDENT INVOLVING GBC9451H(AXA) & GBB4239T(YOUR CLIENT) ON 10.01.2018

WITHOUT PREJUDICE

Dear Susan,

Your client has reported in his gia that out of sudden his vehicle break down due to engine stalled in the middle of the road. Your client's vehicle sudden breakdown with no warning has left our insured no time to react on time to prevent this accident from happening.

Due to mechanical fault of your client's vehicle, we are of the opinion that this accident is not caused by our insured. As such, we would like to reject your claim.

Regards

Kitty Teo
Specialist, Motor Claims Department
AXA Insurance Pte Ltd

8 Shenton Way, #24-01 AXA Tower, Singapore 068811
Email: kitty.teo@axa.com.sg
Customer Care hotline 1800-880 4888
www.axa.com.sg

Please consider the environment before printing this message
This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

----- Original Message -----

From: Eng Pau Low [smc_eplow@yahoo.com.sg]
Sent: 15/11/2019 18:31
To: cst@axa.com.sg; shekhar.batham@axa.com.sg
Subject: [EXTERNAL] Our Ref: GBB4239T180110 Your Ref: CAS201801112404473

TRAFFIC ACCIDENT ALONG SLE (BKE WOODLAND AVENUE 2) NEAR 12KILOMETRES SIGNAGE INVOLVING GBB4239T AND GBC9451H ON10/01/2018 We refer to our letter dated 13/11/2019.
The case was happened almost going to 2 years.

We have yet to receive your favourable response

Kindly let us hear from you in respect of our client's claim as soon as possible.
Thank
Regard
Susan LowSMC Auto Engrg Ws

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.
ref:_00Db0Ky1f._5002v2ZW267:ref



Re:RE: Re:RE: Please let me have your opinion on the liability

Type

🔗 Question

Message

Hi CCL, Please refer to Saw Theng's message dated 29.11.2018 whereby she informed to reject TP claim. TP driver admitted he suddenly stop his vehicle because of his vehicle break down.

Reply

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Monday, 23 March 2020 4:39 PM
To: smc_eplow@yahoo.com.sg
Subject: YOUR REF: GBB 4239T (OUR REF: CC4/ASM18000653/Ugb3s2) *** ACCIDENT INVOLVING GBC 9451H & GBB 4239T ON 10/01/2018 ***

Your Ref: **GBB 4239T** Without Prejudice
Our Ref: CC4/ASM18000653/Ugb3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING GBC 9451H (AXA) & GBB 4239T ON 10/01/2018

We refer to the above matter.

We have reviewed the matter and we are of the view that our driver is not liable for the accident. Your client admitted he suddenly stop his vehicle because of his vehicle break down and thus leads to the collision.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's matter.

Thank you.

Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."


Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18000653/Uga3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KITTY TEO		Date : 31-03-2020 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBC 9451H	Veh. Inspected	GBB 4239T
Policy No.	VCA/P1839374	Coverage (\$)	0.00
Claim No.	S8M006Z7	Excess (\$)	0.00
Assign From	KITTY TEO	Assign Date	15/01/2018
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI L200 DOUBLE (M)	c.c	2477
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MMCJNKB409D003623	Colour	WHITE
Odometer	212266	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205 R16	FALKEN	7 mm
L/H Front Tyre	205 R16	FALKEN	7 mm
R/H Rear Tyre	205 R16	FALKEN	7 mm
L/H Rear Tyre	205 R16	FALKEN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/01/2018	Inspection Date	15/01/2018
Survey held at	SMC AUTO ENGRG WORKS 1 KAKI BUKIT AVE 6 #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 4239T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	REAR FENDER @ \$2150.00 (CONSISTENT)	N/S TO REPAIR SEE LABOUR / O/S BUCKLED	4,300.00	1,850.00
2	REAR FENDER INNER PANEL @ \$1070.00 (CONSISTENT)	O/S BUCKLED	2,140.00	1,020.00
1	REAR CANOPY FRONT STRUCTURE PANEL (INNER FRONT PANEL) (CONSISTENT)	TO REPAIR SEE LABOUR	2,195.00	-
2	REAR TAIL LAMPS @ \$330.00 (CONSISTENT)	O/S CRACKED	660.00	315.00
2	REAR TAIL LAMP SIDE CLIPS @ \$15.00 (CONSISTENT)	NOT NECESSARY	30.00	-
2	REAR TAIL LAMP PANEL @ \$264.00 (CONSISTENT)	TO REPAIR SEE LABOUR	528.00	-
2	REAR REFLECTOR @ \$185.00 (CONSISTENT)	O/S CRACKED	370.00	185.00
1	REAR FLOOR PANEL (CONSISTENT)	BODY DENTED / CRUMPLED	2,455.00	2,450.00
1	REAR FLOOR LOWER INNER PANEL (CONSISTENT)	NO SUCH PARTS	410.00	-
1	REAR END PANEL (CONSISTENT)	BADLY DENTED	760.00	715.00
1	REAR LOWER LAMP (CONSISTENT)	O/S CRACKED	223.00	223.00
2	REAR NUMBER PLATE LAMPS @ \$85.00 (CONSISTENT)	NOT NECESSARY	170.00	-
1	REAR TAILGATE LOWER MEMBER (SUPPORT BAR) (CONSISTENT)	TO REPAIR SEE LABOUR	655.00	-
1	REAR EXHAUST SILENCER (CONSISTENT)	NOT NECESSARY	875.00	-
2	REAR EXHAUST MOUNTING @ \$45.00 (CONSISTENT)	NOT NECESSARY	90.00	-
1	REAR TAILGATE (CONSISTENT)	BADLY DENTED	1,895.00	1,415.00
2	REAR TAILGATE LOCK @ \$225.00 (CONSISTENT)	O/S JAMMED	450.00	225.00
2	REAR TAILGATE LOCK STRIKER @ \$105.00 (CONSISTENT)	NOT NECESSARY	210.00	-
2	REAR TAILGATE HINGES @ \$115.00 (CONSISTENT)	NOT NECESSARY	230.00	-
2	REAR TAILGATE STOPPER @ \$85.00 (CONSISTENT)	NOT NECESSARY	170.00	-
1	REAR TAILGATE INNER COVER (CONSISTENT)	BADLY DENTED	315.00	315.00
1	REAR TAILGATE OUTER HANDLE (CONSISTENT)	TWISTED / CRACKED	246.00	246.00
1	REAR TAILGATE HANDLE OUTER GARNISH (CONSISTENT)	CRACKED	387.00	387.00
1	REAR TAILGATE THIRD BRAKE LIGHT (CONSISTENT)	CRACKED	195.00	195.00
1	REAR RH FENDER COWLING (CONSISTENT)	DISTORTED	460.00	282.00

Report Ref No. CC4/ASM18000653/Uga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR RH FENDER SIDE GARNISH (CONSISTENT)	NO SUCH PARTS	347.00	-
1	REAR RH FENDER MUDFLAP (CONSISTENT)	DEFORMED	135.00	135.00
	LESS 10% DISCOUNT		-	-995.80
			20,901.00	8,962.20
	SPECIAL NETT ITEMS			
1	REAR TAILGATE "70KM/H" STICKER (SN) (CONSISTENT)	NECESSARY	15.00	10.00
1	SET REAR REVERSE SENSOR (SN) (CONSISTENT)	CRACKED	220.00	200.00
			235.00	210.00
	LABOUR			
	REMOVE AND REFIX REAR TAILGATE COMPONENTS.		80.00	40.00
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		100.00	30.00
	REMOVE AND REFIX REAR REVERSE SENSOR.		100.00	50.00
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS. INCLUSIVE OF THE REPAIR OF N/S REAR FENDER, REAR CANOPY FRONT STRUCTURE PANEL, REAR TAIL LAMP PANEL AND REAR TAILGATE LOWER MEMBER (SUPPORT BAR).		2,800.00	2,000.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		1,800.00	1,100.00
	REMOVE AND REFIX REAR CANOPY TO FACILITATE REPAIR.		800.00	200.00
	REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILITATE REPAIRS.	NOT NECESSARY	150.00	-
	TO APPLY RUST-PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		100.00	100.00
			5,930.00	3,520.00
GRAND TOTAL			27,066.00	12,692.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,000.00

Report Ref No. CC4/ASM18000653/Uga3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.