

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD65Y - AIG**AAD1801-088***Not Authorized
Liam & Joel*

Vehicle No.:	SHD65Y - CANDY
Chassis No.:	KL1LA69RJBB092814
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0
Date of Accident :	05.01.2018
Third Party Insurer :	AIG

PART			LIST	
1	1	Rear Bumper	\$	R 1,202.00
2	1	Rear Bumper Beam	\$	R 239.94
3	1	Rear Bumper Centre Absorber	\$	SL 260.00
4	1	Rear Bumper Side Retainer RH	\$	SL 68.76
5	1	Rear Bumper Side Retainer LH	\$	SL 68.76
6	1	Rear Bumper Reflectors RH	\$	SL 119.74
7	1	Rear Bumper Reflectors LH	\$	SL 119.74
8	1	Rear Bumper Tow Hook Cover	\$	SL 93.00
9	1	Rear End Panel Outer	\$	R 623.76
10	1	Rear End Panel Inner Trim	\$	SL 263.84
11	1	Bootlid	\$	R 973.00
12	1	Bootlid inner trim board	\$	SL 400.00
13	1	Bootlid Weatherstrip	\$	SL 344.28
14	1	Bootlid Lock - Top	\$	R 466.56
15	1	Bootlid 'CHEVROLET' Badge	\$	SL 120.62
16	1	Bootlid Logo	\$	SL 138.84
17	1	Bootlid 'EPICA LT' Badge	\$	SL 119.84
18	1	Bootlid Reflector Centre	\$	SL 217.97
19	1	Bootlid Reflector RH	\$	SL 128.40
20	1	Bootlid Reflector LH	\$	SL 128.40
21	1	Bootlid Hinge RH	\$	R 120.00
22	1	Bootlid Hinge LH	\$	R 120.00
23	1	Rear Tail Lamp RH	\$	SL 479.30
24	1	Rear Tail Lamp Panel RH	\$	R 359.00
25	1	Rear Tail Lamp LH	\$	SL 479.30
26	1	Rear Tail Lamp Panel LH	\$	R 359.00
27	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	R 1,110.00
28	1	Rear Fender RH	\$	R 1,145.00
29	1	Rear Fender Inner Trim RH	\$	SL 418.44
30	1	Rear Fender LH	\$	R 1,145.00

X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-088**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD65Y - AIG

31	1	Rear Fender Inner Trim LH	\$	<i>sn</i> 418.44 X
----	---	---------------------------	----	--------------------

TOTAL	\$	12,250.93
10%	\$	1,225.09
	\$	11,025.84

Specical Nett

1	1Set	Licence Plate With Holder	\$	<i>sn</i> 60.00	} X
2	1Set	Bootlid inner trim board Clip	\$	<i>na</i> 40.00	
3	1Set	Rear Bumper Parking Sensor	\$	<i>sn</i> 300.00	
4	1Set	Rear Bumper Fastener Clip	\$	<i>na</i> 44.00	
5	1Set	Rear Fender Inner Trim Clip LH	\$	<i>na</i> 30.00	
6	1Set	Rear Fender Inner Trim Clip RH	\$	<i>na</i> 30.00	
7	1Set	Rear Bumper End Dust Cover Clip	\$	<i>na</i> 30.00	
8	1	Rear Boot Sticker 'Trans-cab'	\$	<i>na</i> 30.00	
9	1	Rear Boot Sticker '6555-3333'	\$	<i>na</i> 30.00	
10	1	Rear Exhaust Mounting	\$	<i>sn</i> 10.00	
11	2	Rear Windscreen Sealant	\$	<i>na</i> 80.00	
12	1	Rear Windscreen Inner Sponge Seal	\$	<i>na</i> 100.00	
13	1	Spare Tyre	\$	<i>sn</i> 180.00	
14	1	Spare Wheel Rim	\$	<i>sn</i> 126.74	

TOTAL	\$	1,090.74
TOTAL PARTS	\$	12,116.58

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	<i>na</i> 2,700.00 X
----	----------------------

To Check Electrical Lighting Concerned.

\$	<i>na</i> 170.00 X
----	--------------------

To Rust-Proofing Of The Affected Areas.

\$	<i>na</i> 170.00 X
----	--------------------

Putty And Spray Painting Of The Affected
Portion.

\$	2,800.00 <i>200</i>
----	---------------------

To reinstall rear bumper parking sensor.

\$	<i>na</i> 170.00 X
----	--------------------

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-088**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD65Y - AIG

To transfer of end panel fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00 X
To transfer of boot fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 X
Towing fees	\$	<i>nn</i> 120.00 X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
	\$	7,410.00
TOTAL	\$	19,526.58

Repair Days~~10 Days~~
1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: