



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2011 HONDA ACCORD 2.4 AUTO 2011 (SKE2115H)

Date of Loss

8 January 2018

Time of Loss

11.00

Loss Description

SKE2115H (INSD) HIT IN REAR OF SLE6097M

Comment

Workshop Details

Total Rebate Amount

51897

Nett Loss Amount

\$41,103.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

16/05/2018



Days of work completion *

125



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SKE2115H

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

15/02/2012



Mileage

261257

Age of Vehicle

5

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2011

ASSESSMENT INFO...

2011

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

WANG NING BO

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... HONDA

ASSESSMENT INFO... HONDA

CATEGORY Model

POLICY INFORMAT... ACCORD 2.4 AUTO 2011

ASSESSMENT INFO... ACCORD 2.4L 5AT

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... MRHCP2630BP070017

CATEGORY Date of Birth

FNOL INFORMATI... 28 November 1984

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 33

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

FNOL INFORMATI... 11

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... K24Z24950573

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 2007

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... 37 CHOA CHU KANG LOOP #01-04

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S8471046F

POST SURVEY INF...

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

11/01/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

500

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

225/50R17

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

225/50R17

Front left side

BRIDGESTONE6mm

Front right side

BRIDGESTONE6mm

Rear left side

BRIDGESTONE6mm

Rear right side

BRIDGESTONE6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/J BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIC (PART
		1	1			FACEFR.BUMPER (SN)			Cracked	403.32				403.32	Revie
		2	1			BEAMR FR BUMPER UPPER (SN)			Necessary	6.82				6.82	Revie
		3	1			BEAML FR BUMPER UPPER (SN)			Necessary	6.82				6.82	Revie
		4	1			CLIP ABUMPER (10 PCS) (SN)			Necessary	25.35				25.35	Revie
		5	1			BEAM COMPFR.BUMPER			Serviceable	0	0	0	0	0	Deny
		6	1			FENDER COMPR FR (SN)			Damaged	396.89				396.89	Revie
		7	1			FENDER ASSYR.FR.LINER (SN)			Deformed	83.26				83.26	Revie
		8	1			HEADLIGHT UNITR (SN)			Cracked	369.33				369.33	Revie
		9	1			BULBHEADLIGHT (D2R)(HID) (SN)			Cracked	227.76				227.76	Revie
		10	1			IGNITERHID (SN)			Damaged	196.88				196.88	Revie
		11	1			CONTROL UNIT ASSY (SN)			Damaged	212.55				212.55	Revie
		12	1			PANEL COMPR.FR.DOOR (SN)			Repair	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIC (PART
		13	1			DISKALUMINIUM WHEEL (SN)			Cut	341.51				341.51	Revie
		14	1			BEARING ASSYFR HUB (SN)			Serviceable	0	0	0	0	0	Deny
		15	1			HUB ASSYFR (SN)			Serviceable	0	0	0	0	0	Deny
		16	1			KNUCKLE COMP FR (SN)			Serviceable	0	0	0	0	0	Deny
		17	1			ARM COMPR.FR.UPPER (SN)			Serviceable	0	0	0	0	0	Deny
		18	1			ARM COMPR FR LOWER (SN)			Serviceable	0	0	0	0	0	Deny
		19	1			FORKR SHOCK ABSORBER (SN)			Serviceable	0	0	0	0	0	Deny

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	R
		1		REMOVE & REPLACE FR R UNDERCARRIAGE PARTS (N)	0	0	0	Deny		
		2		COMPUTERISED WHEEL ALIGNMENT (N)	180	0	0	Reviewing		
		3		INSPECT FR LIGHTING MECHANISM & FOCUS	140	0	0	Reviewing		
		4		REMOVE & RENEW FRONT BUMPER SENSORS	140	0	0	Reviewing		
		5		REMOVE & RENEW FR R FENDER	2240	0	0	Reviewing		
		6		SPRAY PAINTING IN REPAIRED OR REPLACED AREAS. (3P)	1350	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 7 DAYS	Reviewing			
		2	SUNDRIES	Reviewing	30	NECESSARY	
		3	CLIPINNER FENDER (9 PCS) (SN)	Reviewing	22.81	NECESSARY (SUPPLEMENTARY)	
		4	TANKWASHER (SN)	Reviewing	76.83	DEFORMED (SUPPLEMENTARY)	
		5	PUMP SETWASHER (SN)	Reviewing	38.48	DAMAGED (SUPPLEMENTARY)	
		6	BEAMR FR BUMPER UPPER (SN)	Reviewing	24.57	CRACKED (SUPPLEMENTARY)	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$6,013.18

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$4,050.00	\$4,050.00
Spare Parts	\$2,270.49	\$2,270.49
Miscellaneous	\$192.69	\$192.69
Excess	-\$500.00	-\$500.00

Submit for Review