

ASS. REQ. BY

REF: CS/MSG18000671 / Gtd3n2

Meimen

GQ

ASSIGNMENT (Office)

From Person

Christina Wong

MSIG

Date/Time 11/01/2018 @ 1:09pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SKX 4831K

Insured

GU 1147K

at Workshop m/s

Trans Eurokars

Id.

6395 7875

of

No. 5 Ubi close, 408605

Policy No.

A28982994MKC

Claim No.

545283

Sum Insured

Excess

Make of Veh.

(Client's Record)

15/01/2018 @ 3pm owner waiting

CA / REV / REP. / REV 24 HRS

wp

Date/Time 2:01pm @ 11/01/2018

Person Contacted

Ronald

Vehicle IN OUT

Date/Time

Action/Instruction

✓

Estimate

SKX 4831K-X

GU 1147K-X

Part by Part \$4798.69, 5days (fed. 2550.20, 34%)

Xhe.

MSIG

15/01/18

SKX 4831K

15 Dec 2015

Estimated Cost

00 TR NS TRBS 00 RES BLANK NY

To Road (Vehicle) SKX 4831K

at (Location) Trans Eurokars

at (Time) No. 5 Ubi Close

Insured

Policy No.

Client No.

Sum Insured

Excess

Client's Record

5pm @ owner waiting

Make of Car

Ronab

Policy Condition

Remarks: The veh had commenced its repair at the time of inspection.

N.S.	O.S.

Before/Accident value

CAO Accident Room Consistent? Yes or No

CAO Rep. Consistent? Yes or No

Est. Repair days Pass: Yes or No

Est. Repair days Pass: Yes or No

CAO REV / REP / 24 HRS 'wp'

Date

Repair Contacted

Vehicle IN/OUT

Date Time Action Instruction

Make

Mazda 2

1496

Model

red

at (Location)

36397

Engine No.

Chassis

JM6DJ2HAA01100649

Get Good Good Fair Poor Burnt

Steering Inter. Jammed Leaked Burnt or

Brake Inter. Jammed Leaked Burnt or

Mod. Nil STD ARM

Tyre Size

185/6.0R16

11

BS / DUN / EXNOVA GH / RS / LIZA / MIC / DHTSU / PR / SLW

TOYO / YOKO or

Front

Rear

Front

Rear

Survey needed

w/s

15-01-18 5pm

Cost of Damages Front Rear OS NS / U.C. / Roof/Top

N/S Rear

The U.C. / Chassis frame Body Structure affected due to collision

RECEIVED 28 MAR 2018

Use The Report

Preli. Report

Final Report

28/3 Typist

Days Of Repair

5

Resurvey No. of Trip

1

Survey Fee

Transport

200

10

210

Add Fee

Storage

Handling

Transport

200

10

210

200
10

210

TP

4798.69

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2018		11 Jan 2018 13:09 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	APPETIZER PTE LTD, Co. Reg. No.: 200800095R		
Main Claimant:	ONG TECK SWEE, RAYMOND, ID: S8532661I		
Vehicle Reg. No.:	SKX4831K	Date of Loss:	05/01/2018 17:00 - :59
Claim Type:	TP / 545283	Policy/Cover Note No.:	A28982994MKC (Comprehensive) Coverage: 30/06/2017 - 26/06/2018
Vehicle Reg. No. (Insured):	GU1147K	Policy No. (Claimant):	
		Excess:	
Repairer:	Trans Eurokars Pte Ltd () NO. 5 UBI CLOSE, SINGAPORE, 408605 Ubi - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/01/2018]		
Driver/Custodian (Insured):	WANG LIPING (), NRIC: G5061085W, Tel: +6597652428		
Adj Asg. Remarks:	Survey on 15/1/18, 3pm, Owner waiting.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18000671/Gtd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 11-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GU 1147K	Veh. Inspected	SKX 4831K
Policy No.	A28982994MKC	Coverage (\$)	0.00
Claim No.	545283	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	11/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/01/2018	Inspection Date
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/01/2018 10:42
Date Of Accident	05/01/2018 18:00
Exact Location Of Accident	PUNGGOL SAFRA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX4831K
Insured/Policyholder	
Name Of Registered Owner	ONG TECK SWEE, RAYMOND
NRIC No	S8532661I
Email Address	RAY297A@HOTMAIL.SG
Mobile Phone No	(LOCAL) +65-91599874
Alternative Phone No	OTHERS-91599874

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA 2
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100448685-02
Cover Note Number	

Driver

Name of Driver	ONG TECK SWEE, RAYMOND
NRIC No	S8532661I
Date Of Birth	02/10/1985
Occupation	INDOOR
Date Of Driving Pass	31/05/2006
Driving Experience	11 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91599874
Fax Number	
Contact Number	OTHERS-91599874
Email Address	RAY297A@HOTMAIL.SG

Address	BLK 415B FERNVALE LINK #14-54
Postcode	792415
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GU1147K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	WANG LI PING
NRIC/Passport Number	G5061085W
Contact Number	97652428
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	2


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 5 Jan 2018, at about 1800hrs, my car (SKX 4831K) was parked beside a white van (GU 1147K). The van reversed towards the left side of my car resulted some damages to my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2661I
Vehicle Details	
Vehicle No.:	SKX4831K
Vehicle to be Exported:	No
Intended De-registration Date:	16 Jan 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 5-DOOR HATCHBACK 1.5L SP.6EAT
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	P520334653
Chassis No.:	JM6DJ2HAA01100649
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$16,255.00
Original Registration Date:	15 Dec 2015
First Registration Date:	15 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$6,255.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Dec 2025
PARF Rebate Amount:	\$4,691.00
Intended COE Rebate Details	
COE Expiry Date:	14 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$59,200.00
COE Rebate Amount:	\$46,826.00
Total Rebate Amount:	\$51,517.00

The information contained herein is correct as at 16 Jan 2018

OK



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



MSIG INSURANCE SINGAPORE P/L 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Ong Teck Swee Raymond ADDRESS : Blk 415B Fernvale Link #14-54 Singapore 792415 TEL : 91599874	WIP : 55352 EXCESS : DATE: 8-Jan-18
VEH NO :	SKX4831K	DATE IN :	CONTACT PERSON : RONALD 6395 7875
CHASSIS NO :	JM6DJ2HAA01100649	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA2 HB	DATE REG.: 15-Dec-15	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	REAR BUMPER / Cut 1	MDC3R-50-221BBB	\$ 850.80
2	RETAINER(LHS), REAR BUMPER / 1	MD09H-50-2J1	\$ 25.90
3	GROMMET, REAR BUMPER / 4	MBHN1-50-0Z1A	\$ 10.00
4	FASTENER, REAR BUMPER / 7	MB45A-56-146A	\$ 19.60
5	GROMMET, REAR BUMPER / 1	M9991-00-501	\$ 2.80
6	LHS TAILLAMP X NN 1	MD09L-51-160D	\$ 728.00
7	GUARD(LHS), STONE / NCC - 1	MD09H-50-4R2	\$ 14.00
8	WHEEL, DISC (LHR) / Cut 1	M9965-40-5560	\$ 881.00
TOTAL PARTS			\$ 2,532.10
LESS 10%			\$ 253.21
TOTAL PARTS COST			\$ 2,278.89

Labour Description

1	MZ-BR-REAR01	TO REPLACE REAR BUMPER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	630	\$ 1,260.00
2	MZ-SP-SREAR9	TO RESPRAY REAR BUMPER AND REAR FENDER.	1200	\$ 1,800.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	315	\$ 630.00
4	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	NETT ✓	\$ 120.00
5	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT ✓	\$ 560.00
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00

7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
8	MZ-BR-SUNDRI	SUNDRIES.	20	NETT \$ 100.00
			TOTAL LABOUR	\$ - \$ 5,070.00
			TOTAL PARTS	\$ - \$ 2,278.89
			TOTAL	\$ - \$ 7,348.89
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

4-5 Days.

before paint photos.

Guo Qiang - P2880282

15/1/18.

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



MSIG INSURANCE SINGAPORE P/L 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Ong Teck Swee Raymond ADDRESS: Blk 415B Fernvale Link #14-54 Singapore 792415 TEL: 91599874		WIP: 55352 EXCESS: DATE: 8-Jan-18	
VEH NO:	SKX4831K	DATE IN:		CONTACT PERSON:	RONALD 6395 7875
CHASSIS NO:	JM6DJ2HAA01100649	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA2 HB	DATE REG.:	15-Dec-15	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MDC3R-50-221B8B	\$ 850.80	\$ 850.80
2	RETAINER(LHS), REAR BUMPER	1	MD09H-50-2J1	\$ 25.90	\$ 25.90
3	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	\$ 10.00	\$ 10.00
4	FASTENER,REAR BUMPER	7	MB45A-56-146A	\$ 19.60	\$ 19.60
5	GROMMET, REAR BUMPER	1	M9991-00-501	\$ 2.80	\$ 2.80
6	LHS TAILLAMP	1	MD09L-51-160D		\$ 728.00
7	GUARD(LHS), STONE	1	MD09H-50-4R2	\$ 14.00	\$ 14.00
8	WHEEL,DISC (LHR)	1	M9965-40-5560	\$ 881.00	\$ 881.00
TOTAL PARTS				\$ 1,804.10	\$ 2,532.10
LESS 10%				\$ 180.41	\$ 253.21
TOTAL PARTS COST				\$ 1,623.69	\$ 2,278.89
Labour Description					
1	MZ-BR-REAR01	TO REPLACE REAR BUMPER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		\$ 630.00	\$ 1,260.00
2	MZ-SP-SREAR9	TO RESPRAY REAR BUMPER AND REAR FENDER.		\$ 1,200.00	\$ 1,800.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.		\$ 315.00	\$ 630.00
4	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.		\$ 120.00	\$ 120.00
5	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		\$ 560.00	\$ 560.00
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 150.00	\$ 250.00
7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 180.00	\$ 350.00

8	MZ-BR-SUNDRI	SUNDRIES.		\$ 20.00	\$ 100.00
			TOTAL LABOUR	\$ 3,175.00	\$ 5,070.00
			TOTAL PARTS	\$ 1,623.69	\$ 2,278.89
			TOTAL	\$ 4,798.69	\$ 7,348.89
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ 4,798.69	
			GST 7%	\$ 335.91	\$ -
			GRAND TOTAL	\$ 5,134.60	\$ -

REMARKS: SKX4831K

5 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000671/GTD3N2

Date: 29/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28982994MKC
Claimant Vehicle No :	SKX4831K	Insured Vehicle No :	GU1147K
Date of Loss:	05/01/2018	Nature of Claim:	TP
		Claim No:	545283

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX4831K	Engine No:	P520334653
Make & Model:	MAZDA 2, 1.5 HATCHBACK (A)	Chassis No:	JM6DJ2HAA01100649
Reg. Date:	15/12/2015 (Man. Year: 2015)	Odometer:	36397 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R16	Rear Tyre Size:	185/60R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,378.89	1,643.69	735.20	30.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,970.00	3,155.00	1,815.00	36.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,348.89	4,798.69	2,550.20	34.70
+ GST 7.00/7.00% (S\$)	514.42	335.91	178.51	34.70
Nett Amount (S\$)	7,863.31	5,134.60	2,728.71	34.70

INSPECTION

Date of Assignment:	11/01/2018	
Date Inspected:	15/01/2018	Inspected At: Trans Eurokars Pte Ltd NO. 5 UBI CLOSE, SINGAPORE Singapore 408605

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2018)
Parts: 144	MAZDA 2 1.5 HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX4831K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	850.80 FL	*850.80 FL
2	1		*RETAINER (LHS) REAR BUMPER	Necessary	25.90 FL	*25.90 FL
3	4		*GROMMET,REAR BUMPER	Necessary	10.00 FL	*10.00 FL
4	7		*FASTENER,REAR BUMPER	Necessary	19.60 FL	*19.60 FL
5	1		*GROMMET,REAR BUMPER	Necessary	2.80 FL	*2.80 FL
6	1		*LHS TAILLAMP	Not Necessary	728.00 FL	*- FL
7	1		*GUARD (LHS),STONE	Necessary	14.00 FL	*14.00 FL
8	1		*WHEEL,DISC (LHR)	Cut	881.00 FL	*881.00 FL
9	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,632.10	1,824.10
- List Item Discount on L Items 10.00/10.00% (S\$)	253.21	180.41
Total Parts (S\$)	2,378.89	1,643.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER,REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,260.00	630.00
2	TO RESPRAY REAR BUMPER AND REAR FENDER	New	1,800.00	1,200.00
3	TO TRANSFER REVERSE SENSORS	New	630.00	315.00
4	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	120.00
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	560.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
Gross Labour Cost (S\$)			4,970.00	3,155.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >