

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9247E -

AAD1801-101

*Not Authorized
C/Sy & 2600*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD 9247E - JHOW
VF1ABL15AUC279594
RENAULT
LATITUDE
07.01.2018

AIC

PART			LIST	
1	1	BUMPER COVER REAR	\$	<i>R</i> 1,108.46 —
2	1	BUMPER LOWER REAR	\$	<i>R</i> 768.84 —
3	1	BUMPER BRACKET CTR REAR	\$	<i>S</i> 113.47 X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>S</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>S</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61 —
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>S</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>S</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>S</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	<i>R</i> 777.52 —
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 —
13	1	BOOT REAR	\$	<i>R</i> 2,872.68 }
14	1	BOOT FINISHER	\$	<i>S</i> 470.06 }
15	1	BOOT WHEATERSTRIP	\$	<i>S</i> 323.05 }
16	1	BOOT REFLECTOR LAMP LH	\$	<i>S</i> 493.35 }
17	1	BOOT REFLECTOR LAMP RH	\$	<i>S</i> 493.35 }
18	1	BOOT BADGE 'RENAULT'	\$	<i>nn</i> 225.36 }
19	1	BOOT BADGE	\$	<i>nn</i> 225.36 }
20	1	BOOT SWITCH	\$	<i>S</i> 168.13 }
21	1	BOOT LOCK	\$	<i>R</i> 202.67 }
22	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40 }
23	2	LICENCE PLATE LAMP	\$	<i>S</i> 50.52 }
24	2	BOOT RUBBER PLUG	\$	<i>S</i> 221.81 }
25	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13 }
26	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13 }
27	1	TAILLAMP RH	\$	<i>S</i> 552.55 }
28	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70 }
29	1	TAILLAMP LH	\$	<i>S</i> 552.55 }
30	1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70 }
31	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77 }
32	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>S</i> 404.56 }
33	1	EXHAUST REAR	\$	<i>R</i> 7,489.05 }
34	1	EXHAUST CAP REAR	\$	<i>R</i> 230.49 }

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-101

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9247E -

TOTAL	\$	28,762.72
10%	\$	2,876.27
	\$	25,886.45

Specical Nett

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	17.82	} X
11	1SET	BOOT FINISHER CLIP	\$	24.20	
12	1	BOOT STICKER "Trans-cab"	\$	30.00	
13	1	BOOT STICKER "6555-3333"	\$	30.00	
14	1	TAILLAMP CLIP RH	\$	5.00	
15	1	TAILLAMP CLIP LH	\$	5.00	
16	2	REAR WINDSCREEN SELANT	\$	80.00	
17	1	WINDSCREEN MOULDING	\$	100.00	} X
18	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
19	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00	
20	1	SPARE TYRE	\$	330.00	

TOTAL	\$	2,054.02
TOTAL PARTS	\$	27,940.47

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	2001
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-101**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9247E -

To repair and realign rear exhaust pipe.	\$	nn 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	7 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	4 170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	4 380.00 X
Towing Fees	\$	4 120.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	4 170.00 X
To check steering geometry and computer wheel alignment	\$	4 220.00 X

TOTAL	\$	7,710.00
Over All Total	\$	35,650.47

(PARTS BY PARTS)
Repair Days

10Days*2days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: