

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9857E - AIG**AAD1801-114***Not Authorised**U/Ly 87750*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB9857E - CANDY

VF1ABL15AUC273386

RENAULT

LATITUDE

08.01.2018

AIG**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Br</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Br</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Br</i> 113.47 X
4	1	BUMEP R BRACKET SIDE RH REAR	\$	<i>Br</i> 135.97 X
5	1	BUMEP R RETAINER RH REAR	\$	<i>Br</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>Br</i> 43.61 X
7	1	BUMEP R BRACKET SIDE LH REAR	\$	<i>Br</i> 135.97 X
8	1	BUMEP R RETAINER LH REAR	\$	<i>Br</i> 44.99 ✓
9	1	BUMPER REFLECTOR LH	\$	<i>Br</i> 43.61 ✓
10	1	BUMPER BEAM REAR	\$	<i>Br</i> 777.52 X
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>Br</i> 225.95 X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>Br</i> 225.95 X
13	1	BOOT REAR	\$	<i>N.C. (Br)</i> 2,872.68 X
14	1	BOOT FINISHER	\$	<i>Br</i> 470.06 X
15	1	BOOT WHEATERSTRIP	\$	<i>Br</i> 323.05 X
16	1	BOOT REFLECTOR LAMP LH	\$	<i>N.C. (Br)</i> 493.35 X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Br</i> 493.35 X
18	1	BOOT BADGE 'RENAULT'	\$	<i>Br</i> 225.36
19	1	BOOT BADGE	\$	<i>Br</i> 225.36
20	1	BOOT STRUT LH	\$	<i>Br</i> 276.08
21	1	BOOT STRUT RH	\$	<i>Br</i> 276.08
22	1	BOOT HINGE LH	\$	<i>Br</i> 367.84
23	1	BOOT HINGE RH	\$	<i>Br</i> 367.84
24	1	BOOT INNER TRIM	\$	<i>Br</i> 586.45
25	1	BOOT SWITCH	\$	<i>Br</i> 168.13
26	1	BOOT LOCK	\$	<i>Br</i> 202.67
27	1	BOOT LOCK CATCH	\$	<i>Br</i> 74.40
28	2	LICENCE PLATE LAMP	\$	<i>Br</i> 50.52
29	2	BOOT RUBBER PLUG	\$	<i>Br</i> 221.81
30	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Br</i> 671.45
31	1	FENDER PANEL REAR LH	\$	<i>Br</i> 3,299.13 ✓
32	1	WHEELARCH REAR LH	\$	<i>Br</i> 543.47 X
33	1	FENDER WHEEL HOUSE PANEL REAR LH	\$	<i>Br</i> 3,039.04 X
34	1	FENDER PANEL REAR RH	\$	<i>Br</i> 3,299.13 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9857E - AIG**AAD1801-114**

35	1	WHEELARCH REAR RH	\$	543.47 X
36	1	TAILLAMP RH	\$	552.55 X
37	1	TAILLAMP PANEL RH	\$	986.70 X
38	1	TAILLAMP LH	\$	552.55 ✓
39	1	TAILLAMP PANEL LH	\$	986.70 X
40	1	OUTER PANEL REAR (End Panel)	\$	1,471.77 ✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	404.56 X
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	2,189.88 X
43	1	SPARE WHEEL PANEL TRIM	\$	612.21 X
44	1	EXHAUST REAR	\$	7,489.05 X
45	1	EXHAUST CAP REAR	\$	230.49 X
46	1	FUEL CAP	\$	233.02 X

TOTAL	\$	38,236.53
10%	\$	3,823.65
	\$	34,412.88

Specical Nett

1	1SET	PARKING AID	\$	700.00 ✓
2	1SET	REAR BUMPER CLIP	\$	66.00 X
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00 X
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	10.00 X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	20.00 X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	10.00 X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	20.00 X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00 X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00 ✓
10	1	EXHAUST MOUNTING REAR	\$	17.82
11	1SET	BOOT FINISHER CLIP	\$	24.20
12	1	BOOT STICKER "Trans-cab"	\$	30.00
13	1	BOOT STICKER "6555-3333"	\$	30.00
14	1	BOOT INNER TRIM CLIP	\$	45.00
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00
18	1	FENDER INNER TRIM CLIP LH	\$	28.00
19	1	TAILLAMP CLIP RH	\$	5.00
20	1	TAILLAMP CLIP LH	\$	5.00 ✓
21	2	REAR WINDSCREEN SELANT	\$	80.00 400
22	1	WINDSCREEN MOULDING	\$	100.00 300
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00 300
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-114

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9857E - AIG

25	1	SPARE TYRE	\$	<i>330.00</i> X
----	---	------------	----	-----------------

TOTAL	\$	2,197.02
TOTAL PARTS	\$	36,609.90

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>6600</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>1200</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>600</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>600</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00
		<i>} 1000</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
Towing Fees	\$	<i>nn</i> 120.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 <i>1200</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-114

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9857E - AIG

TOTAL	\$	11,160.00
Over All Total	\$	47,769.90

(PARTS BY PARTS)**Repair Days****15 Days***7 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: