

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5369T - AIG*Not Authorised***AAD1801-108***21 Sep @ 3500*

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC5369T - CANDY

VF1ABL15AUC279605

RENAULT

LATITUDE

08.01.2018

AIG

PART			LIST		
1	1	BUMPER COVER FRT	\$	<i>Bur</i> 1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75	X
3	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 207.22	X
4	1	BUMPER RETAINER FRT LH	\$	<i>D.Y</i> 151.41	✓
5	1	BUMPER SUPPORT FRT LH	\$	<i>Sn</i> 123.88	} X
6	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08	
7	1	RADAI TOR GRILLE	\$	<i>Sn</i> 1,707.78	
8	1	RADAI TOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36	
9	1	RADAI TOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75	
10	1	FRAME FULL SUPPORT PANEL	\$	<i>R</i> 615.90	
11	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79	
12	1	LOWER ARM LH	\$	<i>Sn</i> 685.76	
13	1	KUNCKLE ARM LH	\$	<i>Sn</i> 846.98	
14	1	ABSORBER FRT LH	\$	<i>Sn</i> 360.54	
15	1	BONNET	\$	<i>R</i> 1,941.63	} ✓
16	1	HEADLAMP LH	\$	<i>Sn</i> 1,184.43	
17	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15	X
18	1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83	✓
19	1	FENDER INSULATOR LH	\$	<i>Sn</i> 130.84	X
20	1	FENDER BRACKET LOWER LH	\$	<i>Sn</i> 15.79	X
21	1	WHEEL HOUSING PANEL FRT LH	\$	<i>R</i> 4,682.09	X
22	1	WHEELARCH FRT LH	\$	<i>D.Y Sn</i> 278.84	✓
23	1	DOOR MIRROR LH	\$	<i>Sn</i> 1,483.40	X
24	1	DOOR MIRROR GLASS LH	\$	<i>Sn</i> 148.20	X
25	1	DOOR MIRROR BACK COVER LH	\$	<i>Sn</i> 218.46	X
26	1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66	X

TOTAL	\$	22,587.94
10%	\$	2,258.79
	\$	20,329.15

Specical Nett

1 1SET FRONT BUMPER CLIP

\$

R 66.00 ✓

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-108

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5369T - AIG

2	1SET	WHEELARCH CLIP LH	\$	nn	66.00	✓
3	1	TOW COVER FRT	\$	sn	14.50	
4	1	CAP HUB LH FRT	\$	sn	35.00	
5	1	RIM LH FRT	\$	nn	385.00	
6	1	TYRE LH FRT	\$	sn	330.00	
7	1SET	BUMPER SUPPORT FRT CLIP LH	\$	nn	9.80	
8	1SET	BUMPER RETAINER FRT CLIP LH	\$	nn	12.50	
9	1	DOOR STICKER "Trans-cab"	\$	nn	80.00	
10	1	DOOR STICKER "Classic"	\$	nn	30.00	

TOTAL	\$	1,028.80
TOTAL PARTS	\$	21,357.95

To Check Electrical Lighting Concerned.	\$	170.00	201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	400
Putty and spray painting of the affected portion.	\$	4,500.00	4401
To check steering geometry and computer wheel alignment	\$	220.00	601
Towing Fees	\$	120.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To rust-proofing of the affected areas.	\$	170.00	301
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	nn X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	nn X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	nn X

LKK Auto Consultants hence notify

the Client of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be provided and is subject to final approval from Insurance Company

TOTAL	\$	10,480.00
Over All Total	\$	31,837.95

Acknowledged by Repairer

Signature:

Date:

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-108

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5369T - AIG

(PARTS BY PARTS) Repair Days

~~15 Days~~

2 days