

REPAIR ESTIMATE*

VEHICLE NO : SH 7042R

MAKE :

MODEL : HYUNDAI i40

DATE 10/1/2018 9:49

LKK/Kalvin

Pby P
AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 1,052.20
	Front Bumper Bracket (LH) ✓			\$ 24.60
	Front Fender (LH) ✓			\$ 619.00
	Front Fender Shield (LH) X			\$ 169.80
	Frt Wheel Hub Cap ✓			\$ 150.70
	SUB TOTAL			\$ 2,016.30
	LESS 20%			\$ 403.26
	DISCOUNTED TOTAL			\$ 1,613.04
	Labour Charge			
	Panel Beating			\$ 560.00 300
	Spray Painting Charge			\$ 400.00 360
	Tuff Kote			\$ 50.00 20
	TOTAL LABOUR			\$ 1,010.00
	ESTIMATE TOTAL			\$ 2,623.04
1 Calvin LKK 10/1/18 11:02h 2 Days P/P Before Paint photo				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before after spray painting • To display damaged parts during resurvey • Parts prices are subject to confirmation • Third party survey is on "without prejudice" basis • No litigation • Supplier's liability is subject to survey and approval from insurance Company Acknowledged by Repairer Signature _____ Date _____				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				