

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHD33P
Accident Date : 08-Jan-2018

Our Ref : 218009 (AXA) / CHAN

TOH KOK WAH
BLK 451A SENGKANG WEST WAY
#04-369
Singapore 791451

No. : 05704

Date : 10-Jan-2018

PAGE : 1

Not Authored
11 Sep 8?
Revery After Pains
6 days

ESTIMATED COST OF REPAIR FOR TOYOTA ALPHARD 3.5A SGR6899G

1 pc	Tail gate	<i>By</i>	1,537.31	✓
1 pc	Tail gate "ALPHARD" emblem	<i>By</i>	63.90	✓
1 pc	Tail gate "V6" emblem	<i>By</i>	39.80	✓
1 pc	Tail gate logo	<i>By</i>	66.15	✓
1 pc	O/s tail gate side garnish	<i>By</i>	189.10	✓
1 pc	O/s taillamp	Dd/ cut	471.20	✓
1 pc	O/s taillamp lower garnish	<i>By</i>	194.40	✓
1 pc	Rear end panel	Bent	590.90	✓
1 pc	Rear bumper fascia	<i>By</i>	680.50	✓
1 pc	Rear o/s bumper under cover	Deformed	281.50	✓
1 pc	Rear bumper o/s reflector	<i>CM</i>	66.90	✓
2 pcs	Rear bumper side retainer	@ S\$ 72.40 <i>clip</i>	144.80	✓
1 pc	Rear o/s bumper bracket	<i>By</i>	98.91	✓
1 pc	Rear exhaust silencer box	Bent	773.50	✓
1 pc	Rear exhaust chrome pipe	Dented	142.63	✓
			5,341.50	
		Less 25% :	1,335.38	

- 1 pc Rear w/s glass sealant
1 pc Rear bumper reverse sensor(4pc

By 4,006.12
40sn 60.00 sn
svc 7X400.00 sn

To remove & refix rear windscreen
glass and conduct water leak test.

12cl 150.00

To remove roof lining, front and
rear seats, trim board and carpet

Pol 120.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHD33P

Page : 2

To remove air con condenser, pipes
and drier, vacuum and to recharge
gas

nn 120.00 X

To apply undersealing

601 100.00

To remove and renew exhaust
silencer box

601 80.00

To putty and spray replaced parts

601 1,000.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

701 1,100.00

Total : S\$ 7,136.12

=====

Singapore Dollars Seven Thousand One Hundred
and Thirty Six and Cents Twelve Only