

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lion City Rentals Pte Ltd	Cust No/Name KL000023/Lion City Rentals Pte Ltd
60 Anson Road	Reg No/Reg Date SLE8932P / 04/08/201
#11-01 Mapletree Anson	Date In/Mileage / 0
Singapore 079914	Chassis No JMYSRCY1AGU005809
Contact No Mobile: 67420984	Engine No 4A92CJ7389
	Make/Model MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	11/01/2018/ 15:17	QUA	465 / Tay Jian Ye	19600

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 TRANSFER BOTH RH DOOR TRIM, MECHANISM AND ELECTRONICS TO NEW DOORS				275 1100.00
E PNT88000 RENEW BOTH RH DOORS, REPAIR RH 'B' PILLAR AND REALIGN TO THE SAME				825 1650.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				50 100.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
M SUNDRY SUPPLY BODY SEALANT FOR AFFECTED PORTIONS				X 160.00
M SUNDRY SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS				40 160.00
M SUNDRY SUNDRIES				20 50.00
E PNT98000 PAINT WORK RESPRAY RH BOTH DOOR				840 1260.00
M PANEL ASSY,FR DOOR,RH	1.00	1124.00	00.00	R 1124.00
M PANEL ASSY,RR DOOR,RH	1.00	1054.00	00.00	RA 1054.00
M TAPE,RR DOOR SASH,RH	1.00	37.00	00.00	rec 37.00
M TAPE,FR DOOR SASH,RH	1.00	37.00	00.00	X 37.00

SURVEYOR NAME: Pamela Ho 9000068

SURVEYOR SIGNATURE: [Signature]

DATE: 11/01/18 @ 1500hrs

REMARKS: 5 days

Repair to paint  
after

Confirm & accepted by

[Signature]

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7% GST on

Nett	6,932.00	8,932.00
	6932.00	485.24

Total Payable 7,417.24

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.