

Surveyor

REF:

CS3 / ALH 17016118 / Svb-1

Special Instruction:

US: 410000.00

ASSIGNMENT (Office)

From (Person): Marcus Xigo of INC Date/Time: 08012018
 Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: Automax SunleyWorkshop: Eng Soon

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SJD 2125X 6394E Insured: SJM 554R

at Workshop m/s Eng Soon Painting Tel: _____
 of 312 4 Yew Tee Ind Est 313-3

Policy No: 16 2295 397986 003 Claim No: MT/CA/TP/003/0958057-002

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 17082017
 (Client's Record)

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 7 days)Date/Time: 23/1/18 Submit Final Fig LS 6600, 7 days (Red \$ 3400 / 34 %; Original _____ days)

Date/Time	Action/Instruction
	<u>SJD 2125X - CS3 / ALH 17016118 / Svb-1</u>
	<u>SJM 554R - X</u>
<u>23/1/18</u>	<u>Report Send to NTUC & Bill to NTUC</u>

23/1/2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 23 JAN 2018

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date:

200

1) Date/Time 23/1- typist File Pass to _____

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CS3/AIG17016118/Svb-1	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 11-01-2018	
			Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJM 594R	Veh. Inspected	SJD 2125X	
Policy No.	1622953979SG003	Coverage (\$)	0.00	
Claim No.	MT/CA/TP/003/0958057-002	Excess (\$)	0.00	
Assign From	MARCUS XIAO	Assign Date	08/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/08/2017	Inspection Date	11/01/2018	
Survey held at	ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Catherine Chong (LKK Auto)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Monday, 8 January, 2018 9:45 AM
To: assignments
Subject: FW: Our Ref: 1622953979SG003 // BK Ref : BK.18086.17.jl#NTUC Ref : MT/CA/TP/003/0958057-002/AS/VU, Acc Inv: SJD 2125 X & SJF 6209 B & SJH 7076 A ON 17 AUGUST 2017, CLAIMANT: TIONG WEI REN, DARREN adjuster report.PDF; PRS photos.pdf; Survey+Report+(for+Tablet)+2017-11-7.pdf (6).PDF

Attachments:

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Marcus Xiao [mailto:marcus.xiao@income.com.sg]
Sent: Monday, 8 January, 2018 9:28 AM
To: SUR <sur@lkkauto.com>
Cc: Loh, Chee-Heng <Chee-Heng.Loh@aig.com>
Subject: FW: Our Ref: 1622953979SG003 // BK Ref : BK.18086.17.jl#NTUC Ref : MT/CA/TP/003/0958057-002/AS/VU, Acc Inv: SJD 2125 X & SJF 6209 B & SJH 7076 A ON 17 AUGUST 2017, CLAIMANT: TIONG WEI REN, DARREN

Dear LKK

Attached your pre-repair survey report.

Attached TP survey report, please assist to review repair cost and days of repairs and let us have your survey report urgently.

regards

Marcus Xiao

Senior Claims Executive, Motor Insurance

T +65 6430 7937

www.income.com.sg





This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you

From: Loh, Chee-Heng [<mailto:Chee-Heng.Loh@aig.com>]

Sent: Friday, January 05, 2018 3:26 PM

To: Marcus Xiao <marcus.xiao@income.com.sg>

Subject: RE: Our Ref: 1622953979SG003 // BK Ref : BK.18086.17.jl#NTUC Ref : MT/CA/TP/003/0958057-002/AS/VU, Acc Inv: SJD 2125 X & SJF 6209 B & SJH 7076 A ON 17 AUGUST 2017, CLAIMANT: TIONG WEI REN, DARREN

Dear Marcus,

Attached PRS report and photos by LKK.

Thank you.

Best regards,

Loh Chee Heng

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1881 | Fax +(65) 6835 7416

Chee-Heng.Loh@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Wong, Justin

Sent: Friday, January 05, 2018 2:56 PM

To: Marcus Xiao

Cc: Yong, Ivy-AV; Loh, Chee-Heng

Subject: Our Ref: 1622953979SG003 // BK Ref : BK.18086.17.jl#NTUC Ref : MT/CA/TP/003/0958057-002/AS/VU, Acc Inv: SJD 2125 X & SJF 6209 B & SJH 7076 A ON 17 AUGUST 2017, CLAIMANT: TIONG WEI REN, DARREN

Dear Marcus,

Please note that the officer in-charge of this matter is Chee Heng.

He will liaise with you with regards to the survey report matter.

Thank you.

Best Regards,

Justin Wong

AIG

Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1880 | Fax +(65) 6835 7416
Justin.Wong@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Marcus Xiao [<mailto:marcus.xiao@income.com.sg>]

Sent: Thursday, January 04, 2018 3:57 PM

To: Wong, Justin

Cc: Yong, Ivy-AV; bonnie kwok

Subject: FW: #9525062721SG005006#Your Ref : BK.18086.17.jl#NTUC Ref : MT/CA/TP/003/0958057-002/AS/VU, Acc Inv: SJD 2125 X & SJF 6209 B & SJH 7076 A ON 17 AUGUST 2017, CLAIMANT: TIONG WEI REN, DARREN

Without prejudice save as to cost

Re-send email to Mr Justin Wong.

Ms Ivy Yong is on leave.

regards

Marcus Xiao

Senior Claims Executive, Motor Insurance

T +65 6430 7937

www.income.com.sg



This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you

From: Marcus Xiao

Sent: Thursday, January 04, 2018 3:53 PM

To: 'bonnie kwok' <litigation@bonniekwok.com>

Cc: Yong, Ivy-AV <Ivy-AV.Yong@aig.com>

Subject: RE: #9525062721SG005006#Your Ref : BK.18086.17.jl#NTUC Ref : MT/CA/TP/003/0958057-002/AS/VU, Acc Inv: SJD 2125 X & SJF 6209 B & SJH 7076 A ON 17 AUGUST 2017, CLAIMANT: TIONG WEI REN, DARREN

Without prejudice save as to cost

Dear sir

We wrote to you dated 6 December 2017. We have not receive the requested documents from you.

Aside to **Ivy Yong** (AIG) in copy, please refer to attach email from Bonnie Kwok LLC. Please confirm if AIG did survey and let us have complete survey report and all colored photos.

regards

Marcus Xiao
Senior Claims Executive, Motor Insurance
T +65 6430 7937
www.income.com.sg



This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you

From: bonnie kwok [<mailto:litigation@bonniekwok.com>]
Sent: Thursday, January 04, 2018 2:49 PM
To: Allard Seah <allard.seah@income.com.sg>; Marcus Xiao <marcus.xiao@income.com.sg>; Yong, Ivy-AV <Ivy-AV.Yong@aig.com>; Dominic Ho <Dominic.Ho@income.com.sg>
Subject: Re: #9525062721SG005006#Your Ref : BK.18086.17.jl#NTUC Ref : MT/CA/TP/003/0958057-002/AS/VU, Acc Inv: SJD 2125 X & SJF 6209 B & SJH 7076 A ON 17 AUGUST 2017, CLAIMANT: TIONG WEI REN, DARREN

Dear All,

We refer to the above matter.

We hereby give you two (2) clear days' notice that our client intends to proceed with the issue of a Writ of Summons against your insured. In this regard, please let us know if you are instructing solicitors to accept service of process on your insured's behalf.

Regards,

June

On 3 January 2018 at 10:45, Allard Seah <allard.seah@income.com.sg> wrote:

Dear June

Case handler Marcus.

Allard Seah
Assistant Manager, Motor Insurance

T +65 6430 7933

www.income.com.sg



From: bonnie kwok [mailto:litigation@bonniekwok.com]

Sent: Thursday, December 28, 2017 5:39 PM

To: Dominic Ho <Dominic.Ho@income.com.sg>; Marcus Xiao <marcus.xiao@income.com.sg>; Allard Seah <allard.seah@income.com.sg>; Yong, Ivy-AV <Ivy-AV.Yong@aig.com>

Subject: Re: #9525062721SG005006#Your Ref : BK.18086.17.jl#NTUC Ref : MT/CA/TP/003/0958057-002/AS/VU, Acc Inv: SJD 2125 X & SJF 6209 B & SJH 7076 A ON 17 AUGUST 2017, CLAIMANT: TIONG WEI REN, DARREN

Dear Marcus / Dominic / Allard,

Please confirm your 10% share before we revert on Quantum.

Regards,

June

On 26 December 2017 at 16:08, bonnie kwok <litigation@bonniekwok.com> wrote:

WITHOUT PREJUDICE

Dear Marcus / Dominic,

Please confirm your 10% share before we revert on Quantum.

Regards,

June

On 14 December 2017 at 09:30, Yong, Ivy-AV <Ivy-AV.Yong@aig.com> wrote:

Without Prejudice

Dear June,

We refer to your Letter of Demand dated 03 November 2017.

We are prepared to offer your client's claim as follows:

General Damages	S\$1,500.00
Medical Expenses	S\$54.42 (agreed)
Transport Expenses	S\$20.00 (\$20 x 1 trip)
Medical Report Fee	S\$214.00 (agreed)
LTA Search Fee	S\$16.00 (agreed)
GIA Search Fee	Subject to receipts
Costs inclusive of GST	S\$1,605.00
Total	S\$3,409.42

AIG's contribution

@ 90% \$3,068.48

NTUC Income Insurance Co-operative Ltd's contribution @ 10% \$340.94

Kindly confirm acceptance. Meanwhile, please hold your hands on further legal process.

Under MCF Scenario 28 for chain collisions, the vehicle directly behind should be 100% liable of the vehicle in front. Hence, SJF6209B which is the vehicle directly behind your client's vehicle should be 100% liable.

Please note that our above offer is strictly on without prejudice basis to our Insured's rights and should not be construed as an admission of liability. The terms of settlement should not be disclosed in any other related matter in respect to the said accident.

Aside to Dominic,

Would appreciate you could forward this Letter of Demand to the case handler.

Regards,

Ivy Yong

AIG
Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120
Tel +64191637 | Fax +68357416

Ivy-AV.Yong@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6394E
Vehicle Details	
Vehicle No.:	SJD2125X
Vehicle to be Exported:	No
Intended De-registration Date:	23 Jan 2018
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	L13A4022463
Chassis No.:	GE61019656
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$11,781.00
Original Registration Date:	13 Mar 2008
First Registration Date:	13 Mar 2008
Transfer Count:	2
Actual ARF Paid:	\$12,960.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Mar 2018
PARF Rebate Amount:	\$6,480.00
Intended COE Rebate Details	
COE Expiry Date:	12 Mar 2018
COE Category:	A - Car (1600cc & below)

COE Period(Years):	10
QP Paid:	\$12,856.00
COE Rebate Amount:	\$167.00
Total Rebate Amount:	\$6,647.00

The information contained herein is correct as at 23 Jan 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0216B
Vehicle Details	
Vehicle No.:	FBL7105Z
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jan 2018
Vehicle Make:	SUZUKI
Vehicle Model:	GSXR1000K6
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	T713135093
Chassis No.:	JS1B6111100112042
Maximum Power Output:	-
Open Market Value:	\$13,332.00
Original Registration Date:	03 May 2006
First Registration Date:	03 May 2006
Transfer Count:	6
Actual ARF Paid:	\$2,000.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 May 2021
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$3,246.00
COE Rebate Amount:	\$2,147.00
Total Rebate Amount:	\$2,147.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Jan 2018

Condition Codes:
 (1)New (2)Used (3)Damaged (4)Cracked (5)Cut (6)Scratched (7)Deformed
 (8)Discolored (9)Bent (10)Broken (11)Missing (12)Missing (13)Torn
 (14)Unidentified (15)Not Working

MOTOR CAR (Frt)

ACT/11/11/11
 (1)Repairs (2) / (3)Repairs (4) (5)Repairs (6)
 (7)Repairs (8) (9)Repairs (10) (11)Repairs (12)

Aug 2008

Vehicle No: 57D 215X

Front Portion

NAC	INC	Item	CON	ACQ	QTY
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	CRK		
1005	992341	Frt Bumper Clips	ALC	V	
1006	991325	Frt Bumper Bracket	ALC	V	
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	Lower	10/10/08	V
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler	SEA		
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	10/10/08	V	
1022	991328	Frt Grille Emblem	ALC	V	
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BT	V	
1026	992025	Frt Support Panel Top Garnish Cover	10/10/08	V	
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CRK		
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	BT	V	
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock	BT	V	
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge	BT	V	
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	ACQ	QTY
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sucker			
		Frt Tow Hook Cover		ALC	V

No of Items:

Assessor:

original copy

6 days

MOTORCAR (Rear)

4) Not Concept: **NC**

Vehicle No: 5J04125X

Rear Portion

Rear Portion			CON	AC	QTY
NAC	INC	Item			
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	OK	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	OK	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NAC	✓	
1147	992976	Rear Bumper Bracket	NAC	✓	
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993026	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993335	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DT	✓	
1182	991328	Tailgate Emblem	NAC	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding	NAC	✓	
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper A.m			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No:			CON	AC	QTY
NAC	INC	Item			
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	996507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993436	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993383	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			
		Rear side Hook Cover		See ✓	

No. of Items: _____

ASSIGNOR: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Aug 2017 Edit Reg		21 Sep 2017 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured: Yasmin Binte Abdul Hamed, ID: S8018184A

Main Claimant: -

Vehicle Reg. No.: **SJD2125X** Date of Loss: 17/08/2017 00:00 - :59

Claim Type: **TP / 1622953979SG** Policy/Cover Note No.: 2100179410 (Comprehensive)

Vehicle Reg. No. (Insured): **SJM594R** Policy No. (Claimant):

Excess:

Repairer: **Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271**

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com**

Adjuster: **LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 02/10/2017]**

Claimant's Solicitor: **BONNIE KWOK LLC - Tel: 65366026**

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- AIG_SG (22/09/2017): Request To Upload TP GIA Report

☐ **ALL ASSOCIATED TASKS**

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Claim Documents













*SJD2125X (1622953979SG)
[SJM594R]

TP

Aug 17 2017 12:00AM
[Yasmin Binte Abdul Hamed]
Eng Soon Painting Services

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View Use Viewer		
Assessment Reports										1 per page		<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)								Thumbnail	Print	
1	22/09/17 10:59	Accident Statement									Load HTM	
From: SC - Reg. No: SJM594R, Claimant: YASMIN BINTE ABDUL HAMED												
Photos/Images										3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
2	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
3	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
4	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
5	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
6	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
7	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
8	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
9	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
10	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
11	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
12	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
13	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
14	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
15	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
16	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
17	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
18	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
19	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
20	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
21	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
22	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
23	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
24	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
25	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
26	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
27	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
28	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
29	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
30	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
31	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
32	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
33	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
34	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
35	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
36	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
37	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>
38	21/09/17 18:53	General View									Load JPG	<input checked="" type="checkbox"/>

39	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
48	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
49	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
50	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
51	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
52	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
53	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
54	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
55	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
56	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
57	21/09/17 18:53	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
58	21/09/17 18:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
59	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
60	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
61	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
62	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
63	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
64	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
65	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
66	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
67	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
68	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
69	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
70	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
71	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
72	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
73	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
74	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
75	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
76	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
77	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
78	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
79	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
80	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
81	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
82	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
83	21/09/17 18:54	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
84	21/09/17 18:54	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
85	21/09/17 18:54	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
86	21/09/17 18:54	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
87	21/09/17 18:54	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
88	21/09/17 18:54	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
89	21/09/17 18:54	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
90	21/09/17 18:54	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
91	21/09/17 18:54	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
92	21/09/17 18:54	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>

93	21/09/17 18:54	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
94	21/09/17 18:54	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
95	21/09/17 18:54	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
96	21/09/17 18:54	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
97	21/09/17 18:54	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
98	21/09/17 18:54	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
99	21/09/17 18:54	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
100	21/09/17 18:54	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
101	21/09/17 18:54	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
102	21/09/17 18:54	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
103	21/09/17 18:54	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
104	21/09/17 18:54	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17016118/SBS2
Date: 02/11/2017

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100179410
Claimant Vehicle No :	SJD2125X	Insured Vehicle No :	SJM594R
Date of Loss:	17/08/2017	Nature of Claim:	TP
		Claim No:	1622953979SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD2125X	Engine No:	L13A4022463
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GE61019656
Reg. Date:	13/03/2008 (Man. Year: 2008)	Odometer:	151039 km
Colour:	White		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

	Repairer's	Adjuster's	Difference	Diff %
COST OF CLAIMS				
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	21/09/2017		
Date Inspected:	22/08/2017	Inspected At:	Eng Soon Painting Services BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969

Estimated Period of Repair: 6.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cracked	0.00 F	*-F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
3	1		*FRT BUMPER BRACKET	Necessary	0.00 F	*-F
4	1		*FRT BUMPER REINFORCEMENT	*Check	0.00 F	*-F
5	1		*FRT BUMPER SPONGE	*Check	0.00 F	*-F
6	1		*FRT BUMPER GRILLE LOWER	Deformed	0.00 F	*-F
7	1		*FRT BUMPER LOWER SPOILER	Cracked	0.00 F	*-F
8	1		*FRT GRILLE	Deformed	0.00 F	*-F
9	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*-F
10	1		*FRT SUPPORT PANEL	Bent	0.00 F	*-F
11	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Deformed	0.00 F	*-F
12	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*-F
13	1		*FRT RH HEADLAMP ASSY	*Check	0.00 F	*-F
14	1		*BONNET	Bent	0.00 F	*-F
15	1		*BONNET LOCK	Bent	0.00 F	*-F
16	2		*BONNET HINGE	Bent	0.00 F	*-F
17	1		*AIR CON CONDENSER	*Check	0.00 F	*-F
18	1		*AIR CON SUCTION PIPE (LOW PRESSURE)	*Check	0.00 F	*-F
19	1		*AIR CON LIQUID PIPE	*Check	0.00 F	*-F
20	1		*RADIATOR	*Check	0.00 F	*-F
21	1		*RADIATOR COWLING	*Check	0.00 F	*-F
22	1		*RADIATOR FAN ASSY	*Check	0.00 F	*-F
23	1		*RADIATOR FAN CLUTCH	*Check	0.00 F	*-F
24	1		*FRT LH FENDER INNER SHIELD	*Check	0.00 F	*-F
25	1		*FRT RH FENDER INNER SHIELD	*Check	0.00 F	*-F
26	1		*FRT TOW HOOK COVER	Missing	0.00 F	*-F
27	1		*REAR BUMPER	Cracked	0.00 F	*-F
28	1		*REAR BUMPER LOWER GARNISH	Cut	0.00 F	*-F
29	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
30	1		*REAR BUMPER BRACKET	Necessary	0.00 F	*-F
31	1		*REAR BUMPER BEAM	*Check	0.00 F	*-F
32	1		*REAR BUMPER SPONGE	*Check	0.00 F	*-F
33	1		*TAILGATE	Dented	0.00 F	*-F
34	1		*TAILGATE EMBLEM	Necessary	0.00 F	*-F
35	1		*TAILGATE MOULDING	Necessary	0.00 F	*-F
36	1		*REAR TOW HOOK COVER	Scratched	0.00 F	*-F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
--------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17016118/SBS2
 Date: 06/11/2017

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100179410
Claimant Vehicle No:	SJD2125X	Insured Vehicle No:	SJM594R
Date of Loss:	17/08/2017	Nature of Claim:	TP
		Claim No:	1622953979SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD2125X	Engine No:	L13A4022463
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GE61019656
Reg. Date:	13/03/2008 (Man. Year: 2008)	Odometer:	151039 km
Colour:	White		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

	Repairer's	Adjuster's	Difference	Diff %
COST OF CLAIMS				
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing				
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	21/09/2017	Eng Soon Painting Services BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969
Date Inspected:	22/08/2017	Inspected At:
Estimated Period of Repair:	6.0 days	

Adjuster: Sebastian Yeang Wai Keen

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cracked	0.00 F	*-F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
3	1		*FRT BUMPER BRACKET	Necessary	0.00 F	*-F
4	1		*FRT BUMPER REINFORCEMENT	*Check	0.00 F	*-F
5	1		*FRT BUMPER SPONGE	*Check	0.00 F	*-F
6	1		*FRT BUMPER GRILLE LOWER	Deformed	0.00 F	*-F
7	1		*FRT BUMPER LOWER SPOILER	Cracked	0.00 F	*-F
8	1		*FRT GRILLE	Deformed	0.00 F	*-F
9	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*-F
10	1		*FRT SUPPORT PANEL	Bent	0.00 F	*-F
11	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Deformed	0.00 F	*-F
12	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*-F
13	1		*FRT RH HEADLAMP ASSY	*Check	0.00 F	*-F
14	1		*BONNET	Bent	0.00 F	*-F
15	1		*BONNET LOCK	Bent	0.00 F	*-F
16	2		*BONNET HINGE	Bent	0.00 F	*-F
17	1		*AIR CON CONDENSER	*Check	0.00 F	*-F
18	1		*AIR CON SUCTION PIPE (LOW PRESSURE)	*Check	0.00 F	*-F
19	1		*AIR CON LIQUID PIPE	*Check	0.00 F	*-F
20	1		*RADIATOR	*Check	0.00 F	*-F
21	1		*RADIATOR COWLING	*Check	0.00 F	*-F
22	1		*RADIATOR FAN ASSY	*Check	0.00 F	*-F
23	1		*RADIATOR FAN CLUTCH	*Check	0.00 F	*-F
24	1		*FRT LH FENDER INNER SHIELD	*Check	0.00 F	*-F
25	1		*FRT RH FENDER INNER SHIELD	*Check	0.00 F	*-F
26	1		*FRT TOW HOOK COVER	Missing	0.00 F	*-F
27	1		*REAR BUMPER	Cracked	0.00 F	*-F
28	1		*REAR BUMPER LOWER GARNISH	Cut	0.00 F	*-F
29	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
30	1		*REAR BUMPER BRACKET	Necessary	0.00 F	*-F
31	1		*REAR BUMPER BEAM	*Check	0.00 F	*-F
32	1		*REAR BUMPER SPONGE	*Check	0.00 F	*-F
33	1		*TAILGATE	Dented	0.00 F	*-F
34	1		*TAILGATE EMBLEM	Necessary	0.00 F	*-F
35	1		*TAILGATE MOULDING	Necessary	0.00 F	*-F
36	1		*REAR TOW HOOK COVER	Scratched	0.00 F	*-F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

LKK Auto Consultants Pte Ltd/SJD2125X/06/11/2017 09:55

< END OF ESTIMATES >

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road, #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Billing To: Tiong Wei Ren Darren
C/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

Invoice no.: TP17080036

Date: 31 AUG 2017

Vehicle no: SJD 2125 X

Model : Honda FIT 1.3G A

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 21 August 2017 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 645.00
2	Photography Services Develop photographs Storage of digital photographs	
3	To submit report by hand.	
4	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
	TOTAL :	\$ 645.00

Notes :

All cheque payment should be "crossed" and made payable to "Automax Survey".
Please contact us if there are further enquiries on the invoice.



AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road, #07-280, Singapore 470110
Mobile : 9855 8879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP17080036

Date: 31 AUG 2017

*Tiong Wei Ren Darren
C/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969*

THIRD PARTY SURVEY ACCIDENT OCCURED ON 17 August 2017

Workshop Name and Address

Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

As per your instruction dated 21 August 2017
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
SJD 2125 X

1. VEHICLE PARTICULARS

Registration No : SJD 2125 X
Model : Honda FIT 1.3G A
Year / Capacity : 2008 / 1339 cc
Chassis No : GE61019656

Engine No : L13A4022463
Mileage : 199 212 km
Colour : Metallic White

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	195/50/R15	Bridgestone	9.00 mm	Sport
REAR O/S :	195/50/R15	Bridgestone	9.00 mm	Sport
FRONT N/S :	195/50/R15	Bridgestone	9.00 mm	Sport
REAR N/S :	195/50/R15	Bridgestone	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road, #07-280, Singapore 470110

Mobile : 9855 6879 Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the **Front & Rear** portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 07 working days to complete
5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

Disclaimer

Our rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SJD 2125 X

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$\$)	Our Revised Estimation (\$\$)
-----	-------------------	-----------	----------------------------	-------------------------------

1 pc	Tail Gate <i>✓ DT</i>	bent	\$ 736.50	\$ 736.50
1 pc	Tail Gate lock <i>✓</i>	bent/distorted	\$ 232.10	\$ 232.10
1 pc	Tail Gate striker <i>X NN</i>	bent	\$ 17.10	17.10
1 pc	Tail gate badge <i>✓ NEC</i>	bent	\$ 25.00	\$ 25.00
1 pc	Tail gate emblem "FIT" <i>✓ NEC</i>	bent/distorted	\$ 35.00	\$ 35.00
1 pc	Tail gate inner trim board <i>X NN</i>	bent/distorted	\$ 100.20	\$ 100.20
10 pcs	Tail gate inner trim board clips <i>✓ NEC</i>	necessary	\$ 31.20	\$ 31.20 <i>30</i>
1 pc	Tail gate weather stripe <i>X NN</i>	bent/deformed	\$ 92.30	92.30
1 pc	Rear windscreen glass moulding (top) <i>✓ NEC</i>	deformed	\$ 22.70	\$ 22.70
1 pc	Rear windscreen glass moulding (bottom) <i>✓ NEC</i>	deformed	\$ 25.00	\$ 25.00
1 pc	Rear windscreen glass inner seal <i>✓ NEC</i>	deformed	\$ 28.00	\$ 28.00
10 pcs	Rear windscreen clips <i>✓ NEC</i>	necessary	\$ 42.00	42.00 <i>30</i>
2 pcs	Tail lamp <i>✓ R4V LH X NN</i>	distrupted	\$ 413.00	413.00 <i>206.50</i>
2 pcs	Tail lamp sealant <i>✓ NEC</i>	necessary	\$ 60.00	60.00 <i>40</i>
4 pcs	Tail lamp clips <i>✓ NEC</i>	necessary	\$ 15.20	\$ 15.20
2 pcs	Tail lamp base panel <i>R</i>	bent/distorted	\$ 267.00	267.00
1 pc	Rear bumper <i>✓ CRK</i>	bent/distorted	\$ 474.50	\$ 474.50
2 pcs	Rear bumper side retainer <i>✓ NEC</i>	bent/distorted	\$ 28.20	\$ 28.20
2 pcs	Rear bumper bracket <i>✓ NEC</i>	distorted	\$ 19.00	\$ 19.00
10 pcs	Rear bumper clips <i>✓ NEC</i>	necessary	\$ 38.00	38.00 <i>30</i>
1 pc	Rear bumper tow cover <i>✓ Deform</i>	bent/deformed	\$ 13.30	\$ 13.30
1 pc	Rear end panel <i>R</i>	bent/distorted	\$ 276.50	276.50
1 pc	Rear end panel top trim <i>X NN</i>	deformed	\$ 60.80	60.80
4 pcs	Rear end panel top trim clips <i>✓ NEC</i>	necessary	\$ 16.00	\$ 16.00
1 pc	Rear floor panel <i>R</i>	distorted - repair	\$ 737.10	\$ -
1 pc	Exhaust silencer <i>✓ BT</i>	bent/distorted	\$ 464.80	\$ 464.80
1 pc	Front bumper face <i>✓ CRK</i>	bent	\$ 530.50	\$ 530.50
2 pcs	Front bumper side retainer <i>✓ NEC</i>	damaged	\$ 28.00	\$ 28.00
10 pcs	Front bumper clips <i>✓ NEC</i>	necessary	\$ 38.00	38.00 <i>30</i>
2 pcs	Front bumper bracket <i>✓ DT</i>	bent	\$ 53.40	\$ 53.40
1 pc	Front bumper air grille garnish <i>✓ Deform</i>	cracked	\$ 72.90	\$ 72.90
1 pc	Front bumper reinforcement <i>✓ DT</i>	bent	\$ 287.72	\$ 287.72
2 pcs	Front bumper reinforcement bracket <i>✓ DT</i>	bent	\$ 364.50	\$ 364.50
2 pcs	Headlamp assembly <i>✓ CRK</i>	cracked	\$ 1,059.00	\$ 1,059.00
1 pc	Front grille <i>✓ Deform</i>	cracked	\$ 181.40	\$ 181.40
2 pcs	Front grille clips <i>✓ NEC</i>	necessary	\$ 25.80	\$ 25.80
2 pcs	Front grille clips stopper <i>✓ NEC</i>	damaged	\$ 87.40	87.40 <i>30</i>
1 pc	Bonnet <i>✓ BT</i>	bent	\$ 464.70	\$ 464.70
2 pcs	Headlamp assembly <i>X Replaced.</i>	cracked	\$ 1,059.00	1,059.00
1 pc	Front support panel <i>R</i>	bent	\$ 374.60	374.60
1 pc	Air con condenser <i>✓ BT</i>	bent	\$ 1,217.80	1,217.80 <i>880.60</i>

Parts Sub-Total \$ 10,115.22 \$ 9,378.12

Discount 20.00% \$ 2,023.04 \$ 1,875.62

\$ 8,092.18 \$ 7,502.50

*6500.32
- 20%
5200.25*

Vehicle Number : SJD 2125 X

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>PARTS REPLACEMENT-SPECIAL NETT ITEMS</u>				
1 pc	Battery assy ✓ DT	electronically shocked	\$ 480.00	\$ 480.00 150
1 pc	Rear windscreen glass sealant ✓ NEC	necessary	\$ 60.00	\$ 60.00 40
2 pcs	Number plate X) ~ ~	damaged	\$ 90.00	\$ 90.00
2 pcs	Number plate casing X	distorted	\$ 58.00	\$ 58.00
Special Nett Items Sub-Total			\$ 688.00	688.00

2) / 90

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (\$\$)	Our Revised Estimation (\$\$)
	Spare Parts Total c/f	\$ 8,780.18	\$ 8,190.50
1	Towing	\$ 80.00	\$ 80.00
2	To check and reconnect snap wiring incl headlamp adjustment	\$ 150.00	120.00 40
3	To tuff coat affected areas	\$ 180.00	150.00 50
4	To remove and refix interior upholstery	\$ 150.00	120.00 80
5	To remove and replace exhaust silencer and straighten center pipe	\$ 180.00	150.00 80
6	To remove and replace rear windscreen glass	\$ 180.00	150.00 120
7	To respray affected areas	\$ 1,600.00	1,400.00 1200
8	To renew damaged parts, straighten and repair rear fender inner panel, rear floor panel rear chassis member and aligned all parts	\$ 2,000.00	1,800.00 1000
9	To remove and replace air con condenser, piping, vaccum and top up gas.	\$ 380.00	350.00 200
Total		\$ 13,680.18	\$ 12,510.50

2818

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of:

\$ 10,000.00

Fong Kok Heng
Qualified Appraiser



Parts : \$ 5200.25
S/parts : \$ 190.00
Labour = \$ 2850.00

8240.25
Lump Sum - 20%
6592.20

Total = \$ 6600 @ 7 days.



Your Ref: MT/CA/TP/003/0958057-002

Date: 24th January 2018

Our Ref: CS3/AIG17016118/Svbs2-1

M/s NTUC Income Insurance Co-Operative Ltd

73 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556
(The Motor Claims Department)

Attn: Marcus Xiao

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SJD 2125X
INSURED VEHICLE: SJM 594R
ACCIDENT DATE: 17/08/2017

We thank you for your instruction on 17/02/2017.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJD 2125X from M/s Automax Survey.
- b) Colour damaged vehicle photographs of SJD 2125X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJD 2125X
Make & Model	: Honda Fit 1.3G A
Year of Registration	: 2008
Chassis Number	: GE61019656
Engine Capacity	: 1339 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 2125X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL GATE	DENTED	736.50	736.50
1	TAIL GATE LOCK	BENT / DISTORTED	232.10	232.10
1	TAIL GATE STRIKER	NOT NECESSARY	17.10	-
1	TAIL GATE BADGE	NECESSARY	25.00	25.00
1	TAIL GATE EMBLEM "FIT"	NECESSARY	35.00	35.00
1	TAIL GATE INNER TRIM BOARD	NOT NECESSARY	100.20	-
10	TAIL GATE INNER TRIM BOARD CLIPS	NECESSARY	31.20	30.00
1	TAIL GATE WEATHER STRIP	NOT NECESSARY	92.30	-
1	REAR WINDSCREEN GLASS MOULDING (TOP)	NECESSARY	22.70	22.70
1	REAR WINDSCREEN GLASS MOULDING (BOTTOM)	NECESSARY	25.00	25.00
1	REAR WINDSCREEN GLASS INNER SEAL	NECESSARY	28.00	28.00
10	REAR WINDSCREEN CLIPS	NECESSARY	42.00	30.00
2	TAIL LAMP	O/S DISTRUPTED / N/S NOT NECESSARY	413.00	206.50
2	TAIL LAMP SEALANT	NECESSARY	60.00	40.00
4	TAIL LAMP CLIPS	NECESSARY	15.20	15.20
2	TAIL LAMP BASE PANEL	TO REPAIR SEE LABOUR	267.00	-
1	REAR BUMPER	CRACKED	474.50	474.50
2	REAR BUMPER SIDE RETAINER	NECESSARY	28.20	28.20
2	REAR BUMPER BRACKET	NECESSARY	19.00	19.00
10	REAR BUMPER CLIPS	NECESSARY	38.00	30.00
1	REAR BUMPER TOW COVER	DEFORMED	13.30	13.30
1	REAR END PANEL	TO REPAIR SEE LABOUR	276.50	-
1	REAR END PANEL TOP TRIM	NOT NECESSARY	60.80	-
4	REAR END PANEL TOP TRIM CLIPS	NECESSARY	16.00	16.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	737.10	-
1	EXHAUST SILENCER	BENT	464.80	464.80
1	FRONT BUMPER FACE	CRACKED	530.50	530.50

Report Ref No. CS3/AIG17016118/Svbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT BUMPER SIDE RETAINER	NECESSARY	28.00	28.00
10	FRONT BUMPER CLIPS	NECESSARY	38.00	30.00
2	FRONT BUMPER BRACKET	DENTED	53.40	53.40
1	FRONT BUMPER AIR GRILLE GARNISH	DEFORMED	72.90	72.90
1	FRONT BUMPER REINFORCEMENT	DENTED	287.72	287.72
2	FRONT BUMPER REINFORCEMENT BRACKET	DENTED	364.50	364.50
2	HEADLAMP ASSEMBLY	CRACKED	1,059.00	1,059.00
1	FRONT GRILLE	DEFORMED	181.40	181.40
2	FRONT GRILLE CLIPS	NECESSARY	25.80	25.80
2	FRONT GRILLE CLIPS STOPPER	NECESSARY	87.40	50.00
1	BONNET	BENT	464.70	464.70
2	HEADLAMP ASSEMBLY	REPEATED	1,059.00	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	374.60	-
1	AIR CON CONDENSER	BENT	1,217.80	880.60
	LESS 20% DISCOUNT		-2,023.04	-1,300.06
			8,092.18	5,200.26
	<u>SPECIAL NETT ITEMS</u>			
1	BATTERY ASSY (SN)	DENTED	480.00	150.00
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	60.00	40.00
2	NUMBER PLATE (SN)	NOT NECESSARY	90.00	-
2	NUMBER PLATE CASING (SN)	NOT NECESSARY	58.00	-
			688.00	190.00
	<u>LABOUR</u>			
	TOWING.		80.00	80.00
	TO CHECK AND RECONNECT SNAP WIRING INCL HEADLAMP ADJUSTMENT.		150.00	40.00
	TO TUFF COAT AFFECTED AREAS.		180.00	50.00
	TO REMOVE AND REFIX INTERIOR UPHOLSTERY.		150.00	80.00
	TO REMOVE AND REPLACE EXHAUST SILENCER AND STRAIGHTEN CENTER PIPE.		180.00	80.00
	TO REMOVE AND REPLACE REAR WINDSCREEN GLASS.		180.00	120.00
	TO RESPRAY AFFECTED AREAS.		1,600.00	1,200.00

Report Ref No. CS3/AIG17016118/Svbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RENEW DAMAGED PARTS, STRAIGHTEN AND REPAIR REAR FENDER INNER PANEL, REAR FLOOR PANEL REAR CHASSIS MEMBER AND ALIGNED ALL PARTS. INCLUSIVE OF THE REPAIR OF TAIL LAMP BASE PANEL, REAR END PANEL, REAR FLOOR PANEL AND FRONT SUPPORT PANEL.		2,000.00	1,000.00
	TO REMOVE AND REPLACE AIR CON CONDENSER, PIPING, VACUUM AND TOP UP GAS.		380.00	200.00
			4,900.00	2,850.00
GRAND TOTAL			13,680.18	8,240.26
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,600.00

Report Ref No. CS3/AIG17016118/Svbs2-1

YEANG WAI KEEN
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.