

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 324E

DATE 9/1/2018 14:45

MAKE :

DOR: 09.01.18

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>X Repair</i>			\$ 1,349.50
	Boot Lid Rubber <i>X</i>			\$ 110.90
	Boot Lid Lock Upper <i>X</i>			\$ 132.10
	Boot Lid Lock Lower <i>X</i>			\$ 30.30
	Boot Lid Sonata Plate <i>✓</i>			\$ 43.60
	Boot Lid Hyundai Plate <i>✓</i>			\$ 24.20
	Boot Lid 'H' Emblem <i>✓</i>			\$ 26.10
	Boot Lid CRDI Plate <i>✓</i>			\$ 22.70
	Rear Bumper <i>✓</i>			\$ 578.40
	Rear Bumper Reinforcement <i>?</i>			\$ 483.30
	Rear Bumper Clip <i>✓</i>			\$ 22.00
	Rear Bumper Sponge <i>?</i>			\$ 137.40
	Rear Bumper Under Cover <i>?</i>			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>X Repair</i>		\$ 38.00	\$ 76.00
	Rear Panel <i>X Repair</i>			\$ 391.80
	Rear Panel Garnish <i>X</i>			\$ 95.80
	SUB TOTAL			\$ 3,709.90
	LESS 20%			\$ 741.98
	DISCOUNTED TOTAL			\$ 2,967.92
	Boot Lid Comfort Logo & Tel No. Sticker <i>✓</i>			\$ 30.00
	Rear Bumper Reverse Sensor <i>X</i>			\$ 135.70
				\$ 165.70
	Labour Charge			\$ 600
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,670.00
	ESTIMATE TOTAL			\$ 4,803.62
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

CHINA

SUB TOTAL

LESS 20%

DISCOUNTED TOTAL

Boot Lid Comfort Logo & Tel No. Sticker

Rear Bumper Reverse Sensor

Labour Charge

Panel Beating

Spray Painting Charge

Wiring Charge

Tuff Kote

Remove/Refix Reverse Sensor

TOTAL LABOUR

ESTIMATE TOTAL

LKK Auto Cons. to notify the Repairer of the following:

- To reserve the right to inspect and survey
- To display and test the damaged vehicle
- To provide the necessary information
- To provide the necessary information
- To provide the necessary information
- To provide the necessary information
- To provide the necessary information
- To provide the necessary information

Approved by the Surveyor

Approved by the Surveyor

Signature:

Kalia 10/1/18

10/1/18 1430 hrs.

3 Days

45

A Hk Repair p Loto

Larry Ng