

ASS. REC. BY:

REF: CS/CTI18000729/Urd302

Special Instruction

Menmen Marcus

ASSIGNMENT (Office)

From (Person):

Irene Tan

to

CTI

Date/Time:

12/01/18 @ 9:54am

Estimated Cost:

Bill to:

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

FBM 264M

Insured:

YP 8026 T

at Workshop no.:

Ban Hock Hin

Tel:

62816520

of

No. 6 Defu Lane 4

Policy No.:

DMCVSN1767281700

Claim No.:

SNM18D00200C02

Sum Insured:

Excess:

Make of Veh.:

(Client's Record)

D.O.A. 04/01/2018

CA / REV / REP. / REV 24 HRS

w/p?

R.O.D. Endorsement

Date/Time:

11:53am @ 12/1/18

Person Connected:

Raymond

Vehicle: ☒ IN ☐ OUT

Date/Time

Action/Description

✓

EVA


FBM 264M - x

YP 8026 T - x

REF: 0711

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: F3M 264M
 at Workshop m/s: SMH
 of: YP8026T
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: F3M 264M Yr Regn: 6 17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Yamaha F2N150 cc 149
 Colour: Green A/C: Insured / Std / NI / NA
 Sp. Reading: 5936 T. Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MEIRH1615G2002173
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 100 / 80 R17
 R: 140 / 60 R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or MRP
 Front _____ Rear _____
 R/Bal. 2 mm R/Bal. 2 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 4/1/18 D.O.I. 12/1/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
LT, N/S Body
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 6318
19/1/18 contacted client by 312:50 with Raymond.
Red: \$ 67.50, 18%.

19/1/2018

RECEIVED

Date/Time: File Pass to? ☐ : Preli. Report
☒ : Final Report
 Date/Time: File Return to?

Days Of Repair: 2
 Resurvey No. of Trip: 1

Survey Fee: 220
 Transportation: _____
 Photos: _____
 Other: _____
220

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Insp (\$)
☐ : Weekend (\$)
 Report Format: TP
 Lump Sum / I.B.I: 212.50

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jan 2018		12 Jan 2018 09:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]		
Insured:						
Main Claimant:	BAN HOCK HIN COMPANY PTE LTD, Co. Reg. No.: 197000288K					
Vehicle Reg. No.:	FBM264M	Date of Loss:	04/01/2018 00:00 - :59			
Claim Type:	TP / SNM18D00200C02	Policy/Cover Note No.:	DMCVSN1767281700			
Vehicle Reg. No. (Insured):	YP8026T	Policy No. (Claimant):				
		Excess:	S\$0.00			
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520					
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/01/2018]					
Adj Asg. Remarks:	NO ESTIMATE, ASSIGN MARCUS CHUA AS SJE.					

ASSOCIATED MAIL RECEIVED		View All Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Lucas Lee
Sent: Friday, 12 January, 2018 9:42 AM
To: 'Raymond'
Cc: Claims Dept of CTI
Subject: RE: PRS FOR FBM264M (CTI REF: SNM18D00200C02)

Dear Sirs,

Thank you for your confirmation we will arrange accordingly.

Regards,

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6181
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Raymond [<mailto:raymond@bhh.com.sg>]
Sent: Thursday, 11 January, 2018 2:38 PM
To: Lucas Lee
Cc: Claims Dept of CTI
Subject: RE: PRS FOR FBM264M (CTI REF: SNM18D00200C02)

Dear Lucas,

Please assign Marcus Chua for the pre-repair survey.

Thanks

Best Regards,
Raymond
Ban Hock Hin Co., Pte Ltd
Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969
Visit us at <http://www.bhh.com.sg>
Facebook: <http://www.facebook.com/bhhsg>



BAN HOCK HIN
Co., Pte Ltd

No. 6 Dafu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS |



From: Lucas Lee [<mailto:lucas.lee@sg.cntaiping.com>]
Sent: Thursday, 11 January, 2018 2:36 PM
To: Raymond <raymond@bhh.com.sg>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: PRS FOR FBM264M (CTI REF: SNM18D00200C02)

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
DERECK OH SIONG WEE
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6181
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Raymond [<mailto:raymond@bhh.com.sg>]
Sent: Tuesday, 9 January, 2018 2:43 PM
To: Claims Dept of CTI
Subject: Accident Involving FBM264M & YP8026T on 04/01/2018

Dear Sir / Madam,

We attached the third party claim documents for your perusal.

Appreciate for you to arrange for the pre-repair survey at our workshop.

Thanks

Best Regards,
Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS |



This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18000729/Urd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 12-01-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 8026T	Veh. Inspected	FBM 264M
Policy No.	DMCVSN1767281700	Coverage (\$)	0.00
Claim No.	SNM18D00200C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	12/01/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/01/2018	Inspection Date	12/01/2018
Survey held at	BAN HOCK HIN CO. PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

QUOTATION

Customer :

NO. : 32267

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534
MOTOR CLAIMS DEPT

DATE : 06/01/2018
CLAIM NO. : 11074
POLICY NO. : AVFMSB0000631700
FROM : RAYMOND

VEHICLE NO. : FBM0264M
MAKE/MODEL : YAM / FZN150

*Not a full
acc
take the other way
2 day.
12/1/18*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 44886	REPLACE	1.00	\$42.00	42.00
2	BOLT FOOTREST REAR P/N: 44888	REPLACE	1.00	\$5.00	5.00
3	FOOTREST P/N: 45124	REPLACE	1.00	\$15.00	15.00
4	FRONT FLASHER LIGHT ASSY 2	REPLACE	1.00	\$28.00	28.00
5	HOLDER LEVER CLUTCH P/N: 28676	REPLACE	1.00	\$15.00	15.00
6	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	4.00	\$35.00	140.00
7	LEVER CLUTCH P/N: 43143	REPLACE	1.00	\$15.00	15.00
8	RUBBER FOOTREST FRONT P/N: 40321	REPLACE	1.00	\$10.00	10.00
9	SWITCH HANDLE 4	REPLACE	1.00	\$60.00	60.00
10	TRANSPORT CHARGES P/N: 07169 - TOW BACK BIKE FOR ACCIDENT REPAIR.	*	1.00	\$50.00	50.00

SUB TOTAL

GST @ 7 %

GRAND TOTAL

\$380.00

\$26.60

\$406.60

*7- 175
102
157.5
312.50*



Address: No. 6, Defu Lane 4, Singapore 539410

Telephone: +65 6281 6520

Web: www.bhh.com.sg

Fax: (Main) +65 6261 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No alteration/modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



MOTOR CYCLE

CERTIFICATE OF INSURANCE

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP 189) OF THE REPUBLIC OF SINGAPORE
THE ROAD TRANSPORT ACT 1987 OF MALAYSIA
THE AGREEMENT BETWEEN THE MINISTER FOR FINANCE (SINGAPORE) AND THE MOTOR INSURERS' BUREAU OF SINGAPORE DATED 22 FEBRUARY 1975
THE AGREEMENT BETWEEN THE MINISTER OF TRANSPORT (MALAYSIA) AND THE MOTOR INSURERS' BUREAU OF WEST MALAYSIA DATED 15 JANUARY 1968
ANY SUBSEQUENT REVISIONS TO THE ABOVE ACTS AND AGREEMENTS

MYR
E SB
A593SD0
Cov. Type: T
KUKSBSB

CERTIFICATE No. AVFMSB0000631700 ChaNo: ME1RG1615G2002173

1. Index Mark and Registration Number of Vehicle PBM 264 M

2. Name of Policyholder BAN ROCK HIN CO PTE LTD

3. Effective Date of Commencement of Insurance for the purposes of the Ordinance 13 June 2017

4. Date of Expiry of Insurance 29 May 2018

5. Persons or Classes of Persons entitled to drive* (For certificate references MX1 and MX4, see overleaf)

A. THE POLICYHOLDER.

B. ANY AUTHORISED HIRER WHO HAS ENTERED A HIRE CONTRACT WITH THE POLICYHOLDER AND IS DRIVING ON THEIR ORDER OR WITH THEIR PERMISSION.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to Use* (For certificate reference MX1, see overleaf)

USE ONLY FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS OR PROFESSION.

THE POLICY DOES NOT COVER:

1. USE FOR RACING, PACE-MAKING, RELIABILITY TRIAL OR SPEED-TESTING.
2. USE WHILST DRAWING A TRAILER EXCEPT THE TOWING (OTHER THAN FOR REWARD) OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.
3. USE FOR THE CARRIAGE OF PASSENGERS FOR HIRE OR REWARD BY ANY PERSON TO WHOM THE VEHICLE IS HIRED.

Type of Cover : Third Party

* Limitations rendered inoperative by Section 79 of the Road Traffic Ordinance 1958 (Malaysia) or Section 7 of the Motor Vehicle (Third-Party Risks and Compensation) Ordinance 1960 (Republic of Singapore) are not to be included under the headings.

I/WE HEREBY CERTIFY that the policy to which this certificate relates is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and The Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Republic of Singapore)



Approved Insurers

Examined By

A handwritten signature in dark ink, appearing to be a cursive 'L' or similar character.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/01/2018 21:59
Date Of Accident	04/01/2018 13:00
Exact Location Of Accident	CARPARK C7 NEAR BLOCK 354 AT CLEMENTI AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBM264M
Insured/Policyholder	
Name Of Registered Owner	BAN HOCK HIN COMPANY PRIVATE LIMITED
Co Reg No	197000288K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62816520
Vehicle Particulars	
Manufacturer	YAMAHA
Model	FZN150
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	AVFMSB0000631700
Cover Note Number	N.A

Driver

Name of Driver	MUHAMMAD NASIR BIN ABDUL HAMID
NRIC No	S9139192I
Date Of Birth	24/10/1991
Occupation	OUTDOOR
Date Of Driving Pass	25/02/2010
Driving Experience	7 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88136295
Fax Number	
Contact Number	
Email Address	NASIR.ABDULHAMID@GRABTAXI.COM

Address	HDB CLEMENTI, 710 CLEMENTI WEST STREET 2 #10-263
Postcode	120710
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	CLEMENTI NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to Police Report Ref: T/20180104/2094 lodged at Clementi NPC. On 04/01/2018 at about 1200hrs, I parked the motorcycle FBM264M (V1) at lot 74 of carpark C7 near Blk 354 Clementi Ave 2. This is a rented motorcycle belonging to Ban Hock Hin Company which my employer Grab is renting. On the same day at 1326hrs when I returned from my duties around the vicinity, I noticed that bike FD7766K (V2) in lot 75 was fallen over V1 which fell onto the floor. I noticed the following damages on V1 (from the rider's perspective): 1) Completely detached left side mirror 2) Broken front right signal light 3) Dented front number plate. Dent on the left 4) Broken ignition switch 5) IU unit dangling from the motorcycle. I noticed the following damages on V2: 01) A dented and scratched rear storage box I subsequently took many photos of the scene, informed my employer who got the bike towed away. On the same day at around 1400hrs, after V1 was towed away, a Malay male and female came to tell me that they saw a lorry reversing along the carpark road, and when it moved off they saw that V1 and V2 had fallen over. They then snapped a photo of the lorry registration plate which is YP8026T. They did not however see the lorry knocking over my vehicles.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP8026T
Vehicle Make/Model/Colour	ISUZU/NPR85UH5A / WHITE
Details Of Properties	NIL
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

FD7766K

Vehicle Make/Model/Colour

YAMAHA/ FZ16 / BLACK

Details Of Properties

NIL

Vehicle Category

MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

Sketch Plan

Police Report



Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Clementi N.P.C.
20 Clementi Avenue 5 SINGAPORE 129559
Tel No: 1800-6728888

T201801042094

2 of 4

Report No: T201801042094

CONTINUATION OF REPORT

FBM254M	ALLIED WORLD ASSURANCE COMPANY, LTD (SINGAPORE BRANCH)			
---------	--	--	--	--

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
Name	MUHAMMAD NASIR BIN ABDUL HAMID	ID No.	S91391921
Related Vehicle	FBM254M (Motorcycle)	Contact No.	98568347
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B, 2A, 2 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details:

On 04/01/2018, at about 1200hrs I parked the motorcycle FBM254M (V1) at lot 74 of carpark C7 near Bk 354 Clementi Ave 2. This is a rented motorcycle belonging to Bang Hock Hin Company which my employer Grab is renting.

On the same day at 1326hrs when I returned from my duties around the vicinity, I noticed that bike FD7766K (V2) in lot 75 was fallen over V1 which fell onto the floor. I noticed the following damages on V1 (from the rider's perspective):

01) Cracked left side mirror

Police Report



**SINGAPORE
POLICE FORCE**



T/20180104/2094

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

3 of 4

Report No: T/20180104/2094

CONTINUATION OF REPORT

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999



T201801042284

4 of 6

Report No: T201801042284

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report:

Signature Of Informant:

Date/Time:

01/01/2018 10:38

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0288K
Vehicle Details	
Vehicle No.:	FBM264M
Vehicle to be Exported:	No
Intended De-registration Date:	12 Jan 2018
Vehicle Make:	YAMAHA
Vehicle Model:	FZN150
Primary Colour:	Green
Manufacturing Year:	2016
Engine No.:	G3E3E0042374
Chassis No.:	ME1RG1615G2002173
Maximum Power Output:	-
Open Market Value:	\$2,486.00
Original Registration Date:	12 Jun 2017
First Registration Date:	12 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$373.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jun 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,712.00
COE Rebate Amount:	\$6,319.00
Total Rebate Amount:	\$6,319.00

The information contained herein is correct as at 12 Jan 2018

OK

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	FBM264M
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1:	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	YAMAHA
Vehicle Model :	FZN150
Chassis No. :	ME1RG1615G2002173
Propellant :	Petrol
Engine No. :	G3E3E0042374
Engine Capacity :	149 cc
Maximum Power Output :	-
Maximum Laden Weight :	330 kg
Unladen Weight :	122 kg
Year Of Manufacture :	2016
Original Registration Date :	12 Jun 2017
Lifespan Expiry Date :	-
COE Category :	D - Motorcycle
Quota Premium :	\$6,712.00
COE Expiry Date :	11 Jun 2027

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jan 2018		12 Jan 2018 09:54 Edit Adj Rpt	S\$312.50 Edit Estimates	S\$312.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------




































CLAIM SUBFOLDER DETAILS				[Created by insurer]		
Insured:	-, Co. Reg. No.: -					
Main Claimant:	BAN HOCK HIN COMPANY PTE LTD , Co. Reg. No.: 197000288K					
Vehicle Reg. No.:	FBM264M	Date of Loss:	04/01/2018 00:00 - :59			
Claim Type:	TP / SNM18D00200C02	Policy/Cover Note No.:	DMCVSN1767281700			
Vehicle Reg. No. (Insured):	YP8026T	Policy No. (Claimant):				
		Excess:	S\$0.00			
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520					
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 23/01/2018]					
Adj Asg. Remarks:	NO ESTIMATE, ASSIGN MARCUS CHUA AS SJE.					

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete																				
<table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td></tr> </tbody> </table>	Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.													
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

*FBM264M (SNM18D00200C02)
[YP8026T]
TP
BAN HOCK HIN COMPANY PTE LTD
Jan 4 2018 12:00AM
[-]
Ban Hock Hin Co. Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
2	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
3	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
4	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
5	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
6	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
7	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
8	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
9	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
10	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
11	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
12	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
13	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
14	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
15	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
16	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
17	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
18	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
19	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
20	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
21	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
22	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
23	13/01/18 12:20	Odometer Reading						Load JPG	<input checked="" type="checkbox"/>	
24	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
25	13/01/18 12:20	Chassis Number						Load JPG	<input checked="" type="checkbox"/>	
26	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
27	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
28	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
29	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
30	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
31	13/01/18 12:20	General View						Load JPG	<input checked="" type="checkbox"/>	
32	19/01/18 08:05	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
33	19/01/18 08:05	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
34	19/01/18 08:05	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
35	19/01/18 08:05	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	

36	19/01/18 08:05	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
37	19/01/18 08:05	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
38	19/01/18 08:05	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
39	19/01/18 08:05	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	12/01/18 09:52	PRS		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18000729/URD3E2
Date: 19/01/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN1767281700
Claimant Vehicle No : FBM264M Insured Vehicle No : YP8026T
Date of Loss: 04/01/2018 Nature of Claim: TP Claim No: SNM18D00200C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBM264M
Make & Model: YAMAHA FZN150, 149cc Engine No: G3E3E0042374
Reg. Date: 12/06/2017 (Man. Year: 2016) Chassis No: ME1RG1615G2002173
Colour: Green Odometer: 5936 km
Engine Capacity: 149 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/80 R17 Rear Tyre Size: 140/60 R17
Front Left Side: MRF 8 mm Rear Left Side: MRF 8 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	190.00	157.50	32.50	17.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	190.00	155.00	35.00	18.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	380.00	312.50	67.50	17.76
+ GST 7.00/7.00% (\$\$)	26.60	21.88	4.72	17.74
Nett Amount (\$\$)	406.60	334.38	72.22	17.76

INSPECTION

Date of Assignment: 12/01/2018
Date Inspected: 12/01/2018 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)
No. 6 Defu Lane 4
Singapore 539410
Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 19 Jan 2018)
Parts: N/A YAMAHA FZN150 149cc (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for FBM264M)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BAR HANDLE	Bent	42.00 F	*42.00 FL
2	1		*BOLT FOOTREST REAR	Not Necessary	5.00 F	*- FL
3	1		*FOOTREST	Cut	15.00 F	*15.00 FL
4	1		*FRONT FLASHER LIGHT ASSY 2	Broken	28.00 F	*28.00 FL
5	1		*HOLDER LEVER CLUTCH	Cracked	15.00 F	*15.00 FL
6	1		*LEVER CLUTCH	Cut	15.00 F	*15.00 FL
7	1		*RUBBER FOOTREST FRONT	Not Necessary	10.00 F	*- FL
8	1		*SWITCH HANDLE 4	Cracked	60.00 F	*60.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	190.00	175.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	17.50
Total Parts (\$\$)	190.00	157.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR - FOR DISMANTLING AND ASSEMBLING OF PARTS	New	140.00	120.00
2	TRANSPORT CHARGES - TOW BACK BIKE FOR ACCIDENT REPAIR	New	50.00	35.00
Gross Labour Cost (\$\$)			190.00	155.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >