



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2015 MITSUBISHI CANTER FEB21ER3SDEB (CBU) (YN8184E)

Date of Loss

7 January 2018

Time of Loss

5.20

Loss Description

YN8184E (INSD) C/W COLLIDED INTO PROPERTY

Comment

Workshop Details

Total Rebate Amount

47037

Nett Loss Amount

\$24,963.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

03/04/2018



Days of work completion *

81



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

YN8184E

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

15/05/2015



Mileage

144

Age of Vehicle

2

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2015

ASSESSMENT INFO...

2015

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

VARADHARAJ RAMKUMAR

CATEGORY Make

POLICY INFORMAT... MITSUBISHI

ASSESSMENT INFO... MITSUBISHI

CATEGORY Model

POLICY INFORMAT... CANTER FEB21ER3SDEB (CBU)

ASSESSMENT INFO... CANTER FEB21ER3SDEB (CBU)

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... FEB21EA10093

POST SURVEY INF...

CATEGORY Date of Birth

FNOL INFORMATI... 10 June 1987

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 30

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... FEB21EA10093

CATEGORY Engine No

POLICY INFORMAT... 4P10B65140

ASSESSMENT INFO... 4P10B65140

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 2998

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 72000

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 2018

POST SURVEY INF... dd/mm/yyyy



CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy



CATEGORY Address

FNOL INFORMATI... C/O NO.56 SEMBAWANG ROAD #01-06,
779086, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... G6418914Q



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

12/01/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

2700

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

195R15X8

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

195R15X8(D)

Front left side

MICHELIN4mm

Front right side

MICHELIN4mm

Rear left side

MICHELIN3/3mm

Rear right side

MICHELIN3/3mm



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add

Approve

Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			FRONT BUMPER			Bent	480				480	Review
		2	1			O/S FRONT BUMPER SIDE GARNISH			Damaged	200				200	Review
		3	1			O/S FRONT BUMPER BRACKET (*CHECK) (\$100.00)				0				0	Review
		4	1			FRONT GRILLE			Cracked	550				550	Review
		5	1			FRONT GRILLE LOGO			Necessary	45				45	Review
		6	1			O/S HEADLAMP			Damaged	330				330	Review
		7	1			O/S HEADLAMP LOWER RUBBER LID			Damaged	12				12	Review
		8	1			O/S FRONT SIDE LAMP			Cracked	120				120	Review
		9	1			O/S FRONT SIGNAL LAMP			Damaged	135				135	Review
		10	1			O/S FRONT CORNER PANEL			Buckled	265				265	Review
		11	1			O/S FRONT CORNER PANEL INNER SEAL			Cut	18				18	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		12	1			O/S WINGMIRROR-BIG			Cracked	75				75	Reviewi
		13	1			O/S WINGMIRROR-STAY			Damaged	200				200	Reviewi
		14	1			O/S WINGMIRROR STAY CAP COVER			Damaged	12				12	Reviewi
		15	1			O/S WINGMIRROR STAY INNER COVER			Damaged	30				30	Reviewi
		16	1			FRONT WINDSCREEN GLASS			Cracked	650				650	Reviewi
		17	1			FRONT WINDSCREEN GLASS RUBBER			Cut	200				200	Reviewi
		18	1			O/S DOOR FRONT OUTER PILLAR			Bent	750				750	Reviewi
		19	1			O/S FRONT DOOR			Bent	890				890	Reviewi
		20	1			O/S FRONT DOOR STEP GARNISH			Cut	280				280	Reviewi
		21	1			O/S FRONT DOOR HINGES - TOP			Bent	95				95	Reviewi
		22	1			O/S FRONT DOOR HINGES - LOWER			Bent	95				95	Reviewi
		23	1			O/S FRONT DOOR LOCK			Repair	0	0	0	0	0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		24	1			O/S FRONT DOOR WEATHERSTRIP (*CHECK) (\$150.00)				0				0	Review
		25	1			O/S FRONT DOOR VERTICAL OUTER GARNISH			Cut	24				24	Review
		26	1			O/S FRONT DOOR GLASS CHANNEL			Cut	120				120	Review
		27	1			O/S FRONT DOOR INNER TRIMBOARD			Buckled	320				320	Review
		28	1			O/S FRONT DOOR INNER AIR GRILLE			Damaged	25				25	Review
		29	1			O/S FRONT DOOR WHEEL ARCH GARNISH			Cracked	40				40	Review
		30	3			O/S FRONT RIM LOCK NUT			Damaged	14				42	Review
		31	1			O/S FRONT UPPER ARM, BRACKET AND BALL JOINT			Bent	1600				1600	Review
		32	1			O/S FRONT LOWER ARM			Damaged	790				790	Review
		33	1			O/S FRONT KNUCKLE ARM			Bent	1200				1200	Review
		34	1			O/S FRONT KNUCKLE ARM BEARING - INNER			Necessary	55				55	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		35	1			O/S FRONT KNUCKLE ARM BEARING - OUTER			Necessary	50				50	Review
		36	1			O/S FRONT BEARING HUB			Bent	600				600	Review
		37	1			O/S FRONT BRAKE PAD			Serviceable	0	0	0	0	0	Deny
		38	2			O/S FRONT BRAKE ROTOR DISC			Serviceable	0	0	0	0	0	Deny
		39	1			O/S FRONT SHOCK ABSORBER			Bent	155				155	Review
		40	1			O/S FRONT BRAKE OIL SEAL-INNER			Necessary	18				18	Review
		41	1			O/S FRONT BRAKE OIL SEAL - OUTER			Necessary	18				18	Review
		42	1			O/S FRONT TIE ROD (*CHECK) (\$180.00)				0				0	Review
		43	1			O/S FRONT TIE ROD END (*CHECK) (\$95.00)				0				0	Review
		44	1			ENGINE MOUNTING - LH (*CHECK) (\$170.00)				0				0	Review
		45	1			ENGINE MOUNTING - RH (*CHECK) (\$170.00)				0				0	Review

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
	46	1			GEARBOX MOUNTING (*CHECK) (\$280.00)				0				0	Review

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REV
	1		TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS	900	0	0	Reviewing		
	2		TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	60	0	0	Reviewing		
	3		TO REMOVE AND RENEW AIR BAG SENSORS SEAT BELTS ASSY, TO REWIRING AND RE-SETTING PROGRAM (*CHECK) (\$280.00)	0	0	0	Reviewing		
	4		TO REMOVE DOOR'S FITTINGS	60	0	0	Reviewing		
	5		TO DISMANTLE AND CHECK FRONT UNDER-CARRIAGES. TO REPLACE AFFECTED PORTIONS	160	0	0	Reviewing		
	6		TO CONDUCT FRONT WHEEL ALIGNMENT TEST	60	0	0	Reviewing		
	7		TO CHECK AND REALIGNMENT ON CHASSIS MEMBER (*CHECK) (\$300.00)	0	0	0	Reviewing		
	8		TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	600	0	0	Reviewing		
	9		TO FOCUS HEADLAMPS, TO CHECK FRONT WIRING AND LIGHTING OPERATION	20	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS OF
REPAIR : 9
DAYS

Reviewing



2

(REPAIR
COST NOT
CONCLUDE)
(EXCLUDE
CHECK
ITEMS
S\$1,725.00
NETT)

Reviewing



3

O/S
HEADLAMP
BULB

Reviewing

12

NECESSARY



4

ERP
BRACKET

Reviewing

26

NECESSARY



5

O/S FRONT
RIM

Reviewing

480

DENTED



	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		6	O/S FRONT TYRE, FLAP AND TUBE (40%)	Reviewing	128	PUNCTURED	
		7	O/S FRONT BRAKE OIL	Reviewing	20	NECESSARY	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$10,315.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,860.00	\$1,860.00
Spare Parts	\$10,489.00	\$10,489.00
Miscellaneous	\$666.00	\$666.00
Excess	-\$2,700.00	-\$2,700.00

Submit for Review