

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)
Blk 10, #01-20, Sin Ming Industrial Estate Sector C
Singapore 575645

Tel: 64521208 Fax: 64520614 Email: admin@dingauto.sg;ding@dingauto.sg;kenneth.ding@dingauto.sg

(SUPPLEMENTARY)

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

SELAMAT BIN MOHAMAD
179 JALAN LOYANG BESAR
#03-09
Singapore 506926

Claimant Insurer: AIG Asia Pacific Insurance Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:	MSD/VPCP/17-001990	Date of Loss:	10/01/2018
Vehicle Reg. No.:	SLD5283D	Driveable?	
Party At Fault:	THIRD PARTY		
Driver (TP):	NG KIM SAN(HUANG JIN SHAN)		
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Vehicle Reg. Date:	21/06/2016
Vehicle Colour:	Silver		
Engine No:	1ZRY307155	Chassis No:	MR053REH104553196
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO ATTACH STATEMENTS		
Present Location:	DING AUTO PTE LTD (JALAN BOON LAY)		

COST OF CLAIMS	Amount
Parts	2,627.75
Miscellaneous Items	0.00
Labour	1,780.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,407.75
+ GST 7.00% (S\$)	308.54
Nett Amount (S\$)	4,716.29
+ Previous Estimates (S\$)	6,700.45
Claim Total (S\$)	11,416.74

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: Ding Auto Pte Ltd/SLD5283D/16/01/2018 08:37	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	DE / *220.00 F
2	1		*FRONT BUMPER REINF	0.00	0.00	? / *140.00 F PT /
3	1		*FRONT BUMPER SPONGE	0.00	0.00	? / *90.00 F DE /
4	1		*RADIATOR GRILLE	0.00	0.00	CRA / *220.00 F
5	1		*HEAD LAMP LHS	0.00	0.00	CRA / *280.00 F
6	1		*HEAD LAMP RHS	0.00	0.00	CRA / *280.00 F
7	1		*BRACE PANEL	0.00	0.00	PT / *55.00 F
8	1		*CONDENSER	0.00	0.00	? / *250.00 F PT /
9	1		*SUPPORT PANEL	0.00	0.00	R / *300.00 F
10	1		*FRONT NUMBER PLATE	0	0.00	PT / *35.00 FS
11	1		*RADIATOR	0.00	0.00	? / *350.00 F PT /
12	1		*FRONT BUMPER LOWER GRILLE	0	0.00	DE / *80.00 FS X SW

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	2,300.00
+ Margin on L,N Items 15.00% (\$\$)	327.75
Total Parts (\$\$)	2,627.75

Ding Auto Pte Ltd/SLD5283D/16/01/2018 08:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEAT FRONT DAMAGE	New	300 800.00
2	SPRAY FRONT BUMPER	New	200 250.00
3	SPRAY FRONT BONNET	New	X 250.00 NH
4	SPRAY SUPPORT PANEL	New	200 250.00
5	R&R CONDENSER AND REFILL AIR CON GAS	New	60 80.00
6	R&R RADIATOR AND REFILL COOLANT	New	80 150.00
Gross Labour Cost (\$\$)			1,780.00

Ding Auto Pte Ltd/SLD5283D/16/01/2018 08:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rasul
Hp 90010068

10 days

P/P

12/01/18 @ 1800 hrs

Recovery by part

23/1/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: