

Merimen Rasul ASSIGNMENT (Office)
 From (Person): Joel Goh of CTI Date/Time: 12/01/18 @ 3:06pm

Estimated Cost: _____ Bill to: _____

OD ☒ TP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 2518Y Insured: SKF 5845J

At Workshop no: Wah Hong Motors Tel: 65155 988

of 38, Toh Guan Rd East #01-67

Policy No: DMPCSN303868 H02 Claim No: SNM18D00209C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 10/01/2018

(Client's Record) _____

CA / REV / REP. / REV 24 HRS 'wp' R.O.D. Endorsement _____

Date/Time: 3:10pm @ 12/01 Person Contacted: Michael Vehicle ☒ IN/OUT

Date/Time: _____ Action/Instruction: ✓ SLD 2518Y

SLD 2518Y-X

SKF 5845J-CC4/AIG/12017657/Dq2g2z1 D.O.A. % 28/05/2012

12/4/18 Rasul confirmed \$15,332-50 (Real 932-50, 69) 16/4.

Signature: Ramu

REF:


76434

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLO 25184 Yr Regn: 2016 Jun
 Type: Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: HONDA V624 1.5X C.C. 1496
 Colour: Maroon A/C: Insured / Std / NI / NA
 Sp. Reading: 02143 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: Ru11106258
 Gen. Cond: Good B / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60R16
 R: _____
 BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 10/01/18 D.O.I. 12/01/18
 Survey held at Wah Han
 Des. of Damages B / B / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 17 APR 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) 17/4-typist

Report Format : merimen

Lump Sum / I.B.I: (\$) 15,332.50

Days Of Repair: 15

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$) ☐ : S-RS (\$) ☐ : Interview (\$) ☐ : Photos ☐ : Tech. Invs (\$) ☐ : Others ☐ : Weekend (\$)

Survey Fee:
 Transportation:

TOTAL

220

Survey Department Check List (Case Handler)

Reference No. : CS / CTI 18000758 / Rlvcl3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURA

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: Vefon 13 / 4 / 18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18000758/R1vd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 12-01-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKF 5845J	Veh. Inspected	SLD 2518Y
Policy No.	DMPCSN3038681702	Coverage (\$)	0.00
Claim No.	SNM18D00209C02	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	12/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/01/2018	Inspection Date	12/01/2018
Survey held at	WAH HONG & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jan 2018		12 Jan 2018 15:06 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN JUN YUAN, ID: S8208259Z		
Main Claimant:	CHANG WAI FOOK, ID: S1417643H		
Vehicle Reg. No.:	SLD2518Y	Date of Loss:	10/01/2018 18:00 - :59
Claim Type:	TP / SNM18D00209C02	Policy/Cover Note No.:	DMPCSN3038681702 (Comprehensive)
Vehicle Reg. No. (Insured):	SKF5845J	Policy No. (Claimant):	D17MTPV01008260
		Excess:	S\$0.00
Repairer:	Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub, 608581 Jurong East - Tel: +65 65155988		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/01/2018]		
Driver/Custodian (Insured):	TAN JUN YUAN (35 / Male), NRIC: S8208259Z		
Adj Asg. Remarks:	EST-\$18,483.55, ASSIGN LKK AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/01/2018 11:00
Date Of Accident	10/01/2018 18:50
Exact Location Of Accident	ALONG PIE/CHANGI B4 LORNIE ROAD EXIT 20B
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD2518Y
Insured/Policyholder	
Name Of Registered Owner	CHANG WAI FOOK
NRIC No	S1417643H
Email Address	DCURRYPUFF@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90705720
Alternative Phone No	OFFICE-90705720

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 1.5X CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01008260
Cover Note Number	

Driver

Name of Driver	CHANG WAI FOOK
NRIC No	S1417643H
Date Of Birth	07/02/1960
Occupation	INDOOR
Date Of Driving Pass	09/05/1980
Driving Experience	37 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90705720
Fax Number	
Contact Number	OFFICE-90705720
EMail Address	DCURRYPUFF@GMAIL.COM

Address	BLOCK 336 JURONG EAST AVENUE 1 #06-1630
Postcode	2260
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer to the attached Sketch Plan and the accident details

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKF5845J
Vehicle Make/Model/Colour	VEHICLE (B)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	STEVE TAN JUN YUAN
NRIC/Passport Number	S8208259Z
Contact Number	91879147
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKM8205A
-----------------------------	----------

Vehicle Make/Model/Colour	VEHICLE (C)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM KIM HONG EDWIN
NRIC/Passport Number	S8610718Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SLA2287D
Vehicle Make/Model/Colour	VEHICLE (D)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN SIOK PENG
NRIC/Passport Number	S1763721E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


10.30 am

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

PIE / Changi. B4 Lornie Road
Exit 20B



A. SLD 2518Y

B. SKF 5845J

C. SKM 8205A

D. SLA 2287D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On January 10, 2018 at about 6.50 pm, I was driving my vehicle (A) bearing registration number SLD2518Y along PIE towards Changi on the first lane.

The traffic was heavy as it was raining and the road was wet. Just before Lornie Road Exit 20B, a front vehicle suddenly moved his vehicle to the left (lane 2) and I quickly apply my brake. However, a split second later, I heard an impact on my rear and my vehicle was pushed forward and hit onto the front vehicle.

I stopped my vehicle and alight to check and noted that a Vehicle (B) SKF5845J had collided onto my rear and my vehicle was pushed forward and collided onto the front vehicle (C) SKM8205A. Also, there was another vehicle (D) who was in front of Vehicle (C).

As there was no injury to all parties, we exchange particulars as follows:

Third Party Particulars as follows:

Car No (B)	: SKF5845J	Steve Tan Jun Yuan	S8208259Z	91879147
Car No (C)	: SKM8205A	Lim Kim Hong Edwin	S8610718Z	
Car No (D)	: SLA2287D	Tan Siok Peng	S1763721E	

DECLARATION

I/We declare the foregoing particulars are true in every aspect.

Policyholder's Signature
Date & Time

10:30 am

Driver's Signature (if driver
is not the policyholder)
Date / Time

Reporting Centre Personnel Signature
Name :
NRIC / FIN No :

Name: CHANG WAI FOOK
Address: Blk 336 Jurong East Ave 1 #06-1630 S 2260
Policy No: D17MTPV01008260

Date : 11 January, 2018
Vehicle No : SLD2518Y

Quotation for Reinstste / Repairs for vehicle
(Supplementary)

Parts Replacement - Cost Price

Cost Price

1 Pc	Front Bonnet	\$	715.00	PAU -
1 Pc	Front Support Panel	\$	550.00	PA -
1 Pc	Front L/H Side Headlamp (HID)	\$	985.00	BR -
1 Pc	Front R/H Side Headlamp (HID)	\$	985.00	BR -
1 Pc	Front R/H Side Headlamp Lower Bracket	\$	36.00	CRA -
1 Pc	Front L/H Side Headlamp Lower Bracket	\$	36.00	CRA -
1 Pc	Front Bonnet Lock	\$	115.00	PA -
1 Pc	Front L/H Side Hinge	\$	48.00	PA -
1 Pc	Front R/H Side Hinge	\$	48.00	PA -
1 Pc	Front Bumper	\$	390.00	DE -
1 Pc	Front Bumper Grill	\$	335.00	CRA -
1 Pc	Front Grill Base	\$	350.00	CRA -
1 Pc	Front Bumper Reinforcement	\$	315.00	PA -
1 Pc	Front Bumper Lower Grille	\$	85.00	CRA -
1 Pc	Front Bumper Lower Spoiler	\$	225.00	DE -
1 Pc	Front Bumper Lower Refainer	\$	21.00	NE -
1 Pc	Front L/H Side Headlamp Top Bracket	\$	19.00	CRA -
1 Pc	Front R/H Side Headlamp Top Bracket	\$	19.00	CRA -
1 Pc	Front R/H Side Grill Chrome	\$	55.00	MIS -
1 Pc	Front L/H Side Grill Chrome	\$	55.00	MIS -
1 Pc	Front Grill Outer Garnish	\$	250.00	CRA -
1 Pc	Radiator	\$	960.00	PA -
1 Pc	Radiator Fan Cowling	\$	120.00	? CRA -
1 Pc	Air Com Condition	\$	560.00	PA -
1 Pc	Air Com Condition Fan Cowling	\$	105.00	? CRA -
1 Pc	Washer Tank	\$	85.00	? X SVC
1 Pc	Fan Blade	\$	75.00	? CRA -
1 Pc	Front Grill Top Garnish	\$	55.00	DE -
1 Pc	Front Grill Top Centre Bracket	\$	28.00	PA -
1 Pc	Rear Boot	\$	1,035.00	PAU -
1 Pc	Rear End Panel	\$	550.00	PA -
1 Pc	Rear Boot Garnish	\$	75.00	DE -
1 Pc	Rear Boot Lock	\$	105.00	PA -
1 Pc	Rear Top Garnish	\$	225.00	DE -
1 Pc	Rear Bumper	\$	480.00	DE -
1 Pc	Rear R/H Side Tail Lamp	\$	385.00	? X SVC
1 Pc	Rear L/H Side Tail Lamp	\$	385.00	? X SVC
1 Pc	Rear Silencer Box	\$	655.00	PA -
1 Pc	Rear R/H Side Bumper Bracket	\$	21.00	NE -
1 Pc	Rear L/H Side Bumper Bracket	\$	21.00	NE -
1 Pc	Rear R/H Bumper Side	\$	120.00	? X SVC
1 Pc	Rear L/H Bumper Side	\$	120.00	? X SVC
1 Pc	Rear R/H Side Bumper Reflector	\$	65.00	CRA -
1 Pc	Rear L/H Side Bumper Reflector	\$	65.00	? X SVC
1 Pc	Vezel Emblem	\$	75.00	NE -
1 Pc	H- Emblem	\$	28.00	NE -
1 Pc	Boot Rubber	\$	105.00	NE -
1 Pc	Rear Windscreen Moulding	\$	65.00	NE -
1 Pc	Front Number Plate	\$	30.00	CRA -
1 Pc	Rear Number Plate	\$	30.00	X SVC

Name: CHANG WAI FOOK
Address: Blk 336 Jurong East Ave 1 #06-1630 S 2260
Policy No: D17MTPV01008260

Date : 11 January, 2018
Vehicle No : SLD2518Y

Quotation for Reinstste / Repairs for vehicle

11,075
+ 10%
12182.50

Parts total: \$ 12,265.00
cost plus 10%
\$ 12,265.00

MISC & Labour & Charges

1 job remove & replace all the parts mentioned above knocking straighten up necessary affected \$ 2,800.00 ~~4200~~ } 3150
1 job To spray painting on affected areas \$ 1,200.00 1150 }

Labour's Total : \$ 4,000.00
Sub-Total : \$ 16,265.00
GST 7% : \$ 1,138.55
Grand Total : \$ 17,403.55

Thank You
Your Faithfully,

Michael Tee
Wah Hong Motors & Credit Pte Ltd
Tel : 6773 7377
Fax : 6896 6321
Email : michael@wahhong.sg



Resue
4p 90010068
15 days
P/P
12/01/18 @ 1200
Resurvey by paint
12182.50
3150.00
15,332.50
15 days
= P/P

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118000758/R1VD3N2

Date: 23/04/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3038681702
Claimant Vehicle No :	SLD2518Y	Insured Vehicle No :	SKF5845J
Date of Loss:	10/01/2018	Nature of Claim:	TP
		Claim No:	SNM18D00209C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD2518Y	Engine No:	L15B4026262
Make & Model:	HONDA VEZEL, 1.5 1.5X CVT (A)	Chassis No:	RU11106258
Reg. Date:	09/06/2016 (Man. Year: 2015)	Odometer:	2143 km
Colour:	Maroon		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,265.00	12,182.50	82.50	0.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	3,150.00	850.00	21.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	16,265.00	15,332.50	932.50	5.73
+ GST 7.00/7.00% (\$\$)	1,138.55	1,073.28	65.27	5.73
Nett Amount (\$\$)	17,403.55	16,405.78	997.77	5.73

INSPECTION

Date of Assignment:	12/01/2018	
Date Inspected:	12/01/2018 Inspected At:	Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub Singapore 608581
Estimated Period of Repair:	15.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD2518Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BONNET (WCP)	Buckled	715.00 F	*715.00 F
2	1	*FRONT SUPPORT PANEL (WCP)	Bent	550.00 F	*550.00 F
3	1	*FRONT L/H SIDE HEADLAMP (HID) (WCP)	Broken	985.00 F	*985.00 F
4	1	*FRONT R/H SIDE HEADLAMP (HID) (WCP)	Broken	985.00 F	*985.00 F
5	1	*FRONT R/H SIDE HEADLAMP LOWER BRACKET (WCP)	Cracked	36.00 F	*36.00 F
6	1	*FRONT L/H SIDE HEADLAMP LOWER BRACKET (WCP)	Cracked	36.00 F	*36.00 F
7	1	*FRONT BONNET LOCK (WCP)	Bent	115.00 F	*115.00 F
8	1	*FRONT L/H SIDE HINGE (WCP)	Bent	48.00 F	*48.00 F
9	1	*FRONT R/H SIDE HINGE (WCP)	Bent	48.00 F	*48.00 F
10	1	*FRONT BUMPER (WCP)	Deformed	390.00 F	*390.00 F
11	1	*FRONT BUMPER GRILL (WCP)	Cracked	335.00 F	*335.00 F
12	1	*FRONT GRILL BASE (WCP)	Cracked	350.00 F	*350.00 F
13	1	*FRONT BUMPER REINFORCEMENT (WCP)	Bent	315.00 F	*315.00 F
14	1	*FRONT BUMPER LOWER GRILLE (WCP)	Cracked	85.00 F	*85.00 F
15	1	*FRONT BUMPER LOWER SPOILER (WCP)	Deformed	225.00 F	*225.00 F
16	1	*FRONT BUMPER LOWER RETAINER (WCP)	Necessary	21.00 F	*21.00 F
17	1	*FRONT L/H SIDE HEADLAMP TOP BRACKET (WCP)	Cracked	19.00 F	*19.00 F
18	1	*FRONT R/H SIDE HEADLAMP TOP BRACKET (WCP)	Cracked	19.00 F	*19.00 F
19	1	*FRONT R/H SIDE GRILL CHROME (WCP)	Missing	55.00 F	*55.00 F
20	1	*FRONT L/H SIDE GRILL CHROME (WCP)	Missing	55.00 F	*55.00 F
21	1	*FRONT GRILL OUTER GARNISH (WCP)	Cracked	250.00 F	*250.00 F
22	1	*RADIATOR (WCP)	Bent	960.00 F	*960.00 F
23	1	*RADIATOR FAN COWLING (WCP)	Cracked	120.00 F	*120.00 F
24	1	*AIR CON CONDITION (WCP)	Bent	560.00 F	*560.00 F
25	1	*AIR CON CONDITION FAN COWLING (WCP)	Cracked	105.00 F	*105.00 F
26	1	*WASHER TANK (WCP)	Serviceable	85.00 F	*- F
27	1	*FAN BLADE (WCP)	Cracked	75.00 F	*75.00 F
28	1	*FRONT GRILL TOP GARNISH (WCP)	Deformed	55.00 F	*55.00 F
29	1	*FRONT GRILL TOP CENTRE BRACKET (WCP)	Cracked	28.00 F	*28.00 F
30	1	*REAR BOOT (WCP)	Buckled	1,035.00 F	*1,035.00 F
31	1	*REAR END PANEL (WCP)	Bent	550.00 F	*550.00 F
32	1	*REAR BOOT GARNISH (WCP)	Deformed	75.00 F	*75.00 F
33	1	*REAR BOOT LOCK (WCP)	Bent	105.00 F	*105.00 F
34	1	*REAR TOP GARNISH (WCP)	Deformed	225.00 F	*225.00 F
35	1	*REAR BUMPER (WCP)	Deformed	480.00 F	*480.00 F
36	1	*REAR R/H SIDE TAIL LAMP (WCP)	Serviceable	385.00 F	*- F
37	1	*REAR L/H SIDE TAIL LAMP (WCP)	Serviceable	385.00 F	*- F
38	1	*REAR SILENCER BOX (WCP)	Bent	655.00 F	*655.00 F
39	1	*REAR R/H SIDE BUMPER BRACKET (WCP)	Necessary	21.00 F	*21.00 F
40	1	*REAR L/H SIDE BUMPER BRACKET (WCP)	Necessary	21.00 F	*21.00 F
41	1	*REAR R/H BUMPER SIDE (WCP)	Serviceable	120.00 F	*- F
42	1	*REAR L/H BUMPER SIDE (WCP)	Serviceable	120.00 F	*- F
43	1	*REAR R/H SIDE BUMPER REFLECTOR (WCP)	Cracked	65.00 F	*65.00 F
44	1	*REAR L/H SIDE BUMPER REFLECTOR (WCP)	Serviceable	65.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*VEZEL EMBLEM (WCP)	Necessary	75.00 F	*75.00 F
46	1	*H-EMBLEM (WCP)	Necessary	28.00 F	*28.00 F
47	1	*BOOT RUBBER (WCP)	Necessary	105.00 F	*105.00 F
48	1	*REAR WINDSCREEN MOULDING (WCP)	Necessary	65.00 F	*65.00 F
49	1	*FRONT NUMBER PLATE (WCP)	Cracked	30.00 F	*30.00 F
50	1	*REAR NUMBER PLATE (WCP)	Serviceable	30.00 F	*- F

F=Franchise part.

Sub Total (S\$)	12,265.00	11,075.00
+ Margin on L,N Items 0.00/10.00% (S\$)	0.00	1,107.50
Total Parts (S\$)	12,265.00	12,182.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REPLACE ALL THE PARTS MENTIONED ABOVE KNOCKING STRAIGHTEN UP NECESSARY AFFECTED	New	2,800.00	2,000.00
2	TO SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	1,150.00
Gross Labour Cost (S\$)			4,000.00	3,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >