

CARZ AUTO SERVICES PTE LTD

NO 61, WOODLANDS INDUSTRIAL PARK E9

#04-04 E9 PREMIUM

S(757047)

Tel :90236692 Allan /93809969 Alex

Office 69093080

GST : 201409457D

The Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimate

Acknowledged by Repairer

Signature:

Date:

Date : 12.01.2018

Vehicle No. : GBF9939C

Make/Model : TOYOTA PROACE

Chassis YARVBBHVBGZ088586

Date of Accident 09/01/2018

Date of Register 05/18/2017

AIG ASIA PACIFIC INSURANCE PTE LTD**AIG BUILDING ,78 SHENTON WAY****#09-16, SINGAPORE 079120****Parts (List Price)**

	QTY	List Price (\$)	Parts Discount	Final price (\$)
01) Tailgate LH	1	\$1,520.80	25%	\$ 1,140.60
02) Tailgate Logo LH	1	\$85.90	25%	\$ 64.43
03) Tailgate emblem Toyota LH	1	\$65.80	25%	\$ 49.35
04) Tailgate weatherstrip	1	\$225.20	25%	\$ 168.90
05) Tailgate lower lock	1	\$190.60	25%	\$ 142.95
06) Tailgate emble "Proace"	1	\$88.60	25%	\$ 66.45
07) Rear Bumper	1	\$950.60	25%	\$ 712.95
08) Rear Bumper top frame	1	\$223.40	25%	\$ 167.55
09) Rear bumper towing cover	1	\$60.20	25%	\$ 45.15
10) Rear bumper reinforcement	1	\$452.60	25%	\$ 339.45
11) Rear bumper side frame	2	\$230.20	25%	\$ 172.65
12) Rear bumper reflector	2	\$170.40	25%	\$ 127.80
13) Rear end Panel outer	1	\$810.60	25%	\$ 607.95
14) Rear end Panel inner	1	\$720.40	25%	\$ 540.30

Special Nett Items

Bumper Clips	1 set	30		\$ 30.00
70km/hr" sticker	1	20		\$ 20.00
70km/hr Sticker	1	25		\$ 25.00
Sealant	2	60		\$ 60.00
Reverse sensor	1	280		\$ 280.00
Total		\$6,210.30		\$ 4,761.48

Labour Charges

To check wiring /remove and refix rear camera and distance setting	\$ 150.00
To apply anti rust	\$ 250.00
To remove /refit interior upholstery	\$ 80.00
To conduct water leakage test	\$ 250.00
To transfer Tailgate mechanism	\$ 120.00
To remove and refix rear rear windscreen	\$ 120.00
To putty & respray painting	\$ 800.00
To manage control unit,reset memories to specification	\$ 150.00
To remove and refix car decal	\$ 80.00
To knock out dents on affected areas and renew parts	\$ 1,400.00
To respray affected area	\$ 1,000.00
Total	\$ 4,400.00

E. & O. E.

Total S\$:

Lump sum re

20%

Final Amount

\$ 9,161.48

\$ 1,832.30

7,329.18

for Carz Auto Services Pte Ltd

Tanah 97495749
 WP
 12/1/18 @ 12pm
 Resurvey after repair
 6 days
 sure@khaauto.com