

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0548/2017
DATE : 21-DEC-2017

LONPAC INSURANCE BHD.
100 BEACH ROAD
#19-00 SHAW TOWER
S(189702)
TEL : 62507388
FAX : 62963767

OWNER'S NAME : TEO TAI LOON MR
ADDRESS : 15A SIAK KEW AVENUE
S(348057)
TELEPHONE NO : 90625444

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100454588-00000
VEHICLE NO : SLA3950R
MODEL CODE : GP3EKDC
MODEL/YEAR : XV 1.6I-S AWD CVT
ENGINE NO : FB16Y131015
CHASSIS NO : JF1GP3KC5GG165861
MILEAGE : 1 KM
DATE IN : 21/12/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 13/12/2017

Print Date : 21/12/2017
Print Time : 10:33:52

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLA3950R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	TO CONDUCT TP CLAIM LONPAC LOCATION MCPHERSON ROAD		
3	ZZ/002	REPLACE/REPAIR FRT BUMPER, PANEL	1120.00	600
4	ZZ/003	RESPRAY FRT BUMPER, PANEL	840.00	600
5	ZZ/004	TO CONDUCT (FRT / REAR) LIGHTNING TEST	50.00	30
6	ZZ/005	SUNDRIES	100.00	30
TOTAL LABOUR CHARGES			2110.00	

Not Authorised
macf@lkkauto.com R/P Regn
~~AA~~ Before Police Photo
67418034
LKK Auto (MA)
(MA)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is done "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
19 ROBINSON ROAD, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLA3950R

			DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	BUMPER FACE F XUV	57704FJ070	414.00	✓ ant		
2	BRKT SD F XUV RH	57707FJ141	7.20	✓ net		
3	BRKT SD F XUV LH	57707FJ151	7.20	✓ net		
4	COVER HOOK F	57731FJ460	4.70	✓ am		
5	LAMP ASSY HEAD EHR	84001FJ620	853.20	✓ ove		
SUB TOTAL			1286.30	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			257.26	0.00	0.00	0.00
GRAND TOTAL			1029.04	0.00	0.00	0.00
OVERALL TOTAL			1029.04			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.

19 WONG 8, TOA PAYOH

SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLA3950R

TOTAL LABOUR CHARGES 2110.00
TOTAL SPARE PARTS CHARGES 1029.04

GRAND TOTAL 3139.04 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.