

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHD 3238X

MAKE :

MODEL : HYUNDAI i40

DATE 11/1/2018

Ag/Bia-CP/P

IS

LKK-Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper /			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?			\$ 360.00
	Rear Bumper Side Bracket ?		\$ 180.00	\$ 49.00
	Rear Bumper Clips /			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover /			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor /			\$ 135.70
	Rear Bumper Rubber Mat /			\$ 50.00
	Rear Bumper Advertisement Logo /			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) /		\$ 100.00	\$ 200.00
				\$ 435.70
	Labour Charge			
	Panel Beating			200
	Spray Painting Charge			\$ 350.00
	Wiring Charge			\$ 180.00
	R/Refix Reverse Sensor			\$ 50.00
				\$ 120.00
				20
	TOTAL LABOUR			\$ 720.00
	ESTIMATE TOTAL			\$ 2,681.58

Nett
Nett
Nett
Nett

Kalvin LKK

11/1/18 14:00 hrs

20-71

P/P

Before Paint photo

LKK Auto Consultants hereby notify the Repairer of the following:

- Toles
- To display
- Parts prices
- To identify
- N
- S
- IS

Ackr
Signa
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.