Date/Time: 13012018
Insured: SJM 3610U Tel: 68420651 m No: CM 10 1402843
Insured: SJM 3510U Tel: 68420651 m No: CM 10 1402843
Tel: 68420651 m No: 0010 1402863
m No:
(cess:
(cess:
man wolzelle
D.O.A
900 H.O.D. Endorsement:
into, often repair indal 2016

RECEIVED 0 2 FEB 2018

Morranto

2/2/2018

	NUX I	CNMENT
,		IGNMENT
rom:	Date: 51206	Veh No: STT 4506+1 Yr Regnc 12 ORT 200
stimated Cost:		Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
DITPIWS ITP	RES / OD RES / EVA / INV / MV	Truck / Trailer or
o inspect Vehicle	NO: SIT 45064	Make: Tayota Logs cc (19)
t Workshop m/s	N-51 Automotive	Colour A/C: Insured / Std / NI / NA
ıf	a kaki suky one a \$ 0-1918	Sp.Reading T/Radio: Insured / Std / NI / NA
nsured:		Eng/No: 106 48 L
Policy No.		CNO: 186E2000140 88
Claims No.		Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured:	Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record	0	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:		Modi: Nil / S/Rim / STD A/Rim or
		Tyre Size: F: 215 / 45 & 7
(Policy Condition		R:
	had commenced its N/S IO/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair a	at the time of inspection.	3
Bal. or Market Va		- I Digital In the second of t
IDAC Accident R		L/Bal. mm L/Bal. mm
GIA / PR Seen:	1/2	D.O.A. D.O.I. 15 -01 - 16
Est. Repairs:	days Res.: Yes or No	Survey held at VU/S 10AM
Lum Sum:	% 3 Val.: Yes or No	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV /	REP. / 24 HRS [WP] Vehicle: IN / OU	
Date:	Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time	Action / Instruction	
	Estimate COR \$2,800	-\$3,300.
		/ Proto
		1 1 1 -1 -1 1
	,	10/20/2016
	,	· · · · · · · · · · · · · · · · · · ·
		· Stobell
		· (Stobe)
Data/Time Sile Base	107 Proli Report	
Deta/Time, File Pass	, <u> </u>	Days Of Repair:
1) 13/10/2-16-	TUPH :: Final Report	Days Of Repair:
Date/Time, File Reh	TUPH :: Final Report	Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation:
1) 13/10/2-16-	Typif : Final Report	Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation:
1) 13/10/2-16- Date/Time, File Reh	TuppH :: Final Report Add F	Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation: S+RS_SI

STT 4506H SMO 16017 THS GGS-1 TPRES/TL/EVA Policy Type: OD /(TP) Case Handler): Case handler to make sure all Information created by the assignment team are ACCURATE. Admin (Y-Date N-Date Y-Date N-Date (1) Office Assign Form Reference No. C Customer Code C Assign From N Assign Date C Veh No (Inspected) C Veh No (Insured) C D.O.A C Policy No. C C Claim No Insurance Authorisation (CA /REV/REP) C C Report Type Weekend Charges C Survey held at/Repairer N Excess C Surveyor ((Ino Riary): Case handler to make sure the surveryor completed all required information. (1) Assignment Form C Vehicle No Regn Month/Year C N . Vehicle Type Make & Model Engine Capacity. (C.C) C Colour N Odometer. (Sp.Reading) C Chassis No C General Condition N N Steering Brake Modification (Modi) Tyre Size C Tyre Make N Tyre Balance C C Date of Inspection Survey held N Des.of Damages N (2) System - (Views/Merimen) Damaged Vehicle Photographs Uploaded (3) Workshop Estimate/Assignment Form ALL Parts condition N Market Value for OD cases C Estimate Repair Cost for PRI (RSI, TMI, MSIG) C Days of repair C Finalised Amount C Re-inspection Cases to Finalize within 5 Days (4) System - (Views/Merimen) Resurvey photo Uploaded Check By:

Date

Survey Department Check List (Case Handler)



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS3/SMO16017245/Gqb-1

50 RAFFLES PLACE

Date: 12-01-2018

5-0	1/06	FROMCARORE 048623	Date: 12-01-2010	11 11 11 11 11 11 11 11 11 11 11 11 11
NG	APORE LAND TOW	VERSINGAPORE 048623	Code: SMO	
10.3		Policy Particulars	:- THIRD PARTY CLAIM	
170	Insured Veh.	SJM 5610U	Veh. Inspected	SJT 4506H
	moured von.	30111	Coverage (\$)	0.00
	Policy No.	CMTD1602803	Excess (\$)	0.00
	Ciaiii iio.	AGNES CHAN	Assign Date	12/01/2018
	Assign From		ticulars & Condition	
	- 0 00 del	· · · · · · · · · · · · · · · · · · ·	c.c	0
	Make & Model	HIDDEN	Year of Reg.	
	Eligine No.	HIDDEN	Colour	
	Chassis No.		Steering	
	Odometer	•	Modification	
	Brakes			
	General	Cond	litions of Tyres	us illustrations to
3.		Market Market State Control	Make	Balance
		Size		mm
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre	Doecri	ption of Damages	
4.		Descri	phon or bamego	
		Gen	eral Information	
5.	ELECTRICAL STATE	11/09/2016	Inspection Date	12/01/2018
	Accident Date	N-51 AUTOMOTIVE PL		
	Survey held at	2 KAKI BUKIT AVE 2		
		#01-17 KAKI BUKIT AUTOH SINGAPORE 417921		
5a.	On the second of the	to the state of the state of the	Remarks	
Ou.		ON WAS CONDUCTED ON A	"WITHOUT PREJUDICE" BAS S, WE HAVE NOT AUTHOR!	SIS. SED REPAIRS.

Catherine Chong (LKK Auto)

From: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>

Sent: Friday, 12 January, 2018 4:08 PM

To: Ashley Chong (LKK Auto)

Cc: 'assignments'

Subject: RE: ACC INL SJM5610U (I/V)/ SJT4506H ON 11.09.2016; OUR REF: CMTD1602803;

YOUR REF: NEW MATTER

Attachments: 1114_001.pdf; 1115_001.pdf; 1116_001.pdf; 1117_001.pdf; 1113_001.pdf;

SAS2075482.pdf; SAS2075596.pdf

Dear Ashley

We refer to the above matter.

We herewith enclosed 2 GIA reports, the repair bill and the survey report with the photographs for your attention.

Please prepare the paper resurvey of SJT4506H.

Please forward the report with the market value status within 5 days

Thank you.

Best Regards

Agnes Chan

Claims Divison

D: 6329 5327 | T: 6461 6555 | F: 6221 3302

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy.

From: Ashley Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Wednesday, 12 October, 2016 5:21 PM

To: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>

Cc: 'assignments' <assignments@lkkauto.com>

Subject: RE: ACC INL SJM5610U (I/V)/ SJT4506H ON 11.09.2016; OUR REF: CMTD1602803; YOUR REF: NEW MATTER

Dear Agnes,

Refer to your assignment on 14.09.2016 at 4.24PM.

Please be informed that we have inspected the vehicle SJT 4506H on 15.09.2016 at 10.00AM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,

Ashley Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ashley Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Tuesday, 11 October, 2016 9:21 AM

To: 'Chan, Shu Hui Agnes'; ASSIGNMENTS@LKKAUTO.COM

Subject: RE: ACC INL SJM5610U (I/V)/ SJT4506H ON 11.09.2016; OUR REF: CMTD1602803; YOUR REF: NEW MATTER

Dear Agnes,

Thank you for your email.

We will check and revert .

Best Regards,

Ashley Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chan, Shu Hui Agnes [mailto:agnes.chan@sompo.com.sg]

Sent: Monday, 10 October, 2016 5:15 PM

To: Ashley Chong (LKK Auto); ASSIGNMENTS@LKKAUTO.COM

Cc: sur@lkkauto.com

Subject: RE: ACC INL SJM5610U (I/V)/ SJT4506H ON 11.09.2016; OUR REF: CMTD1602803; YOUR REF: NEW MATTER

Dear Ashley

We refer to your email below.

Any preliminary advise for this matter.

Thank you.

Best Regards

Agnes Chan

Claims Divison

D: 6329 5327 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy.

From: Ashley Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Wednesday, September 14, 2016 5:13 PM

To: Chan, Shu Hui Agnes; ASSIGNMENTS@LKKAUTO.COM

Cc: sur@lkkauto.com

Subject: RE: ACC INL SJM5610U (I/V)/ SJT4506H ON 11.09.2016; OUR REF: CMTD1602803; YOUR REF: NEW

MATTER

Dear Agnes,

Thank you for the assignment.

Best Regards,

Ashley Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chan, Shu Hui Agnes [mailto:agnes.chan@sompo.com.sg]

Sent: Wednesday, 14 September, 2016 4:22 PM

To: SUR <sur@lkkauto.com>

Subject: ACC INL SJM5610U (I/V)/ SJT4506H ON 11.09.2016; OUR REF: CMTD1602803; YOUR REF: NEW MATTER

Dear LKK

We refer to the above matter.

We herewith enclosed 2 GIA reports and PRI notice for your attention.

New TPD assignment and please survey under without prejudice basis.

Thank you.

Best Regards

Agnes Chan

Claims Divison

D: 6329 5327 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- Any false reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aloresalu.	
	ACCIDENT STATEMENT
Date Of Report	13/09/2016 13:40
Date Of Accident	11/09/2016 15:50
Exact Location Of Accident	PIE TWDS CHANGI BEFORE EUNOS EXIT
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJT4506H
Insured/Policyholder	
Name Of Registered Owner	TIU INN KIEN
NRIC No	S7409805C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92321393
Alternative Phone No	OFFICE-92321393
Vehicle Particulars	WHO I DON'T HAVE A WAY TO SEE THE TOWN OF THE TAXABLE PARTY.
Manufacturer	ТОУОТА
Model	WISH-1.8 X (A)
Exact Purpose for which vehicle was being used at time of accident	_ PONO POLICIO DE DOMENTA CENTRO
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE SINGAPORE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1541729
Cover Note Number	
Driver	
Name of Driver	TIU INN KIEN
NRIC No	S7409805C
Date Of Birth	24/03/1974

Occupation INDOOR Date Of Driving Pass 01/01/1993

Driving Experience 23 YEARS AND 8 MONTHS

Gender

Mobile Number (LOCAL) +65-92321393

Fax Number

Contact Number OFFICE-92321393

EMail Address NOEMAIL Address

BLK 167 BEDOK SOUTH AVE 3 #08-485

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OWNER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION- HEAD TO REAR (TP HIT INSURED)

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Was any body injured in the Accident?

NO

Was any other material or property damaged?

YES

Was there any video captured by Car Camera?

NO

Number of Passengers (Including Driver)

5

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG PIE TOWARDS CHANGI AIRPORT BEFORE EUNOS EXIT ON A 4 LANES TRAFFIC EXPRESSWAY. ON THE FIRST LANE, (EXTREME RIGHT LANE) THE CAR IN FRONT OF ME APPLIED BRAKE TO A COMPLETE STOP. SO, I APPLIED BRAKE TO ALMOST COMPLETE STOP. I FELT A HEAVY IMPACT FROM THE REAR OF MY VEHICLE. SO, I ALIGHT FROM MY VEHICLE AND REALISED THAT A VEHICLE (SJM5610U) COLLIDED ONTO THE REAR OF MY VEHICLE (SJT4506H), DURING THAT TIME, THE TRAFFIC WAS QUITE HEAVY WITH CLEAR AND DRY WEATHER

Are accident photos available for attachment?

YES

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJM5610U

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE B

Name of Driver

PANG WENG CHING

NRIC/Passport Number

Contact Number

90557999

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signatur Time		Driver's Signature & Time	(If driver is not	the policyholde	r) / Date	Witnessed by Rep Personnel	porting Centre
Sketch Plan	PIE	TOWARDS	CHANGA	BEFORE	Euros	EXIT	
						PIE	CHANGI
	\Rightarrow				-		
		+ -	BD	AD		A-	· SJT 45061
		TITLE		Ť		В-	- 55 m 96101

Sketch Plan #2 Pg. 1

escribe Circumstances of the Accident
I WAS TRAVELUNG ALONG PIE TOWARDS CHANGE THAT LANGE CEXTREME RIGHT LANG). DN A FOUR LANG TRAFFIC EXPRESS WAY, ON THE IST LANGE CEXTREME RIGHT LANG).
THE CAR INFRONT OF ME APPLIED BRAKE TO Q COMPLETE STOP, AND SO I TOO
THE CAR INFRONT OF MY APPLIED BRAKES TO Y CONTROL A HEAVY IMPACT FROM THIS APPLIED THE BRAKE TO GLOBOT COMPLETED STOP I FEEL A HEAVY IMPACT FROM THIS APPLIED THE BRAKE TO GLOBOT COMPLETED STOP MY NEHICLE AND REGULZED THAT A
APPLIED THE BRAKE TO GLIMOST COMPLETED STOP I THEY AND REBUZED THAT A RRAR OF MY VEHICLE, SO I ALIGHTED FROM MY VEHICLE AND REBUZED THAT A
VEHICLE (STM 96104) COLLIDED TO THE REAR OF MY VEHICLE (STT 4506H).
DURING THE TIME THE TRAFFIC HAS JUITE HEAVY, WITH CHEARED AND DRIED WEATHER AND
FLOOR.
PLOOP .
Varicus A - SST 4506H
VEHICLE B - STM 5610 U
Opinion D
/

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (# driver is not the policyholder) / Date 8. Time

Witnessed by Reporting Centre Personnel

Sketch Plan #3 Pg. 1

LETTER OF UNDERTAKING

I/We, TIU INN KIGN	, the owner of vehicle no.	SJ74506H
My/Our Insurance is under M/s AXA Into claim under my/our Policy or against claim to M/s AXA Insurance Singapore I 14(fourteen) days of occurrence or My/Our Third Party claim is handle by my	the Third Party and if the former Pte Ltd with all relevant facts and discovery of damage.	r shall submit such a I documents Within
	×	
Signed and Acknowledge by:		
1/-	; ;	
The state of the s	17	(3/09/2018)
Nric no. and signature of policyholder	Company Stamp	Date

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- Any false reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

ACCI	DEV	т стл	TEM	IEN	т
ACC	UEIN		11-11		

Date Of Report

13/09/2016 14:41

Date Of Accident

11/09/2016 15:50

Exact Location Of Accident

PIE > CHANGI SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SJM5610U

Insured/Policyholder

Country/State of Loss

Name Of Registered Owner

PANG WENG CHING

S8122215J

Email Address

NRIC No

JEFF2000SG@HOTMAIL.COM

Mobile Phone No

(LOCAL) +65-90557999

Alternative Phone No

OFFICE-90557999

Vehicle Particulars

Manufacturer

HYUNDAI

Model

AVANTE-1.6 (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

REPORTING ONLY

If No, Please state action to be taken Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

SOMPO INSURANCE SINGAPORE PTE. LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

Policy Number

D16MTPV01007205

Cover Note Number

Driver

Name of Driver

PANG WENG CHING

NRIC No

S8122215J

Date Of Birth Occupation

06/07/1981 INDOOR

Date Of Driving Pass

18/06/2004

Driving Experience

12 YEARS AND 2 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-90557999

Fax Number

Contact Number

OFFICE-90557999

EMail Address

JEFF2000SG@HOTMAIL.COM

Address

BLK 521 WOODLANDS DRIVE 14 #06-353

Postcode

730521

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION- HEAD TO REAR (INSURED HIT TP)

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Was any body injured in the Accident?

NO

Was any other material or property damaged?

YES

Was there any video captured by Car Camera?

YES

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER SKETCH PLAN

Are accident photos available for attachment?

YES

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJT4506H

Vehicle Make/Model/Colour

Details Of Properties

VEH B

Name of Driver

TIU INN KIEN

NRIC/Passport Number

S7409805C

Contact Number

92321393

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that :


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Driver's Signature (If driver is not the policyholder) / Date & Time & Time Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date Personnel IVAN TEO



Describe Circumstances of the Accident

was driving on the extreme right lane alone PIE (changi) before In Euros Exit. The Vehicle Infront Suddenly stop and I couldn't stop in time and hit the back of his car. Coy.

You had been advised by the workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Reporting Only
Claim OD
Claim TP
Claim OD/TP at other workshop

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel **IVAN TEO**



Kaki Bukit AutoHub 2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail: sales@n51.com.sg Company Reg. No.: 200616038C GST Registration No.: 200616038C

TIU INN KIEN BLK 167 BEDOK SOUTH AVENUE 3 #08-485 SINGAPORE 460167

Contact: 92321393

TAX INVOICE

Date: 25/01/2017

Date in: 13/09/2016

Vehicle Num.: SJT4506H

Make/Model: TOYOTA WISH 1.8X A-2009 Chassis/Eng#: ZGE200014088/2ZR0438985

Accident Date: 11/09/2016 Claim No: CLM13698

Reference: SEPT-30/2016

Policy No.: P1541729 (11/10/2016)

Amount S\$

13,800.00

LUMPSUM REPAIR BILL AS PER SURVEYOR REPORT

REF: 0686-16-n51 DATED 27/12/2016 BY PAR AUTOMOTIVE CONSULTANCY

E. & O.E.

Sub S\$:

13,800.00

Add GST (7%) S\$:

966.00

Total Amount S\$:

14,766.00



for N-51 AUTOMOTIVE PTE LTD









Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 645 31173, Fax: 645 36131.

Report No: 0686-16-N51

27 December 2016

Tiu Inn Kien Blk 167 Bedok South Ave 3 #08-485 Singapore 460167

INVOICE No.

0686-16-N51

Vehicle No.

SJT4506H

S/NO.

SERVICES RENDERED

Amount due

1

Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).

\$1,007.00

Total amount payable

\$1,007.00

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 645 31173, Fax: 645 36131.

Report No: 0686-16-N51

27 December 2016

ACCIDENT VEHICLE SURVEY REPORT

Tiu Inn Kien

Blk 167 Bedok South Ave 3 #08-485

Singapore 460167

VEHICLE INFORMATION:

Vehicle Reg No .:

SJT4506H

Odometer:

106482km

Make & Model:

Toyota Wish 1.8 X A

Colour:

Red

Regn. No. 52986974I.

Chassis number:

ZGE200014088

Date of accident:

11/09/2016

Year of Regn.:

12/10/2009

Date inspected:

14/09/2016

Repairer at:

N-51 Automotive Pte Ltd

2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub

Singapore 417921

STATIC CHECKS, where applicable:

Steering:

serviceable

Footbrake:

serviceable

Handbrake:

serviceable

Paintwork:

Good

General condition:

Good

TIRE CONDITION:

LH / Make

RH / Make

Size

Front:

5mm/Continental

5mm/Continental

215/45R17

Rear:

5mm/Continental

5mm/Continental

215/45R17

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.

Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assesment

PARTS

PARTS				
Description of part	Qty	Condition	Repairer's	Our
STANDARD CONTRACTOR AND CONTRACTOR A			estimate	adjustment
REAR BUMPER	1	squashed	689.00	689:00 535
REAR BUMPER CORNER RETAINER L/R	2	bent	130.00	X 130.00 ////
REAR BUMPER IMPACT BRACKET L/R	2	bent	132.00	132.00 /
REAR BUMPER INNER SIDE SHIELD CLIPS L/R	6	necessary	39.00	39.00 /
REAR BUMPER INNER SIDE SHIELD L/R	2	reuse	91.60	0.00
REAR BUMPER SCREW WITH GARNISH L/R	2	necessary	50.00	× 50.00 N/V
REAR BUMPER SIDE RETAINER L/R	2	necessary	130.00	130.00 //
REAR END PANEL	1	buckled	490.00	490.00 /
REAR END PANEL 'LOWER'	1	bent	463.80	463.80 198
REAR END PANEL INNER TOP GARNISH	1	fractured	129.00	129.00
REAR END PANEL INNER TOP GARNISH CLIPS	4	necessary	26.00	26.00 /
REAR END PANEL LOCK STRIKER	1	bent	43.70	X 43.70 NN
REAR END PANEL TAILGATE ANTENNA SENSOR	1	shorted	158.00	158.00 /
REAR EXHAUST ALUMINIUM HEAT SHIELD	1	reuse	182.25	0.00
REAR EXHAUST GASKET	1	necessary	56.90	X 56.90 /
REAR EXHAUST RUBBER MOUNTING	3	distorted	135.00	X 135.00 7 NM
REAR EXHAUST SILENCER BOX	1	bent	971.00	× 971.00
REAR FENDER INNER AIR VENT L/R	2	reuse	97.00	0.00
REAR FENDER INNER TRIM BOARD COVER L/R	2	reuse	1,418.60	0.00
REAR FENDER INNER TRIM BOARD L/R	2	fractured	1,560.00	1,560.00
REAR FLOOR PANEL	1	repair	848.70	0.00
REAR FLOOR PANEL INNER TOP UPHOLSTERY BOARD	1	deformed	282.60	282.60 /
RR FLOOR SIDE PANEL INNER TOP UPHOLSTERY BOARD L/R	2	deformed	155.20	155.20
REAR FLOOR SIDE PANEL L/R	2	repair	207.60	0.00
REAR SUB CHASSIS FRAME L/R	2	repair	513.60	0.00
REAR TAILGATE	1	buckled	1,418.00	1,418.00 295
REAR TAILGATE 'LOGO' EMBLEM	1	necessary	34.00	34.00
REAR TAILGATE 'VALVE MATIC' EMBLEM	1	necessary	83.90	83,90 /
REAR TAILGATE 3RD BRAKE LAMP	1	reuse	185.00	0.00
REAR TAILGATE DAMPER L/R	2	bent	763.60	× 763.60 /
REAR TAILGATE HINGES L/R	2	bent	522.80	× 522.80
REAR TAILGATE INNER HANDLE	1	warped	45.00	× 48.00
REAR TAILGATE INNER TOP RUBBER SEAL L/R	2	necessary	52.40	× 52.40
REAR TAILGATE INNER TRIM BOARD	1	fractured	480.00	480:00 365
REAR TAILGATE MECHANISM LOCK	1	bent	509.00	X 509.00 ,
REAR TAILGATE NUMBER PLATE LAMP L/R	2	fractured	138.00	× 138.00 \ NN
REAR TAILGATE OUTER CHROME GARNISH	1	fractured	289.45	× 289.45
REAR TAILGATE OUTER CHROME GARNISH CLIPS	4	necessary	26.00	26.00
REAR TAILGATE OUTER LOCK HANDLE SWITCH	1	shorted	106.80	×106.80 /
RR TAILGATE REFLECTOR LAMP BACK RUBBER GASKET \mathbb{L}^r	2	necessary	40.00	× 40.00 (
REAR TAILGATE REFLECTOR LAMP CLIPS L/R	2	necessary	13.00	X 13:00) W/V
REAR TAILGATE REFLECTOR LAMP L/R	2	fractured	130.00	X 130:00 /

		Sub-total 3 Parts-total	S\$ 4,885.00 S\$ 18,070.60	S\$ 3,905.00 S\$ 13,134.76	
	Subtota	al before discount	S\$ 4,885.00	S\$ 3,905.00	120
SPARE TYRE	1	reuse -	280.00	0.00	520
REAR TAILGATE WINDSCREEN SEALANT	1	necessary	100.00	100:00	50
REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS - SET	1	necessary	30.00	30.00	_
REAR TAILGATE SPOILER CLIPS - SET	1	necessary	30.00	× 30:00	/
REAR TAILGATE REVERSE CAMERA	1	shorted	800.00	×800.00	
REAR TAILGATE NUMBER PLATE HOLDER	1	bent	50.00	×50.00	1
REAR TAILGATE NUMBER PLATE	1	bent	25.00	×25.00	SM
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	necessary	30,00	30,00	/
REAR TAILGATE INNER CAMERA RECORDER	1	shorted	800.00	₹800.00	\sim
REAR TAILGATE CARBON STICKER	1	necessary	300,00	300.00	
REAR FLOOR PANEL INSULATOR MAT	1	necessary	350.00	X350.00	NN
REAR FENDER INSULATOR MAT L/R	2	reuse	700.00	0.00	
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	2	necessary	60.00	60,00	/
REAR BUMPER REVERSE SENSOR - SET	1	shorted	800.00	X800.00°	220
REAR BUMPER REFLECTOR L.E.D LAMP L/R - SET	1	shorted	500.00	×500.00	
REAR BUMPER CLIPS - SET	1	necessary	30.00	30.00	
		Sub-total 2	S\$ 162.00	S\$ 162.00	
Percentage discount 10% and 10%		al before discount	S\$ 180.00 S\$ 18.00	S\$ 180.00 S\$ 18.00	
REAR TAILGATE WINDSCREEN MOULDING	1 Subtate	necessary	180.00	180.00	
TO THE CONTROL OF THE STATE OF		Sub-total 1	S\$ 13,023.60	S\$ 9,067.76	4368.75
Percentage discount 25% and 25%		al before discount	S\$ 17,364.80 S\$ 4,341.20	S\$ 12,090.35 S\$ 3,022.59	5825
SPARE TYRE RETAINER LOCK	1	bent .	127.00	×127.00	JNN
REAR TAILLAMP L/R	2	fractured	816.00	×846.00	(
REAR TAILLAMP INNER PANEL L/R	2	repair	156.20	0.00	
REAR TAILLAMP CLIPS L/R	6	necessary	39.00	₹39.00	NN
REAR TAILGATE WIPER NOZZLE	1	reuse	33.60	0.00	75
REAR TAILGATE WIPER MOTOR	1	shorted	509.00	×509.00	JUN
REAR TAILGATE WIPER ARM RUBBER SEAL	1	necessary	30.40	×36.40	(
REAR TAILGATE WIPER ARM COVER	1	reuse	131.35	0.00	
REAR TAILGATE WIPER ARM	1	reuse	161.45	0.00	
REAR TAILGATE WINDSCREEN INNER GARNISH L/R	2	reuse	155.20	0.00	
REAR TAILGATE WINDSCREEN INNER GARNISH 'TOP'	1	reuse	105.80	0.00	
REAR TAILGATE WEATHERSTRIP	1	deformed	219.00		186.3
REAR TAILGATE SPOILER 'ORIGINAL'	1	reuse	986.50	0.00	170.00
REAR TAILGATE RUBBER GUIDE STOPPER L/R	4	deformed	56.80	× 56.80	NN

-	**	~	•	R
	13	.,	ъ.	

Labour Total Parts & Labour Total	S\$ 4,120.00 S\$ 22,190.60	SS 3,140.00 SS 16,274.76	
To apply anti-rust chemical on repaired and replaced panel.	120.00	60.00	
To mount vehicle on to Car 'O' Liner.	400.00	A 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
To provide labour, workmanship to change the above damaged bodyparts, repair, re- construct and re-align body structure, body alignments and damaged consistent to the accident.	1,500.00	1,100.00	800
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	160.00	X 120.00	NN
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1,500.00	1,200.00	100
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00	60.00	/
o remove, reinstall tailgate windscreen	150.00	120.00	/
o remove, reinstall electrical wiring harness, check lighting, and rewire for parking ensor.	150.00	80.00	30

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 13,800.00 and the recommended number of working days for the repairs is within 9 day(s).

B J Loi (I Eng., MIMI, AIRTE) Automotive Appraiser

7/20.75 20%: 5700 6 Days.

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 645 31173, Fax: 645 36131

Report No: 0686-16-N51

27 December 2016

ACCIDENT VEHICLE SURVEY REPORT

Tiu Inn Kien Blk 167 Bedok South Ave 3 #08-485 Singapore 460167

VEHICLE INFORMATION:

Vehicle Reg No.:

SJT4506H

Odometer:

106482km

Make & Model:

Toyota Wish 1.8 X A

Colour:

Red

Regn No: 52986974L

Chassis number:

ZGE200014088

Date of accident:

11/09/2016

Year of Regn.:

12/10/2009

Date inspected:

14/09/2016

Repairer at:

N-51 Automotive Pte Ltd

2 Kaki Bukit Ave 2 #01-18

Kaki Bukit Auto Hub

Singapore 417921

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internation	onale Des Experts En Autom	obile
SOMPO INSURANCE	SINGAPORE PL	Ref : CS3/SMO16017	7245/Gqbs2-1
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TO	OWERSINGAPORE 048623	Date: 02-02-2018	
	Delley Porticulare	Code: SMO	M
l	SJM 5610U	Veh. Inspected	SJT 4506H
Insured Veh.	D16MTPV01007205	Coverage (\$)	0.00
Policy No.	CMTD1602803	Excess (\$)	0.00
Claim No.	AGNES CHAN	Assign Date	12/01/2018
Assign From		iculars & Condition	
2. Make & Model	TOYOTA WISH	c.c	1797
	HIDDEN	Year of Reg.	2009
Engine No. Chassis No.	ZGE200014088	Colour	RED
Odometer	106482	Steering	IN ORDER
	IN ORDER	Modification	SPORTS RIM
Brakes General	GOOD	Modification	
3.	3-3-3-3-3-3-3-3-3-3-3-3-3-3-3-3-3-3-3-	tions of Tyres	
3.	Size	Make	Balance
R/H Front Tyre	215/45R17	CONTINENTAL	6 mm
L/H Front Tyre	215/45R17	CONTINENTAL	6 mm
R/H Rear Tyre	215/45R17	CONTINENTAL	6 mm
L/H Rear Tyre	215/45R17	CONTINENTAL	6 mm
4.	Descrip	tion of Damages	
	ISTAINED DAMAGES AT THE R	EAR PORTION.	
5.		ral Information	
Accident Date	11/09/2016	Inspection Date	15/09/2016
Survey held at	N-51 AUTOMOTIVE PL		
	2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHU SINGAPORE 417921	В	
5a.		Remarks	
A)THE INSPECT B)IN ACCORDAN	ON WAS CONDUCTED ON A'VICE TO YOUR INSTRUCTIONS,	ITHOUT PREJUDICE" BA WE HAVE NOT AUTHORI	SIS. SED REPAIRS.
5b.		te Days of Repair	

ESTIMATED NORMAL PERIOD FOR REPAIR:

6 Working Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 4506H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	SQUASHED	689.00	535.00
- 6	REAR BUMPER CORNER RETAINER L/R	NOT NECESSARY	130.00	-
	REAR BUMPER IMPACT BRACKET L/R	BENT	132.00	132.00
	REAR BUMPER INNER SIDE SHIELD CLIPS L/R	NECESSARY	39.00	39.00
	REAR BUMPER INNER SIDE SHIELD L/R	REUSE	91.60	
	REAR BUMPER SCREW WITH GARNISH L/R	NOT NECESSARY	50.00	-
2	REAR BUMPER SIDE RETAINER L/R	NECESSARY	130.00	130.00
1	REAR END PANEL	BUCKLED	490.00	490.00
1	REAR END PANEL 'LOWER'	BENT	463.80	198.00
	REAR END PANEL INNER TOP GARNISH	FRACTURED	129.00	129.00
	REAR END PANEL INNER TOP GARNISH CLIPS	NECESSARY	26.00	26.00
	REAR END PANEL LOCK STRIKER	NOT NECESSARY	43.70	-
	REAR END PANEL TAILGATE ANTENNA SENSOR	SHORTED	158.00	158.00
1	REAR EXHAUST ALUNIMIUN HEAT SHIELD	REUSE	182.25	-
1	REAR EXHAUST GASKET	NOT NECESSARY	56.90	-
3	REAR EXHAUST RUBBER MOUNTING	NOT NECESSARY	135.00	-
1	REAR EXHAUST SILENCER BOX	NOT NECESSARY	971.00	-
2	REAR FENDER INNER AIR VENT L/R	REUSE	97.00	
	REAR FENDER INNER TRIM BOARD COVER L/R	REUSE	1,418.60	-
	REAR FENDER INNER TRIM BOARD L/R	FRACTURED	1,560.00	1,560.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	848.70)
-	REAR FLOOR PANEL INNER TOP UPHOLSTERY BOARD	DEFORMED	282.60	282.60
2	RR FLOOR PANEL INNER TOP UPHOLSTERY BOARD L/R	DEFORMED	155.20	155.20
2	REAR FLOOR SIDE PANEL L/R	TO REPAIR SEE LABOUR	207.60	
2	REAR SUB CHASSIS FRAME L/R	TO REPAIR SEE LABOUR	513.60	
	REAR TAILGATE	BUCKLED	1,418.00	1,295.00
	REAR TAILGATE 'LOGO' EMBLEM	NECESSARY	34.00	34.00
	REAR TAILGATE 'VALVE MATIC' EMBLEM	NECESSARY	83.90	83.90
	REAR TAILGATE 3RD BRAKE LAMP	REUSE	185.00)
133	REAR TAILGATE DAMPER L/R	NOT NECESSARY	763.6	0
	REAR TAILGATE HINGE L/R	NOT NECESSARY	522.8	0
0.7	1 REAR TAILGATE INNER HANDLE	NOT NECESSARY	45.0	0

Report Ref No. CS3/SMO16017245/Gqbs2-1



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR TAILGATE INNER TOP RUBBER SEAL L/R	NOT NECESSARY	52.40	34
	REAR TAILGATE INNER TRIM BOARD	FRACTURED	480.00	365.00
	REAR TAILGATE MECHANISM LOCK	NOT NECESSARY	509.00	-
	REAR TAILGATE NUMBER PLATE LAMP L/R	NOT NECESSARY	138.00	
	REAR TAILGATE OUTER CHROME GARNISH	NOT NECESSARY	289.45	-
	REAR TAILGATE OUTER CHROME GARNISH CLIPS	NECESSARY	26.00	26.00
	REAR TAILGATE OUTER LOCK HANDLE SWITCH	NOT NECESSARY	106.80	-
	RR TAILGATE REFLECTOR LAMP BACK RUBBER GASKET L/R	NOT NECESSARY	40.00	-
2	REAR TAILGATE REFLECTOR LAMP CLIPS L/R	NOT NECESSARY	13.00	-
1	REAR TAILGATE REFLECTOR LAMP L/R	NOT NECESSARY	130.00	-
	REAR TAILGATE RUBBER GUIDE STOPPER L/R	NOT NECESSARY	56.80	-
1	REAR TAILGATE SPOILER 'ORIGINAL'	REUSE	986.50	1
1	REAR TAILGATE WEATHERSTRIP	DEFORMED	219.00	186.30
1	REAR TAILGATE WINDSCREEN INNER GARNISH 'TOP'	REUSE	105.80	-
2	REAR TAILGATE WINDSCREEN INNER GARNISH L/R	REUSE	155.20	-
1	REAR TAILGATE WIPER ARM	REUSE	161.45	-
-	REAR TAILGATE WIPER ARM COVER	REUSE	131.35	-
	REAR TAILGATE WIPER ARM RUBBER SEAL	NOT NECESSARY	30.40	-
	REAR TAILGATE WIPER MOTOR	NOT NECESSARY	509.00	-
	REAR TAILGATE WIPER NOZZLE	REUSE	33.60	-
ė	REAR TAILLAMP CLIPS L/R	NOT NECESSARY	39.00	·
	REAR TAILLAMP INNER PANEL L/R	TO REPAIR SEE LABOUR	156.20	
	REAR TAILLAMP L/R	NOT NECESSARY	816.00	9
	SPARE TYRE RETAINER LOCK	NOT NECESSARY	127.00	0
	LESS 25% DISCOUNT		-4,341.20	-1,456.25
			13,023.6	4,368.75
	NETT ITEMS			
1 8	1 REAR TAILGATE WINDSCREEN MOULDING (N)	NECESSARY	180.0	
	LESS 10% DISCOUNT		-18.0	
			162.0	0 162.00
	SPECIAL NETT ITEMS			
1	1 SET REAR BUMPER CLIPS (SN)	NECESSARY	30.0	0 30.0
	1 SET REAR BUMPER REFLECTOR L.E.D LAMP L/R (SN)	NOT NECESSARY	500.0	333
	1 SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	800.0	220.0

Report Ref No. CS3/SMO16017245/Gqbs2-1



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	SET REAR FENDER INNER TRIM BOARD CLIPS L/R (SN)	NECESSARY	60.00	60.00
5463	REAR FENDER INSULATOR MAT L/R (SN)	REUSE	700.00	-
	REAR FLOOR PANEL INSULATOR MAT (SN)	NOT NECESSARY	350.00	-
	REAR TAILGATE CARBON STICKER (SN)	NECESSARY	300.00	100.00
1	REAR TAILGATE INNER CAMERA RECORDER (SN)	NOT NECESSARY	800.00	-
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR TAILGATE NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR TAILGATE NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	24
1	REAR TAILGATE REVERSE CAMERA (SN)	NOT NECESSARY	800.00	(#
1	SET REAR TAILGATE SPOILER CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	100.00	50.00
1	SPARE TYRE (SN)	REUSE	280.00	-
	£5 28		4,885.00	520.00
	LABOUR		12427.000	P005-0-0044
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.		150.00	30.00
	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.		150.00	120.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		140.00	60.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.		1,500.00	1,000.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	160.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RECONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL, REAR FLOOR SIDE PANEL L/R, REAR SUB CHASSIS FRAME L/R AND REAR TAILLAMP INNER PANEL L/R.	1	1,500.00	800.00
	TO MOUNT VEHICLE ON TO CAR 'O' LINER.	NOT NECESSARY	400.00	
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	AND STREET, MAIN STREET, STREE	120.00	60.00
			4,120.0	2,070.00



Page No.:4 of 4

RECOMMENDED COST OF LUMP SUM REPAIRS	22,190.60	7,120.75
RECOMMENDED COST OF LUMP SUM REPAIRS		5,700.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/SMO16017245/Gqbs2-1

XING GUO QIANG

M.MATAI, AMSAE-A

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Automotive Assessor Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.