

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHC5917L -

AAD1801-110

Not Authored
Resumy B4 pain 83550:19

Vehicle No.:	SHC5917L - CANDY
Chassis No.:	VF1ABL15AUC281246
Vehicle Make:	RENAULT
Vehicle Model:	LATTITUDE
Date of Accident :	08.01.2018
Third Party Insurer :	III

PART			LIST	
1	1	BUMPER COVER REAR	\$	1,108.46
2	1	BUMPER LOWER REAR	\$	768.84
3	1	BUMPER BRACKET CTR REAR	\$	113.47
4	1	BUMEPR BRACKET SIDE RH REAR	\$	135.97
5	1	BUMEPR RETAINER RH REAR	\$	44.99
6	1	BUMPER REFLECTOR RH	\$	43.61
7	1	BUMEPR BRACKET SIDE LH REAR	\$	135.97
8	1	BUMEPR RETAINER LH REAR	\$	44.99
9	1	ROCKER PANEL OUTER RH	\$	987.49
10	1	FENDER PANEL REAR RH	\$	3,299.13
11	1	WHEELARCH REAR RH	\$	543.47
12	1	TAILLAMP RH	\$	552.55
13	1	TAILLAMP PANEL RH	\$	986.70
14	1	EXHAUST REAR	\$	7,489.05
15	1	EXHAUST CAP REAR	\$	230.49
16	1	DOOR PANEL REAR RH	\$	2,844.66
17	1	DOOR GUIDE REAR RH	\$	176.82
18	1	DOOR HINGE UPPER RH	\$	274.50
19	1	DOOR HINGE LOWER RH	\$	300.55
20	1	DOOR GRAB HANDLE REAR RH	\$	210.96
21	1	DOOR HANDLE OUTER REAR RH	\$	126.49
22	1	DOOR HANDLE CAP REAR RH	\$	35.52
23	1	DOOR HANDLE SEAL REAR RH	\$	7.89
24	1	DOOR HANDLE COVER REAR RH	\$	13.22
25	1	DOOR HANDLE MODULE REAR RH	\$	133.60
26	1	DOOR WHEATHESTRIIP REAR RH	\$	410.66
27	1	DOOR SEAL REAR RH	\$	162.02
28	1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69
29	1	DOOR MOULDING REAR RH	\$	176.82
30	1	DOOR PANEL FRT RH	\$	2,844.66

TOTAL	\$	24,538.24
10%	\$	2,453.82
	\$	22,084.42

Specical Nett

1	1SET	PARKING AID	\$	SH	700.00	} X
2	1SET	REAR BUMPER CLIP	\$	nn	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	nn	10.00	
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	nn	20.00	
6	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	
7	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	
8	1	EXHAUST MOUNTING REAR	\$	SH	17.82	
9	1	TAILLAMP CLIP RH	\$	nn	5.00	
10	1SET	WHEELARCH CLIP RR RH	\$	nn	66.00	
11	2	REAR WINDSCREEN SELANT	\$	nn	80.00	
12	1	WINDSCREEN MOULDING	\$	nn	100.00	
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
14	1	CAP HUB RH RR	\$	SH	35.00	
15	1	RIM RH RR	\$	SH	385.00	
16	1	TYRE RH RR	\$	SH	330.00	
17	1	DOOR STICKER "Trans-cab"	\$	nn	80.00	
18	1	DOOR STICKER "Classic"	\$	nn	30.00	
19	1	DOOR STICKER "6555-3333"	\$	nn	80.00	

TOTAL	\$	2,225.82
TOTAL PARTS	\$	24,310.24

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	4401
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	4001
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
Towing Fees	\$	nn 120.00	X

To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 <i>601</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	<i>nn</i> 380.00 X

TOTAL	\$	10,990.00
Over All Total	\$	35,300.24

(PARTS BY PARTS)
Repair Days

~~15~~ Days
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: