



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS18000785/Ktd3n2

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 07-02-2018



Code : ICS

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKJ 9680U
Policy No.	MPC17B00029700	Coverage (\$)	0.00
Claim No.	DMCP1800008H/LC	Excess (\$)	750.00
Assign From	JANICE GOH	Assign Date	12/01/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JM6BL10Z2D0360984	Colour	METALLIC GREY
Odometer	65166	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 ZR17	MICHELIN	7 mm
L/H Front Tyre	215/45 ZR17	MICHELIN	7 mm
R/H Rear Tyre	215/45 ZR17	MICHELIN	7 mm
L/H Rear Tyre	215/45 ZR17	MICHELIN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/01/2018	Inspection Date	15/01/2018
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE MARKET VALUE IS S\$64,000.00 (EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**