

INS. CASE OWNER:

Irene/Lucas

CC 6 / CT118000789

1 Aug 2012

LKK:

IDAC:

ASSIGNMENT

Surveyor:

ADRIAN

DOI:

11/01/18

Date / Time:

11/01/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKB 97662

Name of Insured:

MUHAMAD BIN AB SAMAD

Insured Tel No.:

HP: 9625 2272

Excess Sec II : S\$

D.O.A: 10/01/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SNM18D00204C02

Policy No.:

DMPCSN 3044 891700

Make / Model:

CHEVROLET CRUZE 1.6L AUTO ABS

Place of Accident:

D/AB 2nd FLOOR
SLE TOWARDS BKE AFTER THAMSON
EXIT

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

WSD 9540

SKB 97662

SGD 5246X



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP: NHT

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SGD 5246X - X ; SKB 97662 - X

24/01/18 (THU) * Pending Est & PA

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 25/1

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

RECEIVED 24 MAY 2018

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

01.

Repair Cost:

S\$

4000.00

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

350.00

(S\$ 50 x 7 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

4350.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

4350.00

Name 1:

NEW HOCK TECK MOTOR PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

REF:

ASSIGNMENT

20/02/06

2006 Feb

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGDS246X Yr Regn: 2006 FebType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Ubs C/C: 1497Colour: Red A/C: Insured / Std / NI / NASp. Reading: 190807 T. Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053HY4204176200Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 175/65 R14R: 175/65 R14BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 11/01/18Survey held at: NHTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Check

LS - \$4000+ (Red: \$9992.55/71%)

MV: 20.5K

PV: 16.7K

Nett: 3.8K

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report1) _____
Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Insp (\$☐ Weekend (\$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I.: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18000789/Aus3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 12-01-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKB 9766Z	Veh. Inspected	SGD 5246X	
Policy No.	DMPCSN3044891700	Coverage (\$)	0.00	
Claim No.	SNM18D00204C02	Excess (\$)	0.00	
Assign From		Assign Date	12/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/01/2018	Inspection Date	11/01/2018	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

ONG HEE LOON

30/01/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP China

Thin Thin

Accident date: 10/01/2018

Estimated repair cost for vehicle no: SGD5246X TOYOTA VIOS 1.5 E M '06

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$590.10 ✓
2	2	Rear Boot Lid Hinge <i>Not new</i>	\$123.05	\$246.10 +
3	1	Rear Boot Lid Emblem Logo		\$42.50 ✓
4	1	Rear Boot Lid Vios Logo		\$43.55 ✓
5	1	Rear Boot Lid Vvti Logo <i>New</i>		\$41.10 ✓
6	1	Rear Boot Lid 1.5 Logo		\$28.70 ✓
7	1	Rear Boot Lid E Logo		\$28.70 ✓
8	1	Rear Boot Lid Centre Moulding <i>Not new</i>		\$172.85 +
9	1	Rear Boot Lid Number Plate <i>Not new</i>		\$50.00 x
10	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$182.25 ✓
11	1	Rear Boot Lid Inner Rubber <i>Not</i>		\$161.40 ✓
12	2	Rear Tail Lamp <i>Cracked</i>	\$281.45	\$562.90 ✓
13	4	Rear Tail Lamp Clip <i>Not</i>	\$8.00	\$32.00 +
14	2	Rear Tail Lamp Panel <i>Dented</i>	\$189.90	\$379.80 ✓
15	1	Rear Bumper <i>Deformed</i>		\$391.40 ✓
16	8	Rear Bumper Clip <i>Not</i>	\$6.50	\$52.00 30
17	2	Rear Bumper Bracket <i>Not new</i>	\$55.80	\$111.60 +
18	2	Rear Bumper Side Retainer <i>Not</i>	\$121.25	\$242.50 88
19	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$350.00 240(2N)
20	1	Rear End Panel <i>Dented</i>		\$781.50 666.70
21	1	Rear End Panel Top Garnish <i>Deformed</i>		\$281.45 65.90
22	2	Rear Fender Inner Trim Board <i>Not</i>	\$314.40	\$628.80 +
23	16	Rear Fender Inner Trim Board Clip <i>Not</i>	\$6.50	\$104.00 x
24	1	Rear Spare Tyre Panel <i>Repair</i>		\$681.75 x
25	1	Rear Spare Tyre Panel Top Cover <i>Not</i>		\$289.95 +
26	2	Rear Spare Tyre Panel Side Cover <i>Not</i>	\$381.20	\$762.40 +
27	1	Rear Spare Tyre Panel & End Panel Sealant <i>Not</i>		\$450.00 60(SN)
28	1	Rear Exhaust <i>Not new</i>		\$781.45 +

29	1	Rear Centre Exhaust		\$787.20 +
30	2	Rear Exhaust Mounting	\$64.80	\$129.60 +
31	1	Rear Exhaust Aluminium Cover		\$95.00 +

Subtotal :- \$9,482.55

S.N 269

3303

247725

Labour charges

To remove & refit cushion

~~\$280.00~~ 60

To remove & refit rear & centre exhaust

~~\$380.00~~ X

To remove & refit reverse sensor

~~\$100.00~~ 50

To check wiring

~~\$100.00~~ 30

Towing fee

~~\$100.00~~ X

Tuff kote

2280

~~\$150.00~~ 40

Panel beating

~~\$1,800.00~~ 1100

Spray painting

~~\$1,600.00~~ 1000

Subtotal :- \$4,510.00

Total:- \$13,992.55

total 5017.25

h/s. AK

06 days

AK

06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



SELL YOUR CAR BY BIDDING
HIGHEST SELLING PRICE GUARANTEED!
OR GET \$100 CASH!



Vios Price Range Depreciation > 10 year(s) Vehicle Type

Advanced Search

Used Car Comparison

--- Comparing 4 Vehicles ---

Toyota Vios 1.5A E (COE till 03/2021)



Add to Shortlist

Toyota Vios 1.5A E (COE till 03/2021)



Add to Shortlist

Toyota Vios 1.5A E (COE till 01/2021)



Add to Shortlist

Toyota Vios 1.5A E (COE till 01/2021)



Add to Shortlist

Clear All

Add all to Shortlist

Back to search result

CAR DETAILS

	Toyota Vios 1.5A E (COE till 03/2021)	Toyota Vios 1.5A E (COE till 03/2021)	Toyota Vios 1.5A E (COE till 01/2021)	Toyota Vios 1.5A E (COE till 01/2021)
Price	\$20,500	\$21,888	\$19,888	\$22,800
Instalment	N.A.	N.A.	N.A.	N.A.
Registration Date	09-Mar-2006	30-Mar-2006	05-Jan-2006	26-Jan-2006
Manufactured	2006	2006	2005	2005
Mileage	98,000 km	150,623 km	199,000 km	-
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,497 cc	1,497 cc	1,497 cc	1,497 cc
Road Tax	\$821 /yr	\$821 /yr	\$821 /yr	\$821 /yr
Power	80.0 kW (107 bhp)	80.0 kW (107 bhp)	80.0 kW (107 bhp)	80.0 kW (107 bhp)
Curb Weight	1,020 kg	1,020 kg	0 kg	0 kg
Features	Stock Unit. Sport Rim 15 Inch. Low Depreciation Of \$6.25K. Accident-free, Champagn Gold Color.	1.5L VVT-i 16 Valves Inline DOHC Engine, 5 Speed Auto Transmission, ABS, EBD, Dual SRS Airbags, Low Fuel Consumption Car.	Powerful And Fuel Efficient 1.5L VVTi Engine, 4 Cylinders Inline, DOHC, 16 Valves, Dual Airbags, ABS, Retractable Side Mirrors With Indicators.	Reliable 1.5L 4 Cyl Valves DOHC VVT-Transmission, Dual
Accessories	Double-din Touch Screen Radio.	Sports Rims, Factory Fitted Audio System, Leather Seat.	Leather Seats, Factory Sports Rims, Factory Fitted Audio, Retractable Side Mirrors With Signal Indicators, Reverse Sensor, Fully Original Conditions.	Factory Fitted Audi Solar Film, Upholst Seats.
Description	Engine Mounting Changed 10 Months Ago. Airbags Mandatory Change-out By Borneo Motors 2 Months Ago. New Brake Pads From 2 Months Ago. Car Is In Good Condition. Low Mileage, Low Fuel Consumption, Low Maintenance. This Is A Car Known To Be Reliable. Feel Free To Come Test Drive.	We Are The COE Specialists. No Gimmicks, Honest Dealing. 1 Owners With Low Mileage Clocked, Car In Superb Condition. No Repairs Needed.\$0 Down Payment With \$2200 Drive Away! 100% Approval! Trade In Welcome, Bank Loan Available. Call Us At Our Showroom For An Appointment Today!	Most Popular Japanese Sedan, Excellent And Original Condition, Low Depreciation At \$6K Plus Only. Low Fuel Consumption. Well Maintained Interior And Exterior.	Extremely Low Down Monthly Instalment! Low Maintenance! Low Fuel Consumption! Sell Paper And Body! E COE Car! Buy It For Of Mind, A Compar Outstanding Award Sales Service Assur Aircon Showroom Condition Now, Do
COE	\$24,771	\$24,771	\$28,317	\$28,317
OMV	\$13,040	\$13,040	\$12,903	\$12,903
ARF	\$14,344	\$14,344	\$14,194	\$14,194
Depreciation	\$6,500 /yr	\$6,810 /yr	\$6,670 /yr	\$7,500 /yr
No. of Owners	2	1	5	2
Type of Vehicle	Sedan	Sedan	Sedan	Sedan
Category	COE Car, Direct Owner Sale, Low Mileage Car	COE Car, Premium Ad Car	COE Car	COE Car
Availability	Available	Available	Available	Available

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 9703D

Vehicle Details

Vehicle No.: SGD5246X

Vehicle to be Exported: No

Intended De-registration Date: 11 Jan 2018

Vehicle Make: TOYOTA

Vehicle Model: VIOS 1.5E M

Primary Colour: Red

Manufacturing Year: 2006

Engine No.: 1NZX383718

Chassis No.: MR053HY4204176200

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$12,271.00

Original Registration Date: 20 Feb 2006

First Registration Date: 20 Feb 2006

Transfer Count: 0

Actual ARF Paid: \$13,499.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details



COE Expiry Date:	19 Feb 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$26,900.00
COE Rebate Amount:	\$16,716.00
Total Rebate Amount:	\$16,716.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Jan 2018

OK

Shirley Hiew (LKK Auto)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Monday, 22 January 2018 11:49 AM
To: Shirley Hiew (LKK Auto)
Subject: RE: (TP : LKK REF - CC3/CTI18000789/Aus3) (OurRef: SNM18D00204C02)
Attachments: SKB9766Z.PDF

Dear Shirley,

Pls refer to the above attachment.

Thank you.

Regards,

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6181
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Monday, 22 January, 2018 11:28 AM
To: Lucas Lee; Claims Dept of CTI; Thin Thin (LKKAuto)
Cc: Irene Tay; Jas Khine (LKKAuto); Admin A
Subject: RE: (TP : LKK REF - CC3/CTI18000789/Aus3) (OurRef: SNM18D00204C02)

Dear Lucas/Irene,

We refer to the above matter.

Meanwhile, Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 15 January 2018 3:37 PM
To: Lucas Lee <lucas.lee@sg.cntaiping.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>
Cc: Irene Tay <irene.tay@sg.cntaiping.com>; Jas Khine (LKKAuto) <jaskhine@lkkauto.com>; Admin A <admin-

a@lkkauto.com>

Subject: RE: (TP : LKK REF - CC3/CTI18000789/Aus3) (OurRef: SNM18D00204C02)

Dear Lucas,

Noted and thanks.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lucas Lee [<mailto:lucas.lee@sg.cntaiping.com>]

Sent: Monday, 15 January 2018 3:19 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: Irene Tay <irene.tay@sg.cntaiping.com>

Subject: (TP : LKK REF - CC3/CTI18000789/Aus3) (OurRef: SNM18D00204C02)

Dear Sirs,

Kindly refer to the above attachment.

Case Handler : Irene Tay

Regards,

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3, Anson Road, #16-00

Springleaf Tower,

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6181

Fax: 6224 7175

Email: claimsdept@sg.cntaiping.com

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18000789/Aub3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 25-05-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 9766Z	Veh. Inspected	SGD 5246X
Policy No.	DMPCSN3044891700	Coverage (\$)	0.00
Claim No.	SNM18D00204C02	Excess (\$)	0.00
Assign From		Assign Date	11/01/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	MR053HY4204176200	Colour	RED
Odometer	190807	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R14	SUMITOMO	6 mm
L/H Front Tyre	175/65 R14	SUMITOMO	6 mm
R/H Rear Tyre	175/65 R14	SUMITOMO	6 mm
L/H Rear Tyre	175/65 R14	SUMITOMO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/01/2018	Inspection Date	11/01/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGD 5246X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	DENTED	590.10	590.10
2	REAR BOOT LID HINGE @\$123.05	NOT NECESSARY	246.10	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	42.50	42.50
1	REAR BOOT LID VIOS LOGO	NECESSARY	43.55	43.55
1	REAR BOOT LID VVTI LOGO	NECESSARY	41.10	41.10
1	REAR BOOT LID 1.5 LOGO	NECESSARY	28.70	28.70
1	REAR BOOT LID E LOGO	NECESSARY	28.70	28.70
1	REAR BOOT LID CENTRE MOULDING	NOT NECESSARY	172.85	-
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
1	REAR BOOT LID INNER LOCK	DAMAGED	182.25	182.25
1	REAR BOOT LID INNER RUBBER	CUT	161.40	161.40
2	REAR TAIL LAMP @\$281.45	CRACKED	562.90	562.90
4	REAR TAIL LAMP CLIP @\$8.00	NOT NECESSARY	32.00	-
2	REAR TAIL LAMP PANEL @\$189.90	DENTED	379.80	379.80
1	REAR BUMPER	DEFORMED	391.40	391.40
8	REAR BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
2	REAR BUMPER BRACKET @\$55.80	NOT NECESSARY	111.60	-
2	REAR BUMPER SIDE RETAINER @\$121.25	NECESSARY	242.50	88.00
1	REAR END PANEL	DENTED	781.50	666.70
1	REAR END PANEL TOP GARNISH	DEFORMED	281.45	65.90
2	REAR FENDER INNER TRIM BOARD @\$314.40	NOT NECESSARY	628.80	-
16	REAR FENDER INNER TRIM BOARD CLIP @\$6.50	NOT NECESSARY	104.00	-
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	681.75	-
1	REAR SPARE TYRE PANEL TOP COVER	NOT NECESSARY	289.95	-
2	REAR SPARE TYRE PANEL SIDE COVER @\$381.20	NOT NECESSARY	762.40	-
1	REAR EXHAUST	NOT NECESSARY	781.45	-
1	REAR CENTRE EXHAUST	NOT NECESSARY	787.20	-
2	REAR EXHAUST MOUNTING @\$64.80	NOT NECESSARY	129.60	-
1	REAR EXHAUST ALUMINIUM COVER	NOT NECESSARY	95.00	-

Report Ref No. CC6/CTI18000789/Aub3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-	-825.75
			8,682.55	2,477.25
	<u>SPECIAL NETT ITEMS</u>			
1	REAR SPARE TYRE PANEL & END PANEL SEALANT (SN)	NECESSARY	450.00	60.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
			800.00	260.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT CUSHION.		280.00	60.00
	TO REMOVE & REFIT REAR & CENTRE EXHAUST.	NOT NECESSARY	380.00	-
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	50.00
	TO CHECK WIRING.		100.00	30.00
	TOWING FEE.	NOT NECESSARY	100.00	-
	TUFF KOTE.		150.00	40.00
	PANEL BEATING INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL.		1,800.00	1,100.00
	SPRAY PAINTING.		1,600.00	1,000.00
			4,510.00	2,280.00
	GRAND TOTAL		13,992.55	5,017.25
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00

Report Ref No. CC6/CT118000789/Aub3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.