

Not Authorised
11 Sep 87
Penny Aka Penny



ESTIMATE TO REPAIR

VEHICLE NO. : SJV 5667 J
MAKE : VOLKSWAGEN
MODEL : NEW GOLF 1.4 AT 5K13G5
YEAR : 2010
CHASSIS NO : WVVZZZ1KZAW022985

SURVEYOR NAME :
DATE OF SURVEY : 15 JAN 2010
TIME OF SURVEY :

DATE : 11-Jan-18
DATE OF ACCIDENT : 8-Jan-18
THIRD PARTY REF : SJM 7557 C / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper			<i>RM</i> \$ 1,132.05	✓
1 pc	Rear Bumper Reinforcement			\$ 606.05	✓
2 pcs	Rear Bumper Retainer		\$ 46.75	<i>RM</i> \$ 93.50	✓
1 pc	Rear End Panel			<i>RM</i> \$ 970.80	✓
1 pc	Tailgate			<i>RM</i> \$ 1,903.15	✓
1 pc	Tailgate "GOLF" Emblem			<i>RM</i> \$ 94.35	✓
1 pc	Tailgate "TS" Emblem			<i>RM</i> \$ 61.15	✓
				\$ 4,861.05	
	Less 10%			\$ 486.11	
				\$ 4,374.95	
1 tube	Rear Windscreen Sealant	S.Nett		<i>RM</i> \$ 40.00	✓
1 pc	Rear Number Plate	S.Nett		<i>RM</i> \$ 40.00	✓
	To putty & spray painting.			\$ 700.00	600
	To remove and refix rear windscreen glass.			\$ 120.00	✓
	To transfer tailgate fittings.			\$ 80.00	60
	To anti-rust.			\$ 60.00	30
	Labour Charges.			\$ 600.00	500
TG-RA/-					\$ 6,014.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____
Tel: 65-64520893 Fax: 65-64520894
UIC Reg No: 199307077D
C.S. Reg No: M2 C019058-C