



ESTIMATE TO REPAIR

VEHICLE NO. : SJV 5667 J
 MAKE : VOLKSWAGEN
 MODEL : NEW GOLF 1.4 AT 5K13G5
 YEAR : 2010
 CHASSIS NO : WVVZZZ1KZAW022985

SURVEYOR NAME :
 DATE OF SURVEY :
 TIME OF SURVEY :

DATE : 11-Jan-18
 DATE OF ACCIDENT : 8-Jan-18
 THIRD PARTY REF : SJM 7557 C / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 1,132.05
1 pc	Rear Bumper Reinforcement				\$ 606.05
2 pcs	Rear Bumper Retainer		\$ 46.75		\$ 93.50
1 pc	Rear End Panel				\$ 970.80
1 pc	Tailgate				\$ 1,903.15
1 pc	Tailgate "GOLF" Emblem				\$ 94.35
1 pc	Tailgate "TS" Emblem				\$ 61.15
					\$ 4,861.05
	Less 10%				\$ 486.11
					\$ 4,374.95
1 tube	Rear Windscreen Sealant	S.Nett			\$ 40.00
1 pc	Rear Number Plate	S.Nett			\$ 40.00
	To putty & spray painting.				\$ 700.00
	To remove and refix rear windscreen glass.				\$ 120.00
	To transfer tailgate fittings.				\$ 80.00
	To anti-rust.				\$ 60.00
	Labour Charges.				\$ 600.00
TG-RA/-					\$ 6,014.95

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd