

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ernest Tay

Date: 19 Jan 2018

Preliminary Advice

Insured Vehicle No : SHC5494P
TP Vehicle No : SKX208L
Make : BMW 318I
Date of Inspection : 16/01/2018
Inspection At : BH Auto Services Pte Ltd (Sin Ming)
Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117
Singapore 575636
Accident Date : 10/01/2018
Assignment Date : 11/01/2018
Est. Duration of Repair : 4 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesrear and front.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,621.15
Revised Amount	:S\$	2,439.25
Check Items (Estimated)	:S\$	2,325.20
Total	:S\$	4,764.45

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.