

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

EQ INSURANCE

Your Ref Vehicle No:
YP4651P(TP claim)

Date: 15/1/2018
Vehicle No: SJH8252B
Model: LANCER
Date of loss: 11/1/2018
Our ref: LSA210TJS
Year: 2008

Qty	Description	List Price	Remarks
1.00	BOOTLID	\$ 971.50	PAU ✓
2.00	BOOTLID HINGE	\$ 196.60	PA ✓
1.00	BOOTLID LOCK	\$ 155.20	PA ✓
1.00	BOOTLID EMBLEM	\$ 55.90	NE ✓
1.00	BOOTLID LOGO - LANCER	\$ 54.70	NE ✓
1.00	BOOTLID LOGO - GLX	\$ 53.80	NE ✓
1.00	REAR NUMBER PLATE GARNISH	\$ 215.30	DE ✓
(1pc) 2.00	REAR NUMBER PLATE LAMP	\$ (94.20) 188.40	? LH
2.00	TAILLAMP	\$ 442.3 884.60	LH-CRA/RH-?
(1pc) 2.00	TAILLAMP PANEL	\$ 113.4 226.80	PA 1pc LH
1.00	REAR BUMPER	\$ 849.70	DE ✓
10.00	REAR BUMPER CLIPS	\$ 30.00	NE ✓
(1pc) 2.00	REAR BUMPER RETAINER	\$ 44.2 88.40	NE ✓ (1pc) LH
1.00	REAR WEATHER STRIP	\$ 198.20	NE ✓
1.00	END PANEL TOP GARNISH	\$ 199.30	DE ✓
1.00	SPARE TYRE BOARD	\$ 289.40	X
(1pc) 2.00	REAR FENDER INNER TRIM	\$ 315.4 630.80	LH-?/RH-X
1.00	END PANEL	\$ 742.50	PA ✓
1.00	SPARE TYRE PANEL		REPAIR
1.00	RH REAR FENDER		REPAIR
1.00	LH REAR FENDER	\$ 914.70	PA ✓
1.00	LH ROOF MOULDING	\$ 256.10	cut ✓
1.00	REAR WINDSCREEN	\$ 781.40	? X SC
TOTAL:		\$ 7,983.30	
LESS 25 %:		\$ 1,995.83	
		\$ 5,987.48	

S/NET

Qty	Description	Unit Price	Remarks
1.00	REVERSE SENSOR	\$ 250.00	220 m ✓
1.00	END PANEL SEALANT	\$ 80.00	60
1.00	REAR SOLAR FIRM	\$ 300.00	150?
1.00	REAR WINDSCREEN SEALANT	\$ 80.00	60
1.00	REAR NUMBER PLATE	\$ 50.00	35 SC
TOTAL:		\$ 760.00	

5493.40
252
4120.05

5,537.6

4,153.2

5291.1
5947.2
1486.8
4,460.4

375

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

Date: 15/1/2018
Vehicle No: SJH8252B
Model: LANCER
Date of loss: 11/1/2018
Our ref: LSA210TJS
Year: 2008

EQ INSURANCE

Your Ref Vehicle No:
YP4651P(TP claim)

LABOUR AND PAINT

Qty	Description	Unit Price	Remarks
1.00	LABOUR FOR REPAIR ON AFFECTED AREA	\$ 2,000.00	1400
1.00	SPRAY PAINT ON AFFECTED AREA	\$ 1,600.00	1200
1.00	CHECK WIRING	\$ 50.00	30
1.00	APPLY RUST PROOF ON AFFECTED PANEL	\$ 100.00	50
1.00	REMOVE & REFIT AFFECTED BOOTLID TO FACILITATE REPAIR	\$ 150.00	60
1.00	REMOVE & REFIT AFFECTED REAR TRIM TO FACILITATE REPAIR	\$ 150.00	60
1.00	TO REMOVE AND REFIT REVERSE SENSOR	\$ 80.00	60
1.00	TO REMOVE AND REFIT REAR WINDSCREEN	\$ 150.00	120
1.00	TO REMOVE AND REFIT PETROL TANK	\$ 200.00	100
1.00	SUNDARIES	\$ 50.00	20

TOTAL: \$ 4,530.00

SUBTOTAL: \$ 11,277.48

Estimate prepared by: WINSON

Telephone : 97684247

winsonls@yahoo.com

Repair

Hp 900/100/68

12 days

4S

12/01/18 @ 1410

Repy after repair

(7,628.2)

6,100

7,935.4

6,388.32

LS / 6,300

\$6,000

Limit Repair

12 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

412005

375.00

3100.00

2595.05

20%

6076.04

45-6,050

Repair limit \$6,000