



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLF6880M*RA

Mr Ang Ying Hin (Hong Rongxing)

Blk 810a Choa Chua Kang Ave 7
#15-505
Singapore 681810

Mobile: 98282567

Vehicle & Document Information

WIP No **20284**
Reg No/Reg Date **SLF6880M*RA / 01/11/2011**
Date In/Mileage **0**
Chassis No **WDD1724482F017801**
Engine No **27186130299052**
Make/Model **MB/SLK 200 CGI ROADSTER R172**
Colour/Trim **027 792 Palladium S/ 042 201 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	11/01/2018/ 11:46	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M BPNSUN

POLICY NO/ACC DATE : MT/00416439 // 08-01-2018
DRIVE IN: 09-01-2018 // TP CAR NO: SKL3125K (AXA INSURANCE)
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

0.10

380.00

S BPNSUB

SUPPLY 1 PC REG. PLATE WITH HOUSING.NETT

60.00

A BPILAB

REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT
ASSY COMPONENTS & REFINISH.

1440.00

A BPIRES

RESPRAY FRONT BUMPER

720.00

M RADIATOR GRILLE SUPPORT

1.00

177.06

00.00

177.06

M RADIATOR GRILLE GARNISH HOLDER

1.00

142.35

00.00

142.35

M RADIATOR GRILLE STAR HOLDER

1.00

72.06

00.00

72.06

M RADIATOR GRILLE STAR

1.00

130.65

00.00

130.65

M CT/F PARKING SENSOR

2.00

273.79

00.00

547.58

Alan Quek

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272

Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on **Nett 3,669.70**
3669.70 256.88

Authorized signatory and company stamp

Total Payable 3,926.58

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg