

INS CASE OWNER:

Stanyng

CC 4 / ASM1800 0803

T1UA3

LKK:

IDAC:

SMR
S8m00723

SURVEYOR:

WTH

ASSIGNMENT
DOI: 17/1/18

Date / Time:

12/1/18

Registered in Merimen:

Pre-assign / CCU / FTE

SJS 1825 L



Insured Vehicle No.:

Name of Insured:

BANERJEE PARAMESH

Insured Tel No.:

HP:

D.O.A:

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SJS 3891R



INSRS:

WSP:

Tel:

Liability:

RMKS:

Sm Yew Hup



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

15/1/18
WTH

SJS 3891R - X; SJS 1825 L - X

Spoke to OI, he confirmed the accident details. Informed TP claim. He mention TP already collided onto front vehicle and stop and he collided onto TP vehicle. He will forward all photos.

RECEIVED 1 MAY 2018

RECEIVED 18 JUN 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

> THIN By Email.
15/1

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 100

Repair Cost:

S\$

6099.00

Loss of Rental (LOR):

S\$

1200.00

(

12 days) x 100

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

7301.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee:

S\$

7301.00

Name 1:

SIN YEW HUP AUTO PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT
15/6/18

15/6/18



新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
Specialise in Insurance Claims and General Motor Repair Work

Co./GST Regn. No. 200921075G

11-Jan-18

THIRD PARTY CLAIM

Third Party Vehicle No : SJS 1825 L

Date of Accident : 10/01/2018

MR ABDUL RAHIM BIN ISMAIL

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

Taufik 97495749
WP 12/1/18 @ 1745
Lumpsum
Resurvey before paint
9 days
syh@lkkauto.com
taufik@lkkauto.com

ESTIMATED COST OF REPAIR TO HONDA CIVIC 1.8L (A): SJV 3891 R

A) Chassis No : JHMFD16307S205902

B) Date of Registration : 06/02/2007

S/No.	Pc/s	Item(s) :-	\$
1	1	Rear boot	610.70 bt ✓
2	1	Rear boot reflector LH	152.70 p cut ✓
3	1	Rear boot logo	28.90 ner ✓
4	1	Rear boot lock	203.60 ds ✓
5	1	Rear boot lock catch	17.10 bt ✓
6	1	Rear boot weatherstrip	99.30 pui ✓
7	1	Tail lamp LH	250.30 mt ✓
8	1	Tail lamp panel LH	90.80 Ro ✓
9	1	Tail lamp lower bracket LH	14.70 ner ✓
10	1	Rear bumper	638.00 de ✓
11	4	Rear bumper clip @ \$3.90	15.60 ner ✓
12	2	Rear bumper side retainer @ \$17.10	34.20 ner ✓
13	1	Rear end panel	347.00 bt ✓
14	1	Rear end panel garnish	61.80 de ✓
15	1	Rear fender inner trim LH	182.70 x de ✓
16	1	Spare tyre well	948.50 bu ✓
17	1	Spare tyre well lower panel	239.10 x Repair ✓
18	1	Spare tyre well insulator	74.10 ner ✓
19	1	Spare tyre top cover	340.70 de ✓
20	1	Front bumper	638.00 de ✓
21	2	Front bumper side retainer (LH) & RH @ \$19.80	39.60 19.80 CBA ✓
22	10	Front bumper clip @3.90	39.00 ner ✓
			5,066.40
			Disc Less 20% 1,013.28
			Balance C/F.... 4,053.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



新友合汽车私人有限公司

SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg

11-Jan-18

Co./GST Regn. No. 200921075G

Specialise in Insurance Claims and General Motor Repair Work

THIRD PARTY CLAIM

Third Party Vehicle No : SJS 1825 L

Date of Accident : 10/01/2018

MR ABDUL RAHIM BIN ISMAIL

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

ESTIMATED COST OF REPAIR TO HONDA CIVIC 1.8L (A): SJV 3891 R

A) Chassis No : JHMFD16307S205902

B) Date of Registration : 06/02/2007

S/No. Pc/s Special Nett Item(s) :-

Balance B/F....

\$

4,053.12

23 1 Rear bumper spoiler

600.00 *CR ✓ 400*

24 1 Rear bumper spoiler lamp

400.00 *CR ✓ 150*

25 1 Reverse Sensor 1 Set

200.00 *AW ✓*

26 1 Front number plate

30.00 *bt ✓*

5,283.12

Labour Charges :

a) To remove and refit rear end panel garnish, rear fender trim LH & RH, rear cushion seat

120.00 *60*

b) To remove and refit rear exhaust muffler

60.00 *50*

c) To remove and refit rear boot mechanism, rear boot lid spoiler

80.00 *40*

d) To antirust

80.00 *50*

e) To check wiring

40.00 *30*

f) To putty and spray paint boot lid in & out, boot lid spoiler, rear bumper, rear bumper spoiler, rear end panel, tail lamp panel x2, rear fender LH, spare tyre well, front bumper, front bumper spoiler

1200
1,500.00

g) To remove and refit boot lid, tail lamp LH, rear bumper, rear bumper spoiler, front bumper, cut & weld tail lamp panel LH, rear end panel, spare tyre well, panel beat rear chassis LH, rear fender LH

1200
1,500.00
8,663.12

GST (7%) :-

606.42

Total :-

9,269.54



新友合汽车私人有限公司
SIN YEW HUP AUTO PTE LTD
 393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
 Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
 Specialise in Insurance Claims and General Motor Repair Work

called 30/1/18

called

4/2/2018

11-Jan-18

THIRD PARTY CLAIM

Third Party Vehicle No : SJS 1825 L

Date of Accident : 10/01/2018

MR ABDUL RAHIM BIN ISMAIL

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

Tajir 97495749
 WP 12/1/18 @ 1745
 Lumpsun
 Rebody before paint
 9 days
 syh@lkkanto.com
 taufik@lkkanto.com

ESTIMATED COST OF REPAIR TO HONDA CIVIC 1.8L (A): SJV 3891 R

A) Chassis No : JHMF016307S205902

B) Date of Registration : 06/02/2007

S/No.	Pc/s	Item(s) :-	\$
1	1	Rear boot	610.70 <i>bt</i>
2	1	Rear boot reflector LH	152.70 <i>? cut</i>
3	1	Rear boot logo	28.90 <i>ner</i>
4	1	Rear boot lock	203.60 <i>les</i>
5	1	Rear boot lock catch	17.10 <i>bt</i>
6	1	Rear boot weatherstrip	99.30 <i>pr</i>
7	1	Tail lamp LH	250.30 <i>mt</i>
*8	1	Tail lamp panel LH	90.80 <i>Ro</i>
9	1	Tail lamp lower bracket LH	14.70 <i>ner</i>
10	1	Rear bumper	638.00 <i>de</i>
11	4	Rear bumper clip @ \$3.90	15.60 <i>ner</i>
12	2	Rear bumper side retainer @ \$17.10	34.20 <i>ner</i>
13	1	Rear end panel	347.00 <i>bt</i>
14	1	Rear end panel garnish	61.80 <i>de</i>
15	1	Rear fender inner trim LH	182.70 <i>x de</i>
16	1	Spare tyre well	948.50 <i>buc</i>
17	1	Spare tyre well-lower panel	239.10 <i>? repair</i>
18	1	Spare tyre well insulator	74.10 <i>ner</i>
19	1	Spare tyre top cover	340.70 <i>de</i>
20	1	Front bumper	638.00 <i>de</i>
21	2	Front bumper side retainer <i>LH & RH</i> @ \$19.80	39.60 <i>19.80</i>
22	10	Front bumper clip @ \$3.90	39.00 <i>ner</i>
			5,066.40
			4807.50
			1,013.28
			4,053.12
			less 961.50
			3846.00

Total parts 4807.50 4716.70

less 20% 961.50

3846.00

S.V. 349M 780.00

4,626.00

Labor 2630.00

7,256.00

45 20% 1,451.20

5804.80

3773.36

780

4553.36

2630

7183.36

4545700*

~(5,800.00 before GST)



新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
Specialise In Insurance Claims and General Motor Repair Work

11-Jan-18 Co./GST Regn. No. 200921075G

THIRD PARTY CLAIM

Third Party Vehicle No : SJS 1825 L

Date of Accident : 10/01/2018

MR ABDUL RAHIM BIN ISMAIL

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

ESTIMATED COST OF REPAIR TO HONDA CIVIC 1.8L (A): SJV 3891 R

A) Chassis No : JHMFD16307S205902

B) Date of Registration : 06/02/2007

S/No. Pc/s Special Nett Item(s) :-

			Balance B/F....	\$	
				4,053.12	
23	1	Rear bumper spoiler		600.00	cr ✓ 400
24	1	Rear bumper spoiler lamp		400.00	cr ✓ 150
25	1	Reverse Sensor 1 Set		200.00	rw ✓
26	1	Front number plate		30.00	bt ✓ 180.00
				5,283.12	

Labour Charges :

a)	To remove and refit rear end panel garnish, rear fender trim LH & RH, rear cushion seat	120.00	60
b)	To remove and refit rear exhaust muffler	60.00	50
c)	To remove and refit rear boot mechanism, rear boot lid spoiler	80.00	40
d)	To antirust	80.00	50
e)	To check wiring	40.00	30
f)	To putty and spray paint boot lid in & out, boot lid spoiler, rear bumper, rear bumper spoiler, rear end panel, tail lamp panel x2, rear fender LH, spare tyre well, front bumper, front bumper spoiler	1,500.00	1200
g)	To remove and refit boot lid, tail lamp LH, rear bumper, rear bumper spoiler, front bumper, cut & weld tail lamp panel LH, rear end panel, spare tyre well, panel beat rear chassis LH, rear fender LH	1,500.00	1200
		8,663.12	
		606.42	
		9,269.54	2630.00
		GST (7%) :-	
		Total :-	



SERVICE REQUESTS

MESSAGES

CLAIMS



Re:MANDATE - Accident Involving SJS 1825L (OI : AXA - S8M00723) and SJV 3891R (TP : LKK REF - CC4/ASM18000803/T1ua3) on 10/01/2018

Type

Information

Message

Hi LKK, Please proceed to settle as per proposed.

[Reply](#)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJS 1825L (Insd veh)	Model:	HONDA
	SJV 3891R (TP veh)		CIVIC 1.8L A
Date of Accident:	10/01/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	9,269.54
Final Repair Cost	:	\$	6,099.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,200.00 12 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum	:	\$ 7,301.00

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No- BOLA Scenario No: _____
BOLA Liability: _____ 100 _____ (%)	Assessed Liability (*): _____ 100 _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown		
1)	SIN YEW HUP AUTO PTE LTD	\$ 7,301.00

NUR SHAQILAH BTE ABDOL
WAHAB

19/06/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

SERVICE REQUESTS

MESSAGES

CLAIMS

<< Service Request Details

Claim	S8M00723	Vehicle Information	
Reference		Incident Vehicle	SJV3891R
CC4/ASM18000803/Title Assessment		Registration #	TPVD HONDA
January 10, 2018		Make	CIVIC-1.8 L (A)
Request Date		Model	
January 24, 2018		Primary Contact/Insured	
Due Date		PARAMESH BANERJEE	
November 30, 2018		50 NANYANG AVENUE, 639798, Singapore	
Vendor Name		PARAMESHB@hotmail.com	
LKK AUTO CONSULTANTS PTE Loss LTD (TP)		Type of	
Third Party Vehicle Damage		Services	
		Claim Handler	

Actions

- Next Step
- Finish the work
- Complete Work
- More

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
AUTHORISATION TO ACT.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	June 19, 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	June 19, 2018
LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 19, 2018
Immediate Advice and Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 30, 2018
LKK INSPECTION PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 30, 2018
LKK Re-Inspection Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 30, 2018
23052018121117- 0001.tif	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 24, 2018
TP ESTIMATE - MARKED.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	January 16, 2018

<< Service Request Details

Claim	S8M00723
Reference	CC4/ASM18000803/TT103352ate
January 10, 2018	Request Date
January 24, 2018	Due Date
November 30, 2018	Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)	Type of Loss
Third Party Vehicle Damage	Services

Actions

Next Step

Finish the work

Complete Work

More

Vehicle Information	
Incident Vehicle Registration #	SJV3891R
Service Address	TPVD HONDA
Model	CIVIC-1.8 L (A)
Primary Contact/Insured	
PARAMESH BANERJEE 50 NANYANG AVENUE, 639798, Singapore PARAMESHB@hotmail.com	
Claim Handler	

⏪

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SJV3891R

Registration State

SINGAPORE

Mileage

129637

Purchase Date

mm/dd/yyyy

Registration Date *

02/06/2007

Age of Vehicle

10

CATEGORY

Manufacturing Year

POLICY INFORMAT...

ASSESSMENT INFO...

2006

CATEGORY

Driver Name

FNOL INFORMATI...

ABDUL RAHIM BIN ISMAIL

CATEGORY	Engine No
POLICY INFORMAT ...	
ASSESSMENT INFO ...	R18A12015380
CATEGORY	Engine Capacity
POLICY INFORMAT ...	
ASSESSMENT INFO ...	1799 cc
CATEGORY	Sum Insured
POLICY INFORMAT ...	
ASSESSMENT INFO ...	0
CATEGORY	Market Value
POLICY INFORMAT ...	
ASSESSMENT INFO ...	0

FNOL INFORMATI...	0
POST SURVEY INF...	
CATEGORY	Driver License #
FNOL INFORMATI...	
POST SURVEY INF...	
CATEGORY	License Type
FNOL INFORMATI...	
POST SURVEY INF...	▼
CATEGORY	License Issue Date
FNOL INFORMATI...	
POST SURVEY INF...	mm/dd/yyyy
CATEGORY	License Expiration Date
FNOL INFORMATI...	
POST SURVEY INF...	mm/dd/yyyy
CATEGORY	Address

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS

English (default) ▾ LKK AUTO CONSULTANTS PTE LTD (TP) ▾



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Front left side

GOODYEAR 6mm

Rear left side

GOODYEAR 6mm

Front right side

GOODYEAR 6mm

Rear right side

GOODYEAR 6mm

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details				Vehicle & Driver Details			Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts	
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)				
		1	1			REAR BOOT			Bent	610.7		20		488.56				
		2	1			REAR BOOT REFLECTOR LH			Cut	152.7		20		122.16				
		3	1			REAR BOOT LOGO			Necessary	28.9		20		23.12				
		4	1			REAR BOOT LOCK			Damaged	203.6		20		162.88				
		5	1			REAR BOOT LOCK CATCH			Bent	17.1		20		13.68				
		6	1			REAR BOOT WEATHERSTRIP			Twisted	99.3		20		79.44				
		7	1			TAIL LAMP LH			Cut	250.3		20		200.24				
		8	1			TAIL LAMP PANEL LH			Repair	0		20		0				
		9	1			TAIL LAMP LOWER BRACKET LH			Necessary	14.7		20		11.76				
		10	1			REAR BUMPER			Deformed	638		20		510.4				

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
	1		TO REMOVE AND REFIT REAR END PANEL GARNISH, REAR FENDER TRIM LH & RH, REAR CUSHION SEAT.	60	0	0	Reviewing	
	2		TO REMOVE AND REFIT REAR EXHAUST MUFFLER.	50	0	0	Reviewing	
	3		TO REMOVE AND REFIT REAR BOOT MECHANISM, REAR BOOT LID SPOILER.	40	0	0	Reviewing	
	4		TO ANTI-RUST.	50	0	0	Reviewing	
	5		TO CHECK WIRING.	30	0	0	Reviewing	
	6		TO PUTTY AND SPRAY PAINT BOOT LID IN & OUT, BOOT LID SPOILER, REAR BUMPER, REAR BUMPER SPOILER, REAR END PANEL, TAIL LAMP PANEL X2, REAR FENDER LH, SPARE TYRE WELL, FRONT BUMPER, FRONT BUMPER SPOILER.	1200	0	0	Reviewing	
	7		TO REMOVE AND REFIT BOOT LID, TAIL LAMP LH, REAR BUMPER, REAR BUMPER SPOILER, FRONT BUMPER, CUT & WELD TAIL LAMP PANEL LH, REAR END PANEL, SPARE TYRE WELL, PANEL BEAT REAR CHASSIS LH, REAR FENDER LH.	1200	0	0	Reviewing	

SERVICE REQUESTS

MESSAGES

CLAIMS

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR	Reviewing		9	
☐		2	REAR BUMPER SPOILER	Reviewing	400	CRACKED	
☐		3	REAR BUMPER SPOILER LAMP	Reviewing	150	CRACKED	
☐		4	SET REVERSE SENSOR	Reviewing	200	NOT WORKING	

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary	Claim Amount	\$7,183.36	Claim Amount	\$7,183.36	

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$2,630.00	\$2,630.00
Miscellaneous	\$780.00	\$780.00

Submit for Review

SERVICE REQUESTS MESSAGES CLAIMS

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	FINAL LUMP SUM	Reviewing	5700		