

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

# **SMRT Accident Vehicle Repair Estimates**

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1911J

Ref. No : TAX/01/18/2029

Reg. Date : 09/07/2014

Vehicle Type : TAXI

Make : TOYOTA PRIUS

Model : PRIUS

Name of Driver : KHOO KEH HOCK

Type of Accident : HEAD TO REAR

Date / Time of Accident : 06/01/2018 09:06:00 PM

Accident Reported Date / Time: 08/01/2018 12:00:00 AM

Surveyor is Required? : Yes

Survey by :

Vehicle is Towed Back? : No

Towed Back Date/Time


Replacement Vehicle issued? : No

Accident Repair Job Card No : 000024093963

Special Instruction to ARC, if any:

DROVE IN / SLE5075H - AXA

Prepared Date : 08/01/2018 08:59:58 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKN36U605746977 Mileage: 0

Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates** 

Quotation from ARC Adjusted by Surveyor, if applicable

Total Labout Charges : 845.00 0.00

Total Spray Painting Charges : 558.00 0.00

Total Material Charges : 1,562.22 1,562.22

Other Charges : 460.00 0.00 **TOTAL** : **3,425.22 0.00** 

 Lum Sum Total
 : 3,450.00
 0.00

 No. of Repair Days
 : 5.00
 0.00

Prepared / Adjusted By :

Arc / Surveyor Sing Off Date : 08/01/2018 01:52:15 PM 01/01/1900 12:00:00 AM

1

Prepared / Adjusted Date :

Remarks :

Prepared Date : 08/01/2018 01:52:15 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date : Prepared Date :

#### **Section D - Details of Repair Estimates**

#### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	845.00	0.00
Total Labour	845.00	0.00

# Part 2 - Spray Painting & Panel Beating Related Works

Total Spray Painting & Panel Beating	558.00	0.00
TO RESPRAY REAR PANEL	180.00	0.00
TO REPSRAY REAR BUMPER	378.00	0.00
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable

### Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	460.00	0.00

# Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
52159- 47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No
52023- 12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No
52016- 47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace	No
52015- 47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
76088- 47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No
76087- 47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace	No
76891- 47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No
58307- 47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No
52576- 47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No
52575- 47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
	TOTAL MATERIALS							1,952.80	1,952.78	•
	TOTAL MATERIALS(Discounted)						1,562.22 1,562.22			

### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
	TOTAL SUPPLEMENTARY MATERIALS								