

Surveyor: XRD

REF:

A/G

CC3/ALH18000827/Gq6

02

# ASSIGNMENT

From:

Date:

Veh No:

SLA 8696H

Yr Regn:

25 Jul 2017

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

Audi A3 Sportback C.C. 999

at Workshop m/s

Premium Auto

Colour:

Red

A/C:

Insured / Std / NI / NA

of

Sp. Reading

4059

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

1700030741

C/No:

WA4822 8V9H A143310

Claims No.

4548281976 54 300 29/1/18

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

600 17/1/18

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD / Rim or

(Policy Condition)

Tyre Size:

F: 205/55R16

R:

11

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

\$122K.

IDAC Accident Rpt:

Consistent? : Yes or No

Front

Rear

GIA / PR Seen:

Consistent? : Yes or No

R/Bal.

8

mm

R/Bal.

8

mm

Est. Repairs:

5

days

Res.: Yes or No

L/Bal.

8

mm

L/Bal.

8

mm

Lum Sum:

%

3 Val.: Yes or No

D.O.A.

D.O.I.

12-01-18

Survey held at

w/s

11:30AM

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

SLA 8696H - X

15/1/18 - Report via merimen

16/01/18 @ 4.47pm Victor informed c/a via merimen.

17/01/18 @ 9.19am Informed Kee Siang c/a & ex: \$600 by email.

29/1/18 @ 4.54pm Informed Kee Siang ex: \$300 after confirmed with AIG office.

16/8/18 @ 2.26pm confirmed with Carline Anal fig \$9986, 5 days.

(Red \$5936, 37/1/18)

RECEIVED 19 SEP 2018

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

5

1) 19/1/18

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐ : Site Insp (\$

) S + RS. \$

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

TOTAL

Report Format :

mer-on

Lump Sum / I.B.I. (\$

9986

300

10

310



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18000827/Gqb	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 15-01-2018	
		Code : AIG	
<b>1. Policy Particulars :- OWN DAMAGE</b>			
Insured Veh.		Veh. Inspected	SLQ 8696H
Policy No.	1700030241	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/01/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	11/01/2018	Inspection Date	12/01/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		
<b>5a. Remarks</b>			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

1/15/2018

Adjuster Immediate Advice

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 15 Jan 2018

**Preliminary Advice**

Vehicle No	: SLQ8696H	Accident Date	: 11/01/2018
Make	: AUDI A3	Policy No.	: 1700030241
Assignment Date	: 15/01/2018	Excess	: S\$0.00
Date of Inspection	: 12/01/2018	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,922.00
Revised Amount	:S\$	10,952.00
Check Items (Estimated)	:S\$	3,720.00
Total	:S\$	14,672.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	122,000.00
COE / PARF Rebate	:S\$	53,370.00
Salvage Value	:S\$	
Margin for Repair	:S\$	68,630.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 16 August 2018 2:26 PM  
**To:** 'Nora Khai'; carrine.leong@premiumauto.com.sg  
**Cc:** 'PAL Claim'; SUR; 'Boo seng yak'; jiayee.yap@premiumauto.com.sg  
**Subject:** RE: FINAL REVISION SLQ8696H - OD AIG - SURVEYED 12 JAN 18

Dear Carrine,

WITHOUT PREJUDICE

Confirm final fig \$9,986.00 before excess \$300.00 & GST and 5 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nora Khai <nora.khai@premiumauto.com.sg>  
**Sent:** Tuesday, 14 August 2018 5:15 PM  
**To:** Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
**Cc:** 'PAL Claim' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: FINAL REVISION SLQ8696H - OD AIG - SURVEYED 12 JAN 18

Dear Shiau Chan,

What is happening to Guo Qiang? All his cases has been pending without revert.

Best Regards,

**Norazima Khairuddin**  
Claims Manager

**Premium Automobiles Pte Ltd** (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183

e. [nora.khai@premiumauto.com.sg](mailto:nora.khai@premiumauto.com.sg) w. [www.audi.com.sg](http://www.audi.com.sg)

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Monday, 29 January 2018 4:54 PM  
**To:** Claims Department; SUR  
**Subject:** RE: SLQ 8696 H OWN DAMAGE CLAIMS

Dear Kee Siang,

We have checked and confirmed with insurance officer, the excess should be \$300.00 instead of \$600.00.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Monday, 29 January 2018 10:15 AM  
**To:** Claims Department <[claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SLQ 8696 H OWN DAMAGE CLAIMS

Dear Kee Siang,

According to the AIG officer, Kian Meng that he did not received any video from the owner.

Please clarify with the owner, who the AIG officer he sent the video?

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Monday, 29 January 2018 9:07 AM  
**To:** Claims Department <[claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SLQ 8696 H OWN DAMAGE CLAIMS

Dear Kee Siang,

Thank you for the email.

Once confirm the excess, will send you an email.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Shiau Chan (LKKAuto)

---

**From:** Chan, Kian Meng <KianMeng.Chan@aig.com>  
**Sent:** Monday, 29 January 2018 4:47 PM  
**To:** Shiau Chan (LKKAuto)  
**Cc:** SUR; Syed-Yusoff, Saliha  
**Subject:** #4548281976SG#027#RE: CONFIRM THE EXCESS OF VEHICLE SLQ 8696H (YOUR REF: 4548281976SG)

Dear Shiau Chan,

Had located the OI video and waived accordingly. Claim should be \$300.00.  
I was told by insured that workshop had not fully completed the transaction? Appreciate if you can advise if there's any refund should be done.

Thank you.

Best regards,  
Chan Kian Meng

AIG

Express Claims Adjuster II  
SG Claims Operations | AIG Shared Services  
Tel: 8001206556 | Ext 1012206

[Kianmeng.chan@aig.com](mailto:Kianmeng.chan@aig.com) | [www.aig.com](http://www.aig.com)

### IMPORTANT NOTICE:

The information in this email (and any attachments hereto) is confidential and may be protected by legal privileges and work product immunities. If you are not the intended recipient, you must not use or disseminate the information. Receipt by anyone other than the intended recipient is not a waiver of any attorney-client or work product privilege. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

---

**From:** Chan, Kian Meng  
**Sent:** Monday, January 29, 2018 9:34 AM  
**To:** 'Shiau Chan (LKKAuto)'  
**Cc:** SUR  
**Subject:** RE: CONFIRM THE EXCESS OF VEHICLE SLQ 8696H (YOUR REF: 4548281976SG)

Dear Shiau Chan,

Unfortunately I have not received any video on my end, nor was it stated video is available in the GIA report – hence the non-waiver.  
Just to confirm, is there any further information about how the video was delivered?

Best regards,  
Chan Kian Meng

AIG

Express Claims Adjuster II  
SG Claims Operations | AIG Shared Services  
Tel: 8001206556 | Ext 1012206

**IMPORTANT NOTICE:**

The information in this email (and any attachments hereto) is confidential and may be protected by legal privileges and work product immunities. If you are not the intended recipient, you must not use or disseminate the information. Receipt by anyone other than the intended recipient is not a waiver of any attorney-client or work product privilege. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

---

**From:** Shiau Chan (LKKAuto) [<mailto:siewsc@lkkauto.com>]

**Sent:** Sunday, January 28, 2018 8:06 PM

**To:** Chan, Kian Meng

**Cc:** SUR

**Subject:** CONFIRM THE EXCESS OF VEHICLE SLQ 8696H (YOUR REF: 4548281976SG)

Dear Kian Meng,

Please confirm the excess.

According to the repairer, the owner of above vehicle had provided the video footage to your good office directly.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 17 January, 2018 9:18 AM  
**To:** 'Claims Department'; SUR  
**Subject:** RE: SLQ 8696 H OWN DAMAGE CLAIMS

Dear Kee Siang,

As instructed by our client, please proceed to repair the insured vehicle **SLQ 8696H (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claims Department [mailto:claims@premiumauto.com.sg]  
**Sent:** Tuesday, 16 January, 2018 3:05 PM  
**To:** SUR <sur@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>  
**Cc:** 'Claims Dept' <claims@premiumauto.com.sg>  
**Subject:** RE: SLQ 8696 H OWN DAMAGE CLAIMS

Dear all,

Kindly advise has AIG given out the approval.

Thank you

Best Regards,  
Claims Advisor

Kee Siang

**Premium Automobiles Pte Ltd** (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183 m. +65 8777 0600

e. [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg) w. [www.audi.com.sg](http://www.audi.com.sg)

**Audi Showroom, Audi Centre** 281 Alexandra Road Singapore 159938 p. +65 6836 2223

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	11 Jan 2018 19:12	Clim Veh Model Changed		[I] Merimen Administrator
2	11 Jan 2018 19:12	Clim Created	Reg No: SLQ8696H. Policy No: 1700030241. Acct Date: 2018/01/11. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA118005715	[I] Merimen Administrator
3	15 Jan 2018 13:14	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[I] CATHERINE CHONG KAI LING
4	15 Jan 2018 13:14	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[I] CATHERINE CHONG KAI LING
5	15 Jan 2018 13:14	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	15 Jan 2018 13:14	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/24	[A] CATHERINE CHONG KAI LING
7	15 Jan 2018 13:14	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	15 Jan 2018 13:14	Clim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	15 Jan 2018 13:14	Clim Veh Model Changed	(205280) AUDI A3 999cc TFSI (A).	[A] CATHERINE CHONG KAI LING
10	15 Jan 2018 13:15	Adj Adjuster Assigned	[None] -> XING GUO QIANG	[A] CATHERINE CHONG KAI LING
11	15 Jan 2018 14:32	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
12	15 Jan 2018 14:32	Clim Details Notified		[A] DENISE TAY KWEE CHENG
13	15 Jan 2018 14:34	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/24	[A] DENISE TAY KWEE CHENG
14	15 Jan 2018 14:41	Adj Mandate Request	Cur.Req:14672.00:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
15	16 Jan 2018 12:04	Clim Registration Modified	Init.Est.->5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Chan, Kian Meng
16	16 Jan 2018 12:04	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
17	16 Jan 2018 16:47	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/24. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
18	16 Jan 2018 16:47	Adj Mandate Set	Approved:10952.00:Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1695028	15/01/2018 14:32	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLQ8696H		10.70

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	2032B
<b>Vehicle Details</b>	
Vehicle No.:	SLQ8696H
Vehicle to be Exported:	No
Intended De-registration Date:	15 Jan 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SPORTBACK 1.0 TFSI S TRONIC (LED)
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	CHZ382442
Chassis No.:	WAUZZZ8V9HA143310
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$23,773.00
Original Registration Date:	25 Jul 2017
First Registration Date:	25 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$15,283.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jul 2027
PARF Rebate Amount:	\$11,462.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	24 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$44,002.00
COE Rebate Amount:	\$41,908.00
<b>Total Rebate Amount:</b>	<b>\$53,370.00</b>

The information contained herein is correct as at 15 Jan 2018

OK



## CERTIFICATE OF INSURANCE

### AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LI LI  
Period of Insurance : 25 Jul 2017 To 24 Jul 2018  
Engine No. : CHZ382442  
Chassis No. : WAUZZZ8V9HA143310

Vehicle No. : SLQ8696H  
Policy No. : 1700030241  
Endorsement No. :  
Issued Date : 02 Aug 2017

#### ABOUT THE COVER

Make/Model : AUDI A3 Sportback 1.0 TFSI S tronic  
Engine Capacity/Tonnage : 999.00 CC  
Driver Restriction : NA  
Sum Insured : Market Value  
Off Peak Car : No  
First Year of Registration : 2017  
Insuring with COE/PAF : Yes

#### Person or Classes of Persons Entitled to Drive\* :

a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

#### Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

#### Loss of Use (15 days)

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

#### EXCESS

##### Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

##### Section 2

Property Damage - \$0

Windscreen : \$100

#### Named Driver and Excess (where applicable)

LI LI - \$600 (Own Damage)

#### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

#### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: AIA CO LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP  
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE  
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.  
AUTHORISED REPRESENTATIVE

Sherry Loh

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

Licence Number: **S8062032B**

Name: **LI LI**

Birth Date: **31 Aug 1980**

Issue Date: **23 Oct 2010**

001904945C




**REPUBLIC OF SINGAPORE**

IDENTITY CARD NO. **S8062032B**

Name: **LI LI**

李 力

Race: **CHINESE**

Date of birth: **31-08-1980**

Country/Place of birth: **CHINA**

Sex: **F**

5201644






**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

**EFFECTIVE DATE**

Class 3 Motor Cars  $\leq$  3000kg with  $\leq$  7 passengers, exclusive of the driver; and other motor vehicles  $\leq$  2500kg **23 Oct 2010**

NP 428A

Licence No: **S8062032B**



**5201644**

**NRIC No: S8062032B**

Date of Issue: **02-08-2013**

APT BLK 221 HOUGANG STREET 21 #06-86  
SINGAPORE 530221  
NRIC No: **S8062032B** Date: **27/07/2017 (R)**




# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0061/2018/NK  
Date : 12-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Li li  
Address : Blk 221 Hougang Street 21  
#06-86  
Singapore 530221  
Telephone : HP +65 90032759  
Type of Claim : Own Damage Claims  
Policy No. : 1700030241  
Vehicle No : **SLQ 8696 H**  
Model Code : Audi A3 Sedan 1.0 TFSI  
Model / Year : Jul-17  
Engine No : CHZ382442  
Chassis No : WAUZZZ8V9HA143310  
Mileage :  
Date In :  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 11-Jan-18  
Place of Accident : Blk 138 Lorong Ah Soo (530138) car park.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLQ 8696 H

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	/
2	To dismantle and renew front bumper, rhs front fender and headlight. Reorganise front crash management components. Reinstall all parts removed.	\$ 2,100.00	1250
3	To respray front bumper and rhs front fender.	\$ 1,500.00	1100
4	To carry out diagnostic check.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 4,152.00	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLQ 8696 H

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER / <i>re</i>	\$ 1,613.00	1290.40
2	FRONT BUMPER GUIDE SECTION RH / <i>MC</i>	\$ 33.00	75.84
3	FRONT BUMPER CENTRE GRILLE / <i>re</i>	\$ 140.00	112
4	CLOSING ELEMENT LOWER CENTRE ? / <i>re</i>	\$ 254.00	203.70
5	CLOSING ELEMENT RH ? / <i>re</i>	\$ 254.00	203.70 ✓
6	AIR GUIDE GRILLE RH ? / <i>re</i>	\$ 164.00	131.20 ✓
7	RADIATOR GRILLE X	\$ 1,239.00	X
8	CLOSING ELEMENT X	\$ 167.00	X
9	STICKER FOR AIRCONDITIONER X X	\$ 7.00	X
10	STICKER FOR CAUTION SIGN X X	\$ 12.00	X
11	FRONT BUMPER COVER ? / <i>re</i>	\$ 105.00	83.60 ✓
12	FOAM FILLER X	\$ 162.00	X
13	REINFORCEMENT BEAM X	\$ 633.00	X
14	FRONT FENDER RH / <i>MC</i>	\$ 746.00	596.80
15	FRONT FENDER RH X / <i>NN</i>	2 \$ 65.00	X
16	FRONT FENDER CLOSING ELEMENT RH / <i>re.</i>	\$ 53.00	42.32
17	FRONT FENDER BRACE RH ? / <i>BT</i>	\$ 84.00	67.04 ✓
18	WHEEL HOUSING LINERS RH / <i>re</i>	\$ 151.00	120.80
19	WHEEL HOUSING LINERS ATTACHMENTS PARTS / <i>MC.</i>	\$ 49.00	39.04
20	LED HEADLIGHT RH / <i>Cut</i>	\$ 4,888.00	3910.40
21	LIFT CYLINDER RH ? / <i>PM</i>	\$ 123.00	98
22	NOISE INSULATION X / <i>NN</i>	\$ 226.00	X
23	SIGNAL HORN LOW TONE ? / <i>Cut.</i>	\$ 177.00	141.60 ✓
24	FRONT NO PLATE X / <i>NN</i>	S/N \$ 25.00	X
25	SUNDRIES ? / <i>MC.</i>	\$ 400.00	18.56 ✓
TOTAL SPARE PARTS		\$ 11,770.00	
TOTAL LABOUR CHARGES		\$ 4,152.00	
GRAND TOTAL		\$ 15,922.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :

Guo Qianfeng - 8888 0282

Surveyed Date :

12/1/18

Authorised Date :

Excess Cost :

Not Authorised.

Liability :

Remarks :

5 Days.

before part photos.

*[Signature]*  
18/1/18

## Please Note

- : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0061/2018/NK
Date	:	12-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

*Hi Guo Qiang*

*You recommended 5 days*

*We took 7 days with checked items  
replaced. Jb - ok - 17 Mar 18*

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

Owner's Name	:	Ms Li li
Address	:	Blk 221 Hougang Street 21 #06-86 Singapore 530221
Telephone	:	HP +65 90032759
Type of Claim	:	Own Damage Claims
Policy No.	:	1700030241
Vehicle No	:	<b>SLQ 8696 H</b>
Model Code	:	Audi A3 Sedan 1.0 TFSI
Model / Year	:	Jul-17
Engine No	:	CHZ382442
Chassis No	:	WAUZZZ8V9HA143310
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	11-Jan-18
Place of Accident	:	Blk 138 Lorong Ah Soo (530138) car park.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLQ 8696 H

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To dismantle and renew front bumper, rhs front fender and headlight. Reorganise front crash management components. Reinstall all parts removed.	\$	2,100.00	\$ 1,250.00
3	To respray front bumper and rhs front fender.	\$	1,500.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 4,152.00</u>	<u>\$ 2,902.00</u>

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax****Material List for Accident Vehicle Regn No. SLQ 8696 H**

S/N	Parts Description	<b>Damaged Parts &amp; Prices</b>	
		<b>S/Nett</b>	<b>Remark</b>
1	FRONT BUMPER	\$ 1,613.00	\$ 1,290.40
2	FRONT BUMPER GUIDE SECTION RH	\$ 33.00	\$ 25.84
3	FRONT BUMPER CENTRE GRILLE	\$ 140.00	\$ 112.00
4	CLOSING ELEMENT LOWER CENTRE	\$ 254.00	\$ 203.20
5	CLOSING ELEMENT RH	\$ 254.00	\$ 203.20
6	AIR GUIDE GRILLE RH	\$ 164.00	\$ 131.20
7	RADIATOR GRILLE	\$ 1,239.00	
8	CLOSING ELEMENT	\$ 167.00	
9	STICKER FOR AIRCONDITIONER	\$ 7.00	
10	STICKER FOR CAUTION SIGN	\$ 12.00	
11	FRONT BUMPER COVER	\$ 105.00	\$ 83.60
12	FOAM FILLER	\$ 162.00	
13	REINFORCEMENT BEAM	\$ 633.00	
14	FRONT FENDER RH	\$ 746.00	\$ 596.80
15	FRONT FENDER RH	2 \$ 65.00	
16	FRONT FENDER CLOSING ELEMENT RH	\$ 53.00	\$ 42.32
17	FRONT FENDER BRACE RH	\$ 84.00	\$ 67.04
18	WHEEL HOUSING LINERS RH	\$ 151.00	\$ 120.80
19	WHEEL HOUSING LINERS ATTACHMENTS PARTS	\$ 49.00	\$ 39.04
20	LED HEADLIGHT RH	\$ 4,888.00	\$ 3,910.40
21	LIFT CYLINDER RH	\$ 123.00	\$ 98.00
22	NOISE INSULATION	\$ 226.00	
23	SIGNAL HORN LOW TONE	\$ 177.00	\$ 141.60
24	FRONT NO PLATE	S/N \$ 25.00	
25	SUNDRIES	\$ 400.00	\$ 18.56
<b>TOTAL SPARE PARTS</b>		<b>\$ 11,770.00</b>	<b>\$ 7,084.00</b>
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 4,152.00</b>	<b>\$ 2,902.00</b>
<b>GRAND TOTAL</b>		<b>\$ 15,922.00</b>	<b>\$ 9,986.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Attn: Motor Claims Dept**  
**Yr Ref: SLQ 8696 H**

Norah Khai  
6768 9911  
6841 1183  
Nora.khai@premiumauto.com.sg  
Body & Paint Dept  
PA/OD/0061/2018/NK

16 Sept 2018

Dear Sir,

**RE: INSURANCE CLAIM FOR SLQ 8696 H, Audi A3 SEDAN 1.0 TFSI.**

With reference to the above-mentioned vehicle, no. **SLQ 8696 H**, claimant, **Ms. Li Li** please find the related document per attached.

1. A copy of the Original invoice no. 85012907- S\$10,364.02
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai  
Claims Dept

Encls

AIG - SLQ 8696 H

from  
Telephone +65-  
Telefax +65-  
EMail  
Our department  
Our Ref  
Your Ref  
Date

total pages

Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733

Service & Parts Centres  
55 Ubi Rd 1  
Singapore 408699  
Telephone (65) 6336 2323  
Telefax (65) 684 1183

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jan 2018 14:32		15 Jan 2018 13:14 <a href="#">Edit Adj Rpt</a>	<b>S\$9,986.00</b> <a href="#">Edit Estimates</a>	<b>S\$9,986.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All																				
<div> <div>CLAIM SUBFOLDER DETAILS</div> <div> <div> <div>Insured:</div> <div>LI LI, ID: S8062032B, Tel: +6590032759, Email: JUNELI2001CN@GMAIL.COM</div> </div> <div> <div>Vehicle Reg. No.:</div> <div>SLQ8696H</div> </div> <div> <div>Claim Type:</div> <div>OD / 4548281976SG</div> </div> <div> <div>Repairer:</div> <div>Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911</div> </div> <div> <div>Handling Insurer:</div> <div>AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com</div> </div> <div> <div>Adjuster:</div> <div>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 24/01/2018]</div> </div> <div> <div>Driver/Custodian:</div> <div>LI LI (37 / Female), NRIC: S8062032B, Tel: +6590032759</div> </div> </div> <div> <div>[Created by insurer]</div> <div> <div>Date of Loss:</div> <div>11/01/2018 13:00 - :59 [5 Months and 17 Days From LTA Reg Date (Man Yr)]</div> </div> <div> <div>Policy/Cover Note No.:</div> <div>1700030241 (Comprehensive)</div> </div> <div> <div>Excess:</div> <div>S\$300.00</div> </div> </div> </div>																								
<div> <div>ASSOCIATED MAIL RECEIVED</div> <div> <div>View All</div> <div>Compose Case Mail</div> </div> <div> <ul style="list-style-type: none"> <li>AIG_SG (29/01/2018): SLQ8696H / OD / 11/01/2018 / Coverage &amp; Excess update</li> <li>AIG_SG (16/01/2018): Alert - Adj Mandate Approved (S\$10952.00) - SLQ8696H - Claim Handler: Chan, Kian...</li> <li>AIG_SG (16/01/2018): SLQ8696H / OD / 11/01/2018 / Coverage &amp; Excess update</li> </ul> </div> </div>																								
<div> <div>ALL ASSOCIATED TASKS</div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

## Claim Documents

\*SLQ8696H (4548281976SG)

OD

Jan 11 2018 1:20PM

[LI LI]

Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		Use Viewer	
										1 per page		<input checked="" type="checkbox"/>	
Video													
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)								Thumbnail		Print	
1	27/02/18 17:39	Video - Accident from OI From:TP - Reg. No: GBD3669G, Claimant: BALI NASI LEMAK-FAST FOOD SHOP										Load MOV	
										1 per page		<input checked="" type="checkbox"/>	
Assessment Reports													
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print	
1	15/01/18 14:34	Adjuster Immediate Advice										Load HTM	
										3 per page		<input checked="" type="checkbox"/>	
Photos/Images													
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print	
1	15/01/18 14:36	General View										Load JPG	
2	15/01/18 14:36	General View										Load JPG	
3	15/01/18 14:36	General View										Load JPG	
4	15/01/18 14:36	General View										Load JPG	
5	15/01/18 14:36	General View										Load JPG	
6	15/01/18 14:36	General View										Load JPG	
7	15/01/18 14:36	General View										Load JPG	
8	15/01/18 14:36	General View										Load JPG	
9	15/01/18 14:36	General View										Load JPG	
10	15/01/18 14:36	General View										Load JPG	
11	15/01/18 14:36	General View										Load JPG	
12	15/01/18 14:36	General View										Load JPG	
13	15/01/18 14:36	General View										Load JPG	
14	15/01/18 14:36	General View										Load JPG	
15	15/01/18 14:36	General View										Load JPG	
16	15/01/18 14:36	General View										Load JPG	
17	15/01/18 14:36	General View										Load JPG	
18	15/01/18 14:36	General View										Load JPG	
19	15/01/18 14:36	General View										Load JPG	
20	15/01/18 14:36	General View										Load JPG	
21	15/01/18 14:36	General View										Load JPG	
22	15/01/18 14:36	General View										Load JPG	
23	15/01/18 14:36	General View										Load JPG	
24	15/01/18 14:36	General View										Load JPG	
25	15/01/18 14:36	General View										Load JPG	
26	15/01/18 14:36	General View										Load JPG	
27	15/01/18 14:36	General View										Load JPG	
28	15/01/18 14:36	General View										Load JPG	
29	15/01/18 14:36	General View										Load JPG	
30	15/01/18 14:36	General View										Load JPG	
31	15/01/18 14:36	General View										Load JPG	
32	15/01/18 14:36	General View										Load JPG	
33	15/01/18 14:36	General View										Load JPG	
34	15/01/18 14:36	General View										Load JPG	
35	15/01/18 14:36	General View										Load JPG	
36	15/01/18 14:36	General View										Load JPG	

37	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
48	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
49	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
50	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
51	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
52	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
53	15/01/18 14:36	General View	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/01/18 14:40	Certificate of Insurance	1	Load PDF	
2	15/01/18 14:40	Driver's Driving License	1	Load PDF	
3	15/01/18 14:40	ESTIMATE	1	Load PDF	
4	15/01/18 14:40	Singapore Accident Statement	1	Load PDF	
5	25/09/18 11:35	WORKSHOP INVOICE	1	Load PDF	
6	25/09/18 11:35	DISCHARGE VOUCHER	1	Load PDF	

### Linked Accident Report Documents

			View	Use Viewer	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	11/01/18 19:12	Accident Statement	1	Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	11/01/18 19:02	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	11/01/18 19:02	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	11/01/18 19:02	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	11/01/18 19:02	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	11/01/18 19:02	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	11/01/18 19:02	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	11/01/18 19:02	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	11/01/18 19:02	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
9	11/01/18 19:02	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
10	11/01/18 19:02	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
11	11/01/18 19:02	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	11/01/18 18:56	Sketch Plan	1	Load JPG	<input checked="" type="checkbox"/>
2	11/01/18 18:56	Sketch Plan #2	1	Load JPG	<input checked="" type="checkbox"/>

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

Our File No: CC3/AIG18000827/GQBN2

Date: 25/09/2018

### REFERENCE

Insured/Claimant: LI LI Policy No: 1700030241  
Date of Loss: 11/01/2018 Nature of Claim: OD Claim No: 4548281976SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ8696H  
Make & Model: AUDI A3, 999cc TFSI (A) Engine No: CHZ382442  
Reg. Date: 25/07/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V9HA143310  
Colour: Red Odometer: 4059 km  
Engine Capacity: 999 cc  
Market Value/New Car Price: S\$122,000.00  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16  
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8 mm  
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,770.00	7,084.00	4,686.00	39.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,152.00	2,902.00	1,250.00	30.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,922.00	9,986.00	5,936.00	37.28
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	15,622.00	9,686.00	5,936.00	38.00
+ GST 7.00/7.00% (S\$)	1,093.54	678.02	415.52	38.00
Nett Amount (S\$)	16,715.54	10,364.02	6,351.52	38.00

### INSPECTION

Date of Assignment: 15/01/2018  
Date Inspected: 12/01/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	1,613.00 FS	*1,290.40 FS
2	1	*FRONT BUMPER GUIDE SECTION RH	Necessary	33.00 FS	*25.84 FS
3	1	*FRONT BUMPER CENTRE GRILLE	Deformed	140.00 FS	*112.00 FS
4	1	*CLOSING ELEMENT LOWER CENTRE	Deformed	254.00 FS	*203.20 FS
5	1	*CLOSING ELEMENT RH	Deformed	254.00 FS	*203.20 FS
6	1	*AIR GUIDE GRILLE RH	Deformed	164.00 FS	*131.20 FS
7	1	*RADIATOR GRILLE	Not Necessary	1,239.00 FS	*- FS
8	1	*CLOSING ELEMENT	Not Necessary	167.00 FS	*- FS
9	1	*STICKER FOR AIRCONDITIONER	Not Necessary	7.00 FS	*- FS
10	1	*STICKER FOR CAUTION SIGN	Not Necessary	12.00 FS	*- FS
11	1	*FRONT BUMPER COVER	Deformed	105.00 FS	*83.60 FS
12	1	*FOAM FILLER	Not Necessary	162.00 FS	*- FS
13	1	*REINFORCEMENT BEAM	Not Necessary	633.00 FS	*- FS
14	1	*FRONT FENDER RH	Buckled	746.00 FS	*596.80 FS
15	2	*FRONT FENDER RH	Not Necessary	65.00 FS	*- FS
16	1	*FRONT FENDER CLOSING ELEMENT RH	Deformed	53.00 FS	*42.32 FS
17	1	*FRONT FENDER BRACE RH	Bent	84.00 FS	*67.04 FS
18	1	*WHEEL HOUSING LINERS RH	Deformed	151.00 FS	*120.80 FS
19	1	*WHEEL HOUSING LINERS ATTACHMENTS PARTS	Necessary	49.00 FS	*39.04 FS
20	1	*LED HEADLIGHT RH	Cut	4,888.00 FS	*3,910.40 FS
21	1	*LIFT CYLINDER RH	Damaged	123.00 FS	*98.00 FS
22	1	*NOISE INSULATION	Not Necessary	226.00 FS	*- FS
23	1	*SIGNAL HORN LOW TONE	Cut	177.00 FS	*141.60 FS
24	1	*FRONT NO PLATE	Not Necessary	25.00 FS	*- FS
25	1	*SUNDRIES	Necessary	400.00 FS	*18.56 FS
Total Parts (S\$)				11,770.00	7,084.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER FROM WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND HEADLIGHT. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,500.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,152.00</b>	<b>2,902.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >