

ISS. REC. BY:

REF: CS/ASM18000841/Agbez

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

enuf claim

From (Person): Yvonne Ang

of ISM

Date/Time: 15-01-2018 12:44pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: STU 2026J

Insured:

at Workshop m/s Progressive

Tel: 6741 5336

of Blk 3022A Ubi Road 1 #D1-45

Policy No: Claim No: S8 M0072U

Sum Insured: Excess: NIL

Make of Veh: D.O.A. 11-01-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 15-01-2018 3pm

Person Contacted: Amy

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	STU 2026J - CI / LAW / 3001391 / DXX Dof: 25/1/2012
16/1/2018	Revert via ASM.
17/3/18 @	1.11pm confirmed with ray Pinski fig 813094.50, 8 days. (Paid @ 2554, 16%)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18000841/Aqb

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 15-01-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SJU 2026J
Policy No.	Coverage (\$)	0.00
Claim No. S8M0072U	Excess (\$)	0.00
Assign From SMART CLAIM (YVONNE ANG)	Assign Date	15/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 11/01/2018	Inspection Date 15/01/2018
Survey held at PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--



Service Request Details

Claim

S8M0072U

Reference

None

Loss Date

January 11, 2018

Request Date

January 15, 2018

Due Date

January 22, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Incident Only

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJU2026J

Make

AUDI

Service Address

3022A, UBI ROAD 1, , 408716

Primary Contact/Insured

YU ZHANG

25 AKYAB ROAD, #27-07 PAVILION 11, 309979, Singapore, Singapore

jarod.zhang66@gmail.com

Claim Handler

Default Owner

Additional Instructions

EXCESS NIL

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 22 March 2018 1:11 PM
To: 'Ray Progressive'
Cc: SUR
Subject: RE: SJU2026J - TO FINALIZE

Dear Ray,

Confirm final fig \$13,094.50 before GST and 8 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray Progressive [<mailto:ray@progauto.com.sg>]
Sent: Wednesday, 7 March 2018 12:56 PM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: FW: SJU2026J - TO FINALIZE

Hi Adrian/ Shiau Chan,

Please assist to finalize this case, thank you.

Regards

Ray

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Thursday, February 22, 2018 2:13 PM
To: Ray Progressive; Shiau Chan (LKKAuto)
Cc: 'Wayne Lim'; msho@progauto.com.sg
Subject: FW: SJU2026J - TO FINALIZE

Dear Shiau Chan,

FYNA-CS/ASM18000841/Aqb

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray Progressive [<mailto:ray@progauto.com.sg>]
Sent: Thursday, 22 February 2018 2:00 PM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: 'Wayne Lim' <wayne@progauto.com.sg>; msho@progauto.com.sg
Subject: SJU2026J - TO FINALIZE



SUPPLEMENTARY LIST OF VEHICLE SJU 2026J UPLOADED

Type

📍 Question

Message

Dear Yvonne, we have received supplementary of \$633.00 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. - Shiau Chan

Reply



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S8M0072U

Our Ref: CS/ASM18000841/Aqb

Date: 16/01/2018

The Motor Claims Department
M/s AXA Insurance Singapore Pte Ltd

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO SJU 2026J


We thank you for the instruction on 15/01/2018

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/1/2018 @ 2PM at the premises of M/s Progressive and have the following to report: -

Workshop Estimate Amount : S\$ 15,015.50
Revised Estimate Amount : S\$ 8,611.50
"Check" Items Amount : S\$ 4,314.00
Total : S\$ 12,925.50
Market Value : S\$ 43,000.00
LTA Reimbursement Value : S\$ 28,457.00
Nett Value : S\$ 14,543.00

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:
Damages Consistent
Days of repair: 8

Yours Faithfully,
Adrian
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 4711H

Vehicle Details

Vehicle No.: SJU2026J
 Vehicle to be Exported: No
 Intended De-registration Date: 16 Jan 2018
 Vehicle Make: AUDI
 Vehicle Model: A6 2.0L TFSI MU S-LINE CVT TC D/AB HID
 Primary Colour: Grey
 Manufacturing Year: 2009
 Engine No.: BPJ159386
 Chassis No.: WAUZZZ4F3AN010667
 Maximum Power Output: 125.0 kW (167 bhp)
 Open Market Value: \$45,477.00
 Original Registration Date: 23 Oct 2009
 First Registration Date: 23 Oct 2009
 Transfer Count: 0
 Actual ARF Paid: \$45,477.00

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 22 Oct 2019
 PARF Rebate Amount: \$25,012.00

Intended COE Rebate Details

COE Expiry Date: 22 Oct 2019
 COE Category: B - Car (1601cc & above)
 COE Period(Years): 10
 QP Paid: \$19,510.00
 COE Rebate Amount: \$3,445.00
Total Rebate Amount: \$28,457.00

The information contained herein is correct as at 16 Jan 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4711H

Vehicle Details

Vehicle No.: SJU2026J
Vehicle to be Exported: Yes
Intended De-registration Date: 11 Jan 2018
Vehicle Make: AUDI
Vehicle Model: A6 2.0L TFSI MU S-LINE CVT TC D/AB HID
Primary Colour: Grey
Manufacturing Year: 2009
Engine No.: BPJ159386
Chassis No.: WAUZZZ4F3AN010667
Maximum Power Output: 125.0 kW (167 bhp)
Open Market Value: \$45,477.00
Original Registration Date: 23 Oct 2009
First Registration Date: 23 Oct 2009
Transfer Count: 0
Actual ARF Paid: \$45,477.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 22 Oct 2019
PARF Rebate Amount: \$25,012.00

Intended COE Rebate Details

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/01/2018 17:14
Date Of Accident	11/01/2018 11:30
Exact Location Of Accident	JUNCTION OF KITCHENER ROAD & KITCHENER LINK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU2026J
Insured/Policyholder	
Name Of Registered Owner	ZHANG YU
NRIC No	S8184711H
Email Address	JAROD.ZHANG66@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91460726
Alternative Phone No	OTHERS-91460726

Vehicle Particulars

Manufacturer	AUDI
Model	A6-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA029411/1
Cover Note Number	

Driver

Name of Driver	ZHANG YU
NRIC No	S8184711H
Date Of Birth	20/02/1981
Occupation	INDOOR
Date Of Driving Pass	15/10/2009
Driving Experience	8 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91460726
Fax Number	
Contact Number	OTHERS-91460726
EMail Address	JAROD.ZHANG66@GMAIL.COM

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: 3:44 PM
 17/1/18

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.: F011011

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
 GST:201006949C RCB NO:201006949C

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY #24-01
 AXA TOWER
 S068811

Estimate No: EST1503164
Date: 11 Jan 2018
Policy No: GA029411/1
Veh Reg No: SJU2026J
Make/Model: AUDI A6 2.0T FSI MU S-LINE
Chassis No: WAUZZZ4F3AN010667
Engine No: BPJ159386
Reg. Date: 23-10-2009

ATTN: Motor Claim Department

Your Ref No: OD 0118-6316
Claim Type: Own Damage
Accident Date: 11-01-2018

Estimate Repair Cost to Vehicle No :SJU2026J

Description	U/Price	Quantity	Price S\$	Amount S\$
Special Net				
1 COOLANT <i>new</i>	20.0000	1 LIT	20.00 ✓	
2 FRONT NUMBER PLATE WITH CASING <i>Best</i>	35.0000	1 SET	35.00 ✓	
			55.00	55.00
Spare Parts				
3 FRONT BONNET <i>Dented</i>	1,650.000	1 PC	1,650.00 ✓	
4 FRONT BONNET HINGE - LH <i>Revised</i>	40.0000	1 PC	40.00 ✓	
5 FRONT BONNET HINGE - RH <i>Not New</i>	40.0000	1 PC	40.00 ✓	
6 FRONT BONNET ABSORBER - RH <i>New</i>	45.0000	1 PC	45.00 ✓	
7 FRONT BONNET TOP HOOK - CENTRE <i>New</i>	50.0000	1 PC	50.00 ✓	
8 FRONT BONNET BOTTOM LOCK - CENTRE <i>Damaged</i>	80.0000	1 PC	80.00 ✓	
9 FRONT BONNET INSOALTOR <i>new</i>	135.0000	1 PC	135.00 ✓	
10 FRONT BONNET INSOALTOR CLIP <i>new</i>	1.5000	15 PCS	22.50 ✓	
11 FRONT BUMPER <i>Distorted</i>	900.0000	1 PC	900.00 ✓	
12 FRONT BUMPER CLIPS <i>new</i>	1.5000	10 PCS	15.00 ✓	
13 FRONT BUMPER SIDE HOLDER - LH <i>New</i>	18.0000	1 PC	18.00 ✓	
14 FRONT BUMPER SIDE HOLDER - RH <i>New</i>	18.0000	1 PC	18.00 ✓	
15 FRONT BUMPER REINFORCEMENT <i>Best</i>	265.0000	1 PC	265.00 ✓	
16 FRONT BUMPER BRACKET - LH <i>New</i>	75.0000	1 PC	75.00 ✓	
17 FRONT BUMPER BRACKET - RH <i>New</i>	75.0000	1 PC	75.00 ✓	
18 FRONT BUMPER TOW COVER - RH <i>Revised</i>	18.0000	1 PC	18.00 ✓	
19 FRONT BUMPER FOG LAMP CHROME W/ COVER - LH <i>new</i>	85.0000	1 PC	85.00 ✓	
20 FRONT BUMPER FOG LAMP CHROME W/ COVER - RH <i>Distorted</i>	85.0000	1 PC	85.00 ✓	
21 FRONT BUMPER FOG LAMP UNIT - LH <i>new</i>	95.0000	1 PC	95.00 ✓	
22 FRONT BUMPER FOG LAMP UNIT - RH <i>Coiled</i>	95.0000	1 PC	95.00 ✓	
23 FRONT BUMPER NOZZLE COVER - LH <i>New</i>	25.0000	1 PC	25.00 ✓	
24 FRONT BUMPER NOZZLE COVER - RH <i>Missing</i>	25.0000	1 PC	25.00 ✓	
25 FRONT BUMPER NOZZLE - LH <i>New</i>	100.0000	1 PC	100.00 ✓	
26 FRONT BUMPER NOZZLE - RH <i>Coiled</i>	100.0000	1 PC	100.00 ✓	
27 FRONT BUMPER LOWER LIP - CENTRE <i>Distorted</i>	150.0000	1 PC	150.00 ✓	
28 FRONT BUMPER UNDER LOWER GARNISH <i>Distorted</i>	300.0000	1 PC	300.00 ✓	
29 FRONT FENDER - RH <i>Distorted</i>	440.0000	1 PC	440.00 ✓	
30 FRONT FENDER COWLING, REAR - RH <i>new</i>	200.0000	1 PC	200.00 ✓	
31 FRONT FENDER COWLING, FRONT - RH <i>Revised</i>	15.0000	1 PC	15.00 ✓	
32 FRONT FENDER CLIP <i>new</i>	1.5000	20 PCS	30.00 ✓	
33 FRONT NUMBER PLATE GARNISH <i>Distorted</i>	65.0000	1 PC	65.00 ✓	
34 GRILLE ASSY <i>Smashed</i>	275.0000	1 PC	275.00 ✓	
35 GRILLE LOGO <i>new</i>	45.0000	1 PC	45.00 ✓	

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
 GST:201006949C RCB NO:201006949C

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY #24-01
 AXA TOWER
 S068811

Estimate No: EST1503164
Date: 11 Jan 2018
Policy No: GA029411/1
Veh Reg No: SJU2026J
Make/Model: AUDI A6 2.0T FSI MU S-LINE
Chassis No: WAUZZZ4F3AN010667
Engine No: BPJ159386
Reg. Date: 23-10-2009

ATTN: Motor Claim Department

Your Ref No: OD 0118-6316
Claim Type: Own Damage
Accident Date: 11-01-2018

Estimate Repair Cost to Vehicle No :SJU2026J

Description	U/Price	Quantity	Price	Amount
			S\$	S\$
36 POWER STEERING COOLER PIPE <i>Best</i>	220.0000	1 PC	220.00	✓
37 SUPPORT PANEL <i>cracked</i>	320.0000	1 PC	320.00	✓
38 RADIATOR <i>Best.</i>	350.0000	1 PC	350.00	✓
39 RADIATOR, SMALL, RH <i>Not new</i>	320.0000	1 PC	320.00	? ✓
40 CONDENSER <i>Best</i>	350.0000	1 PC	350.00	✓
41 AIRCON CONDENSER SIDE GARNISH - LH <i>Not new</i>	15.0000	1 PC	15.00	✓
42 AIRCON CONDENSER SIDE GARNISH - RH <i>cracked</i>	15.0000	1 PC	15.00	✓
43 AIRCON FAN MOTOR W/ FAN BLADE <i>Best</i>	360.0000	1 PC	360.00	? ✓
44 AIRCON FAN COWLING <i>cracked</i>	220.0000	1 PC	220.00	? ✓
45 RADIATOR FAN MOTOR, FAN BLADE & FAN COWLING <i>Best</i>	320.0000	1 PC	320.00	? ✓
46 HEAD LAMP - RH <i>cracked.</i>	1,100.0000	1 PC	1,100.00	✓
47 HEAD LAMP LOWER RETAINER - RH <i>Not new</i>	12.0000	1 PC	12.00	? ✓
48 HEAD LAMP - LH <i>cracked.</i>	1,100.0000	1 PC	1,100.00	? ✓
49 HEAD LAMP LOWER RETAINER - LH <i>Not new</i>	12.0000	1 PC	12.00	? ✓
50 POWER STEERING COOLER PIPE <i>Best ? Best.</i>	460.0000	1 PC	460.00	? ✓
51 RADIATOR TOP HOSE <i>? Not new</i>	30.0000	1 PC	30.00	+ ✓
52 RADIATOR BOTTOM HOSE <i>Not new</i>	100.0000	1 PC	100.00	+ ✓
53 RADIATOR SPARE TANK <i>Not new</i>	40.0000	1 PC	40.00	? ✓
54 WIPER TANK ASSY <i>Not new</i>	85.0000	1 PC	85.00	? ✓
55 CHARCOAL TANK (PULSATION DAMAGE) <i>Not new</i>	45.0000	1 PC	45.00	? ✓
56 CHARCOAL TANK BRACKET <i>Not new</i>	40.0000	1 PC	40.00	? ✓
57 HEAD LAMP CONTROL UNIT - RH <i>Best</i>	500.0000	1 PC	500.00	? ✓
58 HEAD LAMP HID BULB - RH <i>Best.</i>	240.0000	1 PC	240.00	? ✓
59 HEAD LAMP CONTROL UNIT - LH <i>? Not new</i>	500.0000	1 PC	500.00	+ ✓
60 HEAD LAMP HID BULB - LH <i>? Not new</i>	240.0000	1 PC	240.00	+ ✓
			12,570.50	12,570.50
Labour				
61 TO KNOCK OUT DENTS, RH F CHASSIS, CUT/WELD, SUPPORT PANEL, REMOVE & REPLACE ACCIDENT PARTS	1,000.0000	1 JOB	1,000.00 <i>1000</i>	800
62 TO RESPRAY PAINT ON ACCIDENT PORTIONS	950.0000	1 JOB	950.00 <i>950</i>	800
63 TO 4 WHEEL ALIGNMENT	60.0000	1 JOB	60.00	+
64 TO CHECK WIRING	20.0000	1 JOB	20.00	✓
65 TO REMOVE, REPALCE CONDENSER AND REFILL GAS	100.0000	1 JOB	100.00	✓
66 TO RESET ENGINE LIGHT	60.0000	1 JOB	60.00	+
67 TO REMOVE, REPLACE POWER STEERING COOLER PIPE, CHARCOAL TANK, BRACKET AND RELATED PARTS	200.0000	1 JOB	200.00	150
			2,390.00	2,390.00

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWER
S068811

ATTN: Motor Claim Department

Your Ref No: OD 0118-6316
Claim Type: Own Damage
Accident Date: 11-01-2018

Estimate No: EST1503164
Date: 11 Jan 2018
Policy No: GA029411/1
Veh Reg No: SJU2026J
Make/Model: AUDI A6 2.0T FSI MU S-LINE
Chassis No: WAUZZZ4F3AN010667
Engine No: BPJ159386
Reg. Date: 23-10-2009

Estimate Repair Cost to Vehicle No :SJU2026J

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 15,015.50
			Add GST @ 7%	1,051.09
			Total Amount Payable	S\$ 16,066.59

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND SIXTY SIX AND CENTS FIFTY NINE ONLY

For PROGRESSIVE AUTOMOTIVE PTE LTD

AUTHORISED SIGNATURE

Adrian Lij
~~15~~ 15/01/18 P/P.

08 Days.

Authorised Repair

Excess NIL.

15648.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
 GST:201006949C RCB NO:201006949C

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY #24-01
 AXA TOWER
 S068811

Estimate No: EST1503164
Date: 11 Jan 2018
Policy No: GA029411/1
Veh Reg No: SJU2026J
Make/Model: AUDI A6 2.0T FSI MU S-LINE
Chassis No: WAUZZZ4F3AN010667
Engine No: BPJ159386
Reg. Date: 23-10-2009

ATTN: Motor Claim Department

Your Ref No: OD 0118-6316
Claim Type: Own Damage
Accident Date: 11-01-2018

Estimate Repair Cost to Vehicle No. ~~SJU2026J~~

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
Special Net				
1 COOLANT <i>NCC</i>	20.0000	1 LIT	20.00 ✓	
2 FRONT NUMBER PLATE WITH CASING <i>Bent</i>	35.0000	1 SET	35.00 ✓	
			55.00	55.00
Spare Parts				
3 FRONT BONNET <i>Distorted</i>	1,650.0000	1 PC	1,650.00 ✓	
X FRONT BONNET HINGE - LH <i>new</i>	40.0000	1 PC	40.00 ✓	
X FRONT BONNET HINGE - RH <i>new</i>	40.0000	1 PC	40.00 ✓	
6 FRONT BONNET ABSORBER - RH <i>new</i>	45.0000	1 PC	45.00 ✓	
X7 FRONT BONNET TOP HOOK - CENTRE <i>new</i>	50.0000	1 PC	50.00 ✓	
✓8 FRONT BONNET BOTTOM LOCK - CENTRE <i>Distorted</i>	80.0000	1 PC	80.00 ✓	
9 FRONT BONNET INSULATOR <i>new</i>	135.0000	1 PC	135.00 ✓	
10 FRONT BONNET INSULATOR <i>new</i>	1.5000	15 PCS	22.50 ✓	
11 FRONT BUMPER <i>Distorted</i>	900.0000	1 PC	900.00 ✓	
12 FRONT BUMPER CLIPS <i>new</i>	1.5000	10 PCS	15.00 ✓	
13 FRONT BUMPER SIDE HOLDER - LH <i>new</i>	18.0000	1 PC	18.00 ✓	
14 FRONT BUMPER SIDE HOLDER - RH <i>new</i>	18.0000	1 PC	18.00 ✓	
15 FRONT BUMPER REINFORCEMENT <i>Bent</i>	265.0000	1 PC	265.00 ✓	
✓16 FRONT BUMPER BRACKET - LH <i>Distorted</i>	75.0000	1 PC	75.00 ✓	
✓17 FRONT BUMPER BRACKET - RH <i>Distorted</i>	75.0000	1 PC	75.00 ✓	
18 FRONT BUMPER TOW COVER - RH <i>Distorted</i>	18.0000	1 PC	18.00 ✓	
19 FRONT BUMPER FOG LAMP CHROME W/ COVER - LH <i>new</i>	85.0000	1 PC	85.00 ✓	
20 FRONT BUMPER FOG LAMP CHROME W/ COVER - RH <i>Distorted</i>	85.0000	1 PC	85.00 ✓	
21 FRONT BUMPER FOG LAMP UNIT - LH <i>new</i>	95.0000	1 PC	95.00 ✓	
22 FRONT BUMPER FOG LAMP UNIT - RH <i>Cracked</i>	95.0000	1 PC	95.00 ✓	
23 FRONT BUMPER NOZZLE COVER - LH <i>new</i>	25.0000	1 PC	25.00 ✓	
24 FRONT BUMPER NOZZLE COVER - RH <i>Missing</i>	25.0000	1 PC	25.00 ✓	
25 FRONT BUMPER NOZZLE - LH <i>new</i>	100.0000	1 PC	100.00 ✓	
26 FRONT BUMPER NOZZLE - RH <i>Cracked</i>	100.0000	1 PC	100.00 ✓	
✓27 FRONT BUMPER LOWER LIP - CENTRE <i>Distorted</i>	150.0000	1 PC	150.00 ✓	
✓28 FRONT BUMPER UNDER LOWER GARNISH <i>Distorted</i>	300.0000	1 PC	300.00 ✓	
29 FRONT FENDER - RH <i>Distorted</i>	440.0000	1 PC	440.00 ✓	
30 FRONT FENDER COWLING, REAR - RH <i>new</i>	200.0000	1 PC	200.00 ✓	
31 FRONT FENDER COWLING, FRONT - RH <i>Distorted</i>	15.0000	1 PC	15.00 ✓	
32 FRONT FENDER CLIP <i>new</i>	1.5000	20 PCS	30.00 ✓	
33 FRONT NUMBER PLATE GARNISH <i>Distorted</i>	65.0000	1 PC	65.00 ✓	
34 GRILLE ASSY <i>Cracked</i>	275.0000	1 PC	275.00 ✓	
35 GRILLE LOGO <i>Cracked</i>	45.0000	1 PC	45.00 ✓	

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
 GST:201006949C RCB NO:201006949C

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY #24-01
 AXA TOWER
 S068811

Estimate No: EST1503164
Date: 22 Jan 2018
Policy No: GA029411/1
Veh Reg No: SJU2026J
Make/Model: AUDI A6 2.0T FSI MU S-LINE
Chassis No: WAUZZZ4F3AN010667
Engine No: BPJ159386
Reg. Date: 23/10/2009

ATTN: Motor Claim Department

Your Ref No: OD 0118-6316
Claim Type: Own Damage
Accident Date: 11/01/2018

Estimate Repair Cost to Vehicle No :SJU2026J

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
Supplementary Parts to Repair				
Spare Parts				
1 SUPPORT PANEL TOP GARNISH <i>cauled</i>	65.0000	1 PC	65.00	//
2 ENGINE UNDER GARNISH CLIP, GRIP PIN [MISSIN] <i>3 pcs</i>	5.0000	4 PC	20.00	//
3 ENGINE UNDER GARNISH CLIP, PIN [MISSIN]	5.0000	4 PCS	20.00	//
4 FRONT FENDER SIDE STOPPER - RH [MISSING] <i>new</i>	10.0000	1 PC	10.00	//
5 OIL STICK <i>Not on</i>	18.0000	1 PC	18.00	x
6 ENGINE MOUNTING - LH <i>3 pcs torn</i>	165.0000	1 PC	165.00	//
7 ENGINE MOUNTING - RH	165.0000	1 PC	165.00	//
8 FRONT BUMPER NOZZLE PIPE JOINT - RH <i>replaced</i>	15.0000	1 PC	15.00	//
9 POWER STEERING OIL <i>new</i>	20.0000	1 PC	20.00	//
10 <i>progump</i> SIDE COVER-RH <i>miss</i> <i>835P</i>			498.00	498.00
Labour				
11 10 TO REMOVE, REPLACE RH, LH ENGINE MOUNTING	100.0000	1 JOB	100.00 <i>80</i>	100.00
			Total	SS 598.00 <i>63</i>
			GST Amount	SS 41.86
			Total Amount Payable	SS 639.86

Adrian G
 22/01/18
[Signature]

For PROGRESSIVE AUTOMOTIVE PTE LTD

AUTHORISED SIGNATURE

[Signature]

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
 GST:201006949C RCB NO:201006949C

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY #24-01
 AXA TOWER
 S068811

Estimate No: EST1503164
 Date: 22 Jan 2018
 Policy No: GA029411/1
 Veh Reg No: SJU2026J
 Make/Model: AUDI A6 2.0T FSI MU S-LINE
 Chassis No: WAUZZZ4F3AN010667
 Engine No: BPJ159386
 Reg. Date: 23/10/2009

ATTN: Motor Claim Department

Your Ref No: OD 0118-6316
 Claim Type: Own Damage
 Accident Date: 11/01/2018

Estimate Repair Cost to Vehicle No :SJU2026J

Description	U/Price	Quantity	Price	Amount
			S\$	S\$
Supplementary Parts to Repair				
Spare Parts				
1 SUPPORT PANEL TOP GARNISH <i>cauled.</i>	65.0000	1 PC	65.00	—
2 ENGINE UNDER GARNISH CLIP, GRIP PIN [MISSIN] <i>3 pcs</i>	5.0000	4 PC	20.00	—
3 ENGINE UNDER GARNISH CLIP, PIN [MISSIN]	5.0000	4 PCS	20.00	—
4 FRONT FENDER SIDE STOPPER - RH [MISSING] <i>new</i>	10.0000	1 PC	10.00	—
5 OIL STICK <i>new</i>	18.0000	1 PC	18.00	—
6 ENGINE MOUNTING - LH <i>3 pcs from</i>	165.0000	1 PC	165.00	—
7 ENGINE MOUNTING - RH	165.0000	1 PC	165.00	—
8 FRONT BUMPER NOZZLE PIPE JOINT - RH <i>2nd</i>	15.0000	1 PC	15.00	—
9 POWER STEERING OIL <i>new</i>	20.0000	1 PC	20.00	—
10 foglamp side cover - RH - <i>1/2</i> (Missing)			498.00	498.00 <i>5/12</i>
Labour				
10 TO REMOVE, REPLACE RH, LH ENGINE MOUNTING	100.0000	1 JOB	100.00 80.00	100.00
			Total	S\$ 598.00
			GST Amount	S\$ 41.86
			Total Amount Payable	S\$ 639.86

Adrian G
 22/01/18
AG

For PROGRESSIVE AUTOMOTIVE PTE LTD *supp 595.*

AUTHORISED SIGNATURE

supp 595.00
parts 10274.50
oil 55.00
LAB. 2170.00

13094.50

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road | #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
 GST:201006949C RCB NO:201006949C

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY #24-01
 AXA TOWER
 S068811

Estimate No: EST1503164
 Date: 11 Jan 2018
 Policy No: GA029411/1
 Veh Reg No: SJU2026J
 Make/Model: AUDI A6 2.0T FSI MU S-LINE
 Chassis No: WAUZZZ4F3AN010667
 Engine No: BPJ159386
 Reg. Date: 23-10-2009

ATTN: Motor Claim Department

Your Ref No: OD 0118-6316
 Claim Type: Own Damage
 Accident Date: 11-01-2018

Estimate Repair Cost to Vehicle No: SJU2026J

Description	U/Price	Quantity	Price S\$	Amount S\$
Special Net				
1 COOLANT <i>Rec</i>	20.0000	1 LIT	20.00 ✓	
2 FRONT NUMBER PLATE WITH CASING <i>Bent</i>	35.0000	1 SET	35.00 ✓	
			55.00	55.00 <i>SS</i>
Spare Parts				
3 FRONT BONNET <i>Distorted</i>	1,650.000	1 PC	1,650.00 ✓	
4 FRONT BONNET HINGE - LH <i>Rec</i>	40.0000	1 PC	40.00 ✓	
5 FRONT BONNET HINGE - RH <i>Rec</i>	40.0000	1 PC	40.00 ✓	
6 FRONT BONNET ABSORBER - RH <i>Rec</i>	15.0000	1 PC	15.00 ✓	
7 FRONT BONNET TOP LOCK - CENTRE <i>Rec</i>	50.0000	1 PC	50.00 ✓	
✓ 8 FRONT BONNET BOTTOM LOCK - CENTRE <i>Distorted</i>	80.0000	1 PC	80.00 ✓	
9 FRONT BONNET INSULATOR <i>Rec</i>	135.0000	1 PC	135.00 ✓	
10 FRONT BONNET INSULATOR CLIP <i>Rec</i>	1.5000	15 PCS	22.50 ✓	
11 FRONT BUMPER <i>Distorted</i>	900.0000	1 PC	900.00 ✓	
12 FRONT BUMPER CLIPS <i>Rec</i>	1.5000	10 PCS	15.00 ✓	3
13 FRONT BUMPER SIDE HOLDER - LH <i>Rec</i>	18.0000	1 PC	18.00 ✓	
14 FRONT BUMPER SIDE HOLDER - RH	18.0000	1 PC	18.00 ✓	
15 FRONT BUMPER REINFORCEMENT <i>Bent</i>	265.0000	1 PC	265.00 ✓	
✓ 16 FRONT BUMPER BRACKET - LH <i>Distorted</i>	75.0000	1 PC	75.00 ✓	
✓ 17 FRONT BUMPER BRACKET - RH	75.0000	1 PC	75.00 ✓	
18 FRONT BUMPER TOW COVER - RH <i>Distorted</i>	18.0000	1 PC	18.00 ✓	
19 FRONT BUMPER FOG LAMP CHROME W/ COVER - LH <i>Rec</i>	85.0000	1 PC	85.00 ✓	
20 FRONT BUMPER FOG LAMP CHROME W/ COVER - RH <i>Distorted</i>	85.0000	1 PC	85.00 ✓	
21 FRONT BUMPER FOG LAMP UNIT - LH <i>Rec</i>	95.0000	1 PC	95.00 ✓	
22 FRONT BUMPER FOG LAMP UNIT - RH <i>Coiled</i>	95.0000	1 PC	95.00 ✓	
23 FRONT BUMPER NOZZLE COVER - LH <i>Rec</i>	25.0000	1 PC	25.00 ✓	
24 FRONT BUMPER NOZZLE COVER - RH <i>Missing</i>	25.0000	1 PC	25.00 ✓	
25 FRONT BUMPER NOZZLE - LH <i>Rec</i>	100.0000	1 PC	100.00 ✓	
26 FRONT BUMPER NOZZLE - RH <i>Coiled</i>	100.0000	1 PC	100.00 ✓	
✓ 27 FRONT BUMPER LOWER LIP - CENTRE <i>Distorted</i>	150.0000	1 PC	150.00 ✓	
✓ 28 FRONT BUMPER UNDER LOWER GARNISH	300.0000	1 PC	300.00 ✓	
29 FRONT FENDER - RH <i>Distorted</i>	440.0000	1 PC	440.00 ✓	
30 FRONT FENDER COWLING - REAR - RH <i>Rec</i>	200.0000	1 PC	200.00 ✓	
31 FRONT FENDER COWLING - FRONT - RH <i>Distorted</i>	15.0000	1 PC	15.00 ✓	
32 FRONT FENDER CLIP <i>Rec</i>	1.5000	20 PCS	30.00 ✓	
33 FRONT NUMBER PLATE GARNISH <i>Distorted</i>	65.0000	1 PC	65.00 ✓	
34 GRILLE ASSY <i>Smashed</i>	275.0000	1 PC	275.00 ✓	
35 GRILLE LOGO	45.0000	1 PC	45.00 ✓	

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road | #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
 GST:201006949C RCB NO:201006949C

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY #24-01
 AXA TOWER
 S068811

Estimate No: EST1503164
 Date: 11 Jan 2018
 Policy No: GA029411/1
 Veh Reg No: SJU2026J
 Make/Model: AUDI A6 2.0T FSI MU S-LINE
 Chassis No: WAUZZZ4F3AN010667
 Engine No: BPJ159386
 Reg. Date: 23-10-2009

ATTN: Motor Claim Department

Your Ref No: OD 0118-6316
 Claim Type: Own Damage
 Accident Date: 11-01-2018

Estimate Repair Cost to Vehicle No :SJU2026J

Description	U/Price	Quantity	Price	Amount
			SS	SS
✓36 POWER STEERING COOLER PIPE <i>Best</i>	220.0000	1 PC	220.00 ✓	220.00 ✓
✓37 SUPPORT PANEL <i>could</i>	320.0000	1 PC	320.00 ✓	320.00 ✓
✓38 RADIATOR <i>Best</i>	350.0000	1 PC	350.00 ✓	350.00 ✓
X39 RADIATOR SMALL RHP <i>men</i>	320.0000	1 PC	320.00 ✗	320.00 ✗
✓40 CONDENSER <i>Best</i>	350.0000	1 PC	350.00 ✓	350.00 ✓
✓41 AIRCON CONDENSER SIDE GARNISH - LH <i>new Del'd</i>	15.0000	1 PC	15.00 ✓	15.00 ✓
✓42 AIRCON CONDENSER SIDE GARNISH - RH <i>could</i>	15.0000	1 PC	15.00 ✓	15.00 ✓
X43 AIRCON FAN MOTOR W/ FAN BLADE <i>men</i>	360.0000	1 PC	360.00 ✗	360.00 ✗
✓44 AIRCON FAN COWLING <i>could</i>	220.0000	1 PC	220.00 ✓	220.00 ✓
✓45 RADIATOR FAN MOTOR, FAN BLADE & FAN COWLING <i>Byd</i>	320.0000	1 PC	320.00 ✓	320.00 ✓
✓46 HEAD LAMP - RH <i>could</i>	1,100.0000	1 PC	1,100.00 ✓	1,100.00 ✓
X47 HEAD LAMP LOWER RETAINER - RH <i>men</i>	12.0000	1 PC	12.00 ✗	12.00 ✗
✓48 HEAD LAMP - LH <i>could</i>	1,100.0000	1 PC	1,100.00 ✓	1,100.00 ✓
X49 HEAD LAMP LOWER RETAINER - LH <i>men</i>	12.0000	1 PC	12.00 ✗	12.00 ✗
X50 POWER STEERING COOLER PIPE <i>Best Best</i>	460.0000	1 PC	460.00 ✓	460.00 ✓
✓51 RADIATOR TOP HOSE <i>? Extra build</i>	30.0000	1 PC	30.00 ✓	30.00 ✓
X52 RADIATOR BOTTOM HOSE <i>men</i>	100.0000	1 PC	100.00 ✗	100.00 ✗
X53 RADIATOR SPARE TANK <i>men</i>	40.0000	1 PC	40.00 ✗	40.00 ✗
X54 WIPER TANK ASSY <i>men</i>	85.0000	1 PC	85.00 ✗	85.00 ✗
X55 CHARCOAL TANK (PULSATION DAMAGE) <i>men</i>	45.0000	1 PC	45.00 ✗	45.00 ✗
X56 CHARCOAL TANK BRACKET <i>men</i>	40.0000	1 PC	40.00 ✗	40.00 ✗
✓57 HEAD LAMP CONTROL UNIT - RH <i>Byd</i>	500.0000	1 PC	500.00 ✓	500.00 ✓
✓58 HEAD LAMP HID BULB - RH <i>Byd</i>	240.0000	1 PC	240.00 ✓	240.00 ✓
X59 HEAD LAMP CONTROL UNIT - LH <i>? men</i>	500.0000	1 PC	500.00 ✗	500.00 ✗
X60 HEAD LAMP HID BULB - LH <i>? men</i>	240.0000	1 PC	240.00 ✗	240.00 ✗
			12,570.50	12,570.50 (02/4/18)
Labour				
61 TO KNOCK OUT DENTS, RHF CHASSIS, CUT/WELD, SUPPORT PANEL, REMOVE & REPLACE ACCIDENT PARTS	1,000.0000	1 JOB	1,000.00 <i>1800</i>	
62 TO RESPRAY PAINT ON ACCIDENT PORTIONS	950.0000	1 JOB	950.00 <i>900</i>	
63 TO 4 WHEEL ALIGNMENT	60.0000	1 JOB	60.00 ✓	
64 TO CHECK WIRING	20.0000	1 JOB	20.00 ✓	
65 TO REMOVE, REPLACE CONDENSER AND REFILL GAS	100.0000	1 JOB	100.00 ✓	
66 TO RESET ENGINE LIGHT	60.0000	1 JOB	60.00 ✗	
67 TO REMOVE, REPLACE POWER STEERING COOLER PIPE, CHARCOAL TANK, BRACKET AND RELATED PARTS	200.0000	1 JOB	200.00 <i>150</i>	
			2,390.00	2,390.00

2170

PROGRESSIVE AUTOMOTIVE PTE LTD

Bik 3022A Ubi Road I #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWER
S068811

ATTN: Motor Claim Department

Your Ref No: OD 0118-6316
Claim Type: Own Damage
Accident Date: 11-01-2018

Estimate No: EST1503164
Date: 11 Jan 2018
Policy No: GA029411/1
Veh Reg No: SJU2026J
Make/Model: AUDI A6 2.0T FSI MU S-
LINE
Chassis No: WAUZZZ4F3AN010667
Engine No: BPJ159386
Reg. Date: 23-10-2009

Estimate Repair Cost to Vehicle No :SJU2026J

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 15,015.50
			Add GST @ 7%	1,051.09
			Total Amount Payable	S\$ 16,066.59

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND SIXTY SIX AND CENTS FIFTY NINE ONLY

For PROGRESSIVE AUTOMOTIVE PTE
LTD

AUTHORISED SIGNATURE

Adrian Ly
~~#~~ 15/01/18 P/P.

08 Aug.

Authorised Repair

Exam NIL.