

ASS. REC. BY:

REF: CS/FCI8000842 / Ag bnt Special Instruction:

Surveyor:

## ASSIGNMENT (Office)

From (Person): Aini of FCI Date/Time: 18/01/2018 9:57am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKZ 6362Z Insured: SHA 810Dat Workshop m/s Murderm Automotive Tel: 6744 2422of 81k 2022A Ubi Road #01-61Policy No: \_\_\_\_\_ Claim No: SHA 810D

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 11-01-2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS DS1

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 18/01/2018 11:57am Person Contacted: medi Huey Vehicle IN/OUT: OUT

| Date/Time        | Action/Instruction (✓) Estimate                       |
|------------------|-------------------------------------------------------|
|                  | SKZ 6362Z - X                                         |
|                  | SHA 810D - NBA / ATG 14016573 / CI DCA: J86814        |
| 24/1/18 @ 3.21pm | Informed Aini, we are pending estimate from repaired. |
| 01/2/18 @ 4.53pm | revised to Aini by email.                             |
|                  | US \$ 6000, 6 days (red \$ 7830.08, 57%)              |

Signature

REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKZ6362Z Yr Regn: 2016 Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle Co. 1496

Colour: Grey. A/C Insured / Std / NI / NA

Sp. Reading: 37050 T. Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GK81001961

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60 R15

R: 185/60 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 22/01/18

Survey held at Modern

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap.

RECEIVED 2 FEB 2018

Date/Time, File Pass to?

1) 02/2/2018

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee

Transportation

5 + 50 = 55

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) 6000

3x15= 45

170+ 45

50

50

69

384

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18000842/Aqb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 15-01-2018



Code : FCI2

**1. Policy Particulars :- THIRD PARTY CLAIM**

|              |          |                |            |
|--------------|----------|----------------|------------|
| Insured Veh. | SHA 810D | Veh. Inspected | SKZ 6362Z  |
| Policy No.   |          | Coverage (\$)  | 0.00       |
| Claim No.    |          | Excess (\$)    | 0.00       |
| Assign From  | AINI     | Assign Date    | 15/01/2018 |

**2. Vehicle Particulars & Condition**

|              |        |              |   |
|--------------|--------|--------------|---|
| Make & Model |        | c.c          | 0 |
| Engine No.   | HIDDEN | Year of Reg. |   |
| Chassis No.  |        | Colour       |   |
| Odometer     | -      | Steering     |   |
| Brakes       |        | Modification |   |
| General      |        |              |   |

**3. Conditions of Tyres**

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

**4. Description of Damages**

|  |  |
|--|--|
|  |  |
|--|--|

**5. General Information**

|                |                                                                                 |                 |  |
|----------------|---------------------------------------------------------------------------------|-----------------|--|
| Accident Date  | 11/01/2018                                                                      | Inspection Date |  |
| Survey held at | MODERN AUTOMOTIVE PTE LTD<br>BLK 3023A UBI ROAD 1<br>#01-61<br>SINGAPORE 408717 |                 |  |

**5a. Remarks**

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

# Survey Department Check List (Case Handler)

Reference No. : CS/KC18000842/A96  
Policy Type: OD / TP / TP RES / TL / EVA

SHA 810D

Case Handler

Typist

**Admin** ( Cath ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

## (1) Office Assign Form

|                                         | Y-Date | N-Date | Y-Date | N-Date |
|-----------------------------------------|--------|--------|--------|--------|
| C Reference No.                         | ✓      |        |        |        |
| C Customer Code                         | ✓      |        |        |        |
| N Assign From                           | ✓      |        |        |        |
| C Assign Date                           | ✓      |        |        |        |
| C Veh No (Inspected)                    | ✓      |        |        |        |
| C Veh No (Insured)                      | ✓      |        |        |        |
| C D.O.A                                 | ✓      |        |        |        |
| C Policy No                             | ✓      |        |        |        |
| C Claim No                              | ✓      |        |        |        |
| C Insurance Authorisation (CA /REV/REP) | ✓      |        |        |        |
| C Report Type                           | ✓      |        |        |        |
| C Weekend Charges                       | ✓      |        |        |        |
| N Survey held at/Repairer               | ✓      |        |        |        |
| C Excess                                |        |        |        |        |

**Surveyor** ( Adam ): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

|                          |   |  |  |
|--------------------------|---|--|--|
| C Vehicle No             | ✓ |  |  |
| C Regn Month/Year        | ✓ |  |  |
| N Vehicle Type           | ✓ |  |  |
| N Make & Model           | ✓ |  |  |
| C Engine Capacity. (C.C) | ✓ |  |  |
| N Colour                 | ✓ |  |  |
| C Odometer. (Sp.Reading) | ✓ |  |  |
| C Chassis No             | ✓ |  |  |
| N General Condition      | ✓ |  |  |
| N Steering               | ✓ |  |  |
| N Brake                  | ✓ |  |  |
| N Modification (Modi)    | ✓ |  |  |
| C Tyre Size              | ✓ |  |  |
| N Tyre Make              | ✓ |  |  |
| C Tyre Balance           | ✓ |  |  |
| C Date of Inspection     | ✓ |  |  |
| N Survey held            | ✓ |  |  |
| N Des.of Damages         | ✓ |  |  |

## (2) System - (Views/Merimen)

|                                        |   |  |  |
|----------------------------------------|---|--|--|
| C Damaged Vehicle Photographs Uploaded | ✓ |  |  |
|----------------------------------------|---|--|--|

## (3) Workshop Estimate/Assignment Form

|                                                 |   |  |  |
|-------------------------------------------------|---|--|--|
| N ALL Parts condition                           | ✓ |  |  |
| C Market Value for OD cases                     |   |  |  |
| C Estimate Repair Cost for PRI (RSI, TMI, MSIG) | ✓ |  |  |
| C Days of repair                                |   |  |  |
| C Finalised Amount                              |   |  |  |
| C Re-inspection Cases to Finalize within 5 Days |   |  |  |

## (4) System - (Views/Merimen)

|                           |   |  |  |
|---------------------------|---|--|--|
| C Resurvey photo Uploaded | ✓ |  |  |
|---------------------------|---|--|--|

Check By:

Cath  
Case Handler

21/2/18  
Date

\*C: Critical \*N: Non-Critical

21/05/2014

## Catherine Chong (LKK Auto)

---

**From:** Aini Binte Md Min <Aini@msfirstcapital.com.sg>  
**Sent:** Monday, 15 January, 2018 9:57 AM  
**To:** 'assignments@lkkauto.com'  
**Cc:** meeihuey@modernautomotive.com.sg  
**Subject:** NEW ASSIGNMENT (O/REF: SHA810D)  
**Attachments:** 15012018095614-0001.pdf; FW: TP Claim SKZ6362Z & SHA810D (206 KB)

Dear Sirs

New survey assignment for your handling.

Thanks & Regards

Aini  
Motor Claims Department

First Capital Insurance Ltd | 36 Robinson Road, City House, #16-01 Singapore 068877 | TEL: 6507 3848  
Fax: 6507 3849 | Company Reg. No. 195000106C

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.  
Please refer to [www.first-insurance.com.sg](http://www.first-insurance.com.sg) for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.  
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

# First Capital Insurance Limited

Company Reg. No. 195000106C  
GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

Date 12.1.18

Our Ref No. SH810D

Accident Date 11.1.18

Claim Type Third Party

Insured Vehicle SH810D

Third Party Vehicle SKZ63622

Survey Location MODERN AUTOMOTIVE

Contact Person MEEI HUEY

MM TRADING ENTERPRISE

Contact No. 6744 4422 9113 2451

Fax No. 6747 6720

Survey Type Without Prejudice: We admit liability with quantum to be agreed

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person

Fax No. 6841 6315

Contact Number 62563561

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. 3P ACCLDT REPORTS

Cc : Workshop MODERN AUTOMOTIVE

Officer in charge Wrene Jaw 13/01/2018

Attention

## IMPORTANT NOTE

Kindly submit the survey report by email only to [surveyor@first-insurance.com.sg](mailto:surveyor@first-insurance.com.sg) within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 1 February 2018 4:53 PM  
**To:** 'Aini Binte Md Min'; assignments  
**Cc:** SUR  
**Subject:** RE: NEW ASSIGNMENT (O/REF: SHA810D)  
**Attachments:** CSFCI18000842Aqb.pdf

Dear Aini,

Enclosed herewith preliminary advice of SKZ 6362Z.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Shiau Chan (LKKAuto)

Sent: Wednesday, 24 January 2018 3:21 PM

To: 'Aini Binte Md Min' <Aini@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: NEW ASSIGNMENT (O/REF: SHA810D)

Dear Aini,

Please be informed that we have inspected the vehicle SKZ 6362Z on 22/01/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto)

Sent: Monday, 15 January 2018 12:00 PM

To: 'Aini Binte Md Min' <Aini@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: NEW ASSIGNMENT (O/REF: SHA810D)

Dear Aini,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SHA 810D

Date: 01 February 2018

Our Ref: CS/FCI18000842/Aqb

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SKZ 6362Z .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/01/2018 at the premises of M/s MODERN AUTOMOTIVE, and have the following to report:-

|                          |                   |
|--------------------------|-------------------|
| Workshop Estimate Amount | : S\$ 13,830.08 . |
| Revised Estimate Amount  | : S\$ 7,492.24 .  |
| "Check" Items Amount     | : S\$ - .         |
| Market Value             | : S\$ - .         |
| LTA Reimbursement Value  | : S\$ - .         |
| Nett Value               | : S\$ - .         |

**Description of Damage:**

The vehicle sustained damages  
at the rear portion.



Yours faithfully

ADRIAN LING WAI PING  
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI  
Licensed Appraiser

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 24 January 2018 3:21 PM  
**To:** 'Aini Binte Md Min'; assignments  
**Cc:** SUR  
**Subject:** RE: NEW ASSIGNMENT (O/REF: SHA810D)

Dear Aini,

Please be informed that we have inspected the vehicle SKZ 6362Z on 22/01/2018.

We are pending for estimate from repairer.

Best Regards,  
Shiau Chan (Ms) | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,  
#02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)  
Sent: Monday, 15 January 2018 12:00 PM  
To: 'Aini Binte Md Min' <Aini@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
Cc: SUR <sur@lkkauto.com>  
Subject: RE: NEW ASSIGNMENT (O/REF: SHA810D)

Dear Aini,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,  
Catherine Chong | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue  
1, #02-25 | S(408933)

-----Original Message-----

From: Aini Binte Md Min [mailto:Aini@msfirstcapital.com.sg]  
Sent: Monday, 15 January, 2018 9:57 AM  
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>  
Cc: meehuey@modernautomotive.com.sg  
Subject: NEW ASSIGNMENT (O/REF: SHA810D)

Dear Sirs

New survey assignment for your handling.

Thanks & Regards

Aini

MODERN AUTOMOTIVE PTE LTD  
BLK 3023A UBI ROAD 1 # 01-61  
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

First Capital Insurance Ltd

36 Robinson Road  
#16-01 City House  
Singapore 068877  
Tel : 6507 - 3848  
Fax : 6507 - 3849

Quotation

DATE : 22.01.2018  
VEH NO : SKZ6362Z  
MODEL : Honda Shuttle  
D O A : 11.01.2018  
YR REF : SHA810D

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKZ6362Z (HONDA SHUTTLE)

| Item | Description                                   | Qty   | Amt                  |
|------|-----------------------------------------------|-------|----------------------|
| NO   | LIST ITEMS                                    |       |                      |
| 1    | Rear Bumper <i>Deformed</i>                   | 1     | 1,278.50 ✓           |
| 2    | Rear Bumper Clips <i>m</i>                    | 1 set | 30.00 ✓              |
| 3    | Rear Bumper Side Holder <i>m</i>              | 2     | 116.00 ✓             |
| 4    | Rear Bumper Side Garnish <i>new m</i>         | 2     | 370.00 x             |
| 5    | Rear Bumper Side Reflector <i>new m</i>       | 2     | 352.00 x             |
| 6    | Rear Bumper Tow Cover <i>new m</i>            | 1     | 34.70 x              |
| 7    | Rear End Panel <i>Dented</i>                  | 1     | 715.30 ✓             |
| 8    | Rear End Panel Top Garnish <i>Deformed</i>    | 1     | 187.30 ✓             |
| 9    | Tail Lamp <i>new m</i>                        | 2     | 843.60 x             |
| 10   | Tailgate <i>Dented</i>                        | 1     | 1,554.50 ✓           |
| 11   | Tailgate Lock <i>new</i>                      | 1     | 181.70 ✓             |
| 12   | Tailgate Weatherstripe <i>new</i>             | 1     | 168.50 ✓             |
| 13   | Tailgate Inner Trim Board <i>Deformed</i>     | 1     | 320.40 ✓             |
| 14   | Tailgate Inner Trim Board Clips <i>m</i>      | 1 set | 30.00 ✓              |
| 15   | Tailgate Glass Moulding <i>new</i>            | 1     | 138.90 ✓             |
| 16   | Honda Logo <i>new</i>                         | 1     | 30.10 ✓              |
| 17   | Shuttle Emblem <i>new</i>                     | 1     | 52.80 ✓              |
| 18   | Rear Fender Inner Trim Board <i>Deformed</i>  | 2     | 670.00 ✓             |
| 19   | Rear Fender Inner Trim Board Clips <i>new</i> | 1 set | 60.00 ✓              |
| 20   | Tools Tray <i>Deformed</i>                    | 1     | <del>428</del> 428 ✓ |
| 21   | Jack Cover <i>Deformed</i>                    | 1     | 115.80 ✓             |
| 22   | Spare Tyre Panel <i>Repis</i>                 | 1     | 1,980.00 x           |
| 23   | Spare Tyre Panel Top Cover <i>new m</i>       | 1     | 299.50 x             |
| 24   | Rear Exhaust Pipe <i>new</i>                  | 1     | 792.00 x             |
| 25   | Rear Exhaust Mounting <i>new</i>              | 1     | 88.00 x              |

\$ 10,452.40

Less 20%

(2,090.48)

\$ 8,361.92

6077.80

4862.44

RE: ESTIMATE FOR ACCIDENT REPAIR SKZ6362Z (HONDA SHUTTLE)

S/NET ITEMS

|             |                                   |       |   |    |          |     |
|-------------|-----------------------------------|-------|---|----|----------|-----|
| 1           | Reverse Sensor <i>Damaged</i>     | 320   | 1 | \$ | 250.00   | 200 |
| 2           | Rear End Panel Sealant <i>new</i> |       | 1 | \$ | 60.00    | ✓   |
| 3           | Tailgate Glass Sealant <i>new</i> |       | 1 | \$ | 60.00    | ✓   |
|             | Rear Camera                       | 480 X |   | \$ | 370.00   |     |
|             | Rear Video Recorder               | 580 X |   | \$ |          |     |
| TOTAL PARTS |                                   |       |   | \$ | 8,731.92 |     |

LABOUR CHARGE

|             |                                                                 |                |    |                     |          |
|-------------|-----------------------------------------------------------------|----------------|----|---------------------|----------|
| 1           | To knocking & pull out rear side portion and renew damage parts |                | \$ | <del>1,400.00</del> | 1000     |
| 2           | To putty & spray up paint works                                 |                | \$ | <del>1,200.00</del> | 800      |
| 3           | To check wiring system                                          |                | \$ | <del>50.00</del>    | 30.      |
| 4           | To underseal                                                    |                | \$ | <del>150.00</del>   | 50       |
| 5           | To remove reverse sensor                                        |                | \$ | <del>100.00</del>   | 50       |
| 6           | To remove upholstery                                            |                | \$ | <del>150.00</del>   | 80       |
| 7           | To transfer tailgate glass                                      | 2310           | \$ | <del>180.00</del>   | 120      |
| 8           | To transfer tailgate fittings                                   |                | \$ | <del>150.00</del>   | 80       |
| 9           | To remove exhaust pipe                                          | 100            | \$ | 150.00              | X        |
| 10          | To remove rear camera and video recorder                        | <del>200</del> | \$ | 3,530.00            |          |
| GRAND TOTAL |                                                                 |                | \$ | 12,261.92           | 13830.08 |

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display car used part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

total: 7482.24

h/s: GK: 06 Days.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                                 |                 |                            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|-----------------|----------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                                 |                 | Ref : CS/FCI18000842/Aqbn2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                                 |                 | Date : 06-02-2018          |  |
|                                                                                                                                                                                        |                                                                                 |                 | Code : FCI2                |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                                 |                 |                            |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHA 810D                                                                        | Veh. Inspected  | SKZ 6362Z                  |                                                                                     |
| Policy No.                                                                                                                                                                             |                                                                                 | Coverage (\$)   | 0.00                       |                                                                                     |
| Claim No.                                                                                                                                                                              | SHA 810D                                                                        | Excess (\$)     | 0.00                       |                                                                                     |
| Assign From                                                                                                                                                                            | AINI                                                                            | Assign Date     | 15/01/2018                 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                                 |                 |                            |                                                                                     |
| Make & Model                                                                                                                                                                           | HONDA SHUTTLE                                                                   | c.c             | 1496                       |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                          | Year of Reg.    | 2016                       |                                                                                     |
| Chassis No.                                                                                                                                                                            | GK81001961                                                                      | Colour          | GREY                       |                                                                                     |
| Odometer                                                                                                                                                                               | 37050                                                                           | Steering        | IN ORDER                   |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                        | Modification    | SPORTS RIM                 |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                                            |                 |                            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                                 |                 |                            |                                                                                     |
|                                                                                                                                                                                        | Size                                                                            | Make            | Balance                    |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 185/60 R15                                                                      | YOKOHAMA        | 6 mm                       |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 185/60 R15                                                                      | YOKOHAMA        | 6 mm                       |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 185/60 R15                                                                      | YOKOHAMA        | 6 mm                       |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 185/60 R15                                                                      | YOKOHAMA        | 6 mm                       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                                 |                 |                            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                                                                             |                                                                                 |                 |                            |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                                 |                 |                            |                                                                                     |
| Accident Date                                                                                                                                                                          | 11/01/2018                                                                      | Inspection Date | 22/01/2018                 |                                                                                     |
| Survey held at                                                                                                                                                                         | MODERN AUTOMOTIVE PTE LTD<br>BLK 3023A UBI ROAD 1<br>#01-61<br>SINGAPORE 408717 |                 |                            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                                 |                 |                            |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                 |                 |                            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                                 |                 |                            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                                 | 6 Working Days  |                            |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 6362Z

| Qty                         | Description of Parts                   | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|----------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                        |                      |                           |                   |
| 1                           | REAR BUMPER                            | DEFORMED             | 1,278.50                  | 1,278.50          |
| 1                           | SET REAR BUMPER CLIPS                  | NECESSARY            | 30.00                     | 30.00             |
| 2                           | REAR BUMPER SIDE HOLDER                | NECESSARY            | 116.00                    | 116.00            |
| 2                           | REAR BUMPER SIDE GARNISH               | NOT NECESSARY        | 370.00                    | -                 |
| 2                           | REAR BUMPER SIDE REFLECTOR             | NOT NECESSARY        | 352.00                    | -                 |
| 1                           | REAR BUMPER TOW COVER                  | NOT NECESSARY        | 34.70                     | -                 |
| 1                           | REAR END PANEL                         | DENTED               | 715.30                    | 715.30            |
| 1                           | REAR END PANEL TOP GARNISH             | DEFORMED             | 187.30                    | 187.30            |
| 2                           | TAIL LAMP                              | NOT NECESSARY        | 843.60                    | -                 |
| 1                           | TAILGATE                               | DENTED               | 1,554.50                  | 1,554.50          |
| 1                           | TAILGATE LOCK                          | DAMAGED              | 181.70                    | 181.70            |
| 1                           | TAILGATE WEATHERSTRIPE                 | CUT                  | 168.50                    | 168.50            |
| 1                           | TAILGATE INNER TRIM BOARD              | DEFORMED             | 320.40                    | 320.40            |
| 1                           | SET TAILGATE INNER TRIM BOARD CLIPS    | NECESSARY            | 30.00                     | 30.00             |
| 1                           | TAILGATE GLASS MOULDING                | NECESSARY            | 138.90                    | 138.90            |
| 1                           | HONDA LOGO                             | NECESSARY            | 30.10                     | 30.10             |
| 1                           | SHUTTLE EMBLEM                         | NECESSARY            | 52.80                     | 52.80             |
| 2                           | REAR FENDER INNER TRIM BOARD           | DEFORMED             | 670.00                    | 670.00            |
| 1                           | SET REAR FENDER INNER TRIM BOARD CLIPS | NECESSARY            | 60.00                     | 60.00             |
| 1                           | TOOLS TRAY                             | DEFORMED             | 428.00                    | 428.00            |
| 1                           | JACK COVER                             | DEFORMED             | 115.80                    | 115.80            |
| 1                           | SPARE TYRE PANEL                       | TO REPAIR SEE LABOUR | 1,980.00                  | -                 |
| 1                           | SPARE TYRE PANEL TOP COVER             | NOT NECESSARY        | 299.50                    | -                 |
| 1                           | REAR EXHAUST PIPE                      | NOT NECESSARY        | 792.00                    | -                 |
| 1                           | REAR EXHAUST MOUNTING                  | NOT NECESSARY        | 88.00                     | -                 |
|                             | LESS 20% DISCOUNT                      |                      | -2,167.52                 | -1,215.56         |
|                             |                                        |                      | 8,670.08                  | 4,862.24          |
| <b>SPECIAL NETT ITEMS</b>   |                                        |                      |                           |                   |
| 1                           | REVERSE SENSOR (SN)                    | DAMAGED              | 250.00                    | 200.00            |
| 1                           | REAR END PANEL SEALANT (SN)            | NECESSARY            | 60.00                     | 60.00             |

Report Ref No. CS/FCI18000842/Aqbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

| Qty                                                                         | Description of Parts                                                                                          | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1                                                                           | TAILGATE GLASS SEALANT (SN)                                                                                   | NECESSARY     | 60.00                     | 60.00             |
| 1                                                                           | REAR CAMERA (SN)                                                                                              | NOT NECESSARY | 480.00                    | -                 |
| 1                                                                           | REAR VIDEO RECORDER (SN)                                                                                      | NOT NECESSARY | 580.00                    | -                 |
|                                                                             |                                                                                                               |               | 1,430.00                  | 320.00            |
|                                                                             | <b>LABOUR</b>                                                                                                 |               |                           |                   |
|                                                                             | TO KNOCKING & PULL OUT REAR SIDE PORTION AND RENEW DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL. |               | 1,400.00                  | 1,000.00          |
|                                                                             | TO PUTTY & SPRAY UP PAINT WORKS.                                                                              |               | 1,200.00                  | 800.00            |
|                                                                             | TO CHECK WIRING SYSTEM.                                                                                       |               | 50.00                     | 30.00             |
|                                                                             | TO UNDERSEAL.                                                                                                 |               | 150.00                    | 50.00             |
|                                                                             | TO REMOVE REVERSE SENSOR.                                                                                     |               | 100.00                    | 50.00             |
|                                                                             | TO REMOVE UPHOLSTERY.                                                                                         |               | 150.00                    | 80.00             |
|                                                                             | TO TRANSFER TAILGATE GLASS.                                                                                   |               | 180.00                    | 120.00            |
|                                                                             | TO TRANSFER TAILGATE FITTINGS.                                                                                |               | 150.00                    | 80.00             |
|                                                                             | TO REMOVE EXHAUST PIPE.                                                                                       | NOT NECESSARY | 150.00                    | -                 |
|                                                                             | TO REMOVE REAR CAMERA AND VIDEO RECORDER.                                                                     |               | 200.00                    | 100.00            |
|                                                                             |                                                                                                               |               | 3,730.00                  | 2,310.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                                                               |               | <b>13,830.08</b>          | <b>7,492.24</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                               |               |                           | <b>6,000.00</b>   |

Report Ref No. CS/FC118000842/Aqbn2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.