

CC 3, ASM 18000845, KPa3 52

SMJW
S8m00724

Surveyor:

Kenneth

DOI:

ASSIGNMENT

12-1-18

Date / Time:

12-1-18 2:55

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SJR 3914E

Claim No. : S8m00724 // 2750514

Name of Insured : SFA RMKS S

Policy No. : VCP1688911

Insured Tel No. : HP:

Make / Model : M.F. Lancer

Excess Sec II :SS D.O.A : 10-1-18

Place of Accident : MPH BUNTA USLARA

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : ASOGAN SLO MUTHUKRISHNAN

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : 43975444 (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

188

SAC 572M



INSRS: WSP: Long-Cab
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
7/6/18	Non-Reporting ltr (1st):	
2 min	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
29/10/2018 @ 5:38pm	Call OI:	7 29/10/2018
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 7/11/18 Sent By: JSM

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: \$\$ (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: 4/9/18 Confirm with: Jasmine Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 27. If NO or B 28, Ass. Lia :

Repair Cost: W/HST \$ 13161.00 270 accident due to wet road condition and car-ended TP

Loss of Rental (LOR): \$ 828.80 (8 days) x \$103.60

Loss of Use (LOU): \$ (\$ x days)

Loss of Income (LOI): \$ 4w.w (\$ 50 x 8 days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search \$ 5.25 1) Claim status: Normal/Reject/Private Settle

Medical: \$ - 2) Report Format: TP

Disbursement: \$ - (e.g. Tow/ Independent)

Legal Cost \$ - 3) Survey fee: \$ 350.00

Total: \$ 14395.15 Global Sum SS: 14300 W

FINAL PAYMENT Date/Time: 4/9/18 Confirm with: Jasmine Email Call

Payee 1: \$ 14300.00 Name 1: Trans-cab Auto Services Pte Ltd

Payee 2: (Strike if N.A.) \$ Name 2:

Payee 3: (Strike if N.A.) \$ Name 3:

COPY SENT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC3/ASM18000845/Kka3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 15-01-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJR 3914E	Veh. Inspected	SHC 5272M
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00724	Excess (\$)	0.00
Assign From		Assign Date	15/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/01/2018	Inspection Date	12/01/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5272M - AXA

AAD1801-127

Not Authored

LI Pay \$12,300

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC 5272M - CANDY
VF1ABL15AUC276718
RENAULT
LATITUDE
10.01.2018
AXA

PART		LIST
1	1 BUMPER COVER REAR	\$ <i>Bu</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$ <i>Bu</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$ <i>Sm</i> 113.47 ^
4	1 BUMPR BRACKET SIDE RH REAR	\$ <i>Sm</i> 135.97 X
5	1 BUMPR RETAINER RH REAR	\$ <i>Sm</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$ <i>CM</i> 43.61 ✓
7	1 BUMPR BRACKET SIDE LH REAR	\$ <i>Sm</i> 135.97 X
8	1 BUMPR RETAINER LH REAR	\$ <i>Sm</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$ <i>Sm</i> 43.61 X
10	1 BUMPER BEAM REAR	\$ <i>Bu</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ <i>R</i> 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$ <i>Bu</i> 225.95 ✓
13	1 BOOT REAR	\$ <i>Bu</i> 2,872.68 ✓
14	1 BOOT FINISHER	\$ <i>Sm</i> 470.06 X
15	1 BOOT WHEATERSTRIP	\$ <i>161.50 Sm Dist</i> 323.05 <i>306in</i>
16	1 BOOT REFLECTOR LAMP LH	\$ <i>Sm</i> 493.35 X
17	1 BOOT REFLECTOR LAMP RH	\$ <i>R</i> 493.35 ✓
18	1 BOOT BADGE 'RENAULT'	\$ <i>R</i> 225.36 ✓
19	1 BOOT BADGE	\$ <i>R</i> 225.36 ✓
20	1 BOOT STRUT LH	\$ <i>Sm</i> 276.08
21	1 BOOT STRUT RH	\$ <i>Sm</i> 276.08
22	1 BOOT HINGE LH	\$ <i>R</i> 367.84
23	1 BOOT HINGE RH	\$ <i>R</i> 367.84
24	1 BOOT INNER TRIM	\$ <i>Sm</i> 586.45 } X
25	1 BOOT SWITCH	\$ <i>R</i> 168.13
26	1 BOOT LOCK	\$ <i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$ <i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$ <i>Sm</i> 50.52
29	2 BOOT RUBBER PLUG	\$ <i>Sm</i> 221.81
30	1 FENDER PANEL REAR LH	\$ <i>R</i> 3,299.13
31	1 FENDER PANEL INNER TRIM REAR RH	\$ <i>Sm</i> 671.45
32	1 FENDER PANEL REAR RH	\$ <i>Bu</i> 3,299.13 ✓
33	1 WHEELARCH REAR RH	\$ <i>Sm</i> 543.47 X
34	1 TAILLAMP RH	\$ <i>ng. 101</i> 552.55 ✓

162 30.09

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-127

N0.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5272M - AXA

35	1	TAILLAMP PANEL RH	\$	<i>M</i>	986.70 ✓
36	1	TAILLAMP LH	\$	<i>Su</i>	552.55 X
37	1	TAILLAMP PANEL LH	\$	<i>n</i>	986.70 ^
38	1	OUTER PANEL REAR (End Panel)	\$	<i>M</i>	1,471.77 ✓
39	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Su</i>	404.56 X
40	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>n</i>	2,189.88 X
41	1	SPARE WHEEL PANEL TRIM	\$	<i>Su</i>	612.21 X
42	1	EXHAUST REAR	\$	<i>n</i>	7,489.05 X
43	1	EXHAUST CAP REAR	\$	<i>n</i>	230.49 X <i>14 923-91</i>
TOTAL			\$		34,654.02
10%			\$		3,465.40
			\$		31,188.62

Special Nett

1	1SET	PARKING AID	\$	<i>Su/shot</i>	700.00 ✓
2	1SET	REAR BUMPER CLIP	\$	<i>n</i>	66.00 ✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>n</i>	33.00 ✓
4	1SET	BUMEP R BRACKET SIDE CLIP RH RR	\$	<i>n</i>	10.00 X
5	1SET	BUMEP R RETAINER RH CLIP RR	\$	<i>n</i>	20.00 X
6	1SET	BUMEP R BRACKET SIDE CLIP LH RR	\$	<i>n</i>	10.00 X
7	1SET	BUMEP R RETAINER CLIP LH RR	\$	<i>n</i>	20.00 X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>n</i>	22.00 X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>n</i>	66.00 ✓
10	1	EXHAUST MOUNTING REAR	\$	<i>Su</i>	17.82 X
11	1SET	BOOT FINISHER CLIP	\$	<i>n</i>	24.20 X
12	1	BOOT STICKER "Trans-cab"	\$	<i>n</i>	30.00 ✓
13	1	BOOT STICKER "6555-3333"	\$	<i>n</i>	30.00 ✓
14	1	BOOT INNER TRIM CLIP	\$	<i>n</i>	45.00 X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>n</i>	35.00 X
16	1	FENDER INNER TRIM CLIP RH	\$	<i>n</i>	28.00 X
17	1	TAILLAMP CLIP RH	\$	<i>n</i>	5.00 X
18	1	TAILLAMP CLIP LH	\$	<i>n</i>	5.00 X
19	2	REAR WINDSCREEN SELANT	\$	<i>n</i>	80.00 <i>40sn</i>
20	1	WINDSCREEN MOULDING	\$	<i>n</i>	100.00 ✓
21	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>n</i>	100.00 <i>30sn</i>
22	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Su</i>	385.00 X
23	1	SPARE TYRE	\$	<i>Su</i>	330.00 X
TOTAL			\$		2,162.02
TOTAL PARTS			\$		33,350.64

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-127

NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHC5272M - AXA

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	12001
To Rust-Proofing Of The Affected Areas.	\$	170.00	901
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	~ X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	~ X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 1001
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	~ X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	~ X
Towing Fees	\$	120.00	~ X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	220.00	~ X

TOTAL	\$	11,160.00
Over All Total	\$	44,510.64

**(PARTS BY PARTS)
 Repair Days**

15 Days
7 days

LKK Auto Consultant
 I hereby acknowledge and agree to the following:
 • To resurvey before/after spray painting
 • To disassemble parts during resurvey
 • To provide written confirmation
 • Third party survey is on "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed
 is subject to final approval from insurance company
 Acknowledged by Repairer:
 Signature:
 Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M00724
Our ref: CC3/ASM18000845/Kka3

Date: 25.01.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC 5272M


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12.01.2018 at the premises of M/s Trans-cab Auto Services Pte Ltd (Ang Mo Kio) and have the following to report:-

Workshop Estimate Amount	: S\$	44,510.64
Revised Estimate Amount	: S\$	12,300.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 7.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

12/1/18 50 marks

TP Veh	SHC 5272 M
Date of Reg	07 March 2018
DOA	10 Jan 2018

\$

(I) Estimated Book Value

Unit Cost	(OMV \$19,998.00 + 20%)	(PSP) 24,000.00
Import Duty		2,999.70
Registration Fee		140.00
PQP Paid		58,745.00
ARF Paid		12,498.00
Estimated Per Taxi Purchase Price		<u>98,382.70</u>
Estimated Per Taxi Purchase Price		98,382.70
Less 60% of ARF Paid		<u>7,498.80</u>
Estimated Full Lifespan Depreciation		<u>90,883.90</u>
Estimated Full Lifespan Depreciation		90,883.90
Times Balance Life (50/96 months)		<u>47,335.36</u>
Add 60% of ARF Paid		<u>7,498.80</u>
Estimated Book Value		<u><u>54,834.16</u></u>

(II) Adjusted LTA Rebate

PARF Rebate		9,373.00
PQP Paid		58,745.00
Times Balance Life (50/96 months)		<u>30,596.35</u>
Adjusted COE Rebate		<u>30,596.35</u>
PARF Rebate		9,373.00
Add Adjusted COE Rebate		<u>30,596.35</u>
Adjusted LTA Rebate		<u><u>39,969.35</u></u>

(Summary) Estimated Nett Value

Estimated Book Value		54,834.16
Less Adjusted LTA Rebate		<u>39,969.35</u>
Estimated Net Value		<u><u>14,864.81</u></u>



<SEEK MANDATE> - S8M00724 [ACCIDENT INVOLVING SJR 3914E(OI) & SHC 5272M(TP) ON 10/01/2018]

Type

🔔 Question

Message

Liability: Insured rear-ended third party. Spoken to insured, agreed to settle and aware NCD(if any) is affected. We seek your approval to offer Third Party repairer "Trans-Cab Auto Services Pte Ltd" is as follows:
- 1)COR(w/GST): \$13,161.00 + 2) Loss of Rental(8daysx\$103.60): \$828.80 + 3)Loss of Income(8daysx\$50.00): \$400.00 + 4)LTA Search fee: \$5.35 =Total: \$14,395.15. **07days recommendation for repair. **All the relevant documents had been uploaded in SMART CLAIM. For your approval please.
Hsiao Tong - 30 June 2018

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 30.06.2018

Survey Details:

Date of loss	10.01.2018
Date of appointment	12.01.2018
Date of survey	12.01.2018
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHC 5272M
Make and Model	RENAULT LATITUDE (1995CC)
Date of registration	07.03.2014
Excess	
Market Value	
Parf/COE Rebate	
Nett Loss	

Repair details:

Initial Estimate	\$	44,510.64
------------------	----	-----------

Proposed/Revised repair cost:

Parts	\$	13,002.68
Check items (estimate)		
Labour	\$	2,510.00
Total	\$	15,512.68
Lump Sum(if applicable)	\$	12,300.00

Number of days for repair	<u>7</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

Company Registration No. 109607198R

511 RAFFLES PLACE, #02-25 PAVANE INDUSTRIAL PARK, SINGAPORE 408933 TEL : 065 62563561 FAX : 065 62564315

Date: 30.06.2018

Remarks:

Mandate:

Liability(TP)		100%	
Proposed repair cost (w/GST)	\$	13,161.00	
Loss of use			
Loss of rental	\$	828.80	(8days x \$103.60)
Loss of income	\$	400.00	(8days x \$50.00)
LTA search fees	\$	5.35	
Others		-	
Proposed Total	\$	14,395.15	

◀ **Re:RE: <SEEK MANDATE> - S8M00724 [ACCIDENT INVOLVING SJR 3914E(OI) & SHC 5272M(TP) ON 10/01/2018]**

Type

 Information

Message

Pls proceed

Reply

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 28 August 2018 9:55 AM
To: 'jasminetan@transcab.com.sg'; 'Ng Wai Yin'; 'Zhe Wei'
(zhewei.kek@transcab.com.sg); claims@transcab.com.sg
Subject: Your Ref: AAD1801-127 (SHC 5272M) *Our Ref: CC3/ASM18000845/Kpa3s2
[ACCIDENT INVOLVING SJR 3917E(AXA) & SHC 5272M ON 10/01/2018]

Your Ref: **AAD1801-127 (SHC 5272M)**
Our Ref: CC3/ASM18000845/Kpa3s2

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SJR 3917E(AXA) & SHC 5272M ON 10/01/2018

We refer to the above matter.

We propose settlement at a global sum of **\$14,300.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Jasmine Tan <jasminetan@transcab.com.sg>
Sent: Friday, 31 August 2018 8:05 AM
To: Hsiao Tong (LKKAUTO); 'Ng Wai Yin'; 'Zhe Wei'; claims@transcab.com.sg
Subject: RE: Your Ref: AAD1801-127 (SHC 5272M) *Our Ref: CC3/ASM18000845/Kpa3s2 [ACCIDENT INVOLVING SJR 3917E(AXA) & SHC 5272M ON 10/01/2018]

Without Prejudice

Dear Hsiao Tong

Please refer to send us the payment.

Thank you
Best Regards
Jasmine Tan



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Direct Line : (65) 6603 1250
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Tuesday, 28 August 2018 9:55 AM
To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; Ng Wai Yin <waiyin.ng@transcab.com.sg>; 'Zhe Wei' (zhewei.kek@transcab.com.sg) <zhewei.kek@transcab.com.sg>; claims@transcab.com.sg
Subject: Your Ref: AAD1801-127 (SHC 5272M) *Our Ref: CC3/ASM18000845/Kpa3s2 [ACCIDENT INVOLVING SJR 3917E(AXA) & SHC 5272M ON 10/01/2018]

Your Ref: **AAD1801-127 (SHC 5272M)**
Our Ref: CC3/ASM18000845/Kpa3s2

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SJR 3917E(AXA) & SHC 5272M ON 10/01/2018

We refer to the above matter.

We propose settlement at a global sum of **\$14,300.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SJR 3914E (Insd veh)	Model:	RENAULT LATITUDE 2.0L DCI AUTO D/AB 4DR
	SHC 5272M (TP veh)		
Date of Accident:	10/01/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes		<input type="checkbox"/> No	
Repair Estimate	:	\$	47,626.36		
Final Repair Cost	:	\$	13,161.00		
Loss of Token Sum	:	\$	400.00	8	days at \$50.00 per day
Rental (if any)	:	\$	828.80	8	days
LTA / GIA Search Fee	:	\$	5.35		

Others: : \$

Final Settlement Sum (GLOBAL SUM) : \$ 14,300.00

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No:

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks PLEASE SEND THE CHEQUE PAYMENT TO TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST 63 SINGAPORE 569111

Payment Instruction: Payee's Breakdown		
1)	TRANS-CAB AUTO SERVICES PTE LTD	\$ 14,300.00

NUR SHAQILAH BTE ABDOL
WAHAB

11/09/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

Service Request Details

Claim: SRM00724

Reference: CC3/ASM18000845Kpa3s2  Loss Date

January 10, 2018 Request Date

August 21, 2018 Due Date

October 31, 2018 Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP) Type of Loss

Third Party Vehicle Damage Services

Direct settlement

Actions

Next Step: Finish the work

Complete Work

Make

Document Type

Document Sub Type

Upload Documents

Vehicle Information

Incident Vehicle Registration #: SHC5272M

Service Address

TPVD RENAULT

Model: BLK 626 CHOA CHU KANG ST 62, ... 680626

LATITUDE-2.0 L (A)

Primary Contact/Insured

STARMIKES

BLK 626 CHOA CHU KANG ST 62, CENTRE, 680626, Singapore

97973690

mariamal.a@sgh.com.sg

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

Messages Invoices History Documents

Assessment Metrics Notes

Service Request Details

Claim **S8M00724**

Reference **CC3/ASM18000945/Kpa3s2**

Next Step **Finish the work** Complete Work

January 10, 2018 Request Date
August 21, 2018 Due Date
October 31, 2018 Vendor Name

Vehicle Information

Incident Vehicle Registration # **SHC5272M**

Make **Service Address**

LKK AUTO CONSULTANTS PTE LTD (TP)

TPVD RENAULT Model

Third Party Vehicle Damage Services

LATITUDE-2.0 L (A) Model **BLK 626 CHOA CHU KANG ST 62, ... 680626**

Direct settlement

Primary Contact/Insured

STARMIKES
BLK 626 CHOA CHU KANG ST 62, CENTRE, 680626, Singapore
97973690
mariamal.a@sgh.com.sg

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

Messages Invoices History Documents
Assessment Metrics Notes

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	SHCS272M	Purchase Date	<input type="text" value="mm/dd/yyyy"/>																																													
Registration State	SINGAPORE	Registration Date *	<input type="text" value="03/07/2014"/>																																													
Mileage	656779	Age of Vehicle	3																																													
<table border="1"> <thead> <tr> <th>CATEGORY</th> <th>POLICY INFORMATION</th> <th>ASSESSMENT INFORMATION</th> <th>FNOL INFORMATION</th> <th>POST SURVEY INFORMATION</th> </tr> </thead> <tbody> <tr> <td>Manufacturing Year</td> <td>2013</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Make</td> <td>TPVD RENAULT</td> <td>RENAULT</td> <td>TAY KOK POW</td> <td></td> </tr> <tr> <td>Model</td> <td>LATITUDE-2.0 L (A)</td> <td>LATITUDE 2.0L DCI AUTO D</td> <td></td> <td><input type="text" value="mm/dd/yyyy"/></td> </tr> <tr> <td>Type</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Type of Paint</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Chassis No</td> <td></td> <td>VF1ABL15AUC276718</td> <td></td> <td></td> </tr> <tr> <td>Engine No</td> <td></td> <td>M9R8839C000783</td> <td></td> <td></td> </tr> <tr> <td>Engine Capacity</td> <td></td> <td>1995 cc</td> <td></td> <td></td> </tr> </tbody> </table>		CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	FNOL INFORMATION	POST SURVEY INFORMATION	Manufacturing Year	2013				Make	TPVD RENAULT	RENAULT	TAY KOK POW		Model	LATITUDE-2.0 L (A)	LATITUDE 2.0L DCI AUTO D		<input type="text" value="mm/dd/yyyy"/>	Type					Type of Paint					Chassis No		VF1ABL15AUC276718			Engine No		M9R8839C000783			Engine Capacity		1995 cc			Driving Experience	0
CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	FNOL INFORMATION	POST SURVEY INFORMATION																																												
Manufacturing Year	2013																																															
Make	TPVD RENAULT	RENAULT	TAY KOK POW																																													
Model	LATITUDE-2.0 L (A)	LATITUDE 2.0L DCI AUTO D		<input type="text" value="mm/dd/yyyy"/>																																												
Type																																																
Type of Paint																																																
Chassis No		VF1ABL15AUC276718																																														
Engine No		M9R8839C000783																																														
Engine Capacity		1995 cc																																														
		Driver License #	<input type="text"/>																																													

« **Assessment Details**

[General & Workshop Details](#)
[Vehicle & Driver Details](#)
[Vehicle Condition](#)
[Taxes & Ratio](#)
[Parts & Labour](#)
[Miscellaneous](#)
[Summary](#)

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	01/12/2018		General condition	Good
Total Loss	Yes	No	Steering (Serviceable)	Yes No
Towing Charges	0		Footbrake (Serviceable)	Yes No
Voluntary Excess	0		Handbrake (Serviceable)	Yes No
Compulsory Excess	0		Engine Modification	Yes No
Young/Inexperienced/Un- named Driver Excess	0		Pre-accident condition	Good
Other Excess				

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	215/60R16	Rear Tyre Size	215/60R16
Front left side	GITI 9mm	Rear left side	FALKEN 8mm
Front right side	GITI 9mm	Rear right side	FALKEN 8mm

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Parts

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BITTRN	DISC QUNTY%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1			BUMPER COVER REAR			Bent	1108.48		10		997.61	Reviewing	
	2	1			BUMPER LOWER REAR			Buckled	768.84		10		691.96	Reviewing	
	3	1			BUMPER BRACKET CTR REAR			Serviceable	0		10		0	Reviewing	
	4	1			BUMPER BRACKET SIDE RH REAR			Serviceable	0		10		0	Reviewing	
	5	1			BUMPER RETAINER RH REAR			Serviceable	0		10		0	Reviewing	
	6	1			BUMPER REFLECTOR RH			Cracked	43.61		10		39.25	Reviewing	
	7	1			BUMPER BRACKET SIDE LH REAR			Serviceable	0		10		0	Reviewing	
	8	1			BUMPER RETAINER LH REAR			Serviceable	0		10		0	Reviewing	
	9	1			BUMPER REFLECTOR LH			Serviceable	0		10		0	Reviewing	
	10	1			BUMPER BEAM REAR			Bent	777.52		10		699.77	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC QUANTY	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	27	2			LICENCE PLATE LAMP			Serviceable	0		10		0	Reviewing	
	28	2			BOOT RUBBER PLUG			Serviceable	0		10		0	Reviewing	
	29	1			FENDER PANEL REAR LH			Repair	0		10		0	Reviewing	
	30	1			FENDER PANEL INNER TRIM REAR RH			Serviceable	0		10		0	Reviewing	
	31	1			FENDER PANEL REAR RH			Buckled	3299.13		10		2969.22	Reviewing	
	32	1			WHEELARCH REAR RH			Serviceable	0		10		0	Reviewing	
	33	1			TAILLAMP RH			Cracked	552.55		10		497.3	Reviewing	
	34	1			TAILLAMP PANEL RH			Bent	986.7		10		868.03	Reviewing	
	35	1			TAILLAMP LH			Serviceable	0		10		0	Reviewing	
	36	1			TAILLAMP PANEL LH			Repair	0		10		0	Reviewing	
	37	1			OUTER PANEL REAR (END PANEL)			Bent	1471.77		10		1324.59	Reviewing	
	38	1			OUTER PANEL REAR (END PANEL) TRIM			Serviceable	0		10		0	Reviewing	
	39	1			SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)			Repair	0		10		0	Reviewing	
	40	1			SPARE WHEEL PANEL TRIM			Serviceable	0		10		0	Reviewing	

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR RSR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	11		TO TRANSFER OF REAR FENDER FITTINGS. ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	0	0	0	Reviewing		
	12		TOWING FEES.	0	0	0	Reviewing		
	13		TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	120	0	0	Reviewing		
	14		TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	0	0	0	Reviewing		

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Paris & Labour Miscellaneous Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		7	
	2	BOOT WEATHERSTRIP (50%)	Reviewing	161.52	DISTORTED / DENTED	
	3	SET PARKING AID	Reviewing	700	SCRATCHED / SHORTED	
	4	SET REAR BUMPER CLIP	Reviewing	66	NECESSARY	
	5	SET BUMPER BRACKET CTR CLIP	Reviewing	33	NECESSARY	
	6	SET BUMPER BRACKET SIDE CLIP RH RR	Reviewing	0	NOT NECESSARY	
	7	SET BUMPER RETAINER RH CLIP RR	Reviewing	0	NOT NECESSARY	
	8	SET BUMPER BRACKET SIDE CLIP LH RR	Reviewing	0	NOT NECESSARY	
	9	SET BUMPER RETAINER CLIP LH RR	Reviewing	0	NOT NECESSARY	
	10	SET BUMPER LOWER REAR RIVET	Reviewing	0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	24	SPARE TYRE RIM (ROUE 7J 16H 2547)	Reviewing	0	SERVICEABLE	
<input type="checkbox"/>	25	SPARE TYRE	Reviewing	0	SERVICEABLE	

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Claim Amount \$15,512.68

Claim Amount \$15,512.68

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$11,746.16	\$11,746.16
Labour	\$2,510.00	\$2,510.00
Miscellaneous	\$1,256.52	\$1,256.52

Submit for Review

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratto Parts & Labour Miscellaneous Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1		Reviewing	12,300		
		FINAL LUMP SUM				