

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	11	SET BUMPER LOWER REAR CLIP	Reviewing	66	NECESSARY	
	12	EXHAUST MOUNTING REAR	Reviewing	0	SERVICEABLE	
	13	SET BOOT FINISHER CLIP	Reviewing	0	NOT NECESSARY	
	14	BOOT STICKER "TRANS-CAB"	Reviewing	30	NECESSARY	
	15	BOOT STICKER "6555-3333"	Reviewing	30	NECESSARY	
	16	BOOT INNER TRIM CLIP	Reviewing	0	NECESSARY	
	17	SET FENDER WHEELARCH REAR RH CLIP	Reviewing	0	NOT NECESSARY	
	18	FENDER INNER TRIM CLIP LH	Reviewing	0	NOT NECESSARY	
	19	TAILLAMP CLIP RH	Reviewing	0	NOT NECESSARY	
	20	TAILLAMP CLIP LH	Reviewing	0	NOT NECESSARY	
	21	REAR WINDSCREEN SEALANT	Reviewing	40	NECESSARY	
	22	WINDSCREEN MOULDING	Reviewing	100	NECESSARY	
	23	REAR WINDSCREEN INNER SPONGE SEAL	Reviewing	30	NECESSARY	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTRR%	DISC COUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>	41	1			EXHAUST REAR		Repair	Repair	0		10		0	Reviewing	
<input type="checkbox"/>	42	1			EXHAUST CAP REAR		Repair	Repair	0		10		0	Reviewing	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR REAR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
<input type="checkbox"/>	1		PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	880	0	0	Reviewing		
<input type="checkbox"/>	2		PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1200	0	0	Reviewing		
<input type="checkbox"/>	3		TO RUST-PROOFING OF THE AFFECTED AREAS.	90	0	0	Reviewing		
<input type="checkbox"/>	4		TO REINSTALL REAR BUMPER PARKING SENSOR.	60	0	0	Reviewing		
<input type="checkbox"/>	5		TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	60	0	0	Reviewing		
<input type="checkbox"/>	6		TO REPAIR AND REALIGN REAR EXHAUST PIPE.	0	0	0	Reviewing		
<input type="checkbox"/>	7		TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	0	0	0	Reviewing		
<input type="checkbox"/>	8		TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.)	100	0	0	Reviewing		
<input type="checkbox"/>	9		TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, AT TACHMENT AND PERFORM WATER SEEPAGE TEST.)	0	0	0	Reviewing		
<input type="checkbox"/>	10		TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	0	0	0	Reviewing		

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPLU BTRFLS	DISC QUNTN	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	11	1			BUMPER BEAM BRACKET LH REAR			Repair	0		10	0	0	Reviewing	
	12	1			BUMPER BEAM BRACKET RH REAR			Bent	225.95		10		203.36	Reviewing	
	13	1			BOOT REAR			Bent	2872.68		10		2585.41	Reviewing	
	14	1			BOOT FINISHER			Serviceable	0		10		0	Reviewing	
	15	1			BOOT REFLECTOR LAMP LH			Serviceable	0		10		0	Reviewing	
	16	1			BOOT REFLECTOR LAMP RH			Dented	493.35		10		444.02	Reviewing	
	17	1			BOOT BADGE 'RENAULT'			Necessary	225.36		10		202.82	Reviewing	
	18	1			BOOT BADGE			Necessary	225.36		10		202.82	Reviewing	
	19	1			BOOT STRUT LH			Serviceable	0		10		0	Reviewing	
	20	1			BOOT STRUT RH			Serviceable	0		10		0	Reviewing	
	21	1			BOOT HINGE LH			Repair	0		10		0	Reviewing	
	22	1			BOOT HINGE RH			Repair	0		10		0	Reviewing	
	23	1			BOOT INNER TRIM			Serviceable	0		10		0	Reviewing	
	24	1			BOOT SWITCH			Repair	0		10		0	Reviewing	
	25	1			BOOT LOCK			Repair	0		10		0	Reviewing	
	26	1			BOOT LOCK CATCH			Repair	0		10		0	Reviewing	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Sum Insured	0		License Type		
Market Value	0		License Issue Date	mm/dd/yyyy	
			License Expiration Date	mm/dd/yyyy	
			Address		
			Address type		
			Gender	Unknown	
			Marital status	Unknown	
			Identification #	S1312691G	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	6/18/18 5:04 PM	12300	12300	Open	Share	Close
TAY Ernest	1/26/18 10:54 AM	15512.68	15512.68	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKK RESURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	September 8, 2018
Immediate Advice (with mandate) did 300618.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 30, 2018
LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 30, 2018
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 18, 2018
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 18, 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	June 18, 2018
Preliminary Advice.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	January 26, 2018
TP - SURVEY REQUEST.msg	Letters and Correspondence	Surveyor / Assessor	PATIL Anol	January 19, 2018
SHCS272M TP.pdf	Reports & Statement	GIA Report	ANG Yvoine	January 15, 2018
SJR3914E INSD GIA.PDF	Forms / Claim Documents	Claim Form	PATIL Anol	January 15, 2018